

ASS. REC. BY:

REF:

CS3/CTI 19004107/Ecd3

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Boon San (mer. man)

CTI

Date/Time: 6/3/19

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBH 737S

Insured:

GBG 681Z

at Workshop m/s

Bluwei Automotive

Tel:

6745 2088

of

1 Kiki Bukit Ave 6 #01-55

Policy No:

DMCKEN30796H18000

Claim No:

SNM19D 201073C02 / 1

Sum Insured:

Excess:

Make of Veh:

D.O.A.

5/3/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

6/3/19

H.O.D. Endorsement:

Date/Time:

6/3 @ 10pm

Person Contacted:

Sally

Vehicle ☒ IN ☐ OUT


Date/Time	Action/Instruction (X) Estimate
	GBH 737S - X
	GBG 681Z - CS/CTI 19004324/Kids den: 5/3/2019
	Dismantle: 12/3/2019
	After repair: 19/3/2019

Steve

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **GBH 737S** Yt Regn: **28/12/17**
 Type: M.Car / M.Cycle / Bus / Van **(Lorry)** Taxi / Prime Mover /
 Truck / Trailer or
 Make: **NISSAN Cabstar** G.C. **2953**
 Colour: **White** A/C Insured / Std / NI / NA
 Sp. Reading: **19795** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **JN1SC2F 247086111.2**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **Inorder** / Jammed / Leaked / Burnt or
 Brake: **Inorder** / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / **STD A/Rim** or
 Tyre Size: F: **175/80R15**
 R: **11**
 BS **(DUN)** / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: **7** mm Rear: **7** mm
 R/Bal. **7** mm L/Bal. **7** mm
 D.O.A. **5/3/19** D.O.I. **7/3/19**
 Survey held at **Bunel**
 Des. of Damages: **(Frt)** **(Rear)** / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time : Action / Instruction

MV- 64,000
 PV- 39,715
 INV- 24,285

Repair range 7-8K, 8 days

[Signature]
 21/3/2019

Date/Time: File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: **8**

Resurvey No. of Trip: **2**

Survey Fee:

4) Date/Time: File Return to?

2)

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Transportation

1) S + R + G

1) Photos

1) Other

Report Format: **PRE**

Lump Sum / I.B.F. (\$)

☐

Catherine Chong (LKK Auto)

From: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>
Sent: Wednesday, 6 March, 2019 2:09 PM
To: 'Shu Pei (LKKAuto)'; 'assignments'; 'sur@lkkauto.com'; 'Chong Boon Sen'
Subject: RE: ACCIDENT INVOLVING GBH737S & GBG681Z ON 5-3-2019 (CLAIM REF: SNM19D201073C02/1)

Dear Boon Sen,

Thank you for your assignment.

Kindly create claim in merimen.

Best Regards,

Veron Chen | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 6 March 2019 11:24 AM
To: Sim Teo Koon <tk_sim@juseq.com.sg>
Cc: 'Bluwel2088' <bluwel2088@yahoo.com.sg>; Admin A <admin-a@lkkauto.com>
Subject: RE: ACCIDENT INVOLVING GBH737S & GBG681Z ON 5-3-2019 (CLAIM REF: SNM19D201073C02/1)

Without Prejudice

Dear Sir,

We pri.

Dear LKK,

Pls pri.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Sim Teo Koon [mailto:tk_sim@juseq.com.sg]

Sent: Wednesday, 6 March, 2019 11:23 AM

To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>

Cc: 'Bluwel2088' <bluwel2088@yahoo.com.sg>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: RE: ACCIDENT INVOLVING GBH737S & GBG681Z ON 5-3-2019 (CLAIM REF: SNM19D201073C02/1)

Dear Sir,

We refer to your email.

We are instructed that our client is not agreeable to all the surveyors proposed by you.

Pursuant to Appendix C, pre-action protocol for NIMA cases, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

- 1) PAR Automotive Consultancy,
- 2) AEON Auto Consultants LLP,
- 3) Absolute Appraisal Services,
- 4) LCW APPRAISER PTE LTD
- 5) Treasure Appraisal Services,
- 6) Pal's Appraisal Pte Ltd,
- 7) Mc-Coy Appraiser Pte Ltd,
- 8) Prominent Appraiser Services,
- 9) Carlink Consultancy;
- 10) United Appraisal & Management Pte Ltd

Please be informed that if the above is not agreeable by you, our client's motor vehicle is available for pre-repair inspection at the under-stated workshop:-

Bluwel Automotive Service Pte Ltd,
Autobay @ Kaki Bukit.
1, Kaki Bukit Ave 6, Blk C, #01-55, Singapore 417883
Person In-Charge: Ms. Sally. Tel: 6745 2088

*** Further, please remind your appointed surveyor to request for post repair inspection if you wish to do so under NIMA Protocol Appendix C paragraph 2.11.**

Regards,

Sim Teo Koon (On behalf of Mr Michael Yap)

JusEquity Law Corporation.

Tel: 6506 6065, Fax: 6536 9339

E-mail: tk_sim@juseq.com.sg

From: Elaine Cheong [mailto:elaine.cheong@sg.cntaiping.com]

Sent: 06 March 2019 10:33

To: Sim Teo Koon <tk_sim@juseq.com.sg>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: FW: ACCIDENT INVOLVING GBH737S & GBG681Z ON 5-3-2019 (CLAIM REF: SNM19D201073C02/1)

WITHOUT PREJUDICE

Dear Mr Sim,

We refer to your email of 06.03.19.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Aside to Boon Sen,

Please follow up.

Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg No. 200208384E
DID: 6389 6530
Fax: 6224 7478 / 6224 7175
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com



From: Sim Teo Koon [mailto:tk_sim@juseq.com.sg]

Sent: Wednesday, 6 March, 2019 9:48 AM

To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>

Subject: FW: ACCIDENT INVOLVING GBH737S & GBG681Z ON 5-3-2019

Dear Sirs,

Please refer to our Notice of Accident.

Regards,

Sim Teo Koon (On behalf of Mr Michael Yap)

JusEquity Law Corporation

171 Chin Swee Road #02-06, CES Centre

Singapore 169877

Tel: 6506 6065 / 6536 9339

Fax: 6536 5368

E-mail: tk_sim@juseq.com.sg

This message (and all its attachments) is intended only for the use of the individual or entity to whom it is addressed and is privileged and confidential. If you are not the intended recipient, please notify us immediately by return electronic mail, delete this message and you should not disseminate, distribute or copy any information contained herein.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



JusEquity Law Corporation

ADVOCATES & SOLICITORS • COMMISSIONER FOR OATHS

171 Chin Swee Road #02-06, CES Centre, Singapore 169877

Telephone: (65) 6536 9339, Fax: (65) 6536 5368

Email: claims@juseq.com.sg

website: www.juseq.com.sg

Our Ref: JEQ/190183/0319/ BLU

Your Ref: GBG681Z

5 March 2019

JUST FLY IT PTE. LTD.
10 ANSON ROAD # 18 - 03
INTERNATIONAL PLAZA
SINGAPORE 079903

By Post Only

China Taiping Insurance (Singapore) Pte. Ltd.
Singapore

**By Fax: 6224 7478 &
Email**

Dear Sir

ACCIDENT INVOLVING GBH737S & GBG681Z ON 5-3-2019

We act for the owner of vehicle no. GBH737S.

We hereby notify you of a road traffic accident on **5 March 2019** at about **1030 hrs**, at CTE involving our client's vehicle and vehicle registration no. **GBG681Z** driven by you / your insured at the material time. A copy of our client's accident report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Encl.

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.



SINGAPORE POLICE FORCE

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

To: Sim
Dis arrange PRI.
05/3/19.



T/20190305/2051

1 of 5

Report No. T/20190305/2051

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
05/03/2019 12:31

Vide Report No.:
E/20190305/0057

Station Diary No.:
49

Informant's Particulars

Name of Informant: CHENG CHUNG HANG			Address: APT BLK 538 WOODLANDS DRIVE 16 #09-147 SINGAPORE 730538		
ID Type / ID No.: NRIC NO / S9470059J			Contact No.: Home/Office: Mobile: 90042843		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 25	Date of Birth: 19/02/1994	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: SERVICE TECH			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 05/03/2019 10:30	Type of Location: Straight Road
Location: Along Road 1 CENTRAL EXPRESSWAY				
Near to Ang mo Kio Ave 1 Exit				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow: One Way	Traffic Control:	Traffic Volume: Heavy		
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBC699U		TOYOTA	HIACE MANUAL	Silver		0
GBG681Z		NISSAN	NV200 1.5L MT ABS AIRBAG 2WD 6DR	Silver		0



SINGAPORE POLICE FORCE



T/20190305/2051

Police Station Of Origin:

Bishan N.P.C

20 Bishan Street 23 SINGAPORE 579757

Tel No: 1800-5529999

2 of 5

Report No. T/20190305/2051

CONTINUATION OF REPORT

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBH737S		NISSAN	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5	White		4

Details of Person Involved

Any Pedestrian Involved: No

No. of Pedestrians Injured: NIL

Use of Pedestrian Crossing: NA

Driver

Name	RAJENDRA S/O AYYAKANNU	ID No.	S1420597G
Related Vehicle	GBC699U	Contact No.	94519234
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Passenger

Name	HTOO MYAT AUNG	ID No.	G0696617P
Related Vehicle	GBH737S	Contact No.	96874176
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Name	CHENG CHUNG HANG	ID No.	S9470059J
Related Vehicle	GBH737S	Contact No.	90042843
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL



**SINGAPORE
POLICE FORCE**



T/20190305/2051

Police Station Of Origin:

Bishan N.P.C

20 Bishan Street 23 SINGAPORE 579757

Tel No: 1800-5529999

3 of 5

Report No. T/20190305/2051

CONTINUATION OF REPORT

Passenger			
Name	WAI PHYO HAN	ID No.	G3159616K
Related Vehicle	GBH737S	Contact No.	96874174
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	ELUMALAI GOVINDARAJ	ID No.	G8411190U
Related Vehicle	GBH737S	Contact No.	90818605
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	LOW CHEE LEONG	ID No.	G2911406X
Related Vehicle	GBH737S	Contact No.	96874170
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 05/03/2019 at about 1030hrs, I was driving my vehicle (GBH737S) along CTE near to Ang mo kio Ave 1 exit.

My vehicle was travelling on the second lane from the right and there was a vehicle (GBC699U) in front of my vehicle that slow down to a complete stop as such I also slow down my vehicle to a stop. Few second later after my vehicle stop, I felt an impact from the rear of my vehicle and due to the strong impact my vehicle moved forward and hit onto the rear of the vehicle (GBC699U) as such I alight my vehicle and discovered that my vehicle was hit by vehicle (GBG681Z).

I would wish to state that police and ambulance were attended to the accident. There were two persons conveyed by the ambulance. When the accident there was four passengers on board of my vehicle.



**SINGAPORE
POLICE FORCE**



T/20190305/2051

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

4 of 5

Report No. T/20190305/2051

CONTINUATION OF REPORT

My vehicle does have in built camera and it did capture the footage of the accident.

**SINGAPORE
POLICE FORCE**

T/20190305/2051

Police Station Of Origin:

Bishan N.P.C

20 Bishan Street 23 SINGAPORE 579757

Tel No: 1800-5529999

5 of 5

Report No. T/20190305/2051

CONTINUATION OF REPORT**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Sgt 2 TAN CHIN SENG, JASON

Signature Of Interpreter:

Not applicable

Signature Of Informant:

Date/Time:

05/03/2019 12:31

Officer In Charge Of Case:

TP / GIT /

Staff Sgt LEE GUANG HUI

Contact No.: 65476138

SINGAPORE
POLICE FORCE

Classification Of Case:

SN 061

Authentication Stamp

NP168

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6958H
Vehicle Details	
Vehicle No.:	GBH737S
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Mar 2019
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	ZD30029419N
Chassis No.:	JN1SC2F24Z0861112
Maximum Power Output:	-
Open Market Value:	\$27,176.00
Original Registration Date:	28 Dec 2017
First Registration Date:	28 Dec 2017
Transfer Count:	1
Actual ARF Paid:	\$1,359.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$45,112.00
COE Rebate Amount:	\$39,715.00
Total Rebate Amount:	\$39,715.00

The information contained herein is correct as at 07 Mar 2019

OK



ANNOUNCING Autotrust Traders Pte Ltd

as sgCarMart Premium Dealer for the 3rd Consecutive Year



Autotrust Traders Pte Ltd

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

New 5 Years Cgo Renewal Toyota Altis 3.6A



2.5H18" A Low Interest 0%
Finance, 2 Years Warranty,
\$1000 Down Hatchy 2018
GV Credit Pte Ltd. (Sole)



Filter by Category:

Sort by Date Posted 20 results/page

Search Selection	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Nissan Cabstar	Any	Any	Any	2017	Any	Any	Any	Available
 Nissan Cabstar Fuel Type: Diesel Very Good Condition! This Machine Needs No Introduction! Proven And Reliable! Call Me Now! Tags: 2017 Nissan Cabstar, 2017 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan	Nissan Cabstar	\$54,500	\$6,280 /yr	10-Nov-2017	2,953 cc	20,000 km	Truck	Available
 Nissan Cabstar Fuel Type: Diesel Extremely Low Mileage 19700km, With Full Hood And Checkered Plate. 1 Owner, As Good As New. New Tyres, 100% Accident Free. Highest Trade-In, In-House Loan Available. Feel Free To Call Now. Adviser: Pte Ltd Tags: 2017 Nissan Cabstar, 2017 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan	Nissan Cabstar	\$54,800	\$6,370 /yr	13-Oct-2017	2,953 cc	19,700 km	Truck	Available
 Nissan Cabstar Fuel Type: Diesel First Investment Waived, Free First Year Insurance, Free 6 Months Road Tax, Call For Inquiry! Dell Auto Pte Ltd Tags: 2017 Nissan Cabstar, 2017 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan	Nissan Cabstar	\$63,800	\$7,240 /yr	29-Dec-2017	2,953 cc	-	Truck	Available
 Nissan Cabstar Fuel Type: Diesel Monthly \$725 Have Nissan Cabstar Diesel 10 Feet Lorry. Bank Loan Or In House Loan Welcome. Tags: 2017 Nissan Cabstar, 2017 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan	Nissan Cabstar	\$52,800	\$6,560 /yr	22-Mar-2017	2,953 cc	55,800 km	Truck	Available
 SC1 and Services Pte Ltd - Repair & Servicing SC1 Auto Services is a one-stop repair centre with expertise in vehicle servicing, repairs, and spray painting. Here you about this shop								
 Nissan Cabstar Fuel Type: Diesel Scratching Door? 1 Single Pussy Owner With Full Agent Maintain! (Immaculate Condition! No Repairs Needed! View And Test Drive To Believe! Door Step Viewer) Can Be Arranged! Call Our Friendly Sales Person... Pte Ltd Tags: 2017 Nissan Cabstar, 2017 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan	Nissan Cabstar	\$64,800	\$7,350 /yr	29-Dec-2017	2,953 cc	20 km	Truck	Available
 Nissan Cabstar Fuel Type: Diesel Cheapest And Best Condition In The Market. 1 Owner, Low Mileage, Accident Free Unit! Original Condition. No Repairs Needed. Up To Full Loan And Trade In Available! Contact Us For Viewing! Car (S) Pte Ltd Tags: 2017 Nissan Cabstar, 2017 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan	Nissan Cabstar	\$55,000	\$6,960 /yr	31-Jan-2017	2,953 cc	30,455 km	Truck	Available
 Nissan Cabstar Fuel Type: Diesel Brand New Condition Ex-Stock, High Trade In Price, Call For Arrange Viewing, Don't Miss It View To Believe. Pte Ltd Tags: 2017 Nissan Cabstar, 2017 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan	Nissan Cabstar	\$63,800	\$7,240 /yr	29-Dec-2017	2,953 cc	-	Truck	Available
 Nissan Cabstar Fuel Type: Diesel Best Deal Ever, No Gimmick, Free 6 Months Road Tax And Free 1st Year Insurance, 1st Instalment Waived, Warranty And Servicing By Tan Chong Motors, Multi Purpose 10-Ft Truck, Spacious Cabin, Call For V... Pte Ltd Tags: 2017 Nissan Cabstar, 2017 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan	Nissan Cabstar	\$63,800	\$7,240 /yr	29-Dec-2017	2,953 cc	-	Truck	Available



Nissan Cabstar \$64,800 \$7,350 /yr 29-Dec-2017 2,953 cc 18 km Truck Available

Fuel Type: Diesel

Servicing Done! 1 Single Pussy Owner With Full Agent Maintaint Immaculate Condition! No Repairs Needed! View And Test Drive To Believe! Door Step Viewing Can Be Arranged! Call Our Friendly Sales Perso...

Hua Hong Group Pte Ltd

Model: 2017 Nissan Cabstar

Tags: 2017 Nissan Cabstar, 2017 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, used Nissan



Nissan Cabstar \$64,800 \$7,350 /yr 28-Dec-2017 2,953 cc - Truck Available

Fuel Type: Diesel

Excellent Condition. Available In 3 Colors. First Installment Waived, Free First Year Insurance, Free 6 Months Road Tax, Call For Inquiry!

Bed Hong Pte Ltd

Model: 2017 Nissan Cabstar

Tags: 2017 Nissan Cabstar, 2017 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, used Nissan



That's a fine looking car interior

Customise your ride. Replace your leather seats, door panels, steering wheels and more with quality trims of your choice. List of the best workshops available. Each with merchant information, ranking and reviews to help you make the best decision.

Find out more



Nissan Cabstar \$64,800 \$7,350 /yr 28-Dec-2017 2,953 cc - Truck Available

Fuel Type: Diesel

Excellent Condition. Available In 3 Colors. First Installment Waived, Free First Year Insurance, Free 6 Months Road Tax, Call For Inquiry!

Bed Hong Pte Ltd

Model: 2017 Nissan Cabstar

Tags: 2017 Nissan Cabstar, 2017 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, used Nissan




Nissan Cabstar \$63,888 \$7,250 /yr 27-Dec-2017 2,953 cc 36 km Truck Available

Fuel Type: Diesel

Cheapest In The Market! In-house Loan Up To 100% Loan Available! Call Now For Viewing And Test Drive, No Obligation! See To Believe. Like Brand New. Super High Cde. Buy Back Scheme Available Too.

Model: 2017 Nissan Cabstar

Tags: 2017 Nissan Cabstar, 2017 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, used Nissan



Nissan Cabstar \$63,888 \$7,250 /yr 28-Dec-2017 2,953 cc 35 km Truck Available

Fuel Type: Diesel

Cheapest In The Market! In-house Loan Up To 100% Loan Available! Call Now For Viewing And Test Drive, No Obligation! See To Believe. Like Brand New.

Model: 2017 Nissan Cabstar

Tags: 2017 Nissan Cabstar, 2017 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, used Nissan

Save this search criteria, to get email alerts whenever a match is found.

Price Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

11,453 search results, view all results

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is a leading online car marketplace in Singapore. We offer a wide range of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars, SUVs, MPVs, and more. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car rental services. sgCarMart is a leading online car marketplace in Singapore. We offer a wide range of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars, SUVs, MPVs, and more. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car rental services.

sgCarMart is a leading online car marketplace in Singapore. We offer a wide range of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars, SUVs, MPVs, and more. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car rental services. sgCarMart is a leading online car marketplace in Singapore. We offer a wide range of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars, SUVs, MPVs, and more. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car rental services.

Follow sgCarMart.com

About Us Careers Contact Us Sitemap Terms of Service Privacy Policy Personal Data Protection Statement

©2004-2019 sgCarMart. All rights reserved.

MSME19030469 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 06/03/2019 13:41
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 06/03/2019 13:41
 Date Of Accident 05/03/2019 10:30
 Exact Location Of Accident CTE NEAR AMK AVE 1 EXIT
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBH737S
Insured/Policyholder
 Name Of Registered Owner TRINET TECHNOLOGIES PTE LTD
 Co Reg No 199706958H
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No Office-97398489
Vehicle Particulars
 Manufacturer NISSAN
 Model CABSTAR
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category COMMERCIAL VEHICLE
Insurance Company
 Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 1800112411
 Cover Note Number
Driver
 Name of Driver CHENG CHUNG HANG

NRIC No	S9470059J
Date Of Birth	19/02/1994
Occupation	OUTDOOR
Date Of Driving Pass	16/11/2017
Driving Experience	1 YEAR AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90042843
Fax Number	
Contact Number	
EMail Address	NOEMAIL
Address	BLK 538 WOODLANDS DRIVE 16 #09-147
Postcode	730538
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	Name: : HTOO MYAT AUNG Gender: : Male
Passenger 2	Name: : WAI PHYO HAN Gender: : Male
Passenger 3	Name: : ELYMALAI GOVINDARAJ Gender: : Male
Passenger 4	Name: : LOW CHEE LEONG Gender: : Male

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name BISHAN NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD: 20 BISHAN STREET 23 , POSTCODE: 579757 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-5529999 - FAX NO: 65561905

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT: T/20190305/2051.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: WITH TP WORKSHOP

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBG681Z

Vehicle Make/Model/Colour

Details Of Properties VEHICLE B

Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GBC699U

Vehicle Make/Model/Colour

Details Of Properties VEHICLE C

Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name HTOO MYAT AUNG

Approximate Age

Injuries Sustain

Injured person in which vehicle? GBH737S

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

DETAILS OF INJURED PERSON 2

Name ELUMALAI GOVINDARAJ

Approximate Age

Injuries Sustain

Injured person in which vehicle? GBH737S

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

Sketch Plan

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Driver's Signature

Reporting Centre Personnel's Signature

Date & Time: 01/5/19


(If driver is not the policyholder)
Date & Time: 6/6/19

NRIC/FIN No.:

BLUWEL

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 6/3/19

SINGAPORE POLICE FORCE

Driver's Signature

(If driver is not the policyholder)

Date & Time: 6/3/19

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: 6/3/19

1135 hrs

Sketch Plan #3

SINGAPORE
POLICE FORCE

T/20190305/2051

Police Station Of Origin:

Bishan N.P.C.

20 Bishan Street 23 SINGAPORE 579757

Tel No: 1800-5529999

1 of 5

Report No. T/20190305/2051

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:

05/03/2019 12:31

Vide Report No.:

E/20190305/0057

Station Diary No.:

49

Informant's Particulars

Name of Informant:

CHENG CHUNG HANG

Address:

APT BLK 538 WOODLANDS DRIVE 16 #09-147 SINGAPORE 730538

ID Type / ID No:

NRIC NO / S9470059J

Contact No.:

Home/Office:

Mobile: 90042843

Nationality:

SINGAPORE CITIZEN

Email:

Sex:

Male

Age:

25

Date of Birth:

19/02/1994

Type of Informant:

Driver

Race:

Chinese

Language:

Institution / School Name:

Occupation:

SERVICE TECH

Driving Licence Information:

Class: 3

Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police:	Drink Drive: No	Date/Time of Accident: 05/03/2019 10:30	Type of Location: Straight Road
Location: Along Road 1 CENTRAL EXPRESSWAY				
Near to Ang mo Kio Ave 1 Exit				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow: One Way	Traffic Control:	Traffic Volume: Heavy		

Type of Collision Moving Vehicle Against - Parked Vehicle	Anyone conveyed by ambulance: Yes
--	--------------------------------------

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBC699U		TOYOTA	HIACE MANUAL	Silver		0
GBC681Z		NISSAN	NV200 1.5L MT ABS AIRBAG 2WD 6DR	Silver		0

Sketch Plan #4



**SINGAPORE
POLICE FORCE**



T/20190305/2051

2 of 5

Police Station Of Origin:

Despatch N.P.C.

20 Esplanade Street 23 SINGAPORE 579757

Tel No: 1800-5529999

Report No. T/20190305/2051

CONTINUATION OF REPORT

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
NEA4737S		NISSAN	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5	White		4

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	RAJENDRA S/O AYYAKANNU		ID No.	S1420597G
Related Vehicle	GBC699U		Contact No.	94519234
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL
Passenger				
Name	HTOO MYAT AUNG		ID No.	G0696617P

Related Vehicle	GBH737S		Contact No.	96874176
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver Name	CHENG CHUNG HANG		ID No.	S9470059J
Related Vehicle	GBH737S		Contact No.	90042843
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Sketch Plan #5



**SINGAPORE
POLICE FORCE**



T/20190305/2051

3 of 5

Police Station Of Origin

Bishan N.P.C

20 Bishan Street 23 SINGAPORE 579757

Tel No: 1800-5529999

Report No. T/20190305/2051

CONTINUATION OF REPORT

Passenger Name	WAI PHYO HAN		ID No.	G3159616K
Related Vehicle	GBH737S		Contact No.	96874174
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Passenger Name	ELUMALAI GOVINDARAJ		ID No.	G8411190U
Related Vehicle	GBH737S		Contact No.	90818605
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL

		Licence & Expiry Date	
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger Name		ID No.	G2911406X
Related Vehicle	GBH737S	Contact No.	96874170
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details:

On 05-03/2019 at about 1030hrs, I was driving my vehicle (GBH737S) along CTE near to Ang mo kio Ave 1 exit

My vehicle was travelling on the second lane from the right and there was a vehicle (GBC699U) in front of my vehicle that slow down to a complete stop as such I also slow down my vehicle to a stop. Few second later after my vehicle stop, I felt an impact from the rear of my vehicle and due to the strong impact my vehicle moved forward and hit onto the rear of the vehicle (GBC699U) as such I alight my vehicle and discovered that my vehicle was hit by vehicle (GBG681Z)

I would wish to state that police and ambulance were attended to the accident. There were two persons conveyed by the ambulance. When the accident there was four passengers on board of my vehicle.

Sketch Plan #6

**SINGAPORE
POLICE FORCE**



T/20190305/2051

Police Station Of Origin
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

4 of 5

Report No. T/20190305/2051

CONTINUATION OF REPORT

My vehicle does have in built camera and it did capture the footage of the accident.

Accident Sketch Plan



SINGAPORE
POLICE FORCE



T/20190305/2051

5 of 5

Report No. T/20190305/2051

Police Station Of Origin:
Division N.P.C.
20 Rishan Street 23 SINGAPORE 579757
Tel No. 1800-5529999

CONTINUATION OF REPORT

Sketch Plan

Intervenant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E Sgt J TAN CHIN SENG JASON <i>Tan</i>	Signature Of Informant: <i>Chy</i>
Signature Of Interpreter: Not applicable	Date/Time: 05/03/2019 12:31
Officer In Charge Of Case: TP: SD Staff Sgt LEE GUANG HUI Contact No. 65476138	Classification Of Case: SN 061
Authentication Stamp APR 1 2019	<i>Jay</i>

Accident Sketch Plan



SINGAPORE POLICE FORCE ACKNOWLEDGEMENT SLIP

Ref: Report No: E/20190305/0057

SSS T100330 FADLI

(Recipient's Name, NRIC or Passport No. / Rank and No.)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Mar 2019		06 Mar 2019 17:53 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	TRINET TECHNOLOGIES PTE LTD , Co. Reg. No.: 199706958H		
Vehicle Reg. No.:	GBH737S	Date of Loss:	05/03/2019 10:00 - :59 [14 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D201073C02	Policy/Cover Note No.:	DMCVSN30796418000
Vehicle Reg. No. (Insured):	GBG681Z	Policy No. (Claimant):	1800112411
		Excess:	S\$0.00
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 15/03/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBH737S (SNM19D201073C02)
[GBG681Z]
TP
TRINET TECHNOLOGIES PTE LTD
Mar 5 2019 10:00AM
[-]
Bluwel Automotive Service Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports

1 per page ▼ ☒










































No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	06/03/19 14:56	Accident Statement	Load HTM	<input checked="" type="checkbox"/>







Photos/Images
































3 per page ▼ ☒












No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	06/03/19 14:56	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	06/03/19 14:56	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	06/03/19 14:56	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	06/03/19 14:56	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	06/03/19 14:56	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	06/03/19 14:56	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	06/03/19 14:56	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	06/03/19 14:56	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	06/03/19 14:56	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	06/03/19 14:56	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/03/19 08:02	General View	Load JPG	<input checked="" type="checkbox"/>
2	08/03/19 08:02	General View	Load JPG	<input checked="" type="checkbox"/>
3	08/03/19 08:02	General View	Load JPG	<input checked="" type="checkbox"/>
4	08/03/19 08:02	General View	Load JPG	<input checked="" type="checkbox"/>
5	08/03/19 08:02	General View	Load JPG	<input checked="" type="checkbox"/>
6	08/03/19 08:02	General View	Load JPG	<input checked="" type="checkbox"/>
7	08/03/19 08:02	General View	Load JPG	<input checked="" type="checkbox"/>
8	08/03/19 08:02	General View	Load JPG	<input checked="" type="checkbox"/>
9	08/03/19 08:02	General View	Load JPG	<input checked="" type="checkbox"/>
10	08/03/19 08:02	General View	Load JPG	<input checked="" type="checkbox"/>
11	08/03/19 08:02	General View	Load JPG	<input checked="" type="checkbox"/>
12	08/03/19 08:02	General View	Load JPG	<input checked="" type="checkbox"/>
13	08/03/19 08:02	General View	Load JPG	<input checked="" type="checkbox"/>
14	08/03/19 08:02	General View	Load JPG	<input checked="" type="checkbox"/>
15	08/03/19 08:02	General View	Load JPG	<input checked="" type="checkbox"/>
16	08/03/19 08:02	General View	Load JPG	<input checked="" type="checkbox"/>
17	08/03/19 08:02	General View	Load JPG	<input checked="" type="checkbox"/>
18	08/03/19 08:02	General View	Load JPG	<input checked="" type="checkbox"/>


Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
19	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
20	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
21	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
22	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
23	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
24	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
25	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
26	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
27	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
28	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
29	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
30	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
31	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
32	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
33	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
34	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
35	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
36	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
37	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
38	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
39	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
40	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
41	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
42	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
43	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
44	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
45	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
46	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
47	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
48	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
49	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
50	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
51	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
52	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
53	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
54	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
55	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
56	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
57	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
58	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
59	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
60	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
61	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
62	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
63	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
64	08/03/19 08:02	General View	Load JPG	<input checked="" type="checkbox"/>
65	08/03/19 08:02	General View	Load JPG	<input checked="" type="checkbox"/>
66	08/03/19 08:02	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
67	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
68	08/03/19 08:02	General View	 Load JPG	<input checked="" type="checkbox"/>
69	08/03/19 08:02	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
70	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	22/03/19 10:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
115	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	✓
116	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	✓
117	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	✓
118	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	✓
119	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	✓
120	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	✓
121	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	✓
122	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	✓
123	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	✓
124	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	✓
125	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	✓
126	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	✓
127	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	✓
128	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	✓
129	22/03/19 10:09	Photographs of Damaged Parts	 Load JPG	✓
130	22/03/19 10:10	Photo After Spray	 Load JPG	✓
131	22/03/19 10:10	Photo After Spray	 Load JPG	✓
132	22/03/19 10:10	Photo After Spray	 Load JPG	✓
133	22/03/19 10:10	Photo After Spray	 Load JPG	✓
134	22/03/19 10:10	Photo After Spray	 Load JPG	✓
135	22/03/19 10:10	Photo After Spray	 Load JPG	✓
136	22/03/19 10:10	Photo After Spray	 Load JPG	✓
137	22/03/19 10:10	Photo After Spray	 Load JPG	✓
138	22/03/19 10:10	Photo After Spray	 Load JPG	✓
139	22/03/19 10:10	Photo After Spray	 Load JPG	✓
140	22/03/19 10:10	Photo After Spray	 Load JPG	✓
141	22/03/19 10:10	Photo After Spray	 Load JPG	✓
142	22/03/19 10:10	Photo After Spray	 Load JPG	✓
143	22/03/19 10:10	Photo After Spray	 Load JPG	✓
144	22/03/19 10:10	Photo After Spray	 Load JPG	✓
145	22/03/19 10:10	Photo After Spray	 Load JPG	✓
146	22/03/19 10:10	Photo After Spray	 Load JPG	✓
147	22/03/19 10:10	Photo After Spray	 Load JPG	✓
148	22/03/19 10:10	Photo After Spray	 Load JPG	✓
149	22/03/19 10:10	Photo After Spray	 Load JPG	✓
150	22/03/19 10:10	Photo After Spray	 Load JPG	✓
151	22/03/19 10:10	Photo After Spray	 Load JPG	✓
152	22/03/19 10:10	Photo After Spray	 Load JPG	✓
153	22/03/19 10:10	Photo After Spray	 Load JPG	✓
154	22/03/19 10:10	Photo After Spray	 Load JPG	✓
155	22/03/19 10:10	Photo After Spray	 Load JPG	✓
156	22/03/19 10:10	Photo After Spray	 Load JPG	✓
157	22/03/19 10:10	Photo After Spray	 Load JPG	✓
158	22/03/19 10:10	Photo After Spray	 Load JPG	✓
159	22/03/19 10:10	Photo After Spray	 Load JPG	✓
160	22/03/19 10:10	Photo After Spray	 Load JPG	✓
161	22/03/19 10:10	Photo After Spray	 Load JPG	✓
162	22/03/19 10:10	Photo After Spray	Load JPG	✓

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/03/19 17:54	pri contact		Load PDF
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	06/03/19 13:52	Sketch Plan [Linked Accident Report Documents]		Load TIF
2	06/03/19 13:52	Sketch Plan #2 [Linked Accident Report Documents]		Load TIF
3	06/03/19 13:52	Sketch Plan #3 [Linked Accident Report Documents]		Load TIF
4	06/03/19 13:52	Sketch Plan #4 [Linked Accident Report Documents]		Load TIF
5	06/03/19 13:52	Sketch Plan #5 [Linked Accident Report Documents]		Load TIF
6	06/03/19 13:52	Sketch Plan #6 [Linked Accident Report Documents]		Load TIF
7	06/03/19 13:52	Accident Sketch Plan [Linked Accident Report Documents]		Load TIF
8	06/03/19 13:52	Accident Sketch Plan [Linked Accident Report Documents]		Load TIF
9	06/03/19 13:52	Accident Sketch Plan [Linked Accident Report Documents]		Load TIF
10	06/03/19 13:52	Accident Sketch Plan [Linked Accident Report Documents]		Load TIF

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	06/03/19 14:56	Accident Statement		Load HTM
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	06/03/19 14:56	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	06/03/19 14:56	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	06/03/19 14:56	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	06/03/19 14:56	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	06/03/19 14:56	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	06/03/19 14:56	Accident Photo		Load JPG <input checked="" type="checkbox"/>
7	06/03/19 14:56	Accident Photo		Load JPG <input checked="" type="checkbox"/>
8	06/03/19 14:56	Accident Photo		Load JPG <input checked="" type="checkbox"/>
9	06/03/19 14:56	Accident Photo		Load JPG <input checked="" type="checkbox"/>
10	06/03/19 14:56	Accident Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	06/03/19 13:52	Sketch Plan		Load TIF
2	06/03/19 13:52	Sketch Plan #2		Load TIF
3	06/03/19 13:52	Sketch Plan #3		Load TIF
4	06/03/19 13:52	Sketch Plan #4		Load TIF
5	06/03/19 13:52	Sketch Plan #5		Load TIF
6	06/03/19 13:52	Sketch Plan #6		Load TIF
7	06/03/19 13:52	Accident Sketch Plan		Load TIF
8	06/03/19 13:52	Accident Sketch Plan		Load TIF
9	06/03/19 13:52	Accident Sketch Plan		Load TIF
10	06/03/19 13:52	Accident Sketch Plan		Load TIF

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19004107/ECD3S2

Date: 08/04/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30796418000
Claimant Vehicle No :	GBH737S	Insured Vehicle No :	GBG681Z
Date of Loss:	05/03/2019	Nature of Claim:	TP
		Claim No:	SNM19D201073C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH737S		
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Engine No:	ZD30029419N
Reg. Date:	28/12/2017 (Man. Year: 2017)	Chassis No:	JN1SC2F24Z0861112
Colour:	White	Odometer:	19795 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/80R15	Rear Tyre Size:	175/80R15
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	06/03/2019	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit Singapore 417883
Date Inspected:	07/03/2019 Inspected At:	
Estimated Period of Repair:	8.0 days	

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 - \$8,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 08 Apr 2019)

Parts: N/A NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBH737S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >