

22/03/2002

ASS. REC. BY:

REF:

CS3/CTI19004110/Gcd357

Special Instruction:

Surveyor

XGQ

ASSIGNMENT (Office)

From (Person): Bao San (merman)

CTI

Date/Time: 6/3/19

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMC 2654 E

Insured:

SLP 9902L

at Workshop m/s Toh Motor

Tel:

9748 3351

9791 9594

of 160 S/m Drive #05-16

Policy No: DMPCSN 1824/218000

Claim No:

SNM19D201007C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

6/3/19

H.O.D. Endorsement:

Date/Time: 6/3 @ 2:30pm

Person Contacted:

Yi San

Vehicle (IN) OUT

Date/Time Action/Instruction (X) Estimate

SMC 2654 E - X

SLP 9902L - CS/CTI19004110/Gcd357 DOA: 28/2/2019

Dismantle: 8/3/2019

After repair: 15/3/2019

Simultaneous

PRS
Xal.

REF: China

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TS / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Toh Motor

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt.: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No.

SMC2654E

Yr Regn:

28 Jan 2018

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota CHR

C.C.

1797

Colour

yellow

A/C:

Insured / Std / NI / NA

Sp. Reading

6459

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

8YX102123555

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/60 R17

R:

"

BS / DUN / EXNOVA / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

D.O.I.

06-03-19

Survey held at

W/S

Qpm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$5000 - \$6000

RECEIVED 21 MAR 2019

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) S + RS. \$

) Photos

) Others

TOTAL

Report Format :

PRE

Lump Sum / I.B.I.: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Catherine Chong (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 6 March, 2019 10:55 AM
To: Serene Tan
Cc: Admin-D (LKKAuto)
Subject: RE: PRE-REPAIR SURVEY
Attachments: 04032019093214.pdf

Without Prejudice
Save as to costs

Dear Serene,

We pri.

Dear LKK,

Pls pri.

Regards,

Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896171
Fax: 62247175
Email: boonsen.chong@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Serene Tan [mailto:serene.tan@mneduco.com.sg]
Sent: Wednesday, 6 March, 2019 10:38 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>
Subject: RE: PRE-REPAIR SURVEY

Our Ref : MN.IG.T1.1912942.st

WITHOUT PREJUDICE
SAVE AS TO COSTS

NOTICE TO INSURERS OBJECTING TO THE LIST OF MOTOR SURVEYORS PROVIDED WITHIN 2 WORKING DAYS
PURSUANT TO PARAGRAPH 2.6 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)

Hi Boon Sen,

1. We refer to your email below.

2. We are instructed by LUMENS AUTO PTE LTD, the claimant and/or TOH MOTOR ENTERPRISE, the motor workshop for SMC 2654E that they are not agreeable to the appointment of the motor surveyors as stated in your said email.

3. In compliance with The State Courts Practice Directions (Amendment No. 1 of 2016), we propose to use one of the below mentioned motor surveyor to conduct the joint pre-repair survey ("hereinafter referred to as PRS") as a Single Joint Expert ("hereinafter referred to as a SJE").

- | | |
|---|--|
| 1. NICKY SEAH (Absolute Appraisal Services) | 6. ANDREW HOW (Prominent Appraiser Services) |
| 2. MICHAEL YAP TECK CHYE (MC-COY Appraiser Pte Ltd Consultancy) | 7. NG KONG BENG PATRICK (Carlink) |
| 3. DIXON YEO (Treasure Appraisal Services) | 8. ANANDA KUMAR BISWAS S/O B N |
| 4. BISWAS (United Appraisal & Management Pte Ltd) | 9. DENNIS YAP TECK WEE (PAL's Appraiser Pte Ltd) |
| 5. LOI BOON JUAN (Par Automotive Consultancy) | 10. ANDY YAP TECK LEE (LCW Appraiser Pte Ltd) |
| 6. AMAS ONG (AEON Auto Consultants LLP) | |

4. Please let us know within two (2) working days whether you agree to the appointment of any of the above motor surveyors as proposed by the claimant and/or the motor workshop as a Single Joint Expert ("hereinafter referred to as "SJE").

Thanks & Best Regards,
(For and on behalf of Mr Nedumaran Muthukrishnan)
Serene Tan (Ms)
M NEDUMARAN & CO
Advocates & Solicitors
Commissioner for Oaths

Branch Office:

11 Sin Ming Road
#B2-09 (Unit 2), Thomson V Two
Singapore 575629
Tel: 6509-8480 / 6509-8481
Fax: 6509-8482

Email : serene.tan@mneduco.com.sg

IMPORTANT NOTE: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509 8480, if you have received this message in error. Thank you.

From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]
Sent: Wednesday, 6 March 2019 10:34 AM
To: Serene Tan <serene.tan@mneduco.com.sg>; Irene Tay <irene.tay@sg.cntaiping.com>
Subject: RE: PRE-REPAIR SURVEY

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Serene Tan [<mailto:serene.tan@mneduco.com.sg>]

Sent: Wednesday, 6 March, 2019 9:28 AM

To: Irene Tay <irene.tay@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: FW: PRE-REPAIR SURVEY

Kindly assist.

Regards,

Serene

From: Serene Tan

Sent: Tuesday, 5 March 2019 10:39 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: FW: PRE-REPAIR SURVEY

Reminder

From: Serene Tan

Sent: Monday, 4 March 2019 9:37 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: claims@ajaxinspection.com; Igene Lim <igene.lim@mneduco.com.sg>

Subject: PRE-REPAIR SURVEY

URGENT

WITHOUT PREJUDICE

Our Ref: MN.IG.T1.1912942.st

Dear Sirs,

Notice of Accident dated **4/3/2019** attached herein.

Thanks & Best Regards,

(For and on behalf of Mr Nedumaran Muthukrishnan)

Serene Tan (Ms)

M NEDUMARAN & CO

Advocates & Solicitors

Commissioner for Oaths

Branch Office:

11 Sin Ming Road

#B2-09 (Unit 2), Thomson V Two

Singapore 575629

Tel: 6509-8480 / 6509-8481

Fax: 6509-8482

Email : serene.tan@mneduco.com.sg

IMPORTANT NOTE: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509 8480, if you have received this message in error. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

M NEDUMARAN & CO

Advocates & Solicitors
Commissioner for Oaths

UEN NO. 53181067D

Nedumaran Muthukrishnan
LLB (hons) [Buckingham]
Barrister at Law (Lincoln's Inn)

Please reply to our Branch Office for this matter

⇒ Branch Office : 11 Sin Ming Road
#B2-09 (Unit 2) Thomson V Two
Singapore 575629
Tel : 6509-8480 / 6509-8481
Fax : 6509-8482

Email : igene.lim@mneduco.com.sg
serene.tan@mneduco.com.sg

Our Reference : MN/IG/T1/1912942/st
Your Reference : SLP 9902L

Date : 4th March 2019

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

BY EMAIL: claimsdept@sg.cntaiping.com

Dear Sirs,

1. NOTICE OF ACCIDENT TO INSURERS AND PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)
2. ACCIDENT ON 28/02/2019 INVOLVING VEHICLE NOS. SMC 2654E AND SLP 9902L ALONG WOO MON CHEW ROAD.

We are instructed by LUMENS AUTO PTE LTD (owners of motor vehicle no SMC 2654E) and/or TOH MOTOR ENTERPRISE (the motor workshop for SMC 2654E) to notify you of a road traffic accident on 28/2/2019 at about 1150 hours along WOO MON CHEW ROAD involving our client's vehicle registration number [SMC 2654E] and [SLP 9902L] driven by your driver at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged.

Before we proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you with the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

M NEDUMARAN & CO

Nedumaran Muthukrishnan - (Branch Office)

Encl

HENG LEY KANG

(Vehicle: SLP 9902L)

c.c. Workshop : Toh Motor Enterprise
160 Sin Ming Drive
#05-16 Sin Ming Autocity
Singapore 575722
Tel : 9748-3351/ 9791-9594 (Mr Ash Toh/Aik Shan)

(Vehicle : SMC 2654E)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/02/2019 14:06
Date Of Accident	28/02/2019 11:50
Exact Location Of Accident	WOO MON CHEW ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMC2654E
Insured/Policyholder	
Name Of Registered Owner	LUMENS AUTO PTE LTD
Co Reg No	201426961K
Email Address	OPERATIONS@LUMENS.SG
Mobile Phone No	
Alternative Phone No	OFFICE-87781765

Vehicle Particulars

Manufacturer	TOYOTA
Model	CHR 1.8 HYBRID
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	18-MJ001357-R00
Cover Note Number	

Driver

Name of Driver	LEONG CHEE WAI (LIANG ZHIWEI)
NRIC No	S7940286I
Date Of Birth	18/12/1979
Occupation	OUTDOOR
Date Of Driving Pass	14/06/2000
Driving Experience	18 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81666545
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(if driver is not the policyholder)
Date & Time:

CITY AUTO PTE LTD
Blk 8 Sin Ming Road
#01-58/60/62 Sin Ming Ind Est
Singapore 570443
Tel: 6453 1235 Fax: 6453 7944
(Claims Section)

Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6961K
Vehicle Details	
Vehicle No.:	SMC2654E
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	C-HR HYBRID 1.8S CVT
Primary Colour:	Yellow
Manufacturing Year:	2018
Engine No.:	2ZR8453574
Chassis No.:	ZYX102123555
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,921.00
Original Registration Date:	28 Jun 2018
First Registration Date:	28 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$9,690.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jun 2028
PARF Rebate Amount:	\$7,267.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jun 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$37,000.00
COE Rebate Amount:	\$33,510.00
Total Rebate Amount:	\$40,777.00

The information contained herein is correct as at 06 Mar 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Mar 2019		06 Mar 2019 18:05 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	LUMENS AUTO PTE LTD , Co. Reg. No.: 201426961K		
Vehicle Reg. No.:	SMC2654E	Date of Loss:	28/02/2019 11:00 - :59 [8 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D201007C02	Policy/Cover Note No.:	DMPCSN18241218000
Vehicle Reg. No. (Insured):	SLP9902L	Policy No. (Claimant):	18-MJ001357-R00
		Excess:	S\$0.00
Repairer:	Toh Motor Enterprise - Sin Ming (HQ) BLK 16 #01-81 SIN MING IND EST SECTOR A, 575674 Sin Ming - Tel: 9748 3351		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 15/03/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMC2654E (SNM19D201007C02)**
[SLP9902L]






























TP
LUMENS AUTO PTE LTD






































Feb 28 2019 11:00AM

[-]

Toh Motor Enterprise - Sin Ming

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	City Auto Pte Ltd (HQ)	Thumbnail	Print
1	28/02/19 14:25	Video - Accident [Linked Accident Report Documents]	Load MP4	<input type="checkbox"/>
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	City Auto Pte Ltd (HQ)	Thumbnail	Print
1	28/02/19 14:26	Accident Statement	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	City Auto Pte Ltd (HQ)	Thumbnail	Print
1	28/02/19 14:22	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	28/02/19 14:22	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	28/02/19 14:22	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	28/02/19 14:22	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	28/02/19 14:22	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	28/02/19 14:22	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	28/02/19 14:22	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	28/02/19 14:22	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	28/02/19 14:22	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	28/02/19 14:22	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	28/02/19 14:22	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
12	28/02/19 14:22	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
13	28/02/19 14:22	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/03/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
2	21/03/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
3	21/03/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
4	21/03/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
5	21/03/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
6	21/03/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
7	21/03/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
8	21/03/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
9	21/03/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>
10	21/03/19 09:15	General View	Load JPG	<input checked="" type="checkbox"/>






Video			1 per page ▾	✓
No	Finalized On	City Auto Pte Ltd (HQ)	Thumbnail	Print
11	21/03/19 09:15	General View	 Load JPG	✓
12	21/03/19 09:15	General View	 Load JPG	✓
13	21/03/19 09:15	General View	 Load JPG	✓
14	21/03/19 09:15	General View	 Load JPG	✓
15	21/03/19 09:15	General View	 Load JPG	✓
16	21/03/19 09:15	General View	 Load JPG	✓
17	21/03/19 09:15	General View	 Load JPG	✓
18	21/03/19 09:15	General View	 Load JPG	✓
19	21/03/19 09:15	General View	 Load JPG	✓
20	21/03/19 09:15	General View	 Load JPG	✓
21	21/03/19 09:15	General View	 Load JPG	✓
22	21/03/19 09:15	General View	 Load JPG	✓
23	21/03/19 09:15	General View	 Load JPG	✓
24	21/03/19 09:15	General View	 Load JPG	✓
25	21/03/19 09:15	General View	 Load JPG	✓
26	21/03/19 09:15	General View	 Load JPG	✓
27	21/03/19 09:15	General View	 Load JPG	✓
28	21/03/19 09:15	General View	 Load JPG	✓
29	21/03/19 09:15	General View	 Load JPG	✓
30	21/03/19 09:15	General View	 Load JPG	✓
31	21/03/19 09:15	General View	 Load JPG	✓
32	21/03/19 09:15	General View	 Load JPG	✓
33	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
34	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
35	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
36	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
37	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
38	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
39	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
40	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
41	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
42	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
43	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
44	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
45	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
46	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
47	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
48	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
49	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
50	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
51	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
52	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
53	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
54	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
55	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
56	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
57	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
58	21/03/19 09:15	Photographs of Damaged Parts	Load JPG	✓

Video			1 per page ▼	✓
No	Finalized On	City Auto Pte Ltd (HQ)	Thumbnail	Print
59	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
60	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
61	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
62	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
63	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
64	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
65	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
66	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
67	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
68	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
69	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
70	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
71	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
72	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
73	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
74	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
75	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
76	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
77	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
78	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
79	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
80	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
81	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
82	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
83	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
84	21/03/19 09:15	Photographs of Damaged Parts	 Load JPG	✓
85	21/03/19 09:16	Photo After Spray	 Load JPG	✓
86	21/03/19 09:16	Photo After Spray	 Load JPG	✓
87	21/03/19 09:16	Photo After Spray	 Load JPG	✓
88	21/03/19 09:16	Photo After Spray	 Load JPG	✓
89	21/03/19 09:16	Photo After Spray	 Load JPG	✓
90	21/03/19 09:16	Photo After Spray	 Load JPG	✓
91	21/03/19 09:16	Photo After Spray	 Load JPG	✓
92	21/03/19 09:16	Photo After Spray	 Load JPG	✓
93	21/03/19 09:16	Photo After Spray	 Load JPG	✓
94	21/03/19 09:16	Photo After Spray	 Load JPG	✓
95	21/03/19 09:16	Photo After Spray	 Load JPG	✓
96	21/03/19 09:16	Photo After Spray	 Load JPG	✓
97	21/03/19 09:16	Photo After Spray	 Load JPG	✓










Documentation

1 per page ▼



No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/03/19 18:06	pri contact	 Load PDF	
No	Finalized On	City Auto Pte Ltd (HQ)	Thumbnail	Print
1	28/02/19 14:21	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	✓
2	28/02/19 14:21	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	✓
3	28/02/19 14:21	CI [Linked Accident Report Documents]	 Load TIF	
4	28/02/19 14:21	NRIC & Driving license [Linked Accident Report Documents]	 Load JPG	✓

Linked Accident Report Documents

			View	View in Browser ▼
Video			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	City Auto Pte Ltd (HQ)	Thumbnail	Print
1	28/02/19 14:25	Video - Accident	 Load MP4	
Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	City Auto Pte Ltd (HQ)	Thumbnail	Print
1	28/02/19 14:26	Accident Statement	 Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	City Auto Pte Ltd (HQ)	Thumbnail	Print
1	28/02/19 14:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	28/02/19 14:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	28/02/19 14:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	28/02/19 14:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	28/02/19 14:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	28/02/19 14:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	28/02/19 14:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	28/02/19 14:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	28/02/19 14:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	28/02/19 14:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	28/02/19 14:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	28/02/19 14:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	28/02/19 14:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	City Auto Pte Ltd (HQ)	Thumbnail	Print
1	28/02/19 14:21	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	28/02/19 14:21	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	28/02/19 14:21	CI	 Load TIF	
4	28/02/19 14:21	NRIC & Driving license	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19004110/GCD3S2

Date: 28/03/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN18241218000
Claimant Vehicle No:	SMC2654E	Insured Vehicle No:	SLP9902L
Date of Loss:	28/02/2019	Nature of Claim:	TP
		Claim No:	SNM19D201007C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC2654E	Engine No:	2ZR8453574
Make & Model:	TOYOTA C-HR HYBRID, 1.8 S CVT (A)	Chassis No:	ZYX102123555
Reg. Date:	28/06/2018 (Man. Year: 2018)	Odometer:	62159 km
Colour:	Yellow		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R17	Rear Tyre Size:	215/60R17
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 8 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	06/03/2019	
Date Inspected:	06/03/2019	Inspected At: Toh Motor Enterprise - Sin Ming (HQ) BLK 16 #01-81 SIN MING IND EST SECTOR A Singapore 575674
Estimated Period of Repair:	6.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2019)
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC2654E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >