

ASS. REC. BY:

REF: CS/AWA19004(20/AVd3

n2

Special Instruction:

Survivor: Adrian

**ASSIGNMENT (Office)**From (Person): Tang Ben of AWAC Date/Time: 6/3/2019 @ 2:41pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: GMH 2579T Insured: SFH 4822Eat Workshop m/s Precise Auto Service Tel: 67457367of Kaki Bukit Ave 6Policy No: DVPPSB0549151801

Claim No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 3/3/19  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT

Date/Time Action/Instruction (✓) Estimate

16/5/19 Adrian confirmed LS \$1700 (Red 2817.31, 62m)

ASS. REC. BY:

REF:

Adrian

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Vehicle: IN / OUT

Person Contacted: \_\_\_\_\_

Veh No: SM62579T Yr Regn: 2010 JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Wish c.c. 1987Colour: Bronze A/C: Insured / Std / Nil / NASp. Reading: 121542 T/Radio: Insured / Std / Nil / NA

Eng/No: \_\_\_\_\_

C/No: JTDGJ20W105002810Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 18/03/19Survey held at PreciseDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AWA.

RECEIVED 16 MAY 2019

Date/Time, File Pass to?

Date/Time, File Return to?

Part Prices Check:

Survey Fee:

Date:

1) 1615- typist

2) \_\_\_\_\_

3) \_\_\_\_\_

4) \_\_\_\_\_

5) \_\_\_\_\_

6) \_\_\_\_\_

Prel. Report:

Final Report:

IN

OUT

Basic &amp; Add.

S + RS, SI

Photos

Others

TOTAL

150

**Nivitha (LKK Auto)**

---

**From:** Tang, Ben <Ben.Tang@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>  
**Sent:** Wednesday, 6 March 2019 2:21 PM  
**To:** LKK (assignments@lkkauto.com)  
**Cc:** support@preciseauto.sg; SUR (sur@lkkauto.com) (sur@lkkauto.com)  
**Subject:** TP Survey assignment for SMG 2579Y DOA:03.03.2019 Our ref: SFH 4822 E

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us do have consensus in the appointment of Mr Marcus Chua as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 <sup>rd</sup> Party Vehicle	:	SMG 2579 Y
Insured Vehicle	:	SFH 4822 E
Policy Number	:	DVPPSB0549151801
Name of Workshop	:	Precise Auto Service
Contact Number	:	6745 7367
Person to Contact	:	Arine
Estimated Cost of repairs	:	NA

Regards,  
Claims Division

Copy to Precise Auto Service (Your Ref: SMG 2579 Y ) via Email

Note -

- (x)
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
  2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
  3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
  4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

Regards  
Motor Claims  
Claims Group

MSME19029531 / SME Motor Pte Ltd - Kaki Bukit  
ENTRY DATE & TIME: 04/03/2019 16:42  
SUBMITTED BY: Chia Pei Ying

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date Of Report	04/03/2019 16:42
Date Of Accident	03/03/2019 17:00
Exact Location Of Accident	BASEMENT 2 CARPARK AREA AT TAMPINES MALL
Country/State of Loss	SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMG2579T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	PRECISE CAR RENTAL PTE LTD
Co Reg No	201818221G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94897930
Alternative Phone No	OFFICE-94897930
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5101115310-01
Cover Note Number	
<b>Driver</b>	
Name of Driver	YOONG LOON SIONG
NRIC No	S7004709H
Date Of Birth	11/02/1970
Occupation	OUTDOOR
Date Of Driving Pass	18/04/1996
Driving Experience	22 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88222992
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 45 SIMS DRIVE #11-158  
 Postcode 380045  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - HIRER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 0

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

ON 03/03/2019 AT ABOUT 1700HRS, I PARKED MY CAR (SMG2579T) IN TAMPINES MALL'S BASEMENT 2 CARPARK LOT. AT ABOUT 1930HRS, I WENT TO PICK UP MY CAR AND I REALISED THAT VEHICLE B (SFH4822E) WHICH WAS PARKED AT MY CAR BEHIND REVERSED TOO INNER AND DENTED ONTO REAR PORTION OF MY CAR. SO, I IMMEDIATELY WENT TO REPORT TO THE TAMPINES MALL MANAGEMENT AND TRY TO LET THEM CALL OUT TO THE VEHICLE B'S DRIVER. UNTIL AT ABOUT 8.30PM, THE VEHICLE B'S DRIVER CAME OUT. SO, I DISCUSS WITH VEHICLE B DRIVER ABOUT THE INCIDENT WAS CAUSED BY HIM. SO I CALLED TO THE POLICE FOR ASSISTANCE. THE POLICE DID GAVE ME A INCIDENT NO. G/20190303/2040. IO: TEO HOW MING. I HERE TO LODGE THIS REPORT TO CLAIM AGAINST VEHICLE B (SFH4822E)'S INSURANCE FOR MY ACCIDENT DAMAGES.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SFH4822E  
 Vehicle Make/Model/Colour  
 Details Of Properties VEHICLE B  
 Vehicle Category PRIVATE CAR  
 Name of Driver TAN CHYE HIN PATRICK  
 NRIC/Passport Number S1465237Z  
 Contact Number 98381670  
 Address  
 Postcode  
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan Pg. 1

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

4/3/19  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

*PRECISE*



## Sketch Plan #2 Pg. 1

## SKETCH PLAN



(A) SMG 2579T

(B) SFH 4822E

Basement 2 Car Park Areas  
of Tampines Mall.

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 03-03-2019 at about 1700hrs, I was parked my car (SMG 2579T) in Tampines Mall's Basement 2 car park's lot. At about 1930hrs I went to pickup my car and I was realized that Veh B (SFH 4822E) which was parked at my car behind was reversed too inner and dented in to rear portion of my car. So I immediately went to report to the Tampines mall management and try to let them call at the vehicle B's driver, until at about 8:30pm the vehicle B's driver came out so I discuss with the vehicle B's driver about the incident, but the vehicle B's driver didn't admit the incident was caused by him so I called to police come for assist. The police did gave me Incident No: G/20190303/2040 I/O: Teo How Ming. I went to lodge this report to claim the Veh B (SFH 4822E) insurance for my accident damages.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 4/3/19Reporting Centre Personnel's Signature  
Name: 4/3/19  
NRIC/FIN No.: 1505hrs



# PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

15-04-2019

Date of Accident : 03-03-2019

OUR REF : SMG 2579T/T/19

PRECISE CAR RENTAL PTE LTD

1 Kaki Bukit Ave 6  
#02-34 (Auto Bay)  
Singapore 417883

A.V  
Date in/out : 17/03/19 +0

TP AWA  
Veron.

ESTIMATE BILL ON VEH. NO. : SMG 2579T

VEH. MODEL : TOYOTA WISH

CHASSIS NO : JTDGI20W105002810

## LIST ITEM

Rear Bumper Fascia	del		1,078.90
Rear Bumper Side Retainer	nu	2pcs @ 121.25	242.50 136
Rear Bumper Clips	nu	10pcs @ 12.90	129.00 30
Rear Bumper Reflector	nu	2pcs @ 121.20	242.40 +
Rear Bumper Stay	hit dent	2pcs @ 143.70	287.40 82
Tail Gate Weather Stripe	nu		290.85 +
Rear End Panel Top Trim	del		372.40 ✓
Tail Gate Badge		1800.30	61.70 ✓
Tail Gate Emblum 'Deluxe'	nu	1050.22	60.80 ✓
Tail Gate Emblum 'Borneo Motor'			72.10 -
Spare Tyre Carrier	nu		371.70 +
			3,209.75
Less Discount 25% :			802.44
			2,407.31

## SPECIAL NETT ITEM

Reverse Sensor.

Damaged

200

200.  
380.00

## LABOUR CHARGE

To Check Wiring System.

80.00 ~~30~~

To Remove & Refix Reverse Sensor.

120.00 ~~50~~

To Remove & Refix Spare Tyre Carrier.

180.00 ~~X~~

To Respray Affected Areas.

750.00 ~~600~~

To Renew Damaged Parts, Straighten & Repair Tail Gate,  
Rear End Panel & Aligned All Parts.

600.00 ~~300~~

4,517.31

GST 7%:

316.21

**AMOUNT DUE :**

**4,833.52**

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total : 2230.22

YS : 1.7K ✓

04 Days.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA19004120/Avd3n2

(SINGAPORE BRANCH)  
60 ANSON ROAD #08-01 (8th FLOOR)  
MAPLE TREE ANSON  
SINGAPORE 079914

Date : 22-05-2019



Code : AWA

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFH 4822E	Veh. Inspected	SMG 2579T
Policy No.	DVPPSB0549151801	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	BEN TANG	Assign Date	06/03/2019

## 2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH	c.c	1987
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JTDGJ20W105002810	Colour	BRONZE
Odometer	121542	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195/65 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	195/65 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	195/65 R15	BRIDGESTONE	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

## 5. General Information

Accident Date	03/03/2019	Inspection Date	18/03/2019
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 2579T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER FASCIA	DEFORMED	1,078.90	585.30
2	REAR BUMPER SIDE RETAINER @\$121.25	NECESSARY	242.50	136.00
10	REAR BUMPER CLIPS @\$12.90	NECESSARY	129.00	30.00
2	REAR BUMPER REFLECTOR @\$121.20	NOT NECESSARY	242.40	-
2	REAR BUMPER STAY @\$143.70	N/S DENTED	287.40	82.00
1	TAIL GATE WEATHER STRIPE	NOT NECESSARY	290.85	-
1	REAR END PANEL TOP TRIM	DEFORMED	372.40	372.40
1	TAIL GATE BADGE	NECESSARY	61.70	61.70
1	TAIL GATE EMBLEM "DELUXE"	NECESSARY	60.80	60.80
1	TAIL GATE EMBLEM "BORNEO MOTOR"	NECESSARY	72.10	72.10
1	SPARE TYRE CARRIER	NOT NECESSARY	371.70	-
	LESS 25% DISCOUNT		-802.44	-350.08
			2,407.31	1,050.22
<b>SPECIAL NETT ITEMS</b>				
1	REVERSE SENSOR (SN)	DAMAGED	380.00	200.00
			380.00	200.00
<b>LABOUR</b>				
	TO CHECK WIRING SYSTEM.		80.00	30.00
	TO REMOVE & REFIX REVERSE SENSOR.		120.00	50.00
	TO REMOVE & REFIX SPARE TYRE CARRIER.	NOT NECESSARY	180.00	-
	TO RESPRAY AFFECTED AREAS.		750.00	600.00
	TO RENEW DAMAGED PARTS,STRAIGHTEN & REPAIR TAIL GATE,REAR END PANEL & ALIGNED ALL PARTS.		600.00	300.00
			1,730.00	980.00
<b>GRAND TOTAL</b>			<b>4,517.31</b>	<b>2,230.22</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,700.00</b>

Report Ref No. CS/AWA19004120/Avd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.