

ASS. REC. BY:

REF:

CS3 / MSG19004144 / Jcd3²

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Jowyn (merman) of MSIG

Date/Time: 6/3/19

Estimated Cost:

Bill to:

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FU 2470G

Insured: FBG 151L

at Workshop m/s Speedy Motor

Tel: 64815567 | 9388 6867

of 10 AMK #05-21

Policy No: MSD / VMT / 18-377085-CA

Claim No: MSC / V / 19-000091

Sum Insured:

Excess:

Make of Veh:

D.O.A. 8/1/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

7/3/19 Morning

H.O.D. Endorsement:

Date/Time:

6/3/19 @ 4:25pm

Person Contacted:

MS Tan

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	FU 24706 - X
	FBG 151L - X
	Dismantle: 7/3/2019
	After repair: 11/3/2019

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Created	Not Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Mar 2019		06 Mar 2019 13:54 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured: **SIA ENG SOON**, ID: S1675801I, Tel: +6598202907, Email: ENGSOONSIA@SRC.COM.SG

Main Claimant: **TEO WEN HAO**, ID: S8928528C

Vehicle Reg. No.: FU2470G	Date of Loss: 08/01/2019 16:00 - :59 [213 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type: TP / MSC/V/19-000091	Policy/Cover Note No.: MSD/VMT/18-377085-CA (Third Party Only) Coverage: 22/02/2018 - 21/02/2019
Vehicle Reg. No. (Insured): FBG151L	Policy No. (Claimant):
Excess:	

Repairer: **Speedy Motor Cycle Service Centre (HQ)** 10 ANG MO KIO IND PARK 2A #05-21, 568047 Ang Mo Kio - Tel:

Handling Insurer: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: +65 6827 7888 ... [Handled by **Jowyn Tay Mei Ling** - 6643 1307]

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... **[Imm.Advice due 07/03/2019]**

Driver/Custodian (Insured): **SIA ENG SOON (54 / Male)**, NRIC: S1675801I, Tel: +6598202907 Email: ENGSOONSIA@SRC.COM.SG

Adj Asg. Remarks: on WP. SJE : DISAGREED / LIABILITY UNCLEAR Please appoint LKK AUTO to conduct the survey. Speedy Motor Cycle Service Centre Bldg 10 Ang Mo Kio Industrial Park 2A #05-21 Singapore 568047 Person In-Charge: Mr Lim Sam Hee at Tel: 6481 5567 / 9388 6867 Fax No. 6482 5567

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



SINGAPORE POLICE FORCE



T/20190115/2111

Police Station Of Origin:
Serangoon N.P.C
50 Serangoon Avenue 2 #01-02 SINGAPORE
556129
Tel No: 1800-4880999

1 of 3

Report No. T/20190115/2111

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/01/2019 16:45	Vide Report No.:	Station Diary No.: 41
--	------------------	--------------------------

Informant's Particulars

Name of Informant: TEO WEN HAO			Address: APT BLK 240 SERANGOON AVENUE 2 #03-69 SINGAPORE 550240		
ID Type / ID No.: NRIC NO / S8928528C			Contact No.: Home/Office: Mobile: 97273171		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 29	Date of Birth: 14/08/1989	Type of Informant: Rider		
Race: Chinese			Language:		Institution / School Name:
Occupation: TECHNICIAN			Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 08/01/2019 19:00	Type of Location: carpark
Location: Along Road 1 MERLIMAU ROAD				
Inside Singapore Refining Company Pte Ltd located at 1 Merlimau Road				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision:			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBG151L	Motorcycle					0
FU2470G	Motorcycle	HONDA	RVF400RT	Red	Slightly Damaged	0
FX8565L	Motorcycle					0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



Police Station Of Origin:
Serangoon N.P.C
50 Serangoon Avenue 2 #01-02 SINGAPORE
556129
Tel No: 1800-4880999

2 of 3

Report No. T/20190115/2111

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FU2470G	NTUC Income Insurance Co-Operative Limited	5086079768-01	21/03/2018	20/03/2019

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	TEO WEN HAO		ID No. S8928528C
Related Vehicle	NIL		Contact No. 97273171
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 8/1/19 at about 1900hrs, I discovered my motorcycle which is parked at 1 Merlimau Road (Singapore Refining Company Pte Ltd) was damaged. I suspect that someone had an accident which hit onto my bike, however no note was left on my bike.

On 9/1/19 I went back to the carpark and saw that one of my friend's vehicle being parked there and it has a in-car camera. I liaised with my friend in hope to see who hit onto my bike through the in-car camera, however the video was not in full and did not capture the incident.

My bike suffered from a right fairing crack, broken signal light and my damaged helmet. The total repairs for my damages will cost about SGD\$1000.

I wish to inform that I know who owner of FBG151L (Sia Eng Soon) who I believe is the culprit, however he did not liaise with me with regards to the accident up till now.

I wish to state that as of now no one came forward to claim responsibility and I am lodging this report for police assistance.

> **Back to OneMotoring**


Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8528C
Vehicle Details	
Vehicle No.:	FU2470G
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	RVF400RT
Primary Colour:	Red
Manufacturing Year:	2000
Engine No.:	NC13E1603180
Chassis No.:	NC351103177
Maximum Power Output:	-
Open Market Value:	\$10,350.00
Original Registration Date:	21 Mar 2001
First Registration Date:	21 Mar 2001
Transfer Count:	8
Actual ARF Paid:	\$1,553.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Dec 2020
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,517.00
COE Rebate Amount:	\$272.00
Total Rebate Amount:	\$272.00
Message	
<p>Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.</p> <p>This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.</p> <p>This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.</p> <p>For more information, please visit http://www.nea.gov.sg/mtcincentive or contact NEA at 1800-2255-632.</p>	

The information contained herein is correct as at 13 Mar 2019

OK

Class 2A



Share This Listing




Public Comments

Be the first to write a public comment. Ask a question or @mention a friend to check this out!


Post a New Comment


Honda RVF 400(Last Price!)

 2 years ago by [radeemrahman](#)

 44 Likes

 Used

 In Class 2A

 Coe till August 2022. Renewable for 5 or 10 years
Coi \$214x 32months
Reason to sell have 2 bike and car. Letting go as seldom use.
New paintwork n bike in extremely good condition
Viewing available.
Upfront payment 2k
Pm me if interested.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Mar 2019		06 Mar 2019 13:54 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SIA ENG SOON , ID: S1675801I, Tel: +6598202907, Email: ENGSOONSIA@SRC.COM.SG								
Main Claimant:	TEO WEN HAO , ID: S8928528C								
Vehicle Reg. No.:	FU2470G	Date of Loss:	08/01/2019 16:00 - :59 [213 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/19-000091	Policy/Cover Note No.:	MSD/VMT/18-377085-CA (Third Party Only) Coverage: 22/02/2018 - 21/02/2019						
Vehicle Reg. No. (Insured):	FBG151L	Policy No. (Claimant):							
		Excess:							
Repairer:	Speedy Motor Cycle Service Centre (HQ) 10 ANG MO KIO IND PARK 2A #05-21, 568047 Ang Mo Kio - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Imm.Advice due 07/03/2019]								
Driver/Custodian (Insured):	SIA ENG SOON (54 / Male) , NRIC: S1675801I, Tel: +6598202907 Email: ENGSOONSIA@SRC.COM.SG								
Adj Asg. Remarks:	on WP. SJE : DISAGREED / LIABILITY UNCLEAR Please appoint LKK AUTO to conduct the survey. Speedy Motor Cycle Service Centre Bldg 10 Ang Mo Kio Industrial Park 2A #05-21 Singapore 568047 Person In-Charge: Mr Lim Sam Hee at Tel: 6481 5567 / 9388 6867 Fax No. 6482 5567								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FU2470G (MSC/V/19-000091)**
[FBG151L]

TP

TEO WEN HAO

Jan 8 2019 4:00PM

[SIA ENG SOON]


Speedy Motor Cycle Service Centre

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/03/19 08:39	Accident Statement From: SC - Reg. No: FBG151L, Claimant: SIA ENG SOON	 Load HTM	<input checked="" type="checkbox"/>

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/03/19 09:47	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	13/03/19 09:47	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	13/03/19 09:47	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	13/03/19 09:47	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	13/03/19 09:47	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	13/03/19 09:47	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	13/03/19 09:47	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	13/03/19 09:47	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	13/03/19 09:47	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	13/03/19 09:47	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	13/03/19 09:47	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	13/03/19 09:47	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	13/03/19 09:47	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	13/03/19 09:47	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	13/03/19 09:47	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	13/03/19 09:47	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	13/03/19 09:47	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
18	13/03/19 09:47	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
19	13/03/19 09:47	Dismantled Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
20	13/03/19 09:47	Dismantled Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
21	13/03/19 09:47	Dismantled Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
22	13/03/19 09:47	Dismantled Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
23	13/03/19 09:47	Dismantled Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
24	13/03/19 09:47	Dismantled Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
25	13/03/19 09:47	Dismantled Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
26	13/03/19 09:47	Photo After Spray	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
27	13/03/19 09:47	Photo After Spray	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
28	13/03/19 09:47	Photo After Spray	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
29	13/03/19 09:47	Photo After Spray	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
30	13/03/19 09:47	Photo After Spray	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
31	13/03/19 09:47	Photo After Spray	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	13/03/19 09:47	Photo After Spray	 Load JPG	✓
33	13/03/19 09:47	Photo After Spray	 Load JPG	✓
34	13/03/19 09:47	Photo After Spray	 Load JPG	✓
35	13/03/19 09:47	Photo After Spray	 Load JPG	✓
36	13/03/19 09:47	Photo After Spray	 Load JPG	✓
37	13/03/19 09:47	Photo After Spray	 Load JPG	✓
38	13/03/19 09:47	Photo After Spray	 Load JPG	✓
39	13/03/19 09:47	Photo After Spray	 Load JPG	✓
40	13/03/19 09:47	Photo After Spray	 Load JPG	✓
41	13/03/19 09:47	Photo After Spray	 Load JPG	✓
42	13/03/19 09:47	Photo After Spray	 Load JPG	✓
43	13/03/19 09:47	Photo After Spray	 Load JPG	✓
44	13/03/19 09:47	Photo After Spray	 Load JPG	✓
45	13/03/19 09:47	Photo After Spray	 Load JPG	✓
46	13/03/19 09:47	Photo After Spray	 Load JPG	✓
47	13/03/19 09:47	Photo After Spray	 Load JPG	✓
48	13/03/19 09:47	Photo After Spray	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/03/19 08:45	TPD FU2470G GIA REPORT	 Load PDF	
2	06/03/19 08:45	TPD FU2470G - PRI	 Load PDF	
3	06/03/19 08:45	Reject email to TP Lawyer & appoint LKK AUTO	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19004144/JCD3S2

Date: 29/03/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VM/18-377085-CA
 Claimant Vehicle No: FU2470G Insured Vehicle No: FBG151L
 Date of Loss: 08/01/2019 Nature of Claim: TP Claim No: MSC/V/19-000091

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FU2470G**
 Make & Model: HONDA RVF400RT, 399cc (M) Engine No: NC13E1603180
 Reg. Date: 21/03/2001 (Man. Year: 2000) Chassis No: NC351103177
 Colour: Red Odometer: 51223 km
 Engine Capacity: 399 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/60R17 Rear Tyre Size: 150/60R17
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 06/03/2019
 Date Inspected: 07/03/2019 Inspected At: Speedy Motor Cycle Service Centre (HQ)
 10 ANG MO KIO IND PARK 2A #05-21
 Singapore 568047
 Estimated Period of Repair: 3.0 days

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$3,500.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 29 Mar 2019)	
Parts:	N/A	HONDA RVF400RT 399cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FU2470G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >