

2/03/2002

ASS. REC. BY:

REF: C93 / SMO19004192 / Jcd31 Special Instruction:

Surveyor: Hwee Jie

ASSIGNMENT (Office)

*Meimon*

From (Person): Ruth Chua of SMO Date/Time: 07/3/09

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKX 1056B Insured: SKF 3003K

at Workshop m/s B - PROJECT MERKZ Tel: 9092 2291 / 89060657

of 280 Woodlands Ind. Park ES #01-28 Harvest @ Woodlands

Policy No: D18MTPV0101970 Claim No: CMTD1901200

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 05/3/19  
(Client's Record)

CA / REV / REP. / REV 24 HRS 'PRS' H.O.D. Endorsement: \_\_\_\_\_

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN/OUT

Date/Time	Action/Instruction ( ) Estimate
	<u>SKX 1056B x</u>
	<u>SKF 3003K x</u>
	<u>Dismantle: 7/3/2019</u>
	<u>After repair: 14/3/2019</u>


PRVING Hwee Jie  
PRS

REF: SMO

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD (TP) / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: \_\_\_\_\_  
at Workshop n/s 280 woodland Ind Pk E5  
of 01-28  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

Veh No. SKX 1056B Yr Regn: 26 Nov 2015  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: Toyota Axio c.c 1496  
Colour Black A/C: Insured / Std / NI / NA  
Sp. Reading 101615 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: NRE1610008134  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
Tyre Size: F: 185/65R15  
R: \_\_\_\_\_  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or \_\_\_\_\_



(Policy Condition)  
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Front Rear  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. 5/3/19 D.O.I. 7/3/19  
Survey held at D-Project Werkz  
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or \_\_\_\_\_

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range: \$1500 - \$500 6 days.
	<i>[Signature]</i> 25/3/2019

Date/Time. File Pass to?  : Preli. Report  
 : Final Report

Days Of Repair: 6  
Resurvey No. of Trip: 2

Date/Time. File Return to?  
Report Format: PRS  
Lump Sum / I.B.I.: (\$

Add Fee:  : Site Insp (\$  
 : Interview (\$  
 : Tech. Invs (\$  
 : Weekend (\$

Survey Fee:	100
Transportation:	60
) S + PS. SI	60
) Photos	10
) Others	
TOTAL	230

**...CLAIM SUBFOLDER...(New Assignment)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Mar 2019		07 Mar 2019 09:01 Assign				<b>New Assignment</b> Cancel Case

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<b>Show All</b>
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	CHUA SOON HUAT VERNON, ID: S7508997Z								
Main Claimant:	CHUA KWEE TECK, ID: S1501407E								
Vehicle Reg. No.:	SKX1056B	Date of Loss:	05/03/2019 14:00 - :59						
Claim Type:	TP / CMTD1901200	Policy/Cover Note No.:	D18MTPV01019770 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKF3003K	Policy No. (Claimant):							
		Excess:							
Repairer:	D-project Werkz Pte Ltd (HQ) 280 WOODLANDS INDUSTRIAL PARK E5 #01-28 HARVEST@WOODLANDS, 757322 Woodlands - Tel: HP: 90922291 T: 69060657								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/03/2019]								
Driver/Custodian (Insured):	LIM KAY SIN (), NRIC: S01756721, Tel: +6596800771 Email:								
<b>ASSOCIATED MAIL RECEIVED</b>				View All					
There are no mail for this case.				Compose Case Mail					
<input type="checkbox"/> <b>ALL ASSOCIATED TASKS</b> <span style="float: right;">View All   Search Tasks   Create New Task   Complete</span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRS  
Hwee Jie.



> **Back to OneMotoring**

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	1407E
<b>Vehicle Details</b>	
Vehicle No.:	SKX1056B
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5G A
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	2NR8489865
Chassis No.:	NRE1610008134
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,519.00
Original Registration Date:	26 Nov 2015
First Registration Date:	26 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$6,519.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Nov 2025
PARF Rebate Amount:	\$4,889.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	25 Nov 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,001.00
COE Rebate Amount:	\$37,520.00
<b>Total Rebate Amount:</b>	<b>\$42,409.00</b>

The information contained herein is correct as at 13 Mar 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	06/03/2019 12:02
Date Of Accident	05/03/2019 14:05
Exact Location Of Accident	BUKIT TIMAH
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKX1056B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHUA KWEE TECK
NRIC No	S1501407E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-80000000
Alternative Phone No	OFFICE-80000000
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	AXIO-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 28844002 QMY
Cover Note Number	
<b>Driver</b>	
Name of Driver	CHUA KWEE TECK
NRIC No	S1501407E
Date Of Birth	07/05/1961
Occupation	OUTDOOR
Date Of Driving Pass	25/06/1982
Driving Experience	36 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	OFFICE-80000000
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I WAS STATIONARY ALONG BUKIT TIMAH ROAD AND THE JUNCTION OF KHEAM HOCK ROAD AS IT WAS THE RED TRAFFIC LIGHT. SUDDENLY I FELT AN IMPACT AT THE REAR OF MY VEHICLE. A VEHICLE SKF3003K HAD COLLIDED ONTO THE REAR OF MY VEHICLE.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKF3003K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MRS CHEW
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 2

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Mar 2019		07 Mar 2019 09:01 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;"><a href="#">[Created by insurer]</a></span>									
Insured:	<b>CHUA SOON HUAT VERNON</b> , ID: S7508997Z								
Main Claimant:	<b>CHUA KWEE TECK</b> , ID: S1501407E								
Vehicle Reg. No.:	<b>SKX1056B</b>	Date of Loss:	05/03/2019 14:00 - :59 <b>[39 Months and 7 Days From LTA Reg Date (Man Yr)]</b>						
Claim Type:	<b>TP / CMTD1901200</b>	Policy/Cover Note No.:	D18MTPV01019770 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SKF3003K</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>D-project Werkz Pte Ltd (HQ)</b> 280 WOODLANDS INDUSTRIAL PARK E5 #01-28 HARVEST@WOODLANDS, 757322 Woodlands - Tel: HP: 90922291 T: 69060657								
Handling Insurer:	<b>Sompo Insurance Singapore Pte. Ltd. (HQ)</b> - Tel: 6461 6555 ... [Handled by <b>Ruth Chua Gek Tiang</b> - 6329 5153]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ONG HWEE JIE</b> ] ... <b>[Final Rpt due 18/03/2019]</b>								
Driver/Custodian (Insured):	LIM KAY SIN (), NRIC: S0175672I, Tel: +6596800771 Email:								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

**\*SKX1056B (CMTD1901200)**  
**[SKF3003K]**  
**TP**  
**CHUA KWEE TECK**  
**Mar 5 2019 2:00PM**  
**[CHUA SOON HUAT VERNON]**  
**D-project Werkz Pte Ltd**

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>	
<b>Assessment Reports</b>						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail	Print		
1	07/03/19 08:53	<b>Accident Statement</b> From: SC - Reg. No: SKF3003K, Claimant: CHUA SOON HUAT VERNON		 Load HTM	<input type="checkbox"/>		
<b>Photos/Images</b>						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	13/03/19 09:38	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
2	13/03/19 09:38	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
3	13/03/19 09:38	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
4	13/03/19 09:38	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
5	13/03/19 09:38	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
6	13/03/19 09:38	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
7	13/03/19 09:38	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
8	13/03/19 09:38	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
9	13/03/19 09:38	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
10	13/03/19 09:38	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
11	13/03/19 09:38	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
12	13/03/19 09:38	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
13	13/03/19 09:38	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
14	13/03/19 09:38	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
15	13/03/19 09:38	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
16	13/03/19 09:38	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
17	13/03/19 09:38	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
18	13/03/19 09:38	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
19	13/03/19 09:38	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
20	13/03/19 09:38	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
21	13/03/19 09:38	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
22	13/03/19 09:38	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
23	13/03/19 09:38	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
24	13/03/19 09:38	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
25	13/03/19 09:38	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
26	13/03/19 09:39	<b>Dismantled Parts</b>		 Load JPG	<input checked="" type="checkbox"/>		
27	13/03/19 09:39	<b>Dismantled Parts</b>		 Load JPG	<input checked="" type="checkbox"/>		
28	13/03/19 09:39	<b>Dismantled Parts</b>		 Load JPG	<input checked="" type="checkbox"/>		
29	13/03/19 09:39	<b>Dismantled Parts</b>		 Load JPG	<input checked="" type="checkbox"/>		
30	13/03/19 09:39	<b>Dismantled Parts</b>		 Load JPG	<input checked="" type="checkbox"/>		
31	13/03/19 09:39	<b>Dismantled Parts</b>		 Load JPG	<input checked="" type="checkbox"/>		
32	13/03/19 09:39	<b>Dismantled Parts</b>		 Load JPG	<input checked="" type="checkbox"/>		
33	13/03/19 09:39	<b>Dismantled Parts</b>		 Load JPG	<input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
34	13/03/19 09:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
35	13/03/19 09:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
36	13/03/19 09:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	13/03/19 09:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
38	13/03/19 09:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	13/03/19 09:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	13/03/19 09:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	13/03/19 09:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	13/03/19 09:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	13/03/19 09:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	13/03/19 09:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	13/03/19 09:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	13/03/19 09:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	13/03/19 09:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	13/03/19 09:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	13/03/19 09:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	15/03/19 11:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	15/03/19 11:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	15/03/19 11:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	15/03/19 11:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	15/03/19 11:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	06/03/19 15:21	Third Party E-filed GIA report(M)	 Load PDF	
2	07/03/19 09:02	Pre-Repair Survey - OBJ	 Load PDF	
3	07/03/19 09:02	Pre-Repair Survey - ASSIGN LKK	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19004192/JCD3E2

Date: 29/03/2019

## REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTPV01019770

Claimant Vehicle No: SKX1056B Insured Vehicle No: SKF3003K

Date of Loss: 05/03/2019 Nature of Claim: TP Claim No: CMTD1901200

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SKX1056B**  
 Make & Model: TOYOTA AXIO, 1.5 (A) Engine No: 2NR8489865  
 Reg. Date: 26/11/2015 (Man. Year: 2015) Chassis No: NRE1610008134  
 Colour: Black Odometer: 101615 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15  
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 07/03/2019

Date Inspected: 07/03/2019 Inspected At:

D-project Werkz Pte Ltd (HQ)  
 280 WOODLANDS INDUSTRIAL PARK  
 E5 #01-28 HARVEST@WOODLANDS  
 Singapore 757322

Estimated Period of Repair: 6.0 days

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500.00 -\$5,500.00

## REPAIR DETAILS

Reference	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 29 Mar 2019)
<b>Parts:</b> 143	TOYOTA AXIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKX1056B)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >