

INSURANCE

INS. CASE OWNER:

CC 6/AIG1900

4214, 4513 9

LKK  
IDAC

Surveyor:

M. R. R. M. S.

DOI:

ASSIGNMENT

9/2/19

Date / Time:

9/2/19

Registered in Merimen:

9/2/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLK 4008C

Claim No.:

2270077886

Name of Insured:

A. M. W. 4 MIN FARMER MARK W. T. K.

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

Place of Accident:

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SKU 4273L



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Pastech



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting Itr (1st):	
	Non-Reporting Itr (2nd):	
	Non-Reporting Itr (Final):	
	Notification Itr (if non-pickup):	
03/04	Call OI:	
4/14	After call Itr to OI:	
	Documentation Check List:	Handler Typist
25/14	Notification Itr (if non-pickup):	
	After call Itr to OI:	
7/5	Authorization To Act:	
2/5	Release Voucher:	
2/5	Final Repair Bill:	
8/5	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

<b>PRELIMINARY ADVICE</b>		Date/Time:	Send By:
<b>FINALIZATION</b>		Date/Time:	Confirm with:
Repair Cost:	SS	( days) Reduction:	%
<b>FINAL SETTLEMENT</b>		Date/Time:	Confirm with:
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	NIL
Repair Cost:	SS 5700.00		
Loss of Rental (LOR):	SS	( days)	
Loss of Use (LOU):	SS 250 (5.00 x 5 days)		
Loss of Income (LOI):	SS	( \$ x days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]	
GIA/LTA Search	SS 2.00		
Medical:	SS		
Disbursement:	SS	(e.g. Tow/ Independent)	
Legal Cost:	SS		
Total:	SS 5700.00	Global Sum SS:	5700.00
<b>FINAL PAYMENT</b>		Date/Time:	Confirm with:
Payee 1:	SS 5700.00	Name 1:	Fastech Auto Pte Ltd
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPY SENT  
9/5/19

2270077886

(08/11/23) wef

ASS. REC. BY: Marius

REF:

A16/

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKU 4273Lat Workshop m/s RIof SLK 4008C

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 53k.

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR. Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: 4

days

Res: \_\_\_\_\_

Yes or No

Lum Sum: 20

%

3 Val: \_\_\_\_\_

Yes or No

CA / REV / REP. / 24 HRS

71753

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SKU 4273LRegn: 7115Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Monda

Fit

c.c. 1317Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 7302

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: GK31121352Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/452R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Presse

Front

Rear

R/Bal. 6

mm

R/Bal. 6

mm

L/Bal. 6

mm

L/Bal. 6

mm

D.O.A. 7/3/19D.O.I. 7/3/19

Survey held at: \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The O/S Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21A 4503720/3/19 2/5 @ 5100 confirmed with Alan.(Red = 48765 - 50 / 62%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐

Site Insp (\$

) \$ + RS \$

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format : \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_

TOTAL

\$ 2,540

FASTECH AUTO PTE LTD  
BLK1 KAKI BUKIT AVE 6  
#01-46/48/50 AUTOBAY  
SINGAPORE 417883

VEHICLE NO: SKU 4273L

QTY	PARTICULAR	
1 PCS	FRONT BUMPER	665.40
1 PCS	FRONT BUMPER SIDE HOLDER O/S	
1 SET	FRONT BUMPER CLIPS	
1 PCS	FRONT BUMPER FOG LAMP COVER O/S	
1 PCS	FRONT BUMPER REINFORCEMENT	
1 PCS	HEADLAMP O/S	1250.20
1 PCS	FRONT FENDER O/S	
1 PCS	FRONT FENDER INNERSHIELD O/S	
1 SET	FRONT FENDER INNERSHIELD CLIPS	
1 PCS	WIPER WASHER TANK	
1 PCS	FRONT FENDER INNER PANEL O/S	
1 PCS	FRONT SHOCK ABSORBER O/S	399.50
1 PCS	FRONT KNUCKLE ARM O/S	485.20
1 PCS	FRONT KNUCKLE ARM BEARING O/S	
1 PCS	FRONT LOWER ARM O/S	
1 PCS	FRONT DRIVESHAFT O/S	
1 PCS	FRONT STEERING RACK	
1 PCS	FRONT GRILLE	
1 PCS	FRONT SPORT RIM O/S	

Not Authorized  
NKK

45 \$5100  
Hony  
7/3/19

205	\$866.30	—
Set	\$66.50	—
Set	\$45.00	—
Set	\$105.00	—
11	\$288.20	X
11	\$1,650.00	—
10/20	\$625.10	—
10/20	\$199.30	—
Set	\$45.00	—
Set	\$184.00	X
Set	\$625.10	—
Set	\$650.30	—
Set	\$766.20	—
Set	\$250.00	—
Set	\$545.30	—
11	\$1,450.00	X
11	\$1,899.20	X
11	\$315.00	X
20	\$850.00	5005.20
	\$11,425.50	

LABOUR CHARGES:

TO CHECK WIRING  
TO REFILL AIRCON GAS  
TO CONDUCT WHEEL ALIGNMENT  
TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE  
TO SPRAY RUST PROOFING  
LABOUR FOR PANEL BEATING & REPLACING PARTS  
TO PUTTY & SPRAY PAINTING

	\$80.00	20
11	\$150.00	X
	\$150.00	80
	\$300.00	120
	\$80.00	30
	\$800.00	600
	\$880.00	800
TO	\$13,865.50	

FASTECH AUTO PTE LTD is not liable for any damage to the vehicle or its contents.  
• The vehicle is not to be used for any illegal purpose.  
• The vehicle is not to be used for any commercial purpose.  
• The vehicle is not to be used for any purpose other than the purpose for which it was purchased.  
• The vehicle is not to be used for any purpose other than the purpose for which it was purchased.  
• The vehicle is not to be used for any purpose other than the purpose for which it was purchased.  
• The vehicle is not to be used for any purpose other than the purpose for which it was purchased.

Authorised by:   
Signature:   
Date:

P-5326-6  
4245.28  
6395.28

# COMPUTERISED 4 WHEEL ALIGNMENT HUNTER DSP700

Company: FASTECH AUTO PTE LTD  
N: SKU 4273 L  
ite 7.3.19 16:15



SKU 4273 L

Factory Japan 2019.0.1 : Honda : Fit : GK Series : GK3

## Front : Left

Actual	Before	Specified Range
0°16'	0°16'	-1°00' 1°00'
5°10'	5°10'	3°55' 5°55'
-0°20'	-0°20'	-0°09' 0°09'
15°22'	15°22'	11°30' 13°30'
15°38'	15°38'	10°30' 14°30'

Camber  
Caster  
Toe  
SAI  
Included Angle  
Turning Angle Diff.

## Front : Right

Actual	Before	Specified Range
-1°32'	-1°32'	-1°00' 1°00'
5°45'	5°45'	3°55' 5°55'
-0°17'	-0°17'	-0°09' 0°09'
14°59'	14°59'	11°30' 13°30'
13°27'	13°27'	10°30' 14°30'

## Front

Cross Camber  
Cross Caster  
Cross SAI  
Total Toe  
Cross Turn Diff.

Actual	Before	Specified Range
1°47'	1°48'	-1°00' 1°00'
-0°35'	-0°35'	
0°23'	0°23'	
-0°37'	-0°37'	-0°17' 0°17'

## Rear : Left

Actual	Before	Specified Range
-1°39'	-1°39'	-2°30' -0°30'
0°06'	0°06'	0°00' 0°17'

Camber  
Toe

## Rear : Right

Actual	Before	Specified Range
-1°18'	-1°18'	-2°30' -0°30'
0°14'	0°14'	0°00' 0°17'

## Rear

Cross Camber  
Total Toe  
Thrust Angle  
Axle Offset

Actual	Before	Specified Range
-0°21'	-0°21'	
0°21'	0°21'	0°00' 0°34'
-0°04'	-0°04'	
0mm	0mm	

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 7175B

**Vehicle Details**

Vehicle No.: SKU4273L

Vehicle to be Exported: No

Intended Deregistration Date: 07 Mar 2019

Vehicle Make: HONDA

Vehicle Model: FIT 1.3G F PACKAGE CVT ABS D/AIRBAG 2WD

Primary Colour: Grey

Manufacturing Year: 2015

Engine No.: L13B1221352

Chassis No.: GK31121352

Maximum Power Output: 73.0 kW (97 bhp)

Open Market Value: \$13,125.00

Original Registration Date: 27 Jul 2015

First Registration Date: 27 Jul 2015

Transfer Count: 1

Actual ARF Paid: \$8,125.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 26 Jul 2025

PARF Rebate Amount: \$6,093.00

**Intended COE Rebate Details**

COE Expiry Date: 26 Jul 2025

COE Category: A - Car up to 1600cc &amp; 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$61,000.00

COE Rebate Amount: \$38,944.00

**Total Rebate Amount: \$45,037.00**

The information contained herein is correct as at 07 Mar 2019

OK

500+ dealers competed to buy my car!

Sell your car for More Cash

Highest Price or Get \$100 Free

Get Paid Now, Handover Later

SELL YOUR CAR

Post an Advertisement  
Sell it yourself! Advertise it at just \$58 until it's SOLD!

Classic Promo! Best Deal! Fast Selling! Hurry Down Now!

Flexible Loan, Trade In And Welcome. 100% Deposit Refund For Unapproved Loan. Classic Credit - StarAd.

Post an Ad

Advertiser Login

Ways of Selling

Browse by Category

Sort by Date Posted

20 results/page

2 vehicles

honda fit

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	honda fit		Any	Any	2015	Any	Any	Any	Available
	Honda	Fit 1.3A GF (OPC)	\$41,800	\$5,920 /yr	13-Aug-2015	1,317 cc	42,000 km	Hatchback	Available
Very Well Maintained By Previous Owner With No Accident Records. As Good And Clean As It Gets, Car Is In Very Mint Condition. No Repairs Needed, And Comes With Full Servicing Records. Owner Selling Du...									
Tan Wei Auto Pte Ltd									
Posted: 05-Mar-2019 Tags: 2015 Honda Fit, 2015 honda fit, Honda Fit, honda fit, Honda, Fit, fit, Used Honda									
	Honda	Fit 1.3A G	\$51,800	\$7,840 /yr	19-Jun-2015	1,317 cc	60,000 km	Hatchback	Available
Cheapest In Town! High Loan Available, In Excellent Condition, Well Serviced And Maintained, Original Paintwork Since Day 1, Accident Free, Immaculate Condition, In House Loan And Bank Loan Available!...									
Heritage Auto Enterprise Pte Ltd									
Posted: 04-Mar-2019 Tags: 2015 Honda Fit, 2015 honda fit, Honda Fit, honda fit, Honda, Fit, fit, Used Honda									

Save this search criteria, to get email alerts whenever a match is found.

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
--	------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

## View Received Message

This mail is associated with :

**\*SKU4273L (0373027278SG)  
[SLK4008C]**

TP

MOHD AMIN BIN SHARIFF

Mar 7 2019 12:00AM

[Amin-Amin Farnush Mark Lotfi]

Faitech Auto Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** AIG Asia Pacific Insurance Pte. Ltd. (AIG\_SG), sent on 08/03/2019 15:29 PM.  
**To** LKK\_HQ  
**Subject** No OI GIA Report

Hi

Pls be advice that no OI GIA report received  
Pls find OI details below for your further actions

OI name : Amin-Amin Farnush Mark Lotfi

Address :

9

Ocean Way

#04-35

Singapore 098371

Mobile No: 96525081

Thank you

Regards,

Aashween

### DOCUMENTS SUMMARY

There are no documents.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG19004214/Upb3

14 March, 2019

**Amin-Amin Farnush Mark Lotfi**

9 Ocean Way #04-35

Singapore 098371

Dear Sirs,

**ACCIDENT INVOLVING SKU 4273L AND SLK 4008C ON 07.03.2019 ALONG/  
AT NATHAN ROAD**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Hsiao Tong

Claims

Tel : 6742 3197

Fax: 6741 4108

Email : [chewht@lkkauto.com](mailto:chewht@lkkauto.com)

c.c. *Claims Manager*  
*AIG Asia Pacific Insurance Pte Ltd*  
*(Motor Claims Dept)*





Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG19004214/Upb3

04 April 2019

By Registered Mail

Amin-Amin Farnush Mark Lotfi  
9 Ocean Way #04-35  
Singapore 098371

Dear Sir,

**ACCIDENT INVOLVING SKU 4273L AND SLK 4008C ON 07.03.2019 ALONG/  
AT NATHAN ROAD**

We refer to the above subject matter. Your insurer AIG Asia Pacific Insurance Pte Ltd (AIG) has received a third party claim(s) against your motor insurance policy, and has appointed LKK Auto Consultants Pte Ltd to act on their behalf to handle this matter.

We highlight that this accident has not been reported to AIG.

Please note that you had been notified by our via mail by post from our office on 14/03/2019

Kindly proceed to lodge your accident report immediately, giving the version of the accident amongst other things related to the accident. The accident report can be lodged at any of AIG reporting centres. For the listing of AIG reporting centres, you may refer to your Certificate of Insurance or visit AIG Singapore's website.

To enable us to look into the matter immediately, please let us hear from you within fourteen (14) days from date of this letter (by 20/04/2019).

Please be reminded that in accordance with the terms and conditions under your policy, failure of compliance, our principal M/s AIG Asia Pacific Insurance Pte Ltd reserves the right to repudiate liability.

If you need further assistance or clarifications, please contact the undersigned.

Yours faithfully,

Hsiao Tong  
Claims  
Tel : 6742 3197  
Fax: 6741 4108  
Email : chewht@lkkauto.com

c.c     *Claims Manager*  
         *AIG Asia Pacific Insurance Pte. Ltd*  
         *(Motor Claims Dept)*

# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay  
Singapore 417883

Tel No: 67465405 / 67465376 Fax No: 67458520

Tax Reg No: 200006262D

Date :30.03.2019

AIG Asia Pacific Insurance Pte Ltd  
Chartis Building  
78 Shenton Way #07-16  
Singapore 079120

Attn: Motor Claim Department

## **ACCIDENT INVOLVING VEHICLE: SKU 4273L AND SLK 4008C ON 07.03.2019**

We are the authorized repair workshop for the owner of motor vehicle no: **SKU4273L**, which was involved in the captioned accident with your insured vehicle no: **SLK4008C**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1) Cost of Repair (inclusive of GST)	\$	5,457.00
2) Loss Of Use (4days + 1sun X \$100)	\$	500.00
3) GIA Search Fee	\$	2.00
	<u>\$</u>	<u>5,959.00</u>

We enclosed herewith the following documents to support the claims:

- |                                 |                                    |
|---------------------------------|------------------------------------|
| a) Final Repair Invoice         | b) Vehicle Registration Log Card   |
| c) GIA Report/GIA Search Result | d) I/C & Driving Licence           |
| e) Insurance Certificate        | f) Letter of Authorisation, etc... |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

**Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.**

Thank you.

Yours faithfully,

Jason Tang  
For Fastech Auto Pte Ltd



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG19004214/Ugb3

25 April 2019

**AMIN-AMIN FARNUSH MARK LOTFI**  
9 OCEAN WAY  
#04-35  
SINGAPORE 098371

Dear Sir/Madam,

**ACCIDENT INVOLVING SLK 4008C AND SKU 4273L ON 07/03/2019**

We refer to the above accident. We are the Appointed Surveyor and Loss Adjuster Company by your Motor Insurer (AIG Asia Pacific Insurance Pte Ltd.) to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

This is to inform you that we received a Third Party Claim from SKU 4273L.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Cecilia Chong  
Case Handler  
DID: 6749 4274  
FAX: 6741 4108  
EMAIL: ceciliachong@lkkauto.com

c.c AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

DATE : 7th Mar 2019

TO : All Asia Pacific Insurance Pte Ltd

RE : ACCIDENT INVOLVING VEHICLE NO. SKU 4273L & SLK 4008L

ALONG Nathan Road

ON 7/3/2019

I/We, Mohd Amin B M Shuriff

of (NRIC No./ROC No.) S0177175B

of BLK 306 Tampines St 32 #10-04 5520306

owner of vehicle no. SKU 4273L in consideration of M/s FASTECH AUTO

PTE LTD repairing my/our vehicle SKU 4273L at my/our instruction and hereby  
authorise M/s FASTECH AUTO PTE LTD to demand claim settlement whatever  
amount settled/payable by the Insurance Company and/or third party or to commence legal  
proceedings, if necessary, under my name, for the cost of repairs, car rental and/or loss of use,  
etc. and to their appointing solicitor to act for me/us in respect of the said accident/claim and  
all claimed and/or settled shall belong to them absolutely.

I/We further agree and undertake to indemnify them against the above-mentioned claim cost  
which may arisen therewith.

Signature of Owner : 

Name of Owner : \_\_\_\_\_

This Discharge Voucher applies only to the claimant's claim for his property damage and will not affect his personal injuries claim and/or uninsured losses claim in a later date. Further, the settlement terms herein should not be used as an Evidence to prejudice to the claimant's personal injuries claim and/or other uninsured losses claim arising of the subject matter in this action.

### **RELEASE VOUCHER**

#### **(AIG Asia Pacific - Express Third Party Claim)**

"We/I, **Fastech Auto Pte Ltd** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$5,700.00** (Global Sum) for vehicle no. **SKU 4273L** that was damaged pursuant to the accident which occurred on **07/03/2019** (date) along **NATHAN ROAD** involving vehicle no/s **SLK 4008C**.

This is pursuant to the inspection conducted on **07/03/2019** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **MOHD AMIN B M SHARIFF** ("the third party claimant") of vehicle no. **SKU 4273L** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SKU 4273L** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 03 (day) of 05 (month) 2019 (year)

Signed by appointed surveyor

Signed by "the workshop" (with chop)

## TAX INVOICE

### **FASTECH AUTO PTE LTD**

**1 Kaki Bukit Ave 6 #01-48 Autobay**

**Singapore 417883**

**Tel No: 67452063 / 67467158 Fax No: 67458520**

**Tax.Reg No: 200006262D**

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn: Motor Claim Department

Tax Invoice : 20951

Date: 30.03.2019

Vehicle No: SKU 4273L

Make/Model: HONDA FIT 1.3

Accident Date: 07.03.2019

Claim No : 0319-20951

Reference :

Policy No :

---

		Amount
To proceed on lump sum repair	SS	5,100.00

---

E. & O. E.

Total : S\$ 5,100.00

GST @ 7% : S\$ 357.00

*Amount Due* : **S\$ 5,457.00**

---

  
for FASTECH AUTO PTE LTD

All Invoices are subjected to GST

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-19-036415

Date of Request: 07/03/2019

Your Ref No:

Online Purchase

Kim Chwee Auto Pte Ltd  
1 Kaki Bukit Avenue 6 #01-48  
AutoBay@Kaki Bukit  
Singapore 417883

Dear Sir/Madam,

Enquiry Date 07/03/2019

Enquiry By Tang Kok Wee, Allan

Vehicle No. SLK4008C

Accident Date 07/03/2019

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLK4008C	AIG Asia Pacific Insurance Pte. Ltd.	16/01/2019-15/01/2020	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-19-036415

Date of Request: 07/03/2019

Your Ref No:

Online Purchase

Kim Chwee Auto Pte Ltd  
1 Kaki Bukit Avenue 6 #01-48  
AutoBay@Kaki Bukit  
Singapore 417883

Dear Sir/Madam,

Enquiry Date: 07/03/2019

Enquiry By: Tang Kok Wee, Allan

P Vehicle No: SLK4008C

Accident Date: 07/03/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



SINGAPORE POST  
 MACPHERSON RD  
 GST Reg. Add: SINGAPORE POST CENTRE  
 10 EUNOS ROAD 8  
 SINGAPORE 408600  
 GST Reg. No : M2-0105651-9  
 Date: 04 Apr 2019 Time: 09:51:41

Description Amount(S\$) GST@7%  
 Ref. No: PSL01/1926/094/0031  
 Postage Label  
 LOCAL  
 7 X 2.54 17.78 1.16

SUB TOTAL 17.78 1.16

TOTAL AMOUNT 17.78  
 GST COLLECTED BY SINGPOST 1.16

MOP:CASH : \$17.78

Enjoy up to 3% cashback on eligible online and retail spend with the Spree Credit Card.No minimum spend required.T&Cs apply. Sign up now at [singpost.com/spreecard](http://singpost.com/spreecard)

Pay any bills on SAM and earn LinkPoints now! Terms & conditions apply

Thank you for visiting Singapore Post

#Zero-rated for GST

\*Exempt

+Out of Scope

\*\*Supplier Item

Price inclusive of 7% GST where applicable  
 I have checked & confirmed the product is visually good, functional & performed within expectation.



# POSTING RECEIPT FOR REGISTERED ARTICLE(S)

## NOTES:

- Separate forms are to be used for insured and Non-insured Registered Article.
- Please provide all information required and produce this receipt for all enquiries.
- Please tick where applicable. It shall be assumed as Advice of Receipt (AOR) is required or delivery by air is requested if relevant \* is left blank.
- Please indicate the return address on the item(s) to ensure prompt return in event of non-delivery to the addressee(s).
- Please post item(s) at the post office counter according to the sequence stated below.

1. Name & Address of Addressee GOLDBELL CAR RENTAL PTE LTD 10 Raffles Road #02-01 Singapore 088702 (SKA194D)		AOR: ( ) Y ( ) N B* ( ) AIR ( ) SUR Insurance* ( ) Y ( ) N ( ) N Contact:		For Official Use Only (Item numbers are printed in order of posting at counter)  RA TSN Ref: 1926/094/00332 RA No: 04 Apr 2019 RC11424349556 RC11424348156
2. Name & Address of Addressee Amin-Amin Furniture Mart Ltd. 9 Ocean Way #04-35 Singapore 098371 (SLK4008C)		AOR: ( ) Y ( ) N B* ( ) AIR ( ) SUR Insurance* ( ) Y ( ) N ( ) N Contact:		

## Sender's Acknowledgment

I have read, understood and agreed to the terms and conditions of posting on receipt. I accept the maximum liability payable for Registered Mail Service and certify that all information provided by me is true and the item(s) does not contain any hazardous or prohibited item(s).

Name & Signature

Date

(12/2011)

Singapore Post Limited  
 (Reg. No. 198712234M)  
 10 Eunos Road 8  
 #02-01 Singapore Post Centre  
 Singapore 408600

Tel: 1800 811 811  
 Fax: 1800 811 811  
 To check delivery status or to raise an enquiry  
 on your registered article(s), please visit  
[www.singpost.com](http://www.singpost.com)

(Signature)

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

## CLAIM SUBFOLDER TRACKING









































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Mar 2019		07 Mar 2019 00:00	<b>S\$5,100.00</b>	<b>S\$5,100.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	Amin-Amin Farnush Mark Lotfi, ID: G6057385P								
Main Claimant:	MOHD AMIN BIN SHARIFF, ID: S01771758								
Vehicle Reg. No.:	SKU4273L	Date of Loss:	07/03/2019 00:00 - :59 [43 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0373027278SG	Policy/Cover Note No.:	2100497785						
Vehicle Reg. No. (Insured):	SLK4008C	Policy No. (Claimant):	5097696202-01						
		Excess:							
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 18/03/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (22/04/2019): Re: No OI GIA Report</li> <li>AIG_SG (02/04/2019): Re: No OI GIA Report</li> <li>AIG_SG (08/03/2019): No OI GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SKU4273L (0373027278SG)  
[SLK4008C]  
TP  
MOHD AMIN BIN SHARIFF  
Mar 7 2019 12:00AM  
[Amin-Amin Farnush Mark Lotfi]  
Fastech Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown													<input type="button" value="1"/>	Edit				
Photos/Images															3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	07/03/19 17:51	Chassis Number													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
2	07/03/19 17:51	Odometer Reading													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
3	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
4	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
5	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
6	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
7	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
8	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
9	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
10	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
11	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
12	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
13	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
14	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
15	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
16	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
17	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
18	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
19	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
20	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
21	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
22	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
23	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
24	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
25	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
26	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
27	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
28	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
29	07/03/19 17:51	General View													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
30	09/03/19 09:28	Reinspection Photo													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
31	09/03/19 09:28	Reinspection Photo													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
32	09/03/19 09:28	Reinspection Photo													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
33	09/03/19 09:28	Reinspection Photo													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			
34	09/03/19 09:28	Reinspection Photo													<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	09/03/19 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	09/03/19 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	09/03/19 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	09/03/19 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	09/03/19 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	09/03/19 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	09/03/19 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	09/03/19 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	09/03/19 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	09/03/19 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	09/03/19 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	09/03/19 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	09/03/19 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	09/03/19 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	09/03/19 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	09/03/19 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	09/03/19 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	09/03/19 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	09/03/19 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	09/03/19 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	09/03/19 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	09/03/19 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	09/03/19 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	09/03/19 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	09/03/19 09:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	20/03/19 17:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	20/03/19 17:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	20/03/19 17:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	20/03/19 17:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	20/03/19 17:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	20/03/19 17:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/03/19 15:24	TP GIA REPORT	 Load PDF	
2	14/03/19 10:32	Non reporting letter	 Load PDF	
3	10/05/19 10:17	WORKSHOP INVOICE	 Load PDF	
4	10/05/19 10:17	AUTHORISATION TO ACT FORM	 Load PDF	
5	10/05/19 10:17	Release Voucher	 Load PDF	
6	10/05/19 10:17	GIA SEARCH	 Load PDF	
7	10/05/19 10:17	Registered Mail Fee	 Load PDF	
8	10/05/19 10:17	LETTER TO OI	 Load PDF	
No.	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	22/04/19 15:15	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^  
v

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLK4008C (Insd veh)	Model:	HONDA FIT 1.3 (A)
	SKU4273L (TP veh)		
Date of Accident:	07/03/2019		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	14,836.09
Final Repair Cost	:	\$	5,700.00
Loss of Use	:	\$	5.00 days at \$50.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	5,700.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_ 100 \_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Fastech Auto Pte Ltd	:	\$ 5,700.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

10 May  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19004214/UGB3Q2

Date: 10/05/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100497785  
**Claimant Vehicle No :** SKU4273L **Insured Vehicle No :** SLK4008C  
**Date of Loss:** 07/03/2019 **Nature of Claim:** TP **Claim No:** 0373027278SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SKU4273L**  
 Make & Model: HONDA FIT, 1.3 (A) Engine No: L13B1221352  
 Reg. Date: 27/07/2015 (Man. Year: 2015) Chassis No: GK31121352  
 Colour: Grey Odometer: 73021 km  
 Engine Capacity: 1317 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/45Z R16 Rear Tyre Size: 205/45Z R16  
 Front Left Side: Presa 6 mm Rear Left Side: Presa 6 mm  
 Front Right Side: Presa 6 mm Rear Right Side: Presa 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,425.50	4,745.28	6,680.22	58.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,440.00	1,650.00	790.00	32.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,865.50</b>	<b>6,395.28</b>	<b>7,470.22</b>	<b>53.88</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,100.00</b>		
(S\$)	13,865.50	5,100.00	8,765.50	63.22
<b>+ GST 7.00/7.00% (S\$)</b>	970.59	357.00	613.59	63.22
<b>Nett Amount (S\$)</b>	<b>14,836.09</b>	<b>5,457.00</b>	<b>9,379.09</b>	<b>63.22</b>
<b>+ Loss of Use (5.0 x S\$50.00/day) (S\$)</b>		250.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>5,709.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>5,700.00</b>		

## INSPECTION

Date of Assignment: 07/03/2019  
 Date Inspected: 07/03/2019 Inspected At:

Fastech Auto Pte Ltd (HQ)  
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay  
Singapore 417883

Estimated Period of Repair: 4.0 days

---

**Adjuster:** MARCUS CHUA

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	866.30 F	*665.40 FL
2	1		*FRONT BUMPER SIDE HOLDER O/S	Bent	66.50 F	*66.50 FL
3	1		*SET FRONT BUMPER CLIPS	Necessary	45.00 F	*45.00 FL
4	1		*FRONT BUMPER FOG LAMP COVER O/S	Scratched	105.00 F	*105.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	288.20 F	*- FL
6	1		*HEADLAMP O/S	Cracked	1,650.00 F	*1,250.20 FL
7	1		*FRONT FENDER O/S	Dented / Bent	625.10 F	*625.10 FL
8	1		*FRONT FENDER INNERSHIELD O/S	Torn	199.30 F	*199.30 FL
9	1		*SET FRONT FENDER INNERSHIELD CLIPS	Necessary	45.00 F	*45.00 FL
10	1		*WIPER WASHER TANK	Not Necessary	184.00 F	*- FL
11	1		*FRONT FENDER INNER PANEL O/S	Bent	625.10 F	*625.10 FL
12	1		*FRONT SHOCK ABSORBER O/S	Bent	650.30 F	*399.50 FL
13	1		*FRONT KNUCKLE ARM O/S	Bent	766.20 F	*485.20 FL
14	1		*FRONT KNUCKLE ARM BEARING O/S	Necessary	250.00 F	*250.00 FL
15	1		*FRONT LOWER ARM O/S	Buckled	545.30 F	*545.30 FL
16	1		*FRONT DRIVESHAFT O/S	Not Necessary	1,450.00 F	*- FL
17	1		*FRONT STEERING RACK	Not Necessary	1,899.20 F	*- FL
18	1		*FRONT GRILLE	Not Necessary	315.00 F	*- FL
19	1		*FRONT SPORT RIM O/S	Dented	850.00 FS	*500.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,425.50</b>	<b>5,806.60</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	<b>0.00</b>	<b>1,061.32</b>

<b>Total Parts (\$\$)</b>	<b>11,425.50</b>	<b>4,745.28</b>
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	20.00
2	TO REFILL AIRCON GAS	New	150.00	0.00
3	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
4	TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE	New	300.00	120.00
5	TO SPRAY RUST PROOOFING	New	80.00	30.00
6	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	800.00	600.00
7	TO PUTTY & SPRAY PAINTING	New	880.00	800.00
Gross Labour Cost (S\$)			<b>2,440.00</b>	<b>1,650.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >