

ASS. REC. BY:

REF:

CS/FCI 19004037/ksd3

02

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Joanne Yang of ECI Date/Time: 07/3/19

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SCW 7755C Insured: SHD 6927X

at Workshop m/s CHENG HOE Tel: 67556142/0

of B1F 6019 YISHUN IND PARK A #01-377

Policy No: Claim No: D19001634MESH

Sum Insured: Excess:

Make of Veh: D.O.A. 05/3/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: Person Contacted: Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	SCW 7755C
	SHD 6927X CS/FCI 17071472/11962 DOA: 08/11/17.
22/03/19	@ 08:39 a.m. remind RA to Joanne via email.

ASS. REC. BY:

REF:

1021

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.:

Yes or No

Lum Sum:

1.31 %

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SCW 7755C

Yr Regn:

09.16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Lyn Alpha

C.C.

2493

Colour:

M-Black

A/C:

Insured / Std / NI / NA

Sp. Reading

74057

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

AG1430

0034892

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD / A/Rim or

Tyre Size:

F:

235/50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Green - Max

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

5/3/19

D.O.I.

19/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Frt N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1


File pass to

84737.73 email

24/5

84737.73 Confirm E Repairs

C\$ 500/- Red - 10%



24/5/2019

RECEIVED 24 MAY 2019

Date/Time, File Pass to?

24/05/19

☐

: Prel. Report

1)

Typist

☒

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trlp:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

140

Transportation:

50

S + RS \$

50

Fixtures

21

Others

TOTAL

261

Report Format:

Lump Sum / I.B.I. (\$

4,737.73 p/p



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001634MFSH

Date: 22 March 2019

Our Ref: CS/FCI19004232/Ksd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SCW 7755C .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 19/03/2019 at the premises of M/s Cheng Hoe Motor Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,237.73</u> .
Revised Estimate Amount	: S\$ <u>4,737.73</u> .
"Check" Items Amount	: S\$ _____ .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the front n/s portion .



Comments/ Present Status:

Damages Consistent.

Repair days: 4 Days

Yours faithfully,
Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	06-03-2019	Our Ref No. D19001634MFSH
Accident Date	05-03-2019	Claim Type. Third Party
Insured Vehicle	SHD6927X	Third Party Vehicle. SCW7755C
Survey Location	BLK 1019 YISHUN IND. PARK A #01-374	
Contact Person.	JUNE	
Contact No.	67556142/ 0	Fax No. 67557719
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHENG HOE MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	Veh Out

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 22 March 2019 8:39 AM
To: 'Joanne Yong Lai fong'; 'CWS Motor Claims'
Cc: SUR; assignments
Subject: RE: SURVEY ASSESSMENT - D19001634MFSH/1
Attachments: SCW 7755C - Preli Advise -.pdf

Dear Joanne,

Enclosed preliminary revised of vehicle SCW 7755C.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 22 March 2019 8:31 AM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: FW: SURVEY ASSESSMENT - D19001634MFSH/1

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Thursday, 7 March 2019 3:03 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <JoanneYong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001634MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1864G
Vehicle Details	
Vehicle No.:	SCW7755C
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	ALPHARD 2.5S A
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	2ARH616232
Chassis No.:	AGH300034692
Maximum Power Output:	134.0 kW (179 bhp)
Open Market Value:	\$34,733.00
Original Registration Date:	21 Sep 2016
First Registration Date:	21 Sep 2016
Transfer Count:	1
Actual ARF Paid:	\$40,627.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Sep 2026
PARF Rebate Amount:	\$30,470.00
Intended COE Rebate Details	
COE Expiry Date:	20 Sep 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,002.00
COE Rebate Amount:	\$42,973.00
Total Rebate Amount:	\$73,443.00

The information contained herein is correct as at 06 Mar 2019

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SCW7755C
TP/FC

M/S : MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

WS Ref: TP/FC/YS

Claim Type: Third Party

Accident Date: 05/03/2019

TP Veh Reg No: SHD6927X

Estimate No: ES1991283/YISHUN

Date: 18 Mar 2019

Policy No: 5092274359-01

Veh Reg No: SCW7755C

Make/Model: TOYOTA ALPHARD
2.5S A

Chassis No: AGH300034692

Engine No: 2ARH616232

Reg. Date: 21/09/2016

Not Notified

Repair by paint

4737.73

4clap

Estimate Repair Cost to Vehicle No :SCW7755C

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 HEADLAMP LH	3,486.40	1 PC	3,486.40	✓
2 FRONT LH FENDER	1,085.00	1 PC	1,085.00	✓
3 FRONT BUMPER CLIPS	3.89	10 PCS	38.90	✓
			4,610.30	
		Less 25%	1,152.58	3,457.73
Labour				
4 REMOVE & REFIX FRT BUMPER ASSY,FOG LAMPS,GRILLE,FRT LH FENDER,SIDE MIRROR,HEADLAMP,KNOCK & REPAIR FRT SUPPORT PANEL & REALIGN THE SAME	800.00	1 LA	800.00	500
5 REMOVE & REFIX FRT PARKING SENSOR & CHECK SYSTEM	80.00	1 LA	80.00	50
6 PUTTY & RESPRAY ON FRT BUMPER,FRT LH FENDER,BONNET,FRT SUPPORT PANEL	900.00	1 LA	900.00	700
			1,780.00	1,780.00
			Total	S\$ 5,237.73
			Add GST @ 7%	366.64
			Total Amount Payable	S\$ 5,604.37

7. Rustproofing

430/1 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19004232/Ksd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 27-05-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6927X	Veh. Inspected	SCW 7755C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001634MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	07/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALPHARD (A)	c.c	2493	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	AGH300034692	Colour	METALLIC BLACK	
Odometer	74057	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50 R18	GREEN MAX	6 mm	
L/H Front Tyre	235/50 R18	GREEN MAX	6 mm	
R/H Rear Tyre	235/50 R18	GREEN MAX	6 mm	
L/H Rear Tyre	235/50 R18	GREEN MAX	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/03/2019	Inspection Date	19/03/2019	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCW 7755C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HEADLAMP LH	CRACKED	3,486.40	3,486.40
1	FRONT LH FENDER	BENT	1,085.00	1,085.00
10	FRONT BUMPER CLIPS @\$3.89	NECESSARY	38.90	38.90
	LESS 25% DISCOUNT		-1,152.57	-1,152.57
			3,457.73	3,457.73
	<u>LABOUR</u>			
	REMOVE & REFIX FRT BUMPER ASSY, FOG LAMPS, GRILLE, FRT LH FENDER, SIDE MIRROR, HEADLAMP, KNOCK & REPAIR FRT SUPPORT PANEL & REALIGN THE SAME.		800.00	500.00
	REMOVE & REFIX FRT PARKING SENSOR & CHECK SYSTEM.		80.00	50.00
	PUTTY & RESPRAY ON FRT BUMPER, FRT LH FENDER, BONNET, FRT SUPPORT PANEL.		900.00	700.00
	RUSTPROOFING.		30.00	30.00
			1,810.00	1,280.00
	GRAND TOTAL		5,267.73	4,737.73
RECOMMENDED COST OF REPAIRS				4,737.73

Report Ref No. CS/FCI19004232/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.