



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving 1 2007 SUZUKI APV 1.6 (SJL1951S)

Date of Loss 16 February 2019

Time of Loss 20.55

Loss Description SJL1951S (INSD) C/W SLM229Y (TP)

Comment

Workshop Details

Total Rebate Amount 15438

Nett Loss Amount \$7,562.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion * 77



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SJL1951S

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

03/08/2007



Mileage

164656

Age of Vehicle

11

CATEGORY

POLICY INFORMATION

ASSESSMENT
INFORMATIONManufacturing
Year

2007

2007

Make

SUZUKI

SUZUKI

Model

APV 1.6

APV 1.6 AT

Driver Details

CATEGORY

FNOL INFORMATION

POST SURVEY
INFORMATION

Driver Name

WON FENG YIE

Date of Birth

16 January 1968

dd/mm/yyyy



Age

51

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		
Type of Paint		
Chassis No	MHYGDN71V00106001	MHYGDN71V00
Engine No	G16AID126343	G16AID126343
Engine Capacity		1590
Sum Insured	0	0
Market Value	0	23000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	25	
Driver License #		
License Type		
License Issue Date		dd/mm/yyyy
License Expiration Date		dd/mm/yyyy
Address	17 LORONG PISANG EMAS, 597834, Singapore	
Address type	Residential	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Female	
Marital status	Married	
Identification #	S6803412D	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

07/03/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Fair ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

185/70R14

Rear Tyre Size

185/70R14

Front left side

BRIDGESTONE6mm

Rear left side

BRIDGESTONE6mm

Front right side

BRIDGESTONE6mm

Rear right side

BRIDGESTONE6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

Add Approve Deny Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			L/R DOOR REPAIR PAINTING <50%			Repair	0	0	0	0	0	Deny	
		2	1			L/SIDE FRAME CPL REPAIR PAINTING <50%			Repair	0	0	0	0	0	Deny	
		3	1			L/R BUMPER CORNER REPAIR PAINT PLASTIC			Repair	0	0	0	0	0	Deny	

Labour

Add Approve Deny Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		25.0 WU X 45.00 SGD / H	112.5	0	0	Reviewing		
		2		LABOUR COST 66.0 WU X 45.00 SGD / H	297	0	0	Reviewing		
		3		MATERIAL COST	87.8	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

DAYS
OF
REPAIR
: 3
DAYS

Reviewing





SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount

\$497.30

Claim Amount

\$497.30

CATEGORY

ESTIMATE

REVISED AMOUNT

Labour

\$497.30

\$497.30

[Submit for Review](#)