

22001/2002

ASS. REC. BY:

REF: CS/FCI 19004242/Evd 30 Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

Joanne Yong

of

FCI

Date/Time:

07/31/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MVT CS

To Inspect Vehicle No:

SOM 2558D

Insured:

SH 83175

at Workshop in/s

MTM Performance

Tel:

9220404 Erwin Ho

of

48 Ton Guan Road East #01-115 Enterprise Hub

Policy No:

Claim No:

D1900618MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

01/3/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

WP

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT


Date/Time	Action/Instruction () Estimate
	SOM 2558D b;
	SH 83175 b
13/3/19	Email preli revised to FCI

Steve

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Veh No: **SOM 25580** Yr Regn: **5/06/12**
 Type: **M.Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Toyota Lexus GS350** CC: **3.5**
 Colour: **White** A/C: _____ Insured / Std / NI / NA
 Sp. Reading: **120395** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 Ci/No: **JTH BE1BL505009124**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: **Inorder** / Jammed / Leaked / Burnt or
 Brake: **Inorder** / Jammed / Leaked / Burnt or
 Modi: Nil / **S/Rim** / STD A/Rim or
 Tyre Size: F: **235/45R18**
 R: **11**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal. **7** mm R/Bal. **7** mm
 L/Bal. **7** mm L/Bal. **7** mm
 D.O.A. **11/3/19** D.O.I. **11/3/19**
 Survey held at **MTM Performance**
 Des. of Damages: Frt / **Rear** / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time / Action / Instruction
 MV - 80,000
 PV - 69,042
 NV - 10,958
 finalize with Erwin (9221 0404) L/S 12650 - 2 days 13/3/19
 (Red 1151.59, 309)

RECEIVED 13 MAR 2019

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: **2**
 Resurvey No. of Trip: **-**

13/3 - typist

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:	130
Transportation	50
S + R5	
Photos	35
Other	
TOTAL	215

Report Format: **CWS**
 Lump Sum / I.B.F. (\$): **2650+**

MOTOR SURVEY ASSIGNMENT

Date	06-03-2019	Our Ref No. D19001618MFSH
Accident Date	01-03-2019	Claim Type. Third Party
Insured Vehicle	SH8317S	Third Party Vehicle. SDM2558D
Survey Location	48 TOH GUAN ROAD EAST #01-115 ENTERPRISE HUB	
Contact Person.	ERWIN HO	
Contact No.	92210404/ 92210404	Fax No. 0
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MTM PERFORMANCE AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

Raubich
 11/3/2019
 After 4pm

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 13 March 2019 9:16 AM
To: 'CWS Motor Claims'
Cc: SUR; 'Joanne Yong Lai fong'
Subject: RE: SURVEY ASSESSMENT - D19001618MFSH/1, SDM 2558D
Attachments: SDM 2558D PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SDM 2558D
Date of survey: 11/3/2019
Number of days : 2 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 7 March 2019 12:57 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joaneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001618MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19001618MFSH

Our ref: CS/FCI19004242/Evd3

Date : 13/3/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SDM 2558D


We thank you for your instruction on 7/3/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 11/3/2019 at the premises of M/s MTM PERFORMANCE AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$3,801.59
Revised Estimate Amount	: S\$3,482.57
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

STEVE CHEN
Automotive Assessor

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0635B
Vehicle Details	
Vehicle No.:	SDM2558D
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS GS350 LUXURY AUTO
Primary Colour:	Blue
Manufacturing Year:	2012
Engine No.:	2GR8756791
Chassis No.:	JTHBE1BL505009124
Maximum Power Output:	233.0 kW (312 bhp)
Open Market Value:	\$64,609.00
Original Registration Date:	05 Jun 2012
First Registration Date:	05 Jun 2012
Transfer Count:	1
Actual ARF Paid:	\$64,609.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jun 2022
PARF Rebate Amount:	\$41,995.00
Intended COE Rebate Details	
COE Expiry Date:	04 Jun 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$83,700.00
COE Rebate Amount:	\$27,047.00
Total Rebate Amount:	\$69,042.00

The information contained herein is correct as at 11 Mar 2019

OK

CHEAPEST CAR INSURANCE RENEWAL  **Compare 10+ Insurers** **GET A CHEAPER QUOTE NOW**

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

New 5 Years Coe Renewal Toyota Altis 1.6A



2.88%P.A Low Interest@GV Finance. 2 Years Warranty. \$2000 Down Monthly From \$56
GV Credit Pte Ltd StarAd

Lake View Credit Pte Ltd [view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category

Sort by Date Posted 20 results/page

2 vehicles

Lexus GS350

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Lexus GS350		Any	Any	2012	Any	Any	Any	Availabl
	Lexus GS350	Lexus GS350 Luxury	\$86,800	\$17,890 /yr	28-Mar-2012	3,456 cc	97,000 km	Luxury	Availabl
		Strictly Need To Make Appointment! Looking For A Sporty, Reliable, Powerful Yet Elegant Daily Driver! Passionate And Car Enthusiast Owned. Look No Further. This GS350 Is Fully Loaded. Why Buy A GS250 ...							
		Swee Seng Motors Posted: 26-Feb-2019 Tags: 2012 Lexus GS350, 2012 lexus gs350, Lexus GS350, lexus gs350, Lexus, GS350, gs350, Used Lexus							
	Lexus GS350	Lexus GS350 Luxury	\$80,888	\$14,750 /yr	26-Jun-2012	3,456 cc	110,000 km	Luxury	Availabl
		\$1300 Monthly, Fierce And Luxury Looks With Customized Bodykit, Full Soundproof, Tip Top Condition, Luxury Model And Perfect Colour Combination Of Exterior And Interior. As Good As New, Consignment Un...							
		Posted: 17-Jan-2019 Tags: 2012 Lexus GS350, 2012 lexus gs350, Lexus GS350, lexus gs350, Lexus, GS350, gs350, Used Lexus							

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view [Expired ads](#)

20 results/pag

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rate: insurance. Find buy used Lexus GS350, Lexus GS350 Singapore, used Lexus GS350 Singapore, used Lexus GS350, used vehicles Singapore or even buy used Lexus GS350 Singapore. We new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partne for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

[Compare](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/03/2019 11:59
Date Of Accident	01/03/2019 16:30
Exact Location Of Accident	AT MARITIME SQUARE PICK UP/DROP OFF POINT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDM2558D
Insured/Policyholder	
Name Of Registered Owner	TAN POH HENG WILLIAM
NRIC No	S8240635B
Email Address	BAOXING@LIVE.COM
Mobile Phone No	(LOCAL) +65-86887745
Alternative Phone No	OFFICE-86887745

Vehicle Particulars

Manufacturer	LEXUS
Model	GS350-3.5 LUXURY (L10) (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 80459244 QMX
Cover Note Number	

Driver

Name of Driver	TAN POH HENG WILLIAM
NRIC No	S8240635B
Date Of Birth	28/11/1982
Occupation	INDOOR
Date Of Driving Pass	11/01/2010
Driving Experience	9 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-86887745
Fax Number	
Contact Number	OFFICE-86887745
EEmail Address	BAOXING@LIVE.COM

Address	BLOCK 352 KANG CHING ROAD #08-73
Postcode	610352
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CHU THI THI HANG GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	JURONG NPP - PLEASE REFER TO THE ATTACHED POLICE REPORT FOR THE ACCIDENT DETAILS.
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Please refer to the attached Police Report and the Sketch Plan for the accident details.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SH8317S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	FOO HEW CHEW
NRIC/Passport Number	S6813114F
Contact Number	96928116
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 2

Passenger 1 NAME: :

GENDER: :

DETAILS OF INJURED PERSON 1

Name TAN POH HENG WILLIAM
Approximate Age 36
Injuries Sustain
Injured person in which vehicle? SDM2558D
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address BLOCK 352 KANG CHING ROAD #08-73
Postcode 610352

DETAILS OF INJURED PERSON 2

Name CHU THI THI HANG
Approximate Age 36
Injuries Sustain
Injured person in which vehicle? SDM2558D
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address BLOCK 352 KANG CHING ROAD #08-73
Postcode 610352

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 02/03/2019

11.40 AM

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190301/2165

Police Station Of Origin:
Jurong NPP
158 Yung Loh Road #01-58 SINGAPORE
610158
Tel No: 1800-2659999

1 of 4

Report No. T/20190301/2165

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/03/2019 19:39	Vide Report No.:	Station Diary No.: 50
--	------------------	--------------------------

Informant's Particulars

Name of Informant: TAN POH HENG, WILLIAM			Address: APT BLK 352 KANG CHING ROAD #08-73 SINGAPORE 610352		
ID Type / ID No.: NRIC NO / S8240635B			Contact No.: Home/Office: Mobile: 86887745		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 36	Date of Birth: 28/11/1982	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: SELF EMPLOYED			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 01/03/2019 16:30	Type of Location: Straight Road
Location: Along Road 1 MARITIME SQUARE				
Pick up/Drop Off Point				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SDM2558D		LEXUS		White	Slightly Damaged	1
SH8317S		HYUNDAI		Blue	Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190301/2165

3 of 4

Report No. T/20190301/2165

Police Station Of Origin:
Jurong NPP
158 Yung Loh Road #01-58 SINGAPORE
610158
Tel No: 1800-2659999

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20190301/2165

Police Station Of Origin:
Jurong NPP
158 Yung Loh Road #01-58 SINGAPORE
610158
Tel No: 1800-2659999

2 of 4

Report No. T/20190301/2165

CONTINUATION OF REPORT

Passenger			
Name	CHU THI THU HANG	ID No.	S8267958H
Related Vehicle	SDM2558D	Contact No.	NIL
Hospital/Clinic	LIGHTHOUSE CLINIC AND SURGERY	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	01/03/2019	Date Discharge	01/03/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	TAN POH HENG, WILLIAM	ID No.	S8240635B
Related Vehicle	SDM2558D	Contact No.	86887745
Hospital/Clinic	LIGHTHOUSE CLINIC AND SURGERY	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	01/03/2019	Date Discharge	01/03/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	FOO HEE CHEW	ID No.	S6813114F
Related Vehicle	SH8317S	Contact No.	96928116
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 01/03/2019 at about 1630hrs, I drove my car SDM2558D with my wife namely Chu Thi Thu Hang S8267958H as my passenger and came to a stop at Harbour Front Centre's Pick up/Drop off point to meet a friend there. I pulled my handbrake and my car was stationery. One minute later, suddenly I felt an impact from the back and it caused my vehicle to move forward. I quickly checked on my wife and went out of my vehicle. I discovered a blue comfort taxi SH8317S has knocked onto the rear of my vehicle. We exchanged particulars and the taxi driver left the area. My wife is pregnant thus I brought her to Lighthouse Clinic and Surgery Pte Ltd to see the doctor. I felt pain on the back of my neck thus I also consulted the doctor at the same clinic. My wife and I were given 3 days MC by the doctor. There are CCTVs at the pick up/drop off point at Harbour Front Centre.



**SINGAPORE
POLICE FORCE**



T/20190301/2165

Police Station Of Origin:
Jurong NPP
158 Yung Loh Road #01-58 SINGAPORE
610158
Tel No: 1800-2659999

4 of 4

Report No. T/20190301/2165

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J / Sgt 3 KUMARAVAL KIONG ANANTHAN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 01/03/2019 19:39
Officer In Charge Of Case: TP / AET / SSI 2 YEO GEAK ENG CECILIA Contact No: 65476404	Classification Of Case:
Authentication Stamp NP168 Singapore Police Force	SN 124

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8240635B



Name

TAN POH HENG, WILLIAM
(CHEN BAOXING, WILLIAM)

陈宝兴

Race

CHINESE

Date of birth

28-11-1982

Sex

M

S8240635B

Country of birth

SINGAPORE

4912847



NRIC No. **S8240635B**



Date of issue

11-12-2012

Address

APT BLK 352 KANG CHING ROAD
#08-73
SINGAPORE 610352

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S8240635B**
Name:

TAN POH HENG, WILLIAM
(CHEN BAOXING, WILLIAM)

Birth Date: **28 Nov 1982**

Issue Date: **11 Jan 2010**



8688 7745

baoxing@live.com

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars= \leq 3000kg with \leq 7 passengers, exclusive of the driver; and other motor vehicles \leq 2500kg 11 Jan 2010

NP 428A





MSIG

MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
 Tel +65 6827 7888, Fax +65 6827 7800
 Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
 (REPUBLIC OF SINGAPORE)
 THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
 Individual Ownership

MOTOR MAX
 Comprehensive

Certificate No. A 80459244 QMX

Excess : SGD750

Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
 SDM2558D

2. Name of Policyholder
 TAN POH HENG, WILLIAM

Levins G5 350 luxury

3. Effective Date of the Commencement of Insurance for the purposes of the Act
 17/07/2018

4. Date of Expiry of Insurance
 28/06/2019

5. Persons or Classes of Persons entitled to drive*

TAN POH HENG, WILLIAM

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.
 The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.

Approved Insurers

for Chief Executive Officer

ATSY201807201404

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



MTM Performace Auto Pte Ltd

07/03/2019

To : MS First Capital

Re: Quotation for repair cost for SDM2558D

Item	Description	Qty	Amount (S\$)
1	Rear bumper / <i>DD</i>	1	1,055.98
2	Rear bumper retainer <i>RM - RR</i> (70.03)	<i>2/1</i>	340.05
3	Rear re-enforcement bar <i>RT</i>	1	597.80
4	Rear bumper lower lip / <i>CUT</i>	1	622.31
5	Rear bumper lower chrome / <i>RM CUT</i>	1	201.05
6	Reverse sensor / <i>RR</i>	1	235.40
7	Labour for all	1lot	428.00 <i>350 400</i>
8	Spray paint	1	321.00 <i>250 300</i>

3801.59

Less
1070
 2882.57
- 10%
 2594.31
 790
 3294.31

L/S - 2635.44
= 2650

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

[Signature]
 13/3/19

Steve (LKK)
8322 8813

with prejudice 11/3/19 5pm
2 cks
L/S
R AL spray

stevechen@lkkauto.com



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19004242/Evd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 15-03-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 8317S	Veh. Inspected	SDM 2558D
Policy No.		Coverage (\$)	0.00
Claim No.	D19001618MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	07/03/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA LEXUS GS350	c.c	3456
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	JTHBE1BL505009124	Colour	WHITE
Odometer	120395	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/45 R18	YOKOHAMA	7 mm
L/H Front Tyre	235/45 R18	YOKOHAMA	7 mm
R/H Rear Tyre	235/45 R18	YOKOHAMA	7 mm
L/H Rear Tyre	235/45 R18	YOKOHAMA	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	01/03/2019	Inspection Date	11/03/2019
Survey held at	MTM PERFORMANCE AUTO PTE. LTD. 48 TOH GUAN ROAD EAST #01-115 ENTERPRISE HUB SINGAPORE 608586		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDM 2558D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED	1,055.98	1,055.98
2	REAR BUMPER RETAINER	O/S BROKEN	340.05	170.03
1	REAR RE-ENFORCEMENT BAR	BENT	597.80	597.80
1	REAR BUMPER LOWER LIP	CUT	622.31	622.31
1	REAR BUMPER LOWER CHROME RH	CUT	201.05	201.05
1	REVERSE SENSOR	BROKEN	235.40	235.40
	LESS 10% DISCOUNT		-	-288.26
			3,052.59	2,594.31
LABOUR				
	LABOUR FOR ALL.		428.00	400.00
	SPRAY PAINT.		321.00	300.00
			749.00	700.00
GRAND TOTAL			3,801.59	3,294.31
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,650.00

Report Ref No. CS/FCI19004242/Evd3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.