

ASS. REC. BY:

REF:

CS3/LPC19004253/Eqd3

n2

Special Instruction:

Surveyor:

Steve

ASSIGNMENT (Office)

From (Person):

Ang Li Li

of

LPC

Date/Time:

02/3/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No.:

GBH 92868

Insured:

GBA 6571A

at Workshop info:

-OMEGA Auto PL

Tel:

92718287 Terence Lam

of

160 S/M Drive #06-06 S/M Autocity SC (575722)

Policy No.:

Claim No.:

18/19/19/VC00/021496

Sum Insured:

Excess:

Make of Veh:

D.O.A.

05/3/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

LP

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

GBH 92868 x

GBA 6571A x

05/3/19

submit RES.

REF: **hpc****ASSIGNMENT**From: _____ Date: **12/3/19**

Estimated Cost: _____

OD ☒ TP ☐ WS ☐ / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: **GBH 92865**
at Workshop m/s: **Omega Auto**
of **160 Sin Ming Drive #06-06**

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: **Before 12pm**

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **GBH 92865** Yr Regn: **8/11/18**Type: M.Car / M.Cycle / Bus ☒ Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Toyota Hiace** C.C. **2982**Colour: **Silver** A/C: Insured / Std / NI / NASp. Reading: **27563** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **JTFHT02P 900-245696**Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / ☒ STD A/Rim orTyre Size: F: **195 R15C**R: **11**BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. **7** mm R/Bal. **7** mmL/Bal. **7** mm L/Bal. **7** mmD.O.A. **5/3/19** D.O.L. **12/3/19**Survey held at **Omega Auto** **11am**Des. of Damages: Frt ☒ Rear ☐ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV - 70.000**PV - 23.518****NV - 46.482**

RECEIVED 25 MAR 2019

Date/Time, File Pass to?

☐

: Preli. Report

11/25/19 **hpc**☐

: Final Report

Date/Time, File Return to?

2)

Report Format: **PRS**

Lump Sum / I.B.I. (\$) _____

Days Of Repair:

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$ _____)☐ Interview (\$ _____)☐ Tech. Invs (\$ _____)☐ Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

450

Catherine Chong (LKK Auto)


From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 7 March, 2019 4:09 PM
To: Kuru & Co; MT_Claim_SG; assignments@lkkauto.com; Admin-D (LKKAuto)
Subject: RE: YRef: 18/19/19/VC00/021496 ORef: L19.0312.cj //ACCIDENT INVOLVING gbH9286S & GBA6571A ON 05.03.19 ALONG JURONG ISLAND EXPRESSWAY NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY [External General]

Lonpac External - General

Dear Catherine/Nivitha

FYA

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: Thursday, 7 March, 2019 4:07 PM
To: MT_Claim_SG; assignments@lkkauto.com; Admin-D (LKKAuto); ONG LI LI
Subject: Re: YRef: 18/19/19/VC00/021496 ORef: L19.0312.cj //ACCIDENT INVOLVING gbH9286S & GBA6571A ON 05.03.19 ALONG JURONG ISLAND EXPRESSWAY NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY [External General]

Dear Li Li

We confirm that you have objected to our client's list of surveyors. Our client's vehicle is at the following address:

OMEGA AUTO PTE LTD
160 Sin Ming Drive

#06-06 Sin Ming Autocity
Singapore (575722)
Tel: Terence Lau (9271 8287)

PRG

Veh Out

Please inform your surveyor to conduct the pre-repair survey within 2 working days, failing which our client will have no alternative but to proceed with the repair of his vehicle.

Regards
Irene
Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building

Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

On Thursday, 7 March 2019, 3:53:22 pm SGT, ONG LI LI <long@lonpac.com> wrote:

Lonpac External - General

Without Prejudice

Save as to Costs

Dear Irene

We are not agreeable with your list of proposed surveyors and we shall assign LKK Auto Consultants Pte Ltd to conduct the survey. Please provide the details of your client's workshop.

Dear Catherine/Nivitha

FYA


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Kuru & Co [<mailto:kurulegal@yahoo.com.sg>]

Sent: Thursday, 7 March, 2019 3:48 PM

To: MT_Claim_SG; assignments@lkkauto.com; Admin-D (LKKAuto); ONG LI LI

Subject: YRef: 18/19/19/VC00/021496 ORef: L19.0312.cj //ACCIDENT INVOLVING gbH9286S & GBA6571A ON

WITHOUT PREJUDICE

Dear Sirs

We refer to your email of even date.

Our client is objecting to your list of surveyors. Attached is our client's list of proposed surveyors for your consideration.

Please state the surveyor you will be appointing to be the single joint expert or that you are objecting to our client's proposed list of surveyors.

If we do not hear from you **within 2 working days**, it shall be deemed that you have agreed to the appointment of any of the surveyors listed by our client.

Regards

Irene

Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

On Thursday, 7 March 2019, 3:32:28 pm SGT, ONG LI LI <long@lonpac.com> wrote:

Lonpac External - General

Without Prejudice

Save as to Costs

Dear Sir/Mdm

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick <input type="checkbox"/>
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]

Sent: Thursday, 7 March, 2019 2:16 PM

To: MT_Claim_SG; ONG LI LI

Subject: L19.0312.cj //ACCIDENT INVOLVING gbH9286S & GBA6571A ON 05.03.19 ALONG JURONG ISLAND EXPRESSWAY NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

Dear sirs

ACCIDENT INVOLVING gbH9286S & GBA6571A ON 05.03.19

ALONG JURONG ISLAND EXPRESSWAY

NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

We act for **OMEGA AUTO PTE LTD**, whose vehicle registration number **GBH 9286S** was damaged in the above accident.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards

Irene

Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

- Big Box Retail Warehouse Opens in Jurong East Today
- Consolidated Info on MRT/LRT Maintenance & Breakdo...
- Mercedes GLC

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Cde Renewal Toyota Altia 1.6A



2.0BHP A Low Interest Gv
Finance, 2 Years Warranty,
\$2000 Down Monthly From \$56
GV Credit Pte Ltd - Stand



Browse by Category

< Back (1 2 3 4 5 6) Next >

Sort by Date Posted

20 results/page

114 vehicles

Toyota Hiace

Advanced Search

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

Toyota Hiace

Any

Any

2018

Any

Any

Any

Available



Toyota Hiace

\$66,800

\$6,840 /yr

14-Dec-2018

2,982 cc

1 km

Van

Available

Fuel Type: Diesel

Cheapest In Market With COE, New Unit Nett Price Inclusive Of GST, ARF, Road Tax And Registration Fees! Cash Deal Welcome! For A Piece Of Mind, Buy Agent Unit! Latest Euro 6 Toyota Hiace Model With Bo...

Yes Motoring

Posted: 12-Mar-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace

\$66,800

\$6,880 /yr

26-Nov-2018

2,982 cc

1 km

Van

Available

Fuel Type: Diesel

Cheapest In Market With COE, New Unit Nett Price Inclusive Of GST, ARF, Road Tax And Registration Fees! Cash Deal Welcome! For A Piece Of Mind, Buy Agent Unit! Latest Euro 6 Toyota Hiace Model With Bo...

Yes Motoring

Posted: 12-Mar-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace

\$69,688

\$7,260 /yr

16-Oct-2018

2,982 cc

-

Van

Available

Fuel Type: Diesel

Monthly \$808. Free 12 Times Servicing & 3 Year Warranty. Price Inclusive Guarantee 10 Year COE And GST. No Gimmicks, No Hidden Cost. Book Now Before You Miss The Deal!

ABWIN Bus Pte Ltd

Posted: 12-Mar-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace

\$71,988

\$7,510 /yr

11-Oct-2018

2,754 cc

3,842 km

Van

Available

Fuel Type: Diesel

Almost New PT Toyota Hiace 2.8 Auto 5 Doors Rear Aircon, 5 Doors For Easy Loading And Unloading Of Goods. Ready Stock Available. We Provide Flexible In House And Bank Loan Up To 100%. High Trade In For...

ABWIN Bus Pte Ltd

Posted: 12-Mar-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Audio Panel (TA-8233B)

1+1 / 2 DIN Audio Panel for Avalon (2011-2013)

More info about this product



Toyota Hiace

\$63,988

\$6,930 /yr

01-Jun-2018

2,982 cc

-

Van

Available

Fuel Type: Diesel

Toyota Hiace SDR Euro 6 Manual. Suitable For All Business Trade. Easy Access For Unloading And Loading Of Goods. We Provide Flexible In House And Bank Loan Up To 100%. No Hidden Cost. Trade In Welcome...

ABWIN Bus Pte Ltd

Posted: 12-Mar-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace Commuter

\$92,988

\$9,520 /yr

17-Dec-2018

2,982 cc

-

Van

Available

Fuel Type: Diesel

Be It Medical Transport Or Non Emergency Ambulance, We Provide A 1 Stop Service To Cater All Your Needs. Easy Approval In House Loan With Low Interest Rate Available. High Trade In For Your Used Vehicle...

ABWIN Bus Pte Ltd

Posted: 12-Mar-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace Commuter

\$90,800

\$9,930 /yr

02-May-2018

2,754 cc

-

Bus

Available

Fuel Type: Diesel

(Latest Model) Comes With Front Sensing, Auto Adaptive Headlamps, 3 Years Or 100000km Warranty Whichever Come First, Include 6 Months Road Tax, And Lots Of Accessories, High Loan With Low-Interest Rat...

KSL Automotive Pte Ltd

Posted: 12-Mar-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace

\$65,800

\$6,730 /yr

17-Dec-2018

2,982 cc

-

Van

Available

Fuel Type: Diesel

Guaranteed Delivery, High Flexible Loan, No Top Up Needed, No Hidden Cost. Best Timing To Buy. Full Loan, High Trade-In Available, Call Us Now For Viewing!

Compare

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5188K
Vehicle Details	
Vehicle No.:	GBH9286S
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 5DR MT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	1KD2828775
Chassis No.:	JTFHT02P900245696
Maximum Power Output:	-
Open Market Value:	\$28,136.00
Original Registration Date:	08 Nov 2018
First Registration Date:	08 Nov 2018
Transfer Count:	1
Actual ARF Paid:	\$1,407.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	07 Nov 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$24,362.00
COE Rebate Amount:	\$23,518.00
Total Rebate Amount:	\$23,518.00

The information contained herein is correct as at 12 Mar 2019

OK

MBHH10030516-01 / Ajax Mers Pte Ltd - Bukit Merah
ENTRY DATE & TIME: 06/03/2019 15:50
SUBMITTED BY: Elizabeth Lee

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 06/03/2019 15:50
Date Of Accident 05/03/2019 12:00
Exact Location Of Accident ALONG JURONG ISLAND EXPRESSWAY
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBH9286S
Insured/Policyholder
Name Of Registered Owner OMEGA AUTO PTE LTD
Co Reg No 200205188K
Email Address JOGHENTERPRISE@HOTMAIL.COM
Mobile Phone No
Alternative Phone No OFFICE-92718287

Vehicle Particulars

Manufacturer TOYOTA
Model HIACE VAN TURBO 5DR MT
Exact Purpose for which vehicle was being used at time of accident COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company ALLIED WORLD ASSURANCE COMPANY, LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number AVCPSB0093731800
Cover Note Number N.A

Driver

Name of Driver MARIMUTHU PRABU
Passport No/FIN G5435774K
Date Of Birth 04/03/1988
Occupation OUTDOOR
Date Of Driving Pass 14/01/2015
Driving Experience 4 YEARS AND 1 MONTH
Gender MALE
Mobile Number (LOCAL) +65-91686448
Fax Number
Contact Number
EMail Address JOGHENTERPRISE@HOTMAIL.COM

Address NA
 Postcode
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle Involved in this accident? NO
 Number of vehicles (including own vehicle) Involved in the accident 2
 Was any body Injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

My vehicle GBH9286S was stationary at the traffic light at JURONG ISLAND EXPRESSWAY waiting for green light when a vehicle GBA6571A hit onto rear of my GBH9286S. No injuries involved. That's all.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBA6571A
 Vehicle Make/Model/Colour RENAULT / KANGOO DCI70
 Details Of Properties N.A
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver ALAGARSAMY VIJAYANAND
 NRIC/Passport Number G7666641K
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan

IMPORTANT NOTICE


1. Please report correctly the details of the accident to police and the relevant authority.
2. This Form must be completed by the Policyholder (holder of the Auto Insurance Policy).
3. Information provided must be as truthful and accurate as possible. Any false information or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of liability on the part of any insured person.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Ministry of the Civil Service (Ministry of Civil Service) to the General Insurance Association of Singapore (GIA) for archiving and that it will not be used for a purpose other than that specified by interested parties.
7. By the judgement of this report to the insurers, you hereby consent to the disclosure of the report at the time and to the use of the report being made available elsewhere.
8. Consent under the Personal Data Protection Act (PDPA):
 (a) I understand, acknowledge, agree and consent that:
 (i) my insurer, my workshop and the General Insurance Association of Singapore (GIA) may be permitted to use my, disclose and/or process my personal information (including but not limited to the following: my other personal information provided by me or processed by my insurer, collectively the "Personal Information") and disclose and transfer such Personal Information to third parties who have had the vehicles involved in this accident (all insureds) who have insured vehicles involved in this accident; and the disclosure referred to by the "insurers", the insurers' lawyers, the Ministry of Civil Service and any relevant government agency/authority (such as the police), for the purpose(s) of:
 (i) processing, handling and/or dealing with my claims involving the settlement of the claims and/or processing investigations relating to the claims;
 (ii) handling the accident claims; claims;
 (iii) carrying out and/or dealing with the settlement or settlement of the claims; and
 (iv) administering my claims (including the mailing of correspondence, statements, reports or notices in the claims) and/or processing of certain personal data about me in my claim; and/or any of the above as well as on the official record of any relevant government agency/authority;
 (b) I hereby consent to my insurer, my workshop and the General Insurance Association of Singapore (GIA) to use my Personal Information for the purpose(s) of:
 (i) all relevant and/or have insured vehicles involved in this accident; and the insurers' lawyers and/or any relevant government agency/authority to collect, use, disclose and/or process my Personal Information for the purpose(s) of the above; and
 (ii) my Personal Information may also be disclosed by any of the insurers' lawyers and/or any relevant government agency/authority to third parties, which may be acted outside of Singapore, for one or more of the above purposes.



VERIFIED BY AJAX MARS
REPORTING OFFICER
MOHD FADZY BIN ISMAIL

Policyholder's Signature / Date & Time: Driver's Signature (if driver is not the policyholder) / Date & Time: Witnessed by Reporting Centre Personnel

Sketch Plan



Sketch Plan #2 Pg. 1

ACCIDENT STATEMENT (2000 characters)

My vehicle GBH9286S was stationary at the traffic light at JURONG ISLAND EXPRESSWAY waiting for green light when a vehicle GBA6571A hit onto rear of my GBH9286S. No injuries involved. That's all.


Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHD FADZLY BIN ISMAIL

MARS Officer





Registered Owner or Driver's Signature

Job Complete Date/Time

Date/Time:



PRE-REPAIR INSPECTION REPORT				
LONPAC INSURANCE BHD		Ref: CS3/LPC19004253/Eqd3n2		
300 BEACH ROAD		Date: 26-03-2019		
#17-04/07 THE CONCOURSESINGAPORE 199555		Code: LPC2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	GBA 6571A	Veh. Inspected	GBH 9286S	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/19/19/VC00/021496	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	07/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTFHT02P900245696	Colour	SILVER	
Odometer	27563 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	MICHELIN	7 mm	
L/H Front Tyre	195 R15C	MICHELIN	7 mm	
R/H Rear Tyre	195 R15C	MICHELIN	7 mm	
L/H Rear Tyre	195 R15C	MICHELIN	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	05/03/2019	Inspect Date / Time	12/03/2019 (11:00 AM)	
Survey held at	160 SIN MING DRIVE #06-06 SIN MING AUTOCITY			
Repairer	OMEGA AUTO PL			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC19004253/Eqd3n2

Inspected By



CHEN TSUE YEE

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.