

ASS. REC. BY:

REF:

CS/AIG 19004756/DS d307

Special Instruction:

Surveyor

Mingun

ASSIGNMENT (Office)

From (Person):

Hor Yinnul

of

AIG

Date/Time:

6/3/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLA S2SE

Insured:

SMF6999T

at Workshop m/s

Goh Lee Hwa

Tel:

9145 4773 Alfred

of

BLK 5033 AMK #01-255

Policy No:

Claim No:

603249927054

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

4/3/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

6/3

Person Contacted:

Alfred

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLA S2SE - 1X

SMF6999T - X

REF:

ASSIGNMENT

From _____ Date _____
 Estimated Cost _____
 UD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res: Yes or No

Lump Sum:

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date

Person Contacted:

Veh No: SLA 525E at Regn: 2016 Feb

Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Camry

G.C. 2494

Colour:

Blue

A/C Insured / Std / NI / NA

Sp. Reading

100935

T/Ratio: Insured / Std / NI / NA

Eng/No:

2ARU296599

C/No:

NR053AK5004010575

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55 R17

R:

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Yokohama

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

04/03/2019

D.O.I.

07/03/2019

Survey held at

Goh Lee Hwa AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

AIG SMF 69997

SSE only finalized repair cost. Settlement will be
 through lawyer.

Final 215 3000/- with 4 days 7 up
 (\$4,224.10 Red - 59%)

Date/Time, File Pass to?

26/04/19

1)

Type 3

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B. (\$

3,000/- HS)

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation

) 3 + RS \$1

) Photos

) Other

) Total

Total

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

290

10

260

Alfred 9145 4773

* Pre-Repair Inspection Request – SLA525E vs SMF6999T (OI) on D.O.A.: 04/03/2019

From: Hor, Yinrul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY; Fan, Winnie-LW; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur
Sent: 5/3/2019 11:19:02 AM
Attachments:  [img-306092508.pdf](#)  [img-306092508.pdf](#)

Hi,

Please refer to the enclosed request from **Kuru & Co.**

Claim no : 6032499270SG003
Case Owner : WEI ZHONG BENNIE TAN

If you have any queries/concerns, please let us know.

Thanks & Regards,

Yin Rul, Hor (Viviane)
AIG
Claim Adjuster II, Singapore FWO, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

Yinrul.Hor@aig.com | www.aig.sg

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: Wednesday, March 06, 2019 11:11 AM
To: Hor, Yinrul
Cc: Fong, Andy-SY; Fan, Winnie-LW; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur
Subject: L19.0306.cj (Pls quote our ref) PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMF6999T AND SLA525E ON 04/03/2019

Hi Hor, Yinrul

Our client is agreeable to the following surveyor as the SJE: Bryan of LKK Auto Consultants Pte Ltd

Please arrange for your surveyor to survey our client's vehicle at the following address:

GOH LEE HWA AUTOMOBILE PTE LTD
Blk 5033 Ang Mo Kio Ind Pk 2
#01-255
Singapore 569536
Contact: **Alfred/9145 4773**

Bryan
OUT

Please instruct your surveyor to conduct the pre-repair survey **immediately** and complete the pre-repair survey within 2 working days of his appointment.

Kindly let us have the pre-repair and/or post repair survey report upon completion of the survey.

As solicitors on record, our client shall look to you for payment of our legal costs plus disbursements should you reach a direct settlement with our client's repairer.

Regards
Irene
Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

On Wednesday, 6 March 2019, 10:39:08 am SGT, Hor, Yinrul <Yinrul.Hor@aig.com> wrote:

<p>This is a secure, encrypted message. To read it, open the attachment.</p> <p>这是安全加密信息。如要阅读此信息，请开启附件。</p> <p>นี่คือการรักษาความปลอดภัยของข้อมูลที่เข้ารหัสลับ เพื่ออ่านให้เปิดไฟล์ที่แนบมา</p> <p>이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.</p> <p>Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.</p> <p>Click here by 2019-03-13 10:39 +08 to read your message. After that, open the attachment.</p>
--

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the individual(s) named. If you have received this email in error or simply do not

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinru.Hor@aig.com

To: kurulegal@yahoo.com.sg

Cc: Andy-SY.Fong@aig.com, Winnie-

LW.Fan@aig.com, Baljit.Kaur@aig.com, NoorMarisa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com

Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMF6999T AND SLA525E ON 04/03/2019

Date: Wed, 6 Mar 2019 02:37:30 +0000

Without Prejudice

Your Reference : L19.0306.cj

Our Reference : 6032499270SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Yin Ruí, Hor (Viviane)

AIG

Claim Adjuster II: Singapore FNOL Claims Operations - Auto

Shared Services - Malaysia | Global Business Services

Yinru.Hor@aig.com | www.aig.sg

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]

Sent: Wednesday, March 06, 2019 9:31 AM

To: AIG SGP, Claims-Survey

Subject: L19.0306.cj // ACCIDENT INVOLVING SLA525E & SMF6999T ON 4/3/19 ALONG SLIP ROAD OF NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

Dear sirs

**ACCIDENT INVOLVING SLA525E & SMF6999T ON 4/3/19
ALONG SLIP ROAD OF
NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY**

We act for TSL BUILDERS PTE LTD, whose vehicle registration number SLA 525E was damaged in the above accident.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

A copy of our client's SAS report is enclosed.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards

Irene

Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/03/2019 08:28
Date Of Accident	04/03/2019 12:15
Exact Location Of Accident	LORONG 6 TOA PAYOH TOWARDS PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA525E
Insured/Policyholder	
Name Of Registered Owner	TSL BUILDERS PTE LTD
Co Reg No	199903297E
Email Address	TSLBUILDERS22@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96387506
Alternative Phone No	OFFICE-96387506

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY 2.5 AUTO

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VA1/GA443317
Cover Note Number	

Driver

Name of Driver	TAY SWEE LAI
NRIC No	S6812096I
Date Of Birth	20/03/1968
Occupation	INDOOR
Date Of Driving Pass	30/01/1992
Driving Experience	27 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96387506
Fax Number	
Contact Number	
Email Address	TSLBUILDERS22@HOTMAIL.COM

Address	BLK 567 HOUGANG ST 51#07-57
Postcode	530567
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMF6999T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ROY
NRIC/Passport Number	
Contact Number	96692745
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to revoke policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:





Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT



← PIE

SLA525E
A

B
SMF 6999T

Lov 6 Ton Psych.

White vehicle A (SLA525E) turning to PIE
Vehicle B (SMF 6999T) turn and want to overtake
A. But hit the back right side of Vehicle A.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

[Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/EPN No.:



redefining / insurance

AXA Insurance Pte Ltd
 ☎ 1800 680 4888 (Within Singapore)
 (65) 6880 4888 (International)
 ☎ (65) 6880 4740
 ✉ customer.care@axa.com.sg
 🌐 www.axa.com.sg

date
 12/02/2019

policy number
 VA1 / GA443317

account number
 14888

Certificate of Insurance

Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1980 (Road Transport Act, 1987) (Malaysia)
 - Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	TSL BUILDERS PTE LTD	Certificate number	GA443317 / 1
Cover	Comprehensive	Chassis number	MZ053AK5004010575
Plan name	Toyota Prestige	Engine number	2ARU296899
NCD applicable	50%		
Vehicle registration number	SLA525E		
Period of Insurance	from 19/02/2019 to 19/02/2020 (both dates inclusive)		
Finance loan company	Nil		

Authorized Drivers

(c) Any person who is driving on the Policyholder's order or with their permission
 Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

- Use of the motor vehicle is connected to the Policyholder's business
- Use for the carriage of passengers (besides commercial hire or reward) in connection with the Policyholder's business
- Use for social, domestic, and personal purposes

The Policy does not cover:

- Use for commercial hire or reward, or for racing, pace-making, reliability trial, or speed testing
- Use while drawing a trailer, except for the towing of a disabled person's mechanically propelled vehicle

* Limitations rendered inoperative by Section 9 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 25 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	SGD 1,500.00
	Windscreen Excess	Not Applicable

Young / Inexperienced driver excess

An additional excess of \$2500 (to be added to any excess imposed under the Policy) whilst the Insured Motor Car is being driven by any driver aged below 25 years old and / or has been issued a valid driving license to drive in Singapore for the relevant class of vehicle for less than one year.

Young and / or inexperienced driver shall mean any person who :

- Is less than 25 years old, and/or
- Has been issued with a valid driving license to drive in Singapore for the relevant class of vehicle for less than 1 year

Additional clauses & endorsements to your policy

Nil



I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorized signature

AXA Insurance Pte Ltd (199903512M)
 6 Shenton Way, #24-01, AXA Tower,
 Singapore 068511
 Customer Centre, #B1-02

1 of 3



NP 428A



Sketch Plan Pg. 5

Date: 04/03/19

To: Owner of Vehicle Number: SLA525E

The following has been advised to you via your workshop, EDGE through their staff, Shirley.

Please tick the applicable box if you had been advice on the content as seen below:

- ☒ You had been advised by the workshop that in the event that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
- ☐ You had been advised by the workshop on the liability and merits of the case accordingly.
- ☐ You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
- ☐ There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.
- ☐ The Estimation waiting time for the spare parts to arrive is _____.
The estimated arrival time does not include the repair period.
- ☐ You will be driving the vehicle out despite being advised by the workshop mechanic/ personnel that the vehicle may not be road worthy.
- ☐ For vehicles below Three (3) years old, your insurance company will use only genuine original parts to repair your vehicle.
- For vehicles above Three (3) years old, your insurance company will be carrying out repairs using any combination of genuine original parts and/or original equipment manufacturer (OEM) parts.
- ☐ You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.
- ☐ For vehicles below Five (5) years old, you had been advised by the workshop to check with the local distributor on your warranty status.
- ☐ Others _____

Signed and acknowledge by:

[Signature]
Name and signature of policyholder/ authorised driver

[Signature]
Name and signature of workshop personnel including company stamp



GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Email: starauto28@gmail.com

Co.reg no. 200808259H

Reference No: 60319**Date: 06.03.2019****TSL Builders Pte Ltd****55 Serangoon North Ave. 4****#05-10 S9 Building****Singapore 555859.****Toyota Camry 2.5****Estimated Repair Cost for Vehicle Reg. No: SLA 525 E****REPLACEMENT OF DAMAGED PANELS / PARTS**

1 Pc. Rear Boot Lamp RH <i>Crack</i>	432.50	✓
1 Pc. Rear Tail Lamp RH <i>2 mandy crack</i>	562.30	✓
1 Pc. Rear Bumper <i>Dented / distord</i>	778.90	✓
1 Pc. Rear Bumper Reinforcement <i>also Dented</i>	425.30	✓
1 Pc. Rear Bumper Lamp <i>Scratched</i>	69.90	✓
1 Pc. Rear Bumper Sponge <i>HH</i>	335.00	X
1 Pc. Rear Bumper Retainer <i>2 broken</i>	133.90	✓
1 Pc. Rear Bumper Lower Lip <i>HH</i>	249.50	X
1 Pc. Rear Bumper Sensor <i>Down</i>	545.00	✓ 220/- SN
1 Pc. Rear Exhaust Box <i>2 bit / Dented</i>	1,039.30	✓
1 Pc. Rear Exhaust Box Chrome Pipe <i>bit</i>	155.80	✓
1 Pc. Logo <i>SVC</i>	99.80	X
1 Pc. 2.5 Emblem <i>SVC</i>	62.30	X
1 Pc. Camry Emblem <i>SVC</i>	89.60	X
10 Pcs. Bumper Clips <i>Nec</i>	65.00	✓ 30/- SN.
	@ 6.50	

Total (Panels / Parts): 5,044.10 (SGD)*25% discount on parts.**LWT 3597.90**25% 2698.42**SN 250/-**Leban 860.00*

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Email: starauto28@gmail.com

Co.reg no. 200808259H

LABOR CHARGESTo check wiring & remove & renew parking sensor
& refit.~~200.00~~ 60/-To knocking, straightening repair & renew all accident
Damage affected area.~~800.00~~ 400/-To respray painting on all accident affected area.
(Pearl Colour)~~980.00~~ 400/-

To rust proof all accident affected area.

860.00

~~200.00~~ 40/-**Total (Labor Charges): 2,180.00 (SGD)****TOTAL COST SUMMARY**PANELS / PARTS
LABOR CHARGES5,044.10
2,180.00

3808.42

1/8 3000/-

Grand Total: 7,224.10 (SGD)

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to 'Goh Lee Hwa Automobile Pte Ltd'

07/03/2019 @ 1130am

N/A Andre

2/Sum 4 days.

Signature

2KK Auto

Page 2 of 2

LKK Auto Consultants hence notify
the Repairer of the following:

- To respray all damaged parts
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)






































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Mar 2019 Edit Reg		06 Mar 2019 00:00 Edit Adj Rpt	S\$3,000.00 Edit Estimates	S\$3,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TANG LI KIANG , ID: S6913077A								
Main Claimant:	TSL BUILDERS PTE LTD , Co. Reg. No.: 199903297E								
Vehicle Reg. No.:	SLA525E	Date of Loss:	04/03/2019 12:00 - :59 [36 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6032499270SG	Policy/Cover Note No.:	1800095890 (Comprehensive)						
Vehicle Reg. No. (Insured):	SMF6999T	Policy No. (Claimant):							
		Excess:							
Repairer:	Goh Lee Hwa Automobile Pte Ltd (HQ) Block 5033 Ang Mo Kio Industrial Park 2 #01-255, 569536 Ang Mo Kio - Tel: 64825168								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 25/03/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (18/03/2019): Request to upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLA525E (6032499270SG)**
[SMF6999T]
TP
TSL BUILDERS PTE LTD
Mar 4 2019 12:00PM
[TANG LI KIANG]
Goh Lee Hwa Automobile Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio		View View in Browser
Assessment Reports		1 per page 1 <input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG) Accident Statement From: SC - Reg. No: SMF6999T, Claimant: TANG LI KIANG
1	18/03/19 11:00	<div style="display: flex; align-items: center;"> <div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div> <div>Load HTM</div> </div>
Photos/Images		3 per page 3 <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ) <div style="display: flex; align-items: center;"> <div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div> <div>Load JPG</div> </div>
1	26/04/19 14:25	Rear View Left
2	26/04/19 14:25	Rear View Right
3	26/04/19 14:26	General View
4	26/04/19 14:26	General View
5	26/04/19 14:26	General View
6	26/04/19 14:26	General View
7	26/04/19 14:26	General View
8	26/04/19 14:26	General View
9	26/04/19 14:26	General View
10	26/04/19 14:26	General View
11	26/04/19 14:26	General View
12	26/04/19 14:26	General View
13	26/04/19 14:26	General View
14	26/04/19 14:26	General View
15	26/04/19 14:26	General View
16	26/04/19 14:26	General View
17	26/04/19 14:26	General View
18	26/04/19 14:26	General View
19	26/04/19 14:26	General View
20	26/04/19 14:26	General View
21	26/04/19 14:26	General View
22	26/04/19 14:26	General View
23	26/04/19 14:26	General View
24	26/04/19 14:26	General View
25	26/04/19 14:26	General View
26	26/04/19 14:26	General View
27	26/04/19 14:26	General View
28	26/04/19 14:26	General View
29	26/04/19 14:26	General View
30	26/04/19 14:26	General View
31	26/04/19 14:26	General View
32	26/04/19 14:26	General View
33	26/04/19 14:27	Odometer Reading

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	26/04/19 14:27	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
35	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	26/04/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	26/04/19 14:28	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
64	26/04/19 14:28	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
65	26/04/19 14:28	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
66	26/04/19 14:28	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
67	26/04/19 14:28	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
68	26/04/19 14:28	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
69	26/04/19 14:28	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
70	26/04/19 14:28	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19004256/DSD3E2

Date: 29/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800095890
Claimant Vehicle No : SLA525E **Insured Vehicle No :** SMF6999T
 Date of Loss: 04/03/2019 Nature of Claim: TP Claim No: 6032499270SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLA525E**
 Make & Model: TOYOTA CAMRY, 2.5 (A) Engine No: 2ARU296599
 Reg. Date: 19/02/2016 (Man. Year: 2016) Chassis No: MR053AK5004010575
 Colour: Blue Odometer: 100935 km
 Engine Capacity: 2494 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,044.10	2,948.42	2,095.68	41.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,180.00	860.00	1,320.00	60.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,224.10	3,808.42	3,415.68	47.28
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	7,224.10	3,000.00	4,224.10	58.47

INSPECTION

Date of Assignment: 06/03/2019
 Date Inspected: 07/03/2019 Inspected At: Goh Lee Hwa Automobile Pte Ltd (HQ)
 Block 5033 Ang Mo Kio Industrial Park 2
 #01-255
 Singapore 569536
 Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LAMP RH	Cut / Cracked	432.50 F	*432.50 FL
2	1		*REAR TAIL LAMP RH	Mtg Cracked	562.30 F	*562.30 FL
3	1		*REAR BUMPER	Dented / Distorted	778.90 F	*778.90 FL
4	1		*REAR BUMPER REINFORCEMENT	Dented	425.30 F	*425.30 FL
5	1		*REAR BUMPER LAMP	Scratched	69.90 F	*69.90 FL
6	1		*REAR BUMPER SPONGE	Not Necessary	335.00 F	*- FL
7	1		*REAR BUMPER RETAINER	Broken	133.90 F	*133.90 FL
8	1		*REAR BUMPER LOWER LIP	Not Necessary	249.50 F	*- FL
9	1		*REAR BUMPER SENSOR	Damaged	545.00 FS	*220.00 FS
10	1		*REAR EXHAUST BOX	Bent / Dented	1,039.30 F	*1,039.30 FL
11	1		*REAR EXHAUST BOX CHROME PIPE	Bent	155.80 F	*155.80 FL
12	1		*LOGO	Serviceable	99.80 F	*- FL
13	1		*2.5 EMBLEM	Serviceable	62.30 F	*- FL
14	1		*CAMRY EMBLEM	Serviceable	89.60 F	*- FL
15	10		*BUMPER CLIPS	Necessary	65.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,044.10	3,847.90
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	899.48
Total Parts (\$\$)	5,044.10	2,948.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING & REMOVE & RENEW PARKING SENSOR & REFIT	New	200.00	60.00
2	TO KNOCKING, STRAIGHTENING REPAIR & RENEW ALL ACCIDENT DAMAGE AFFECTED AREA	New	800.00	400.00
3	TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED AREA. (PANEL COLOUR)	New	980.00	400.00
4	TO RUST PROOF ALL ACCIDENT AFFECTED AREA	New	200.00	0.00
Gross Labour Cost (\$\$)			2,180.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >