

ASS. REC. BY:

REF:

CS3/ASM19004270/EC042

Special Instruction:

SUVA/OY

ASSIGNMENT (Office)

From (Person):

of

ASM

Date/Time:

08/3/19

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

FBM 9207U

Insured:

SKM 77877

at Workshop m/s

ASIA MOTORSPORTS

Tel:

6745 3811

of

586 GEYLANG ROAD

Policy No:

Claim No:

S9MDIGCO

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

06/3/19

CA / REV / REP. / REV 24 HRS

PPS

Date/Time:

Person Contacted:

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	FBM 9207U x
	SKM 77877 x
	NO GIA.
	Dismantle: 27/3/2019



Steve

REF:

AXA

ASSIGNMENT

Form

Date 08/3/19

Veh No

FBM 9207U

Veh Regn

Estimated Cost

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

FBM 9207U

Make

Yamaha GOR 155

c.c

155

at Workshop n/s

ASIA MOTORSPORTS

Colour

Red

A/C

Insured / Std / NI / NA

of

568 GEYLANG ROAD SC389574)

Sp/Reading

16404

T/Radio: Insured / Std / NI / NA

Insured

Eng/No

Policy No.

C/No

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Mod: Nil / S/Rim / STD A/Rim or

67453871

Tyre Size

F:

50/60-14

R:

70/80-14

(Policy Condition)

		X	X
N/S	O/S		

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

~~MOTOROLLERS~~ IRC

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

7

mm

R/Bal.

7

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

6/3/19

D.O.I

8/3/19

Lump Sum:

%

3 Val: Yes or No

Survey held at

Asia Motorsports

2:41pm

CA / REV / REP. / 24 HRS

PRS

Des. of Damages: (Frt) / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Pending documents

Repair range 3K-4K, 3 days

27/3/2019

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair:

3

n)

☐

: Final Report

Resurvey No. of Trip:

1

Date/Time, File Return to?

Survey Fee:

100

n)

Transportation

1) Site Insp

2) Interview

3) Tech. Insp

4) Other

Report Format :

PRS

Lump Sum / L.B.E (€)

Add Fee:

☐

Site Insp (€)

☐

Interview (€)

☐

Tech. Insp (€)

☐

Weekend (€)

100
100



Service Request Details

Claim

S9M01GC0

Reference

None

Loss Date

6 March 2019

Report Date

8 Mar 2019 9:13:16 AM

Request Date

8 March 2019

Due Date

8 March 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

[Complete Work](#)[More ▾](#)

Vehicle Information

Incident Vehicle Registration #

FBM9207U

Make

TPVD YAMAHA

Model

GDR155A (AEROX)-155CC

As per MTO KSPART
- PRI

PO 3299
bryen
w/leg

GBD 3835T
veh. ✓
got estimate x

Primary Contact/Insured

SU ENG HOCK

BLK 288A JURONG EAST STREET 21, #04-358, 601288, Singapore

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

GIA NOT REPORTED

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

TYPE



SENT

8/3/19 12:36 PM

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT

VEHICLE IN -PRS ONLY

BODY



Catherine Chong (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Friday, 8 March, 2019 12:36 PM
To: assignments
Cc: Admin A
Subject: FW: NOTICE OF ACCIDENT: ACCIDENT INVOLVING FBM 9207 U & SKM 7787 T ON 6 MARCH 2019

****SMARTCLAIM NEW CASE****

SPOKEN WITH WKSP -VEH IN ***CAN SURVEY TODAY OR NEXT MON 11/03 (MONDAY OPERATING HOUR 10AM - 6.30PM)

PRS CASE*

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Asia Motorsports Solution Pte Ltd <asiamotorsports@hotmail.com>
Sent: Thursday, 7 March 2019 5:37 PM
To: customer.service@axa.com.sg; SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Subject: NOTICE OF ACCIDENT: ACCIDENT INVOLVING FBM 9207 U & SKM 7787 T ON 6 MARCH 2019

Your Ref:

Our Ref: FBM 9207 U

7 March 2019

AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01
AXA Tower
Singapore 068811

Attn: Claims Department

Dear Sir/Mdm,

**PROPERTY CLAIM
(WITHOUT PREJUDICE
TO: Any Personal Injury
Claims)**

Via Email

X EST (17)
Geylang
Steve

NOTICE OF ACCIDENT: ACCIDENT INVOLVING FBM 9207 U & SKM 7787 T ON 6 MARCH 2019

We are instructed to notify you of a road traffic accident on **6 March 2019** at about **1830H** at **Toh Guan Road East** involving our client's vehicle registration number **FBM 9207 U** and vehicle registration number **SKM 7787 T** driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice and your proposed list of 10 recommended motor surveyors for our appointment.

Kindly note that if we do not hear from you by **11 March 2019 (Monday), 1800H**, we will be forwarding **our proposed list of 10 motor surveyors** for your appointment, in accordance to the new regulations.

Thank you and we hope to hear from you soonest.

Regards,

Asia Motorsports

6745 3811

6746 5110 (fax)

asiamotorsports@hotmail.com

178 Paya Lebar Road #01-01/02 Singapore 409030

(.)



For Service Reservation, SMS to: 9383 5711


Products Maxi Scooter & Automatic (products.asp?cat=1)

AEROX 155

ONE STAGE AHEAD



(images_information/pgallery_139_331.jpg)



(images_information/pgallery_139_466.jpg) (images_information/pgallery_139_467.jpg) (images_information/pgallery_139_468.jpg) (images_information/pgallery_139_469.jpg)




(images_information/pgallery_139_470.jpg) (images_information/pgallery_139_471.jpg) (images_information/pgallery_139_472.jpg) (images_information/pgallery_139_473.jpg)



(images_information/pgallery_139_474.jpg) (images_information/pgallery_139_475.jpg)

Make :	Yamaha
Model :	Aerox 155
Displayment :	155.00 ccm
Fuel Tank :	4.60 litres
Oil Capacity :	1L

COLORS AVAILABLE



OVERVIEW

ONE STAGE AHEAD

Yamaha Aerox 155VVA, One Stage Ahead
Smart Key for Smart Choice.

Latest color is available for delivery.

The new generation 155cc engine equipped with "Variable Valve Actuation" (VVA) makes the engine pull performance more powerful. equipped with "Forged Piston & DiAsil Cylinder" is strong and lightweight so that maximum engine performance, and also equipped with "Smart Motor Generator" (SMG) which makes the motor sound smoother when turned on.

TECHNICAL SPECIFICATIONS

ENGINE

Engine Type :	Single cylinder, four-stroke
Displacement :	155.00 ccm
Max. Power :	11.0 kW / 8000 rpm
Max. Torque :	13.8 Nm / 6250 rpm
Compression Ratio :	10.5:1
Bore x Stroke :	58.0 x 58.7 mm
Ignition System :	TCI
Starter System :	Electric starter



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
AXA INSURANCE PTE LTD		Ref: CS3/ASM19004270/Ecd3e2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE		Date: 05-04-2019	
068811			
ATTN : PETER WANG		Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SKM 7787T	Veh. Inspected	FBM 9207U
Policy No.		Coverage (\$)	0.00
Claim No.	S9M01GC0	Excess (\$)	0.00
Assign From	PETER WANG	Assign Date	08/03/2019
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA GDR 155	c.c	155
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	RED
Odometer	16404 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	50/60-14	IRC	7 mm
L/H Front Tyre			mm
R/H Rear Tyre	70/80-14	IRC	7 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.			
5. General Information			
Accident Date	06/03/2019	Inspect Date / Time	08/03/2019 (02:41 PM)
Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 568 GEYLANG ROAD SINGAPORE 389514		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	

Report Ref No. CS3/ASM19004270/Ecd3e2

Inspected By



CHEN TSUE YEE

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.