

15/5/2010

INS. CASE OWNER:

peter

CC 4 ASM
AXA1900 4274, Up6b

LKK:

IDAC:

Surveyor:

Mortins

DOI:

ASSIGNMENT

U/n/uh.

Date / Time :

8/7/19.

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

FBL 6467K

Name of Insured

Muhammad ARIW BIN AMIS

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

8/7/19

Is driver the owner?

(YES / NO)

Nature of Accident :

Claim No.:

SQM01GDA/102986

Policy No.:

D291260

Make / Model :

HONDA

Place of Accident :

TE

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No

SKE 1A13C

INSRS:
WSP:
Tel:
Liability:
RMKS:RICO
60INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

8/8/19-4

FBL 6467K-4

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE:

After call ltr to OI:

9/4/19-5L

OK 14/4/19
an

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with Yvonne Teoh

Email

Cal

Final Liability:

SS

(Agreed / Assessed)

BOLA S/N No. : 27

If NO or B 28, Ass. Lia :

Repair Cost:

SS

1337.50

Loss of Rental (LOR):

SS

400

(

4

days) x \$100

Loss of Use (LOU):

SS

-

(\$

x

days)

Loss of Income (LOI):

SS

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

36.45

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$350

Total:

SS

1773.95

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Cal

Payee 1:

SS

1773.95

Name 1:

RICO 60 Auto Services Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

WH 14/4/19

(G8/11/13) wef

ASS. REC. BY: Marcus

REF:

AXA

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKE1913C
R. 10 60

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

206.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKE1913C

Yr Regn:

12 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Honda civic

C.C.

1799

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

205021

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMFD163095203181

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

7/3/19

D.O.I.

11/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27A14830

12/3/19 4/5 \$ 1250 confirmed with John.
4/5 \$ 1250 (Red \$ 10420.64 / 89%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. \$ SI

) Photos

) Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

)

x

3/8/2019

Claim Portal

LKK AUTO CONSULTANTS PTE LTD (TP)

More

Kito 60 - veh in.

Service Request Details

Claim

S9M01GDA

Reference

None

Loss Date

7 March 2019

Report Date

8 Mar 2019 1:08:09 PM

Request Date

8 March 2019

Due Date

8 March 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Complete Work

More

Vehicle Information

Incident Vehicle Registration #

SKE1913C

Make

TPVD

Model

Service Address

Primary Contact/Insured

ANIS MUHAMMAD AKID BIN
720 WOODLANDS AVENUE 6, #06-616, 730720, Singapore

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions
NON-REPORTED

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

TYPE



SENT

8/3/19 1:53 PM

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT

VEHICLE IN

BODY



Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupe@lkkauto.com>
Sent: Friday, 8 March 2019 1:54 PM
To: assignments
Cc: Admin A
Subject: FW: PRI Arrangement for SKE 1913 C
Attachments: PRI Arrangement.pdf

SMARTCLAIM NEW CASE

SPOKEN WITH SHANELLE-VEH IN ***CAN SURVEY TODAY*KINDLY ARRANGE SURVEYOR

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Enquiry <claims@rico60.com>
Sent: Friday, 8 March 2019 11:12 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>; SG AXA Insurance SM Claims Service Team <cst@axa.com.sg>
Subject: PRI Arrangement for SKE 1913 C

Dear All,

Kindly arrange PRI to survey the said vehicle as follows:

Our Client – SKE 1913 C
Your Insured – FBL 6467 K
DOA – 07/03/2019

Thank you.

Best Regards,
Shanelle Lim



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Mobile: +65 9187 8064 | Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: claims@rico60.com



<MANDATE IA> - S9M01GDA [ACCIDENT INVOLVING FBL 6467K(OI) & SKE 1913C(TP) ON 07/03/2019]

Type

🔗 Question

Message

Liability: 100%. Insured rear-ended third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$1873.95. Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Jia Le - 12 April 2019

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 12/03/2019

Survey Details:

Date of loss	7-Mar-19
Date of appointment	8-Mar-19
Date of survey	11-Mar-19
Location of survey	RICO 60 AUTO SERVICES PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SKE 1913C
Make and Model	HONDA CIVIC 1.8L
Date of registration	19/12/2009
Excess	
Market Value	\$20,000
Part Rebate	\$14,830
Nett Loss	\$5,170

Repair details:

Initial Estimate	\$ 11,670.64
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 509.25	(LESS 50%)
Check items (estimate)	\$ -	
Labour	\$ 770.00	
Total	\$ 1,279.25	
Lump Sum(if applicable)	\$ 1,250.00	

Number of days for repair	3
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Recommend repair days - 3days + 2PRS = 5days

Mandate:

Liability(TP)		100%	
Proposed repair cost	\$	1,337.50	
Loss of use		NIL	
Loss of rental	\$	500.00	(\$100 x 5days)
Loss of income		NIL	
LTA search fees	\$	7.45	
GIA reports	\$	29.00	
Proposed Total	\$	1,873.95	



Pls proceed DS with quantum as proposed

Type

🔗 Question

Message

LOR is subject to rental receipt.

Reply

Hsiao Tong (LKKAuto)

From: Enquiry <claims@rico60.com>
Sent: Friday, 15 March 2019 5:33 PM
To: Hsiao Tong (LKKAuto)
Subject: LOD for SKE 1913 C
Attachments: Letter Of Demand (PDF).pdf

Dear Hsiao Tong,

Attached file as per your pursuant.
Kindly release DV/cheque.

Thank you.

Best Regards,
Shanelle Lim



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Mobile: +65 9187 8064 | Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: enquiry@rico60.com

Jia Le (LKK Auto)

From: Rico 60 <claims@rico60.com>
Sent: Thursday, 18 April 2019 10:43 AM
To: Jia Le (LKK Auto)
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: RE: DV for SKE 1913 C (Our Ref : S9M01GDA) (DOA: 07/03/2019)
Attachments: Discharge Voucher.pdf

Dear Jia Le,

Attached file as per your pursuant.

Kindly release cheque.

Thank you.

Best Regards,
Yvonne Teoh



RICO 60 AUTO SERVICES PTE. LTD.
Co. & GST Reg. No.: 201807623M
8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit
#02-24, Singapore 415875
Tel: +65 6286 6060 | Fax: +65 6286 7060
Email: claims@rico60.com

From: Jia Le (LKK Auto)
Sent: Wednesday, 17 April 2019 11:22 AM
To: Rico 60
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: RE: LOD for SKE 1913 C

Without Prejudice

Dear Sirs/Mdm,

Thank you for your acceptance.

Please duly sign the DV enclosed and return to us (LKK) for our necessary action.

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Rico 60 [mailto:claims@rico60.com]

Sent: Tuesday, 16 April 2019 10:25 AM

To: Jia Le (LKK Auto)

Cc: Hsiao Tong (LKKAuto)

Subject: RE: LOD for SKE 1913 C

Dear Jia Le,

Offer accepted.

Please release DV/Cheque.

Thank you.

Best Regards,

John Ong



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Mobile: +65 8811 2101 | Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: claims@rico60.com

From: Jia Le (LKK Auto)

Sent: Tuesday, 16 April 2019 10:18 AM

To: claims@rico60.com

Cc: Hsiao Tong (LKKAuto)

Subject: RE: LOD for SKE 1913 C

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 1,337.50
---------------------------	-------------

2. Loss of Rental (4days x \$100.00)	\$ 400.00
3. LTA/GIA Search Fee	\$ 36.45
TOTAL	\$ 1,773.95

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Enquiry <claims@rico60.com>

Sent: Friday, 15 March 2019 5:33 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: LOD for SKE 1913 C

Dear Hsiao Tong,

Attached file as per your pursuant.
Kindly release DV/cheque.

Thank you.

Best Regards,
Shanelle Lim



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Mobile: +65 9187 8064 | Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: enquiry@rico60.com

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	FBL 6467K (Insd veh)	Model:	HONDA CIVIC (A)
	SKE 1913C (TP veh)		
Date of Accident:	07/03/2019		

Global Sum Settlement	:	☐ Yes	☒ No	
Repair Estimate	:	\$		12,614.79
Final Repair Cost	:	\$		1,337.50
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		400.00 4 days
LTA / GIA Search Fee	:	\$		36.45

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	1,773.95

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:	Agreed Liability	_____100_____	(%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____	(%)	Assessed Liability (*): _____	(%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____ _____			

Payment Instruction: Payee's Breakdown			
1)	RICO 60 AUTO SERVICES PTE. LTD.	:	\$ 1,773.95

NUR SHAQILAH BTE ABDOL
WAHAB

26/04/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM19004274/Upb3s2		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811 ATTN: PETER WANG		Date : 26-04-2019		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBL 6467K	Veh. Inspected	SKE 1913C	
Policy No.	P2190260	Coverage (\$)	0.00	
Claim No.	S9M01GDA	Excess (\$)	0.00	
Assign From	PETER WANG	Assign Date	08/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC (A)	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JHMF16309S203181	Colour	BLACK	
Odometer	205021	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45R17	DUNLOP	6 mm	
L/H Front Tyre	225/45R17	DUNLOP	6 mm	
R/H Rear Tyre	225/45R17	DUNLOP	6 mm	
L/H Rear Tyre	225/45R17	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/03/2019	Inspection Date	11/03/2019	
Survey held at	RICO 60 AUTO SERVICES PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKE 1913C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NOT NECESSARY	148.60	-
1	REAR BOOTLID (CONSISTENT)	NOT NECESSARY	910.50	-
1	REAR BOOTLID LOGO (CONSISTENT)	NOT NECESSARY	60.70	-
2	REAR BOOTLID LAMP LH+RH (CONSISTENT)	NOT NECESSARY	320.70	-
1	REAR BOOTLID OPENER SWITCH (CONSISTENT)	NOT NECESSARY	113.40	-
1	REAR BOOTLID WEATHERSTRIP (CONSISTENT)	NOT NECESSARY	189.70	-
1	REAR BOOTLID INNER TRIM (CONSISTENT)	NOT NECESSARY	227.30	-
1	TAILLAMP RH (CONSISTENT)	SCRATCHED	709.20	280.40
1	TAILLAMP CLIP RH (CONSISTENT)	NOT NECESSARY	18.00	-
1	TAILLAMP PANEL RH (CONSISTENT)	TO REPAIR SEE LABOUR	384.00	-
1	REAR BUMPER (CONSISTENT)	DEFORMED / WARPED	857.70	638.00
1	REAR BUMPER BRACKET RH (CONSISTENT)	NOT NECESSARY	45.80	-
1	REAR BUMPER SIDE RETAINER RH (CONSISTENT)	BENT	63.50	20.10
1	REAR FENDER RH (CONSISTENT)	TO REPAIR SEE LABOUR	1,167.40	-
1	REAR FENDER INNER TRIM RH (CONSISTENT)	NOT NECESSARY	753.00	-
1	REAR FENDER COWLING RH (CONSISTENT)	NOT NECESSARY	98.30	-
1	END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	689.00	-
1	END PANEL TOP GARNISH (CONSISTENT)	NOT NECESSARY	262.60	-
1	SPARE WHEEL PANEL (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	SPARE WHEEL PANEL TOP BOARD (CONSISTENT)	NOT NECESSARY	192.50	-
	LESS 20% DISCOUNT		-1,442.38	-
	LESS 50% DISCOUNT		-	-469.25
			5,769.52	469.25
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
2	REVERSE SENSOR (SN) (CONSISTENT)	NOT NECESSARY	300.00	-
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
10	REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	100.00	40.00

Report Ref No. CC4/ASM19004274/Upb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
10	BOOTLID INNER TRIM CLIPS (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
10	REAR FENDER INNER TRIM CLIPS (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
10	REAR FENDER COWLING CLIPS (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
			900.00	40.00
	LABOUR			
	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK & REALIGN. INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL RH, REAR FENDER RH AND END PANEL.		2,500.00	300.00
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.		1,200.00	400.00
	TO RUST PROOF ACCIDENT AFFECTED AREA.	NOT NECESSARY	120.00	-
	TO RNR REAR WINDSCREEN.	NOT NECESSARY	300.00	-
	TO RNR REAR BOOT MECHANISM.	NOT NECESSARY	120.00	-
	TO RNR REAR LUGGAGE COMPARTMENT.	NOT NECESSARY	400.00	-
	TO RNR REVERSE SENSOR & CHECK FUNCTION.		120.00	50.00
	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION. }		120.00	20.00
	TO CHECK WIRING LAYOUT AND TAILGATE LAMP FUNCTION. }		120.00	-
	TO DO WATER LEAK TEST.	NOT NECESSARY	120.00	-
			5,120.00	770.00
GRAND TOTAL			11,789.52	1,279.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,250.00

Report Ref No. CC4/ASM19004274/Upb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.