




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19004277/Ahb3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: STACEY NG			Date : 11-06-2019	
			Code : ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	PH 5115M	Veh. Inspected	SLR 5097B	
Policy No.	CN026097	Coverage (\$)	0.00	
Claim No.	S9M01MCV	Excess (\$)	0.00	
Assign From	STACEY NG	Assign Date	08/03/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU11115603	Colour	WHITE	
Odometer	32916	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60R16	DUNLOP	6 mm	
L/H Front Tyre	215/60R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60R16	DUNLOP	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	07/03/2019	Inspection Date	08/03/2019	
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>6 Working Days</b>		