AIG

Taufikh | REF

SMJ2599 4 — 2019 Feb.

Veh No

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Make: Hyundai Avante — cc 1591

Colour: Grey — A/C Insured / Std / Nil / NA

Sp.Reading: 444 — T/Radio Insured / Std / Nil / NA

Eng No:

C/No: KMHD841CMKU865544

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Kumho.

Front			Rear		
R/Bal.	6	mm	R/Bal.	6	mm
L/Bal.	6	mm	L/Bal.	6	mm

D.O.A. — D.O.I. 14/3/19 @ 3pm

Survey held at: ~~PAH~~ Mova BM.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collison

(Client's Record)

Make of Veh

(Policy Condition)

X	
N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value

IDAC Accident Report — Consistent? : Yes or No

GIA / PR Seen — Consistent? : Yes or No

Est. Repairs — days — Res.: Yes or No

Lum Sum — % — 3 Val.: Yes or No

GA / REV / RLP / 24 HRS

Vehicle IN / OUT

Date — Person Contacted: Jufrian

Date / Time — Action / Instruction

Date/time File Pass to:

☐ : Preli. Report

☐ : Final Report

Date/time File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Photos

Other

Total

Add Fee: ☐ Site Insp S$

☐ Interview S$

☐ Tech Rev S$

☐ Weekend S$

Report Format

Lump Sum / EB E G