

ASS: REC BY

REF: CS3/SM017020609/Evd3+

Special Instructions

Surveyor

Wilson

ASSIGNMENT (Office)

From (Person)

Irene Henny

of

SMO

Date/Time

8/3/19

Estimated Cost

Bill to

OD-TP/WS/TP RES / OD RES / EVA / DV / MV / CS

To Inspect Vehicle No:

YM 8287Y

Insured:

PC6250A

at Workshop n/s

Twin Car Automotive

Tel:

68420051

of 2 Kaki Bkt Ave 2 #01-17, 417921

Policy No:

Claim No:

CM7D1703793 / AGC

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/10/2017

CA / REV / REP. / REV 24 HRS

'wp'

R.O.D. Endorsement

Date/Time

27/10/17 @ 246pm

Person Contacted

Melody

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

YM 8287Y - NA / INCL 7020549 / KA - D.O.A : 26/10/2017

PC 6250A - NA / INCL 7020549 / KA - D.O.A : 26/10/2017

Dismantle Part: 09.11.2017

25/11/17 5.12pm Email to Irene

Note:

check mv

- 85k (EST)

LTA: \$17,065

NV:

67,935

RECEIVED 15 MAR 2019

Steve,

Pls check repair limit.

450.160=

14/3/19 Submit LS \$17,850 (Red 15,250, 46%), 15 days

14/3

Catherine Chong (LKK Auto)

From: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>
Sent: Friday, 8 March, 2019 10:36 AM
To: 'sur@lkkauto.com'; 'assignments' (assignments@lkkauto.com)
Subject: ACC INL PC6250A/ IV / YM8287Y/ SLP3706B ON 26.10.2017; OUR REF: CMTD1703793; YOUR REF: CS3-SMO17020609/Wbe2
Attachments: survey report.pdf; SAS2299463.pdf; SAS2298963.pdf; SAS2299508.pdf; photo 1.pdf; photo 2.pdf; photo 3.pdf

Dear LKK

We refer to the above matter.

We herewith enclosed GIA reports, the repair bill, the photographs and the survey report for your attention.

Please prepare the paper resurvey of YM8287Y.

Please forward the report with the market value status within 5 days.

Thank you.

Best Regards

Agnes Chan

Claims Divison

D: 6329 5327 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Paper Survey

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



Download on the
App Store

or



GET IT ON
Google Play

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5723C
Vehicle Details	
Vehicle No.:	YM8287Y
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Mar 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	FM65FM1RDEA
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	6M60123861
Chassis No.:	FM65FMB00010
Maximum Power Output:	-
Open Market Value:	\$53,707.00
Original Registration Date:	18 Feb 2008
First Registration Date:	18 Feb 2008
Transfer Count:	2
Actual ARF Paid:	\$2,686.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Nov 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$22,958.00
COE Rebate Amount:	\$17,065.00
Total Rebate Amount:	\$17,065.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 12 Mar 2019

OK

Sign up for EZ-Pay
with DBS/POSB bank cards!

Preferred payment partner



Mitsubishi fm65 Price Range Depreciation Year Reg Vehicle Type

[Advanced Search](#)
[Home](#) » [Used Cars](#) » [ABWIN \(1994\) Pte Ltd](#) » Mitsubishi Fuso Fighter FM65

Mitsubishi Fuso Fighter FM65

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)
ABWIN

YOUR FIRST CHOICE AUTOMOTIVE SERVICE PROVIDER



Price	\$43,800	Lifespan	27-Dec-2030
Depreciation ⓘ	\$24,370 /yr <small>View models with similar depre</small>	Reg Date	28-Dec-2010 <small>(1yr 9mths 15days COE left)</small>
Mileage	N.A.	Manufactured ⓘ	2010
Road Tax ⓘ	N.A.	Transmission	Manual
Dereg Value ⓘ	\$5,751 as of today (change)	OMV ⓘ	\$69,638
COE ⓘ	\$32,001	ARF ⓘ	\$3,482
Engine Cap	7,545 cc	No. of Owners ⓘ	2
Curb Weight ⓘ	6,980 kg		
Type of Vehicle	Truck		

Category

-

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started

Posted on: 31-Jan-2019 | Last Updated on: 31-Jan-2019

Upfront Payment

[more Financial info](#)

Transfer Fee ⓘ	\$25	
Down Payment ⓘ	\$4,380 (change)	Maximum 90% Loan
1st Instalment ⓘ	\$1,989	Based on 3.4% interest rate
Total Upfront Payment ⓘ	\$6,394 <small>(Without Insurance)</small>	Check with seller for exact figure

Tags: Mitsubishi Fuso, mitsubishi fuso, 2010 Mitsubishi Fuso, 2010 mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi



[Shortlist](#) [Compare](#) [Add note](#)
[Report Error](#) [More Actions](#)

Seller Information

Company	ABWIN (1994) Pte Ltd • dealer's pricelist • 153 vehs sold 168 vehs available	
Address	20 Kaki Bukit Road 2 Search cars nearby this location	
Office No	68416666	
Contact Person(s)	Ban Yip 92795559 Joey 85186788 Tony 90065775	

ABWIN
ONE-STOP
 AUTOMOTIVE SOLUTIONS


Recommended for you

1-6 of 18

[Compare](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	26/10/2017 16:57
Date Of Accident	26/10/2017 09:30
Exact Location Of Accident	W'LANDS AVE3 TWDS W'LANDS SQUARE B4MARSILINGMRTSTN
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	YM8287Y
Insured/Policyholder	
Name Of Registered Owner	HUK SENG TRANSPORT PTE LTD
Co Reg No	200605732C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98506121
Alternative Phone No	OFFICE-63245412
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	FUSO
Exact Purpose for which vehicle was being used at time of accident	WORK USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5052291018-05
Cover Note Number	
Driver	
Name of Driver	SIM LEE MENG
NRIC No	S1069941Z
Date Of Birth	20/10/1951
Occupation	OUTDOOR
Date Of Driving Pass	29/09/1969
Driving Experience	48 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98506121
Fax Number	
Contact Number	OTHERS-98506121
EMail Address	NOEMAIL

Address	BLK 516 HOUGANG AVE 10 #12-209
Postcode	530516
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC6250A
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLP3706B
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (POPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN Woodlands Ave 3 Toward Woodlands Square Before Marsiling MRT Station.



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the above date and time, I was driving along Woodlands Ave 3 toward Woodlands Square on the 2 line of a 3 lanes road. Some where before Marsiling MRT station, vehicle C (SLP 3706B) ahead of me slowed down and stopped due to the red light. As such I applied brake and stopped completely behind vehicle C (SLP 3706B). Out of the sudden, vehicle B (PC 6250A) came from the rear and collided directly onto the rear portion of my vehicle. Upon the impact, my vehicle surged forward and collided onto the rear portion of vehicle C (SLP 3706B). After the accident, I alighted and realised that I was involved in a chain accident of 3 vehicle.

A - YM 8287Y, B - PC 6250A, SLP 3706B

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.

Sketch Plan #3

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1069941Z



Name

SIM LEE MENG

Race

CHINESE

Date of Birth

20-10-1951

Sex

M

Country of Birth
SINGAPORE

S1069941Z

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S1069941Z

Name

SIM LEE MENG

Birth Date: 20 Oct 1951

Issue Date: 14 Aug 2003




900743475F



4881641

NRIC No. S1069941Z



Date of Issue

08-09-2012

Address

APT BLK 516 HOUGANG AVENUE 10
#12-209
SINGAPORE 530516

ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class 2 Motor cars up to 3500 kg with up to 7 passengers, exclusive of the driver, and motor tractors/vehicles up to 2200 kg
Class 4 Heavy motor cars and motor tractors up to 3500 kg

20 Sep 1969

02 Jan 2004

S / No. 9000031857

Signature

NP 425A



Licence No. S1069941Z

Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	27/10/2017 16:12
Date Of Accident	26/10/2017 09:30
Exact Location Of Accident	ALONG WOODLANDS AVE 3 TOWARDS WOODLANDS AVE 5
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	PC6250A
Insured/Policyholder	
Name Of Registered Owner	A.Z BUS PTE LTD
Co Reg No	200304649K
Email Address	HILMI@AZBUS.COM.SG
Mobile Phone No	(LOCAL) +65-97480340
Alternative Phone No	OFFICE-97480340
Vehicle Particulars	
Manufacturer	HIGER
Model	KLQ6118K AUTO
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTSCBU000255
Cover Note Number	
Driver	
Name of Driver	LIU ZHIGUO
NRIC No	G6417176W
Date Of Birth	16/06/1977
Occupation	OUTDOOR
Date Of Driving Pass	17/06/2010
Driving Experience	7 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97480340
Fax Number	
Contact Number	
Email Address	HILMI@AZBUS.COM.SG

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON THE DATE AND TIME MENTIONED, I WAS DRIVING ALONG THE SAID MENTIONED ROAD, WHEN MY HAND PHONE EARPIECE FELL OFF. WHEN I ATTEMPTED TO PICK IT UP, MY VEHICLE SURGED FORWARD AND HIT THE REAR OF VEHICLE B. NOBODY WAS INJURED. STATEMENT WAS READ TO MY SUPERVISOR AND TRANSLATED TO ME IN MANDARIN AND I ACKNOWLEDGED IT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YM8287Y
 Vehicle Make/Model/Colour MITSUBISHI/FUSO/RED
 Details Of Properties
 Name of Driver SIM LEE MENG
 NRIC/Passport Number S1069941Z
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver) 1

Details of Witness

Name
 Phone Number
 Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer collectively the "Personal Information" and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police, for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 collectively the "Purposes";
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS
REPORTING OFFICER
HASHIM BIN KAMARI

Policyholder's Signature / Date & Time

Driver's Signature / If driver is not the policyholder / Date & Time

Witnessed by Reporting Centre
Personal: 27/10/17

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

ON THE DATE AND TIME MENTIONED, I WAS DRIVING ALONG THE SAID MENTIONED ROAD, WHEN MY HANDPHONE EARPIECE FELL OFF. WHEN I ATTEMPTED TO PICK IT UP, MY VEHICLE SURGED FORWARD AND HIT THE REAR OF VEHICLE B.

NOBODY WAS INJURED. STATEMENT WAS READ TO MY SUPERVISOR AND TRANSLATED TO ME IN MANDRIN AND I ACKNOWLEDGED IT.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
HASHIM BIN KAMARI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

27 October 2017 at 11:38 AM

Date/Time:

27 October 2017 at 11:39 AM

Accident Photo



TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

HUK SENG TRANSPORT PTE LTD
1 WHOLESALE CENTRE #02-18
SINGAPORE 110001

Contact : 63245214 98506121

TAX INVOICE

Date : 25/10/2018

Date in : 26/10/2017

Vehicle Num. : YM8287Y

Make/Model : MITSUBISHI FM65FM1RDEA-2008

Chassis/Eng# : FM65FMB00010/6M60123861

Accident Date : 26/10/2017

Claim No : CLM13894

Reference : OCT-32/2017

Policy No. : 5052291018-05 (17/02/2018)

LUMP SUM REPAIR BILL
AS PER SURVEYOR REPORT
REF : CLM13894TP/T DATED 22/10/2018
BY CARLINK CONSULTANCY

Amount S\$

33,100.00

E. & O.E.	Sub S\$:	33,100.00
Add GST (7%) S\$:		2,317.00
Total Amount S\$:		35,417.00



for TWINCAR AUTOMOTIVE PTE LTD

CARLINK CONSULTANCY

60 Hillside Drive, Singapore 549009
Fax: 62874788 Tel: 62856178

INVOICE

M/S Huk Seng Transport Pte Ltd
C/o Kaki Bukit Autohub
2 Kaki Bukit Avenue 2, #01-17
Singapore 417921

Invoice No: CLM13894TP/T
Date: 22nd October 2018

S/N	DESCRIPTION	QTY	UNIT PRICE (\$)	AMOUNT (\$)
1	<u>Vehicle No: YM 8287 Y</u> Charges for accident vehicle inspection and appraisal report, transportation, photographs & misc*** (photographs - 257 copies)			\$1,657.00
			Total:	\$1,657.00

We thank you for the opportunity to serve you and assure you of our best at all times


PATRICK NG
Automotive Engineer Assessor
MIMI, MIRTE, LCGI, I ENG, LAE, CGLI ETC.

Note: Payment by cheque should be crossed and made payable to "CARLINK CONSULTANCY"

CARLINK CONSULTANCY


60 Hillside Drive
Singapore 549009

Tel : 62856178

Fax : 62874788

ACCIDENT VEHICLE INSPECTION / ASSESSMENT REPORT

Our Ref: CLM13894TP/T

1 REFERENCE			
Date of request	:	6th November 2017	
Requested by	:	M/S Huk Seng Transport Pte Ltd C/o Kaki Bukit Autohub, 2 Kaki Bukit Avenue 2, #01-17 Singapore 417921	
Type of claim	:	Third party	
Workshop	:	M/S Twincar Automotive Pte Ltd Kaki Bukit Autohub, 2 Kaki Bukit Avenue 2, #01-17 Singapore 417921	
Date of survey	:	6th November 2017	
Accident date	:	26th October 2017	
2 DETAILS OF VEHICLE			
Registration No.	:	YM 8287 Y	
Make & Model	:	Mitsubishi FM65FM1RDEA	
Engine No.	:	6M60123861	
Chassis No.	:	FM65FMB00010	
Year of Registration	:	18th February 2008	
Speedometer reading	:	358011 Km	
Transmission	:	Manual	
Colour	:	Red	
3 STATIC CHECK			
Steering	:	see annex(es)	Paintwork : Good
Footbrake	:	see annex(es)	Modification : Nil
Handbrake	:	see annex(es)	General condition : Good
4 TYRE CONDITION			
		<u>Nearside/Make</u>	<u>Offside/Make</u> <u>Size</u>
Front tyre	:	7mm/LLAOS	7mm/LLAOS : 22.5-R16
Rear tyre	:	7mm/LLAOS	7mm/LLAOS : 22.5-R16
5 POINT OF IMPACT			
See Annex(es) and Motor Accident Reports			
6 REMARK			
This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not authorised any repair.			

Report No.

CLM13894TP/T

Vehicle No. YM8287Y

Parts and Labour Assessment**PARTS**

Description of part	Repairer's Qty	Qty	Condition	Repairer's estimate	Our adjustment
FRONT BUMPER ASSY	1	1	DENTED/BENT	1,020.90	1,020.90 ✓ 00
FRONT BUMPER BRACKET	2	2	BENT	374.10	374.10 ✓ R
FRONT BUMPER HEADLAMP GARNISH LH	1	0	SERVICEABLE	341.80	0.00 X
FRONT BUMPER HEADLAMP GARNISH RH	1	1	DENTED/BENT/CUT	341.80	341.80 X R
FRONT BUMPER HEADLAMP LH	1	0	SERVICEABLE	1,003.00	0.00 X
FRONT BUMPER HEADLAMP RH	1	1	GRAZED/CRACKED	1,003.00	1,003.00 ✓ CUT
FRONT CORNER PANEL RH	1	1	GRAZED/DEFORMED	1,013.40	1,013.40 X R
FRONT GRILLE ASSY	1	1	DISTORTED/CUT	1,108.90	1,108.90 X R
FRONT GRILLE BADGE	1	1	NECESSARY	62.50	62.50 X NN
FRONT GRILLE FIGHTER EMBLEM	1	1	NECESSARY	82.50	82.50 X NN
FRONT SIDE LAMP RH	1	1	GRAZED/CRACKED	445.06	445.06 X NN
Subtotal before discount				S\$ 6,796.96	S\$ 5,452.16
Percentage discount 25% and 25%				S\$ 1,699.24	S\$ 1,363.04
Sub-total				S\$ 5,097.72	S\$ 4,089.12
40 PAX STICKER	1	1	NECESSARY	10.00	10.00 ✓ NEC
60 KM/H STICKER	1	1	NECESSARY	10.00	10.00 ✓ NEC
FRONT NUMBER PLATE	1	1	DENTED/BENT	30.00	30.00 X NN
HYDRAULIC CYLINDER JACK (INNER) LH	1	1	DISTORTED/LEAKED	1,600.00	1,600.00 ✓ BT
HYDRAULIC CYLINDER JACK (INNER) RH	1	1	DISTORTED/LEAKED	1,600.00	1,600.00 ✓ BT
HYDRAULIC CYLINDER JACK (OUTER) LH	1	1	DISTORTED/LEAKED	1,800.00	1,800.00 ✓ BT
HYDRAULIC CYLINDER JACK (OUTER) RH	1	1	DISTORTED/LEAKED	1,800.00	1,800.00 ✓ BT
HYDRAULIC CYLINDER JACK DUST COVER (INNER) LH	1	1	GRAZED/CUT	250.00	250.00 ✓ NEC
HYDRAULIC CYLINDER JACK DUST COVER (INNER) RH	1	1	GRAZED/CUT	250.00	250.00 ✓ NEC
HYDRAULIC CYLINDER JACK DUST COVER (OUTER) LH	1	1	GRAZED/CUT	250.00	250.00 ✓ NEC
HYDRAULIC CYLINDER JACK DUST COVER (OUTER) RH	1	1	GRAZED/CUT	250.00	250.00 ✓ NEC
HYDRAULIC CYLINDER JACK HOSE	2	2	LEAKED	600.00	600.00 X NN
HYDRAULIC CYLINDER JACK LOCK PIN	8	8	NECESSARY	40.00	40.00 ✓ NEC
HYDRAULIC CYLINDER JACK PRIVOT PIN (LONG)	2	2	BENT/JAMMED	300.00	300.00 ✓ NEC

2023.90
-25%
1517.92

HYDRAULIC CYLINDER JACK PRIVOT PIN (SHORT)	6	6	BENT/JAMMED	600.00	600.00	/ BT
HYDRAULIC CYLINDER JACK TEFLON WHEEL	2	2	CUT	240.00	240.00	/ BT
REAR BUMPER ASSY (COMPLETE)	1	1	DENTED/BENT	1,800.00	1,800.00	X NAI
REAR LIFT PLATFORM SUPPORT LINKAGE ASSY	1	1	DENTED/DISTORTED	4,800.00	4,800.00	X NAI
REAR NUMBER PLATE	1	1	DENTED/BENT	30.00	30.00	/ NLC
REAR NUMBER PLATE LAMP	1	1	GRAZED/CRACKED	69.00	69.00	/ NLC
TAILGATE "MAX 1500KG" STICKER	1	1	NECESSARY	15.00	15.00	/ NLC
TAILGATE "PALFINGER" STICKER	1	1	NECESSARY	120.00	120.00	/ NLC
TAILGATE 'WARNING' STICKER	1	1	NECESSARY	15.00	15.00	/ NLC
TAILGATE LIFT PLATFORM	1	1	DENTED/CUT/DISTORTED	12,500.00	12,500.00	/ BT 8,000
TAILGATE RED/WHITE CAUTION STICKER LH	1	1	NECESSARY	80.00	80.00	/ NLC
TAILGATE RED/WHITE CAUTION STICKER RH	1	1	NECESSARY	80.00	80.00	/ NLC
TAILGATE REFLECTOR LH	2	2	NECESSARY	24.00	24.00	/ NLC
TAIL LAMP BRACKET LH	1	1	BENT	110.00	110.00	X NAI
TAIL LAMP BRACKET RH	1	1	BENT	110.00	110.00	X NAI
TAIL LAMP LH	1	1	GRAZED/CRACKED	230.00	230.00	/ CUT
TAIL LAMP RH	1	1	GRAZED/CRACKED	230.00	230.00	/ BT
Subtotal before discount				S\$ 29,843.00	S\$ 29,843.00	
Sub-total				S\$ 29,843.00	S\$ 29,843.00	17881
Parts-total				S\$ 34,940.72	S\$ 33,932.12	

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	200.00	150.00	/ 50
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	2,800.00	2,000.00	800
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	3,000.00	2,800.00	2000
To apply anti-rust chemical on repaired and replaced panel.	200.00	100.00	50
Labour Total	S\$ 6,200.00	S\$ 5,050.00	
Parts & Labour Total	S\$ 41,140.72	S\$ 38,982.12	2920

Results of inspection of the accident vehicle are as shown above,

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 33,100.00 and the recommended number of working days for the repairs is within 30 day(s).


PATRICK A. SURVEVOR
Automotive Appraiser

18,698.92
22,298.92
L/S - 17,839.13
= 17,850
15 days




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref : CS3/SMO17020609/Evd3e2-1	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623			Date : 15-03-2019	
				
			Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 6250A	Veh. Inspected	YM 8287Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1703793/AGC	Excess (\$)	0.00	
Assign From	AGNES CHAN	Assign Date	08/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI FM65FM1RDEA	c.c	7545	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	FM65FMB00010	Colour	RED	
Odometer	358011	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	11 R22.5	LEAD	5 mm	
L/H Front Tyre	11 R22.5	LEAD	5 mm	
R/H Rear Tyre	11 R22.5	BRIDGESTONE	4 mm	
L/H Rear Tyre	11 R22.5	BRIDGESTONE	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/10/2017	Inspection Date	06/11/2017	
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			15 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YM 8287Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER ASSY	DENTED	1,020.90	1,020.90
2	FRONT BUMPER BRACKET	TO REPAIR SEE LABOUR	374.10	-
1	FRONT BUMPER HEADLAMP GARNISH LH	SERVICEABLE	341.80	-
1	FRONT BUMPER HEADLAMP GARNISH RH	TO REPAIR SEE LABOUR	341.80	-
1	FRONT BUMPER HEADLAMP LH	SERVICEABLE	1,003.00	-
1	FRONT BUMPER HEADLAMP RH	SERVICEABLE	1,003.00	1,003.00
1	FRONT CORNER PANEL RH	TO REPAIR SEE LABOUR	1,013.40	-
1	FRONT GRILLE ASSY	TO REPAIR SEE LABOUR	1,108.90	-
1	FRONT GRILLE BADGE	NOT NECESSARY	62.50	-
1	FRONT GRILLE FIGHTER EMBLEM	NOT NECESSARY	82.50	-
1	FRONT SIDE LAMP RH	NOT NECESSARY	445.06	-
	LESS 25% DISCOUNT		-1,699.24	-505.98
			5,097.72	1,517.92
<u>SPECIAL NETT ITEMS</u>				
1	40 PAX STICKER (SN)	NECESSARY	10.00	10.00
1	60 KM/H STICKER (SN)	NECESSARY	10.00	10.00
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	30.00	-
1	HYDRAULIC CYLINDER JACK (INNER) LH (SN)	BENT	1,600.00	1,600.00
1	HYDRAULIC CYLINDER JACK (INNER) RH (SN)	BENT	1,600.00	1,600.00
1	HYDRAULIC CYLINDER JACK (OUTER) LH (SN)	BENT	1,800.00	1,800.00
1	HYDRAULIC CYLINDER JACK (OUTER) RH (SN)	BENT	1,800.00	1,800.00
1	HYDRAULIC CYLINDER JACK DUST COVER (INNER) LH (SN)	NECESSARY	250.00	250.00
1	HYDRAULIC CYLINDER JACK DUST COVER (INNER) RH (SN)	NECESSARY	250.00	250.00
1	HYDRAULIC CYLINDER JACK DUST COVER (OUTER) LH (SN)	NECESSARY	250.00	250.00
1	HYDRAULIC CYLINDER JACK DUST COVER (OUTER) RH (SN)	NECESSARY	250.00	250.00
2	HYDRAULIC CYLINDER JACK HOSE (SN)	NOT NECESSARY	600.00	-
8	HYDRAULIC CYLINDER JACK LOCK PIN (SN)	NECESSARY	40.00	40.00
2	HYDRAULIC CYLINDER JACK PRIVOT PIN (LONG) (SN)	NECESSARY	300.00	300.00

Report Ref No. CS3/SMO17020609/Evd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
6	HYDRAULIC CYLINDER JACK PRIVOT PIN (SHORT) (SN)	BENT	600.00	600.00
2	HYDRAULIC CYLINDER JACK TEFON WHEEL (SN)	BENT	240.00	240.00
1	REAR BUMPER ASSY (COMPLETE) (SN)	NOT NECESSARY	1,800.00	-
1	REAR LIFT PLATFORM SUPPORT LINKAGE ASSY (SN)	NOT NECESSARY	4,800.00	-
1	REAR NUMBER PLATE (SN)	NECESSARY	30.00	30.00
1	REAR NUMBER PLATE LAMP (SN)	NECESSARY	69.00	69.00
1	TAILGATE "MAX 1500KG" STICKER (SN)	NECESSARY	15.00	15.00
1	TAILGATE "PALFINGER" STICKER (SN)	NECESSARY	120.00	120.00
1	TAILGATE 'WARNING' STICKER (SN)	NECESSARY	15.00	15.00
1	TAILGATE LIFT PLATFORM (SN)	BENT	12,500.00	8,000.00
1	TAILGATE RED/WHITE CAUTION STICKER LH (SN)	NECESSARY	80.00	80.00
1	TAILGATE RED/WHITE CAUTION STICKER RH (SN)	NECESSARY	80.00	80.00
2	TAILGATE REFLECTOR (SN)	N/S BROKEN	24.00	12.00
1	TAILLAMP BRACKET LH (SN)	NOT NECESSARY	110.00	-
1	TAILLAMP BRACKET RH (SN)	NOT NECESSARY	110.00	-
1	TAILLAMP LH (SN)	CUT	230.00	230.00
1	TAILLAMP RH (SN)	BROKEN	230.00	230.00
			29,843.00	17,881.00
	LABOUR			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSING. (TO FR)		200.00	50.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		2,800.00	800.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT BUMPER BRACKET, FRONT BUMPER HEADLAMP GARNISH RH, FRONT CORNER PANEL RH AND FRONT GRILLE ASSY.		3,000.00	2,000.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		200.00	50.00
			6,200.00	2,900.00
	GRAND TOTAL		41,140.72	22,298.92
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			17,850.00

Report Ref No. CS3/SMO17020609/Evd3e2-1



Report Ref No. CS3/SMO17020609/Evd3e2-1

MARKET VALUE: \$85,000.00(EST)-LTA REIMBURSEMENT VALUE: \$17,065.00=NETT VALUE: \$67,935.00

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.