

ASS. REC. IV.

## REF

CI/TPD19604300/Pk

### Special Instructions

## Summary

### ASSIGNMENT (Office)

From (Person): Kamalah Kanbe

of

SPF

Date/Time:

20/2/2019

Estimated Cost:

Bill Ver.

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: FBE 8770 H

Imineed

at Workshop 10.

Tel:

and

Policy No: MHASPF06000014051

Clămărești

TP/IP/69903/2018

Sum insured:

### Experiment

Make of Veh:

(Client's Record)

D.O.A. 20/12/2018

CA / REV / REP / REV 24 HRS

H.O.D. Pauloyanment

Unit/Time

Person Connected:

Vehicle IN/OUT

Date/Time

Action/Instruction ( )	Estimate
1. Review the project schedule and identify the critical path.	
2. Identify the resources required for each activity.	
3. Calculate the total duration of the project.	
4. Identify the activities that can be delayed without affecting the project completion date.	
5. Develop a contingency plan for potential risks.	
6. Communicate the project schedule and progress to the project team.	
7. Monitor the project progress and update the schedule as needed.	
8. Report the project status to the project sponsor.	
9. Review the project schedule and make adjustments as needed.	
10. Close the project and document the lessons learned.	

FBE 8770 H-X.

135015

2

10 NUM CARAS

FBE8770H

**Rohaizal (LKKAUTO)**

**From:** Kamaliah KAMIS (SPF) <Kamaliah\_KAMIS@spf.gov.sg>  
**Sent:** Wednesday, 20 February 2019 12:30 PM  
**To:** Rohaizal (LKKAUTO)  
**Cc:** Bryan Ang (LKKAUTO); Jackson MU (SPF); Guang Hui LEE (SPF); SPF-TP FAIT  
**Subject:** Mechanical Inspection Report Request

Hi Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the 10 vehicles below:

**a) Case IAFP-IB-20190201 - Mechanical Inspection of Motor Car, SCK1726P (TP/IP/01847/2019)**

On 10 January 2019 at about 10.49 am, Police incident was created regarding an accident along Bukit Batok Road by Bukit Batok West Avenue 6. The motor car, SCK1726P, was travelling on the right of 2-lanes along Bukit Batok Street 21 making a right turn into Bukit Batok West Ave 6 when traffic light was green only. While making a right turn, the motor car collided onto a pedestrian (deceased) who was crossing at the pedestrian crossing from the motor car's left to right view. The pedestrian was conveyed to NTFGH by ambulance. On the same day, at 12.06 pm, the pedestrian succumbed to her injuries and was pronounced dead by Doctor at NTFGH.

**Vehicle to be inspected: SCK1726P (Potential Defendant)**

IO In-Charge: SI Dzul Hairie

**b) Case: IAFP-IB-20190201 - Mechanical Inspection of Motorcycle, FBE8770H (TP/IP/69903/2018)**

On 20 December 2018 at 12.21 pm, the deceased was riding FBE 8770 H on the left lane of 3 lanes when his motorcycle hit the side kerb and skidded. The deceased was sent to National University Hospital (NUH) and succumbed to her injuries on the same day and was pronounced dead at NUH.

**Vehicles to be inspected: FBE8770H (Deceased)**

IO In-Charge: SIO Yazid

**c) Case: IAFP-IB-20190201 - Mechanical Inspection of Motorcycle, JSC2795 (TP/IP/00599/2019)**

**d) Case: IAFP-IB-20190201 - Mechanical Inspection of Police Motor Car, QX327E (TP/IP/00599/2019)**

On 3<sup>rd</sup> January 2019 at 8.43 am, the rider with pillion (deceased) was riding JSC 2795 along Woodlands Road entering into BKE when the rider collided onto the rear of the police car QX 327 E which was stationary on the chevron. As a result the rider and deceased was flung off the motorcycle. The rider and pillion of the motorcycle was then sent to KTPH and the pillion was pronounced dead in hospital.

**Vehicles to be inspected: JSC2795 (Potential Defendant)**

**Vehicles to be inspected: QX327E (Involved Party)**

IO In-Charge: SIO Yazid

**e) Case: IAFP-IB-20190201 - Mechanical Inspection of Motor Car, SLL3915K (TP/IP/62683/2018)**