

## APPENDIX IV

RIGHT

C1/TPD1900H303/Pc

### Symptomatic Infections

Summary

ASSIGNMENT (Office)

From (Person): Kamillah Kamis

4.96

QPF

Date/Time:

20/3/2019

Continued

1311.002

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CF

To inspect Vehicle No.

QX327E

Insured:

2nd Wenkeberg mds.

Tel:



Policy No. MHASPF06000014a51

Claim No.

TP/IP/00599/2019

None found.

**Abstract.**

Make of Veh.  
(Officer's Record)

FOIA

31/2019

CA / REV / REP / REV 24 HRS

### 11.6.14. Embolism

Date/Time:

Peram Continued

Vehicle IN / OUT

File/Time
-----------

Action/Instruction ( )	Estimate
1. Read the problem carefully.	
2. Identify the given information.	
3. Determine what is being asked.	
4. Plan a solution strategy.	
5. Execute the plan.	
6. Check the solution.	

QX327E-X

331-2

④  
10 new cases  
QX 327E  
**Rohaizal (LKKAUTO)**

**From:** Kamaliah KAMIS (SPF) <Kamaliah\_KAMIS@spf.gov.sg>  
**Sent:** Wednesday, 20 February 2019 12:30 PM  
**To:** Rohaizal (LKKAUTO)  
**Cc:** Bryan Ang (LKKAUTO); Jackson MU (SPF); Guang Hui LEE (SPF); SPF-TP FAIT  
**Subject:** Mechanical Inspection Report Request

Hi Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the 10 vehicles below:

a) Case IAFP-IB-20190201 - Mechanical Inspection of Motor Car, SCK1726P (TP/IP/01847/2019)

On 10 January 2019 at about 10.49 am, Police incident was created regarding an accident along Bukit Batok Road by Bukit Batok West Avenue 6. The motor car, SCK1726P, was travelling on the right of 2-lanes along Bukit Batok Street 21 making a right turn into Bukit Batok West Ave 6 when traffic light was green only. While making a right turn, the motor car collided onto a pedestrian (deceased) who was crossing at the pedestrian crossing from the motor car's left to right view. The pedestrian was conveyed to NTFGH by ambulance. On the same day, at 12.06 pm, the pedestrian succumbed to her injuries and was pronounced dead by Doctor at NTFGH.

Vehicle to be inspected: SCK1726P (Potential Defendant)

IO In-Charge: SI Dzul Hairie

b) Case: IAFP-IB-20190201 - Mechanical Inspection of Motorcycle, FBE8770H (TP/IP/69903/2018)

On 20 December 2018 at 12.21 pm, the deceased was riding FBE 8770 H on the left lane of 3 lanes when his motorcycle hit the side kerb and skidded. The deceased was sent to National University Hospital (NUH) and succumbed to her injuries on the same day and was pronounced dead at NUH.

Vehicles to be inspected: FBE8770H (Deceased)

IO In-Charge: SIO Yazid

c) Case: IAFP-IB-20190201 - Mechanical Inspection of Motorcycle, JSC2795 (TP/IP/00599/2019)

d) Case: IAFP-IB-20190201 - Mechanical Inspection of Police Motor Car, QX327E (TP/IP/00599/2019)

On 3<sup>rd</sup> January 2019 at 8.43 am, the rider with pillion (deceased) was riding JSC 2795 along Woodlands Road entering into BKE when the rider collided onto the rear of the police car QX 327 E which was stationary on the chevron. As a result the rider and deceased was flung off the motorcycle. The rider and pillion of the motorcycle was then sent to KTPH and the pillion was pronounced dead in hospital.

Vehicles to be inspected: JSC2795 (Potential Defendant)

Vehicles to be inspected: QX327E (Involved Party)

IO In-Charge: SIO Yazid

e) Case: IAFP-IB-20190201 - Mechanical Inspection of Motor Car, SLL3915K (TP/IP/62683/2018)