

ASS. REC. BY:

REF:

CG3/EG119004310/Gcd307

Special Instruction:

SURVA/01

GQ

ASSIGNMENT (Office)From (Person): Jeannie Cheng of EG1 Date/Time: 7/3/2019

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CSTo Inspect Vehicle No: FBG 6085E Insured: SDK3838Aat Workshop m/s: _____ Tel: 97660243 Fairouzof Bik 540 Ang Mo Kio Ave 10 CarparkPolicy No: _____ Claim No: CDMPG19000236/SL/JC

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 20/1/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 7/3 Person Contacted: _____ H.O.D. Endorsement: _____
Vehicle: IN OUT

Date/Time	Action/Instruction (X) Estimate
	FBG 6085E - X
<u>8/3 9am</u>	Call back after lunch still sleeping.
<u>8/3 1pm</u>	Fairoz said arrange on Tuesday 12/3/2019 at 4pm.

Surveyor: 602


REF: EGi

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBG 6085 E Yr Regn: Sept 12
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda CB400 C.C. 399
 Colour: Black A/C: Insured / Std / NI / NA
 Sp.Reading: 107212 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JH2NC4294 B/K 300 266
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or
 Brake: Good / Jammed / Leaked / Burnt or
 Modi: OK / S/Rim / STD A/Rim or
 Tyre Size: F: 120/60ZR17
 R: 160/60ZR17
BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front	Rear
R/Bal. <u>5</u> mm	R/Bal. <u>5</u> mm
L/Bal. _____ mm	L/Bal. _____ mm
D.O.A. _____	D.O.I. <u>12-03-19530</u>
Survey held at <u>BLK 540 AMK AVE 10 Carpent.</u>	
Des. of Damages: Frt / Rear / <u>O/S</u> / N/S / U/C / Rooftop or	

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>\$2000 - \$3000</u>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: -

Survey Fee:

Transportation:

_____ \$ + RS. _____ SI

) Photos

) Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format : PR2

Lump Sum / I.B.I. (\$) _____

50

50

Celine Fong (LKKAuto)

From: Jeannie Cheng <jeannie.cheng@ergo.com.sg>
Sent: Thursday, 7 March 2019 5:20 PM
To: Admin-D (LKKAuto)
Cc: SUR
Subject: RE: PRS IRO SDK3838A | OI : FBG6085E | DOA: 20/01/2019| ERGO REF: CDMPG19000236/SL/JC

Hi LKK,

Please contact the repairer, Mr Muhammad Fairoz at 9766 0243 directly for arrangement of the pre-repair inspection.

Thank you.

Warmest Regards,
Jeannie Cheng
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
jeannie.cheng@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.
Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.
ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Jeannie Cheng
Sent: Thursday, March 07, 2019 3:14 PM
To: admin-d@lkkauto.com
Cc: sur@lkkauto.com; ERGO Insurance Pte. Ltd. (Claims Department); Survey Report (ERGO Insurance Pte. Ltd.)
Subject: RE: PRS IRO SDK3838A | OI : FBG6085E | DOA: 20/01/2019| ERGO REF: CDMPG19000236/SL/JC

Hi LKK,

With reference to the above matter,

We have rejected to their PRS list, please assist to conduct this survey request from Lee Shergill LLP, their client's vehicle can be surveyed at the location as per stated in the letter attached.

Catherine Chong (LKK Auto)

From: Jeannie Cheng <jeannie.cheng@ergo.com.sg>
Sent: Thursday, 7 March, 2019 3:14 PM
To: admin-d@lkkauto.com
Cc: sur@lkkauto.com; ERGO Insurance Pte. Ltd. (Claims Department); Survey Report (ERGO Insurance Pte. Ltd.)
Subject: RE: PRS IRO SDK3838A | OI : FBG6085E | DOA: 20/01/2019| ERGO REF: CDMPG19000236/SL/JC
Attachments: (GIA) TP OIV.pdf

Hi LKK,

With reference to the above matter,

We have rejected to their PRS list, please assist to conduct this survey request from Lee Shergill LLP, their client's vehicle can be surveyed at the location as per stated in the letter attached.

Attached are the necessary documents for your further actions (Note: Reports not to be released to any Third Party).

Note: To survey on without prejudice basis and inform the repairer in writing, that you are required to conduct a post-repair inspection before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Kindly acknowledge receipt of this email.

NOTE: Please assist to quote our ref as the subject matter, when forwarding the Preliminary Reports / Survey Reports.

Thank you.

Warmest Regards,
Jeannie Cheng
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 036985
jeannie.cheng@ergo.com.sg

www.ergo.com.sg

ERGO

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message. Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Jeannie Cheng
Sent: Thursday, March 07, 2019 3:02 PM
To: 'raj@leeshergill.com'; 'aileen@leeshergill.com'; 'gurmesh@leeshergill.com'; 'fiza@leeshergill.com'
Subject: PRS IRO SDK3838A | OI : FBG6085E | DOA: 20/01/2019| ERGO REF: CDMPG19000236/SL/JC

WITHOUT PREJUDICE

Dear Sirs,

With reference to your fax dated 06 March 2019, we are not selecting any of the motor surveyors as listed.

As such, we will proceed with the Pre-repair Inspection and will be appointing LKK Auto Consultants to survey your client's vehicle.

Thank you.

Warmest Regards,
Jeannie Cheng
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
jeannie.cheng@ergo.com.sg

www.ergo.com.sg

ERGO

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

Ang Mo Kio Ave 10
BKE 540 Carpark
12/3/19 4pm.

Lee Shergill LLP

Advocates & Solicitors

Raj Singh Shergill LLB Hons (NUS) Chia Aileen LLB Hons (NUS)

Service of court documents by facsimile and/or email is not accepted

111 North Bridge Road
#07-07 Peninsula Plaza
Singapore 179098
Tel: +65 6535 1376
Fax: +65 6535 5362URL: <http://www.leeshergill.com>

6 March 2019

IMMEDIATE ATTENTIONErgo Insurance Pte. Ltd.
Motor Claims Department
5 Temasek Boulevard
#04-05 Suntec Tower Five
Singapore 038985
*Your Reference: SDK 3838A***BY FAX NO. 6829 9247/6829 9248
& PDX**No. of page(s) including this page:
2+enclosures*Our Reference: LSP/RSS/13038/19/ff*

Dear Sirs,

**CLAIMANT: MUHAMMAD AIMAN BIN JURAIMI (NRIC NO. S9303536D)
PERSONAL INJURY & PROPERTY DAMAGE CLAIM ARISING OUT OF ROAD
TRAFFIC ACCIDENT INVOLVING FBG 6085E & SDK 3838A ALONG EUNOS
ROAD 05 ON 20.01.2019 AT AROUND 1245 HRS**

We hereby give notice on behalf of the repairer – Garage One-33 LLP and/or the owner of motor vehicle registration no. FBG 6085E that this motor vehicle was involved in an accident on 20 January 2019 with motor vehicle registration no. SDK 3838A the driver of which was insured with Ergo Insurance Pte. Ltd. and caused the accident by negligent driving/control/management. A copy of the Singapore accident statement filed is enclosed.

Take Notice that the vehicle will be made available for purpose of pre-repair survey if you are so minded, at the carpark of Block 540 Ang Mo Kio Avenue 10, Singapore 560540.

In this regard, we propose the following surveyors:

- 1) Lee Appraisal Services – Dylan Lee;
- 2) ROG Associates – Mr Roger Gan; and
- 3) Premier Appraiser Services – Mr Leslie K.C. Lim.

In the event, you are not agreeable to the above, you may appoint your independent surveyor to assess our client's motor vehicle. May we propose in line with the amicable and fair spirit of settlement for both surveyors to meet, appraise the vehicle in the repairer's presence and agree on a fair amount. Kindly liaise with our Ms Fiza Fazakir (fiza@leeshergill.com) at 65351376 or Mr Muhammad Fairuz of Garage One-33 LLP at 9766 0243 in respect of any inspection or survey.

Take Further Notice that in the event you fail to respond within *2 working days* (excluding Saturdays, Sundays and Public Holidays) of your receipt of this notice as to whether you wish to carry out or waive a pre-repair survey, the workshop will in due course proceed to

Privileged/confidential information may be contained in this letter and is intended only for the use of the addressee. If you are not the addressee, or person responsible for delivering to the person addressed, you may not copy or deliver this to anyone else. If you receive this letter by mistake, please notify us immediately by telephone and destroy this. Thank you.

In association
with Bajwa & Co


Lee Shergill LLP

Advocates & Solicitors

Ref : LSP/RSS/13038/19/ff

repair the vehicle and/or have it surveyed as they deem fit, without further notice and without prejudice to the right to claim loss of use in accordance with the Pre-action Protocol for Non-Injury Motor Accident Cases.

Yours Faithfully



LEE SHERGILL LLP

Email : raj@leeshergill.com; aileen@leeshergill.com; gurmesh@leeshergill.com
fiza@leeshergill.com

cc Mr Muhammad Fairoz
Garage One-33 LLP

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8790H
Vehicle Details	
Vehicle No.:	FBG6085E
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	CB400
Primary Colour:	Black
Manufacturing Year:	2012
Engine No.:	NC42E1121390
Chassis No.:	JH2NC4294BK300266
Maximum Power Output:	-
Open Market Value:	\$8,382.00
Original Registration Date:	12 Sep 2012
First Registration Date:	12 Sep 2012
Transfer Count:	1
Actual ARF Paid:	\$1,258.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Sep 2022
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,801.00
COE Rebate Amount:	\$626.00
Total Rebate Amount:	\$626.00

The information contained herein is correct as at 20 Mar 2019

OK

MVA310009890 / VAC - Kaki Bukit
ENTRY DATE & TIME: 21/01/2019 10:20
SUBMITTED BY: SITI FADHLON BTE ABUL KADER

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 21/01/2019 10:20
Date Of Accident 20/01/2019 12:45
Exact Location Of Accident EUNOS ROAD 05
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number FBG6085E
Insured/Policyholder
Name Of Registered Owner JURAIME BIN AHMAD
NRIC No S1638790H
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-97517727
Alternative Phone No OTHERS-97517727
Vehicle Particulars
Manufacturer HONDA
Model CB400
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category MOTORCYCLE
Insurance Company
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage THIRD PARTY
Fleet Policy NO
Policy Number 6093988754-01
Cover Note Number
Driver
Name of Driver MUHAMMAD AIMAN BIN JURAIME
NRIC No S9303536D
Date Of Birth 07/02/1993
Occupation INDOOR
Date Of Driving Pass 10/07/2013
Driving Experience 5 YEARS AND 6 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-93890514
Fax Number
Contact Number
Email Address NOEMAIL

Address BLK 408 #04-183 TAMPINES STREET 41
 Postcode 520408
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured CHILDREN
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name CHANGI N.P.C
 Police Station Address ROAD: 9 SIMEI STREET 2, POSTCODE: 529914, COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

Type Of Accident; HEAD TO SIDE LOCATTION: EUNOS ROAD 05 AT OPEN CARPARK NEAR BLK 417 EUNOS ROAD 5 AS PER POLICE REPORT No. T/20190120/2140;

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SDK3838A
 Vehicle Make/Model/Colour MERCEDES BENZ E 250
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver SERENE PHUNG SAU LING (SERENE PAN SHAOLING)
 NRIC/Passport Number S7614764A
 Contact Number 96926769
 Address
 Postcode
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF INJURED PERSON 1

Name	MUHAMMAD AIMAN BIN JURAIMÉ
Approximate Age	25
Injuries Sustain	.
Injured person in which vehicle?	FBG6085E
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 408 #04-183 TAMPINES STREET 41
Postcode	520408

Accident Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

21 JAN 2010



IDAC KAKI BUKIT (VAC)

Accident Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

21 JAN 2010

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
Reporting Centre
Name: Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190120/2140

Police Station Of Origin:
Changi N.P.C
9 Simei Street 2 SINGAPORE 529914
Tel No: 1800-5872999

1 of 3

Report No. T/20190120/2140

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/01/2019 22:28		Vide Report No.:		Station Diary No.: 80
Informant's Particulars				
Name of Informant: MUHAMMAD AIMAN BIN JURAIME		Address: APT BLK 408 TAMPINES STREET 41 #04-183 SINGAPORE 520408		
ID Type / ID No.: NRIC NO / S9303536D		Contact No.: Home/Office: Mobile: 93890514		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 25	Date of Birth: 07/02/1993	Type of Informant: Rider	
Race: Malay		Language: English	Institution / School Name:	
Occupation: Other assistant engineers		Driving Licence Information: Class: 2B,2A,2 Date of Expiry:		

General Information on the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 20/01/2019 12:45	Type of Location: Car Park
Location: Along Road 1 EUNOS ROAD 5 AT OPEN CARPARK NEAR BLK 417 EUNOS ROAD 5				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190120/2140

Police Station Of Origin:
Changi N.P.C
9 Simei Street 2 SINGAPORE 529814
Tel No: 1800-5872999

1 of 3

Report No. T/20190120/2140

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/01/2019 22:28		Vide Report No.:		Station Diary No.: 80
Informant's Particulars				
Name of Informant: MUHAMMAD AIMAN BIN JURAIME		Address: APT BLK 408 TAMPINES STREET 41 #04-183 SINGAPORE 520408		
ID Type / ID No.: NRIC NO / 59303536D		Contact No.: Home/Office: Mobile: 93890514		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 25	Date of Birth: 07/02/1993	Type of Informant: Rider	
Race: Malay		Language: English	Institution / School Name:	
Occupation: Other assistant engineers		Driving Licence Information: Class: 2B, 2A, 2 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 20/01/2019 12:45	Type of Location: Car Park
Location: Along Road 1 EUNOS ROAD 5 AT OPEN CARPARK NEAR BLK 417 EUNOS ROAD 5				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Registration	Condition	No. of Passenger
FBG0085E	Motorcycle	HONDA	CB400		Slightly Damaged	0
SDK3838A	Car	MERCEDES BENZ				0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190120/2140

Police Station Of Origin:
Changi N.P.C
9 Simel Street 2 SINGAPORE 529914
Tel No: 1800-5872999

2 of 3

Report No. T/20190120/2140

CONTINUATION OF REPORT

Rider			
Name	MUHAMMAD AIMAN BIN JURAIME	ID No.	S9303536D
Related Vehicle	FBG6085E (Motorcycle)	Contact No.	93890514
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2 Date of Expiry: NIL
Date Treatment	20/01/2019	Date Discharge	20/01/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	SERENE PHUNG SAU LING (SERENE PAN SHAOLING)	ID No.	S7614784A
Related Vehicle	SDK3838A (Car)	Contact No.	96926769
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 20/01/2018 at about 1245hrs, I was in the open carpark near Blk 417 Eunos Road 5. I was on my bike, FBG6085E and reversing it to come out of the lot when a car, SDK3838A collided into the rear left of my bike. She then drove off however stopped at the side of the road and then alighted and approached me. After the collision, the bike fell to the right and I fell together with my bike. My bike then trapped my right leg under however I managed to get up. We then exchanged particulars and we both left as she informed me that she had to pick up her daughter.

On the same day, in the afternoon, I then felt pain in my leg area and felt aching in my shoulders. I then went to see a doctor at Changi General Hospital and was issued with 3 days of medical leave.

I wish to state that during the collision, another bike to my right also fell down. I managed to speak to the owner who informed that it was okay and he then rode off. I wish to add that I have his particulars. There was also a witness who approached me after the collision and also assisted me in lifting both the bikes.

I made a check on my bike and found a few scratches. I am unsure of the cost of the damages and will be bringing my bike to IDAC tomorrow.

Accident Sketch Plan Pg. 1



Changi
General Hospital
SingHealth

ORIGINAL

MEDICAL CERTIFICATE

EMD201913746

Name MUHAMMAD AIMAN BIN JURAIME		NRIC No. S88085380	
THIS IS TO CERTIFY that the above-named is unfit for duty for a period of <u>3</u> days from <u>20 JAN 2019</u> to <u>23 JAN 2019</u> inclusive.			
Type of medical leave granted:			
<input type="checkbox"/> Hospitalization Leave	<input checked="" type="checkbox"/> Outpatient Sick Leave		
Admitted on: _____	<input type="checkbox"/> Maternity Leave,	Delivered on: _____	
Discharged on: _____	<input type="checkbox"/> Sterilization Leave,	Operated on: _____	
This certificate is not valid for absence from court attendance.			
Diagnosis		Surgical Operation (if applicable)	
Fit for light duty from <u>N.A.</u> to <u>N.A.</u>			
Comments:			
The above-named patient attended my clinic at <u>N.A.</u> and left at <u>N.A.</u> No medical leave is necessary.			
Hospital/Clinic	Ward No.	Signature, Name (in BLOCK LETTERS) and Designation/MCR No.	
Emergency Medicine	CGH Accident & Emergency	 DEEPU ALKERE NANJUNDASWAMY . 83528Z	
Changi General Hospital	Date 20-Jan-2019		



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
ERGO INSURANCE PTE LTD		Ref: CS3/EGI19004310/Gcd3e2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER		Date: 04-04-2019		
FIVE SINGAPORE 038985		Code: EGI		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SDK 3838A	Veh. Inspected	FBG 6085E	
Policy No.		Coverage (\$)	0.00	
Claim No.	CDMPG19000236/SL/JC	Excess (\$)	0.00	
Assign From	JEANNIE CHENG	Assign Date	07/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CB400	c.c	399	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	JH2NC4294BK300266	Colour	BLACK	
Odometer	107212 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/60Z R17	BRIDGESTONE	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	160/60Z R17	BRIDGESTONE	5 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
5. General Information				
Accident Date	20/01/2019	Inspect Date / Time	12/03/2019 (05:30 PM)	
Survey held at	BLK540 ANG MO KIO AVE 10 CAR PARK			
Repairer	-			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

Report Ref No. CS3/EGI19004310/Gcd3e2

Inspected By



XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.