

ASS. REC. BY:

REF:

CC3/SMD19004311/God327

Special Instruction:

CUTV/01

ASSIGNMENT (Office)From (Person): Goh Pau Loong of SMD Date/Time: 8/3/2019

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: S6K 9001Y Insured: SLN 2638Gat Workshop m/s Alpha Car Tel: _____of Blk C Kaki Bukit Ave 6 #01-59Policy No: DIQMTRENT000058Claim No: CMTD1901226

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 5/3/2019

(Client's Record)

11/3/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	<u>S6K 9001Y-X</u>
	<u>SLN 2638G-X</u>
	<u>Dismantle: 12/3/2019</u>
	<u>After repair: 21/3/2019</u>

PRS
Gill

REF:

SNO.

ASSIGNMENT

2008 31 Oct
~~2007~~

From: Date: 11/3/2019.

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGK9001Y

at Workshop m/s Alpha Car

of BIK C Kaki Bukit #01-59

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

11/3/2019.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

~~\$15K~~ \$26K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

9

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No.

SGK9001Y

Yr Regn:

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Fit

C.C.

1339

Colour:

Blue

A/C

Insured / Std / NI / NA

Sp. Reading:

129056

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GE61085915

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65 R14

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

5/3/19

D.O.I.

11-03-19

Survey held at

w/s

4:20pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

~~\$1000 = \$500~~ \$8000 \$9000

RECEIVED 25 MAR 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 9

Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format: PRS

Lump Sum / I.B.I. (\$

Survey Fee:

Transportation:

) \$ + RS. SI

) Photos

) Others

TOTAL

100

60

60

10

230

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Mar 2019		08 Mar 2019 15:04 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ETHOZ GROUP LTD, Co. Reg. No.: 198104531H		
Main Claimant:	KEVIN TAN PENG KHIM, ID: S7801118A		
Vehicle Reg. No.:	SGK9001Y	Date of Loss:	05/03/2019 14:00 - :59
Claim Type:	TP / CMTD1901226	Policy/Cover Note No.:	D19MTRENT000058 (Third Party Only)
Vehicle Reg. No. (Insured):	SLN2638G	Policy No. (Claimant):	
		Excess:	
Repairer:	Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay, 417883 Kaki Bukit - Tel: 65098258		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/03/2019]		
Driver/Custodian (Insured):	CARNEGIE ALAN WYBROW (), NRIC: G5943276T, Tel: +6592315520 Email:		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Monday 11/3/19.
X est

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1118A
Vehicle Details	
Vehicle No.:	SGK9001Y
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	L13A4095612
Chassis No.:	GE61085915
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$11,850.00
Original Registration Date:	31 Oct 2008
First Registration Date:	31 Oct 2008
Transfer Count:	5
Actual ARF Paid:	\$11,850.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Oct 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$15,142.00
COE Rebate Amount:	\$14,018.00
Total Rebate Amount:	\$14,018.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 13 Mar 2019

OK

▶ Fit Used Vehicle List (20 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Available
Honda Fit 1.3A (COE till 01/2021)	\$12,900	\$6,820 /yr	02-May-2006	1,339 cc	178,000 km	Karz Konzept	Available
Well Maintained By Young Couple. Selling It Close To Paper Value For Short Term Driving. Losing Paper Value. Call Now To Enquire More Office No. - - Kelvin - 82513333 Tan - 81173333							
Honda Fit 1.3A (COE till 12/2021)	\$19,800	\$7,180 /yr	15-Dec-2006	1,339 cc	139,000 km	Car Search	Available
1 Of The Popular Hatchback For Your Family And Daily Usage. Back Spacious For Goods Delivery! Fuel Saving Yet Powerful Drive. Smooth Engine, Easy To Maintain Unit, Consignment Unit. Viewing Strictly B... Office No. - 62620728 Lester - 96192666 Rachel - 91126538 Justin - 91827511 Matthew - 91186851							
Honda Fit 1.3A (COE till 01/2022)	\$16,500	\$5,710 /yr	31-Jan-2007	1,339 cc	-	Elite Autostyle Pte Ltd	Available
Excellent And Original Condition, Well Maintained Interior And Exterior, High Loans Available. Call Now To Arrange For A Viewing Appointment Office No. - - Daniel - 93802853 Zhi Rong - 93654050							
Honda Fit 1.3A (COE till 05/2022)	\$22,800	\$7,220 /yr	10-May-2007	1,339 cc	110,000 km	Esprit Motor Trading	Available
- Office No. - 64568623 Francis Goh - 96608623							
Honda Fit 1.3A (COE till 10/2022)	\$23,800	\$6,570 /yr	26-Oct-2007	1,339 cc	119,432 km	Car Search	Available
Beautifully Fitted J's Racing Bodykit In Nardo Grey. Low Mileage, Taken Care Extremely Well By Owner. View To Believe! Trade-Ins Available Viewing By Appointment Only! Office No. - 62620728 Justin - 91827511 Rachel - 91126538 Matthew - 91186851 Lester - 96192666							
Honda Fit 1.3A G (COE till 03/2023)	\$22,800	\$5,700 /yr	12-Mar-2008	1,339 cc	133,000 km	Elite Autostyle Pte Ltd	Available
Fuel Efficient, Fun & Reliable Hatchback Up For Sale. An Under Utilised Unit With Very Low Mileage. Selling Off Due To Lack Of Usage. Passing It Off To The Next Owner With A Peace Of Mind. Consignment... Office No. - - Dave - 90480809 Zhi Rong - 93654050							
Honda Fit 1.3A G Skyroof (COE till 03/2023)	\$22,800	\$5,630 /yr	15-Apr-2008	1,339 cc	180,000 km	Car Fleet Auto Pte Ltd	Available
Balloon Scheme Available! We Are sgCarMart Premium Dealer 2015 To 2017! Buy With Confidence! No Hidden Costs! In House Loan Or Bank Loan Available! Fast And Easy Loan Approval! High Loan Or Over Trade... Office No. - 69096423 Mr An - 84269807 Syukur Nico - 82440004							
Honda Fit 1.3A G (COE till 05/2028)	\$48,000	\$5,210 /yr	30-May-2008	1,339 cc	108,000 km	Monster Motors Pte Ltd	Available
Honda's Signature Compact And Nimble VTEC Hatchback In Factory Black Exterior And Red On Black Leather Upholstery. Buy With A Peace Of Mind. Always Parked Under Shelter. Regularly Serviced At Reputable... Office No. - - Valentino - 96534300 Alex Lim - 92207602							
Honda Fit 1.3A G (New 5-yr COE)	\$27,200	\$5,430 /yr	11-Jul-2008	1,339 cc	-	Grande Car Gallery Pte Ltd	Available

Clean Interior And Own By Non Smoker. Fuel Saving Yet Powerful Drive. In House Loan Available, At Low Monthly Installment, Flexible Loan

Available. 100% Accident Free. Trade In Are Welcome, View To Be...

Office No. - 64524300

Mark - 93803299

Honda Fit 1.5A RS (COE till 08/2028)	\$46,800	\$4,960 /yr	19-Aug-2008	1,496 cc	162,000 km	Carro	Availal
---	-----------------	--------------------	--------------------	-----------------	-------------------	--------------	----------------

Schedule A Test Drive Today. Viewing Is Strictly By Appointment Only.

Office No. - 67146652

Paul - 87671091

Honda Fit 1.3A G (COE till 08/2023)	\$24,999	\$5,610 /yr	27-Aug-2008	1,339 cc	122,000 km	Carland Automobile	Availal
--	-----------------	--------------------	--------------------	-----------------	-------------------	---------------------------	----------------

\$500 For Monthly Installment, New Paintwork, New Rims And Tyres, 2 Owners, Low Mileage Done, Excellent Maintained Condition, No Repair Needed And Comes With 6 Months Warranty.

Office No. - 62912129

Lee - 90044780

Honda Fit 1.3A L Skyroof (COE till 08/2023)	\$28,600	\$6,400 /yr	01-Sep-2008	1,339 cc	105,000 km		Availal
--	-----------------	--------------------	--------------------	-----------------	-------------------	--	----------------

Excellent And Original Condition, Well Maintained Interior And Exterior, Low Mileage Done, Original Sporty Red Paintwork, Call Now For View

Office No. - -

Khai - 85117955

Honda Fit 1.3A G (OPC) (New 5-yr COE)	\$28,800	\$5,750 /yr	04-Sep-2008	1,339 cc	93,000 km	AA Trust Automotive	Availal
--	-----------------	--------------------	--------------------	-----------------	------------------	----------------------------	----------------

AA Trust Certified Quality 1 Owner Vehicle! Extremely Well Maintained By 1 Owner Only! Price Inclusive Of Conversion To Normal Plate! Low Fuel Consumption! Low Maintenance Cost! Smooth And Responsive ...

Office No. - 63450381

James Yew - 97975757 | Dave - 98500051 | Clement - 93365036 | Willey - 91692071

Honda Fit 1.3A G (COE till 09/2023)	\$24,600	\$5,470 /yr	12-Sep-2008	1,339 cc	-	XL Motor Trading Pte Ltd	Availal
--	-----------------	--------------------	--------------------	-----------------	----------	---------------------------------	----------------

Beautiful Car Number. Tip Top Condition. No Repair Needed.

Office No. - -

Jasslyn - 92466642

Honda Fit 1.3A GF (COE till 10/2023)	\$25,800	\$5,640 /yr	10-Oct-2008	1,339 cc	105,000 km	Victory Cars Trading Pte Ltd	Availal
---	-----------------	--------------------	--------------------	-----------------	-------------------	-------------------------------------	----------------

In-House Loan Or Bank Loan Available At 3.18% Only! No Gimmicks, In-House 6 Months Comprehensive Warranty With 24/7 Breakdown Recovery Service. We Welcome STA Or Pre-purchase Inspection. Reputable Com...

Office No. - 63854916

Mr Lee - 86885879 | Mr Lim - 92470299 | Mr Quek - 90096473 | Mr Tan - 90999505

Honda Fit 1.3A G (COE till 10/2023)	\$25,800	\$5,600 /yr	20-Oct-2008	1,339 cc	125,000 km	Privilege Group Pte Ltd	Availal
--	-----------------	--------------------	--------------------	-----------------	-------------------	--------------------------------	----------------

In House Loan Or Bank Loan Available At 3.18% Only! No Gimmicks.

Office No. - 64755115

Hong - 88766878 | Andy Lieu - 86881155 | Desmond Ang - 83821155 | Francis - 96358298

Honda Fit 1.3A G (COE till 10/2023)	\$27,388	\$5,930 /yr	24-Oct-2008	1,339 cc	130,000 km	Hamilton Autohub Pte Ltd	Availal
--	-----------------	--------------------	--------------------	-----------------	-------------------	---------------------------------	----------------

New 5 Years COE, Low Monthly \$380, Low Depre, High Loan Package Available, New Paint, New Sportrims, Well Maintained, Call Now & Arrange Test Drive.

Office No. - 62979001

Andy Ang - 92366391

Honda Fit 1.3A G Skyroof (COE till 11/2023)	\$29,800	\$6,420 /yr	03-Nov-2008	1,339 cc	150,000 km	Esprit Motor Trading	Availal
--	-----------------	--------------------	--------------------	-----------------	-------------------	-----------------------------	----------------

-

Office No. - 64568623

Francis Goh - 96608623

Honda Fit 1.3A G (New 5-yr COE)	\$30,800	\$6,150 /yr	27-Nov-2008	1,339 cc	-	Gen Y Automobile	Availal
--	-----------------	--------------------	--------------------	-----------------	----------	-------------------------	----------------

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/03/2019 16:37
Date Of Accident	05/03/2019 14:00
Exact Location Of Accident	CAIRNHILL CIRCLE TWDS CAIRNHILL RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGK9001Y
Insured/Policyholder	
Name Of Registered Owner	KEVIN TAN PENG KHIM
NRIC No	S7801118A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81611619
Alternative Phone No	OFFICE-81611619

Vehicle Particulars

Manufacturer	HONDA
Model	FIT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P10103208R00
Cover Note Number	

Driver

Name of Driver	KEVIN TAN PENG KHIM
NRIC No	S7801118A
Date Of Birth	03/01/1978
Occupation	INDOOR
Date Of Driving Pass	14/12/2009
Driving Experience	9 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81611619
Fax Number	
Contact Number	OFFICE-81611619
E-Mail Address	NOEMAIL

Address	BLK 968 HOUGANG AVE 9 #12-630
Postcode	530968
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : JEBSON TAN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	EUNOS NPP
Police Station Address	ROAD: 629 BEDOK RESERVOIR ROAD #01-1620 , POSTCODE: 470629 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT: T/20190306/2079.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLN2638G
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLN1505M
Vehicle Make/Model/Colour
Details Of Properties VEHICLE C
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SJN3881A
Vehicle Make/Model/Colour
Details Of Properties VEHICLE D
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SHA7116D
Vehicle Make/Model/Colour
Details Of Properties VEHICLE E
Vehicle Category TAXI
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name KEVIN TAN PENG KHIM
Approximate Age
Injuries Sustain
Injured person in which vehicle? SGK9001Y
Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name JEBSON TAN

Approximate Age

Injuries Sustain

Injured person in which vehicle? SGK9001Y

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan Pg. 1


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

x 
Policyholder's Signature
Date & Time:

x 
Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

ALPHA CATR

Sketch Plan #2 Pg. 1

SKETCH PLAN

Cornhill Circle
towards
Cornhill Rd




Vehicle A: SGK 9001 Y
Vehicle B: SCH 2638 G
Vehicle C: SCH 1505 M
Vehicle D: SHH 3881 A
Vehicle E: SHA 711 C D


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer To police Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

x 
Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190306/2079

1 of 4

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

Report No. T/20190306/2079

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/03/2019 13:55	Vide Report No.:	Station Diary No.: 27
--	------------------	--------------------------

Informant's Particulars

Name of Informant: KEVIN TAN PENG KHIM			Address: APT BLK 968 HOUGANG AVENUE 9 #12-630 SINGAPORE 530968		
ID Type / ID No.: NRIC NO / S7801118A			Contact No.: Home/Office: Mobile: 81611619		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 41	Date of Birth: 03/01/1978	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: SALES MANAGER			Driving Licence Information: Class: 3		
			Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 05/03/2019 14:00	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 CAIRNHILL CIRCLE CAIRNHILL ROAD Beside Cairnhill Crest Condo				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Chain Collision				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGK9001Y	Car	HONDA	FIT 1.3G A	Blue	Slightly Damaged	1
SHA7116D	Comfort Taxi	HYUNDAI		Blue	Slightly Damaged	1
SJU3881A	Car	TOYOTA	Wish	Black	Seriously Damaged	0
SLN1505M	Car	HONDA	HRV	Red	Slightly Damaged	0
SLN2638G	Car	MAZDA	6	Grey	Slightly Damaged	1



**SINGAPORE
POLICE FORCE**



T/20190306/2079

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

2 of 4

Report No. T/20190306/2079

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SGK9001Y	AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED	P10103208R00	25/10/2018	24/10/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	KEVIN TAN PENG KHIM		ID No.	S7801118A
Related Vehicle	SGK9001Y (Car)		Contact No.	81611619
Hospital/Clinic	W.P.SIM FAMILY CLINIC & SURGERY		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	05/03/2019		Date Discharge	05/03/2019
No. of Days granted Medical Leave	04		Degree of Injury	Slight
Driver				
Name	LIM SEAH HOR		ID No.	S16121087J
Related Vehicle	SHA7116D (Comfort Taxi)		Contact No.	91192007
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	ARTHUR LOW KIA WEI		ID No.	S1795380Z
Related Vehicle	SJU3881A (Car)		Contact No.	82828236
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL



**SINGAPORE
POLICE FORCE**



T/20190304/2160

3 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190304/2160

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

TP /
ZENG ZI CONG

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /
Staff Sgt MOHAMED HUSNUL TAUFIQ BIN MD
YUSOF

Contact No.: 65476358

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:

04/03/2019 19:48

Classification Of Case:



**SINGAPORE
POLICE FORCE**

Signature:

LETTER OF UNDERTAKING

I/We, Sin Sheng Huat Coffee Pte Ltd, the owner of vehicle no. SMF4930D

My/Our Insurance is under M/s AXA Insurance Pte Ltd, I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Pte Ltd with all relevant facts and documents **within 14(fourteen) days of occurrence or discovery of damage.**



My/Our Third Party claim is handle by my/our preferred workshop, Chew Motor Pte Ltd

Signed and Acknowledge by:


Whitaker
Nric no. & signature of policyholder


Company stamp

6/2/19
Date



Accident Sketch Plan Pg. 1



**Budget
Direct
insurance**

Certificate of Insurance

Comprehensive Car Policy
Policy Number: P10103208R00

Motor Vehicles (Third-Party Risks And Compensation) Act (Chapter 189) (Republic of Singapore), Motor Vehicles (Third-Party Risks And Compensation) Rules, 1996 Edition (Republic of Singapore), Road Transport Act, 1987 (Malaysia), Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

Certificate Number P10103208R00 (Comprehensive / Named Driver Plan)

1) Vehicle Registration Number	:	SGK9001Y
Chassis Number	:	GE61085915
2) Effective Date / Time of Commencement of Insurance for the Purpose of the Act	:	25/10/2018 (14:41)
3) Date / Time of Expiry of Insurance	:	24/10/2019 (23:59)
4) Excess (i) Policy	:	S\$ 1,000.00
(ii) Windscreen	:	S\$ 100.00
5) Policyholder	:	Kevin Tan Peng Khim
6) Persons or Classes of Persons Entitled to Drive*		
Drivers named as a Main / Named Driver in this Certificate of Insurance only.		
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by any reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of accident or loss. Please refer to the Product Disclosure Document for full terms and conditions.		
Main Driver / Date of Birth	:	Kevin Tan Peng Khim (03/01/1978)
Named Driver(s) / Date of Birth	:	Jebson Tan Khang Hwai (16/09/1976)
7) Limitation as to use*		
Use only for social, domestic and pleasure purposes. The Policy does not cover use for hire or reward, tuition or driving tests, racing, pace-making, reliability trials, speed-testing or the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.		
* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.		
8) Finance Company	:	Tokyo Century Leasing (Singapore) Pte Ltd

I / We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

Issued in Singapore on
25/10/2018

Auto & General Insurance (Singapore) Pte. Limited
Trading as Budget Direct Insurance



Simon Birch

...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Mar 2019		08 Mar 2019 15:04 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ETHOZ GROUP LTD , Co. Reg. No.: 198104531H								
Main Claimant:	KEVIN TAN PENG KHIM , ID: S7801118A								
Vehicle Reg. No.:	SGK9001Y	Date of Loss:	05/03/2019 14:00 - :59 [124 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1901226	Policy/Cover Note No.:	D19MTRENT000058 (Third Party Only)						
Vehicle Reg. No. (Insured):	SLN2638G	Policy No. (Claimant):							
		Excess:							
Repairer:	Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay, 417883 Kaki Bukit - Tel: 65098258								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 19/03/2019]								
Driver/Custodian (Insured):	CARNEGIE ALAN WYBROW (), NRIC: G5943276T, Tel: +6592315520 Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGK9001Y (CMTD1901226)
[SLN2638G]
TP
KEVIN TAN PENG KHIM
Mar 5 2019 2:00PM
[ETHOZ GROUP LTD]
Alpha Car Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On		Sompo Insurance Singapore Pte. Ltd. (HQ)							Thumbnail	Print	
1	08/03/19 15:04		Accident Statement From: SC - Reg. No: SLN2638G, Claimant: ETHOZ GROUP LTD							Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
2	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
3	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
4	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
5	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
6	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
7	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
8	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
9	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
10	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
11	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
12	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
13	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
14	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
15	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
16	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
17	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
18	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
19	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
20	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
21	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
22	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
23	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
24	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
25	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
26	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
27	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
28	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
29	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
30	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
31	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
32	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	
33	12/03/19 10:33		General View							Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
34	12/03/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
35	12/03/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
36	12/03/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
37	12/03/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
38	12/03/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
39	12/03/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
40	12/03/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
41	12/03/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
42	12/03/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
43	12/03/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
44	12/03/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
45	12/03/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
46	12/03/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
47	12/03/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
48	12/03/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
49	12/03/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
50	12/03/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
51	12/03/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
52	12/03/19 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
53	12/03/19 10:33	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
54	12/03/19 10:33	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
55	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	21/03/19 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
84	21/03/19 10:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
85	21/03/19 10:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
86	21/03/19 10:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
87	21/03/19 10:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
88	21/03/19 10:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
89	21/03/19 10:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
90	21/03/19 10:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
91	21/03/19 10:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
92	21/03/19 10:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
93	21/03/19 10:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
94	21/03/19 10:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
95	21/03/19 10:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
96	21/03/19 10:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
97	21/03/19 10:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
98	21/03/19 10:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
99	21/03/19 10:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
100	21/03/19 10:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
101	21/03/19 10:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
102	21/03/19 10:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
103	21/03/19 19:20	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
104	21/03/19 19:20	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
105	21/03/19 19:20	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
106	21/03/19 19:20	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
107	21/03/19 19:20	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
108	21/03/19 19:20	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
109	21/03/19 19:20	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
110	21/03/19 19:20	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
111	21/03/19 19:20	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
112	21/03/19 19:20	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
113	21/03/19 19:20	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	07/03/19 15:11	Third Party E-filed GIA report(M)	Load PDF	
2	08/03/19 11:25	PRI - No Consensus & pending workshop location	Load HTM	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19004311/GCD3E2

Date: 27/03/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTRENT000058
Claimant Vehicle No:	SGK9001Y	Insured Vehicle No:	SLN2638G
Date of Loss:	05/03/2019	Nature of Claim:	TP
		Claim No:	CMTD1901226

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGK9001Y	Engine No:	L13A4095612
Make & Model:	HONDA FIT, 1.3 (A)	Chassis No:	GE61085915
Reg. Date:	31/10/2008 (Man. Year: 2008)	Odometer:	129056 km
Colour:	Blue		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R14	Rear Tyre Size:	185/65 R14
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	08/03/2019	
Date Inspected:	11/03/2019 Inspected At:	Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay Singapore 417883
Estimated Period of Repair:	9.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000.00 - \$9,000.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Mar 2019)
Parts: 144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGK9001Y)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >