

Assoc. REP. DIV.

REF:

C8/CTI14004369 / ~~Ktd3~~ ^V

n2

Special Instructions

Surveyor

marcas

ASSIGNMENT (Office)

Member

From Person

Irene Tay

at

CTI

Date/Time

8/3/19 @ 5:25pm

Estimated Cost

Billed to

OD ^① / WS / TP RES / OD RES / EVA / INV / MV / CG

To Inspect Vehicle No

SCK 3131S

Insured

GBF 1967M

at Workshop info

Thurs Eurocar
5 ubi close

Tel

9127 7128

of

Policy No

DMCVSN 1808161800

Claim No

SNM19D201090C02

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A 5/3/19

CA / REV / REP / REV 24 HRS

1 up

12/3/2019 @ 3pm

H.O.D. Endorsement

Date/Time

11:17am 8/3/19

Person Contacted

Ronald

Vehicle

IN ^① OUT

Date/Time

Action/Instruction (✓) Estimate

SCK 3131S - X

GBF 1967M -

REF: C99

ASSIGNMENT

From: Date: 12/3/19

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: SCK 31315
at Workshop m/s: Trans Eurokars
of: 5 ubi close

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: 3pm (waiting)
Ronald

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: 2 Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SCK 31315 Yr Regn: 9.18

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Mazda CX-5 c.c. 1998

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 15211 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JM6KF2W7AK0229245

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / SRim / STD A/Rim or

Tyre Size: F: 225/65R17
R:BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 5/3/19 D.O.I. 12/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

25/7/19 Confirmed final by \$ 6196.00 with Catherine.
(Ked: 1740.87, 21%)

RECEIVED 26 JUL 2019

Date/Time: File Pass to?

☐ Prel. Report

Days Of Repair: 3

1) JSA Typist

☒ Final Report

Resurvey No. of Trip: 1

Date/Time: File Return to?

Survey Fee:

2)

Add Fee: ☐ Site Insp (\$)

Transportation:

☐ Interview (\$)

Photos

☐ Tech. Invs (\$)

Cibers

☐ Weekend (\$)

TOTAL

Report Format:

Lump Sum / I.B.I.: (\$ 6196.00)

110

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Authored	Status
Main	08 Mar 2019		08 Mar 2019 17:25 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:				
Main Claimant:	PEA GEOK HWA			
Vehicle Reg. No.:	SCK3131S	Date of Loss:	05/03/2019 16:00 - :59	
Claim Type:	TP / SNM19D201090C02	Policy/Cover Note No.:	DMCVSN1808161800	
Vehicle Reg. No. (Insured):	GBF1967M	Policy No. (Claimant):		
		Excess:	S\$350.00	
Repairer:	Trans Eurokars Pte Ltd (HQ) 5 Ubi Close, 408605 Ubi - Tel:			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/03/2019]			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Friday, 8 March 2019 5:20 PM
To: ronald.yap@eurokars.com.sg; 'assignments'
Subject: FW: ARANGE FOR SURVEY / YOUR REF: GBH1967M / OUR REF: SCK3131S (CLAIM REF: SNM19D201090C02/7)
Attachments: 1811_190308092707_001.pdf

WITHOUT PREJUDICE

Dear Ronald,

We refer to your email of 08.03.19.

Our insured have yet to report the accident to us.

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6224 7478 / 6224 7175
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com



From: Angie Foo
Sent: Friday, 8 March, 2019 2:20 PM
To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>
Subject: FW: ARANGE FOR SURVEY / YOUR REF: GBH1967M / OUR REF: SCK3131S -SNM19D201090

Dear Elaine/Irene,

PLEASE CONDUCT PRS ASAP –GBH1967M –SNM19D201090

Best Regards,

Angie Foo

Claims Executive

Claims Department – Motor Division

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6186

Fax (65) 6224 7175 / 6224 7478

Email: angie.foo@sg.cntaiping.com

Email: claimsdept@sg.cntaiping.com

Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Claims Dept of CTI

Sent: Friday, 8 March, 2019 2:07 PM

To: Angie Foo

Subject: FW: ARANGE FOR SURVEY / YOUR REF: GBH1967M / OUR REF: SCK3131S

From: ronald.yap@eurokars.com.sg [mailto:ronald.yap@eurokars.com.sg]

Sent: Friday, March 08, 2019 9:14 AM

To: Claims Dept of CTI

Cc: jess.francis@eurokars.com.sg

Subject: ARANGE FOR SURVEY / YOUR REF: GBH1967M / OUR REF: SCK3131S

Dear China Taiping,

As per subject / attached, let us have your appointed surveyor for arrangements.

Thank You,

Ronald Yap
Insurance Claims

Trans Eurokars Pte Ltd

5 Ubi Close, Singapore 408605
T: 6395 8899 H: 9127 7928
ronald.yap@eurokars.com.sg

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: mazdacanon@mazda.com.sg <transeurokars@eurokars.com.sg>

Sent: 08 March 2019 09:27

To: Ronald Yap <ronald.yap@eurokars.com.sg>

Subject: Attached Image

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3131G
Vehicle Details	
Vehicle No.:	SCK31315
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Mar 2019
Vehicle Make:	MAZDA
Vehicle Model:	CX-5 2.0 AT PREMIUM 2WD
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	PE31268907
Chassis No.:	JM6KF2W7AK0229245
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$27,823.00
Original Registration Date:	11 Sep 2018
First Registration Date:	11 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$30,953.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Sep 2028
PARF Rebate Amount:	\$23,214.00
Intended COE Rebate Details	
COE Expiry Date:	10 Sep 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$34,381.00
COE Rebate Amount:	\$32,637.00
Total Rebate Amount:	\$55,851.00

The information contained herein is correct as at 13 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/03/2019 13:27
Date Of Accident	05/03/2019 16:50
Exact Location Of Accident	BLK 614A WOODLANDS AVENUE 4 MSCP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCK3131S
Insured/Policyholder	
Name Of Registered Owner	PEA GEOK HWA
NRIC No	S1563131G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97313188
Alternative Phone No	OTHERS-97313188

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA CX5
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800108384
Cover Note Number	

Driver

Name of Driver	PEA GEOK HWA
NRIC No	S1563131G
Date Of Birth	22/07/1962
Occupation	INDOOR
Date Of Driving Pass	22/01/1980
Driving Experience	39 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97313188
Fax Number	
Contact Number	OTHERS-97313188
Email Address	NOEMAIL

Address	BLK 612 WOODLANDS AVENUE 4 #12-467
Postcode	730612
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	NANYANG N.P.C
Police Station Address	ROAD: 2 JURONG WEST AVE 5 , POSTCODE: 649482 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7929999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH1967M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 – 17:00
UEN: S65500200 / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:


Original Report No : MTE 119030456 Vehicle Registration No: SEA 3P31S
Name (as shown in NRIC) : PEA GEOK HWA NRIC/FIN/Passport No : S 15631316
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : BLK 612 WOODLANDS AVE 4 #12-467 Singapore (720617)
Contact (Tel) : 97313188 Mobile No.: _____
Email Address : NUGMAIL
Date of Accident : 05/03/2019 Time of Accident : 16:50
Place of Accident : BLK 614A Woodlands Ave 4 AISC
Insurance Company: AIG ASIA PACIFIC INSURANCE PTE LTD

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

I would like to attach video footage.

Policyholder / Driver's Signature
Date:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date:

Police Report

NOTICE OF COMPLIANCE

1. This is to confirm that PEA GEOK HWA (NRIC no: S1563131G) has reported to the police a traffic accident which occurred at Blk 614A WOODLANDS AVENUE 4 MULTISTORY CARPARK. On 05/03/2019 at around 1009hrs, drove my vehicle and parked at the multistory carpark Deck 1B lot 36. I noticed that there was a silver Cabstar lorry bearing registration number: GBH1967M parked on lot 37 beside my vehicle. My vehicle was still intact and normal at this point of time.
2. On the same day at 1650hrs, I went to collect my vehicle and noticed that there were scratch marks and cracks on the right side front bumper, and there was white paint stained onto the scratch mark area of my vehicle. I also noticed that the lorry was no longer parked there. Later that evening, I went back to the multistory carpark and tried to look for the lorry. I managed to find the lorry and discovered that the lorry had black paint rub onto the left side of the vehicle. I suspect that the lorry had collided against my parked vehicle when the driver was moving off.
3. I wish to state that I did not manage to contact the driver of the said lorry. There is no foreign vehicle involved. No one was injured in the incident. I am lodging this report for insurance claims.

Particulars of the drivers involved: -

A1) PEA GEOK HWA

S1563131G

VEHICLE NO.: SCK3131S (black Mazda CX5)


HP: 97313188

- 2 He has therefore complied with Sec 84(2) of the Road Traffic Act, Cap 276.

Date: 06/03/2019 Name of Issuing Officer: Sgt(2) Lim Ming Yan
e/S/D Ref: 45 Police Post/ Unit: Nanyang NPC

Original * to be issued to informant

Duplicate * to be retained at police post or unit



SKETCH PLAN


PLEASE SEE POLICE REPORT
- NO SKETCH AVAILABLE

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

PLEASE SEE POLICE REPORT

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20190306/2080

1 of 3

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

Report No. T/20190306/2080

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/03/2019 13:58	Vide Report No.:	Station Diary No.: 101
--	------------------	---------------------------

Informant's Particulars

Name of Informant: PEA GEOK HWA	Address: APT BLK 612 WOODLANDS AVENUE 4 #12-467 SINGAPORE 730612		
ID Type / ID No.: NRIC NO / S1563131G	Contact No.: Home/Office: Mobile: 97313188		
Nationality: SINGAPORE CITIZEN	Email:		
Sex: Male	Age: 56	Date of Birth: 22/07/1962	Type of Informant: Driver
Race: Chinese	Language: Chinese		Institution / School Name:
Occupation: SELF-EMPLOYED	Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 05/03/2019 16:50	Type of Location: Car Park
Location: Along Road 1 WOODLANDS AVENUE 4 BLK 614A WOODLANDS AVENUE 4 MULTISTORY CARPARK DECK 1B LOT 36				
Weather:		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBH1967M	Lorry				Slightly Damaged	0
SCK3131S	Car	MAZDA	CX-5 2.0 AT PREMIUM 2WD	Black	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



SINGAPORE POLICE FORCE



T/20190306/2080

2 of 3

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

Report No. T/20190306/2080

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SCK3131S	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1800108384	11/09/2018	10/09/2020

Details of Person Involved				
Any Pedestrian Involved: No			Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL				
Driver				
Name	PEA GEOK HWA		ID No.	S1563131G
Related Vehicle	SCK3131S (Car)		Contact No.	97313188
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	

Brief Details.

On 05/03/2019 at about 1009hrs, I parked my vehicle, a black Mazda CX5 bearing registration number: SCK3131S at Blk 614A Woodlands Avenue 4 Multistory Carpark Deck 1B Lot 36. I noticed that there was a white Cabstar lorry parked beside me at Lot 37 however I did not take note of the registration plate number. My vehicle was still intact and normal at this time.

On the same day at about 1650hrs, I went to my vehicle and discovered that there were scratch marks and dents on the right side of my front bumper. I also discovered white paint that had ran onto my vehicle. The lorry was no longer parked beside me, however I suspect that the scratches and dents were caused by the lorry. Later in the evening, I made a check at the multistory carpark and found the lorry. Upon further checks, I discovered that the lorry registration number was GBH1967M, and the lorry had scratch marks on the left side of the vehicle, and there were black paint that had ran onto the lorry.

I wish to state that I was unable to contact the driver of the said lorry. I also wish to state that there was no foreign vehicle involved and no injuries. I wish to further state that upon checks on my in-vehicle camera, I discovered that on 05/03/2019 at about 1508hrs, the said lorry had moved off from the parked position and made a left turn. Hence, I suspect that the left side of the vehicle collided against the right side of my front bumper.



**SINGAPORE
POLICE FORCE**



T/20190306/2080

3 of 3

Report No. T/20190306/2080

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

J /

Sgt 2 LIM MING YAN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / HRT /

Sr Staff Sgt ESTHER CHONG

Contact No.: 65476368

Authentication Stamp
NP108



Signature :

Singapore Police Force

SN-127

Signature Of Informant:

Date/Time:

06/03/2019 13:58

Classification Of Case:



TRANS EUROKARS PTE LTD

ESTIMATE COST OF REPAIRS

EUROKARS GROUP

CHINA TAIPING INSURANCE P/L		NAME : Mr Pea Geok Hwa		WIP : 45283	
3 ANSON ROAD		ADDRESS : Blk 612 Woodlands Avenue 4		EXCESS :	
#16-00 SPRINGLEAF TOWER		#12-467		DATE: 6-Mar-19	
SINGAPORE 079909		Singapore 730612			
ATTN : MOTOR CLAIMS		TEL : 97313188			
FAX :					
VEH NO :	SCK3131S	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6KF2W7AK0229245	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	CX5	DATE REG.:	11-Sep-18	POLICY NO.:	
NATURE OF WORKS					
Parts Description					
NO	QTY		REVISED	PRICES	
1	FRONT BUMPER	1	MKB8B-50-031EBB	re/wor	974.30
2	FOAM, FRONT REINFORCEMENT	1	MKB7W-50-111	11	\$ x 45.50
3	FASTENER, FOAM	2	MFD01-68-AC3	11	\$ x 11.80
4	RETAINER SIDE, SENSOR	1	MKD47-67-UCSA51	rec	\$ - 17.30
5	SENSOR SIDE, ULTRASONIC	1	MKD47-67-UC1 51	shrd	\$ - 193.90
6	PAD PROTECTOR, SENSOR	3	MG001-67-061	11	\$ 22.20
7	CLIP, FRONT BUMPER	15	MC274-50-133	rec	\$ - 52.50
8	FASTENER, FRONT BUMPER	5	MB45A-56-146A	rec	\$ - 14.00
9	RIVET, FRONT BUMPER	8	MTK21-50-355	rec	\$ - 69.60
10	RIVET, FRONT BUMPER	14	MS51S-51-833	rec	\$ - 53.20
11	FRONT GRILLE ASSY	1	MKB8B-50-710J	11	\$ 1,020.00
12	PIN LOCATOR, FRONT GRILLE	2	MKD45-50-1K5A	11	\$ 5.40
13	GROMMET, FRONT GRILLE	2	MKD45-50-ES1	11	\$ 5.40
14	FASTENER, FRONT GRILLE	8	MGD7A-50-EA1	11	\$ 24.00
15	HEADLAMP RHS	1	MKB9J-51-031F	sc	\$ 3,393.00
16	RIVET, HEADLAMP	1	MB092-51-833	rec	\$ 3.30
17	CLIP, HEADLAMP	2	MDR61-50-133	rec	\$ 12.20
18	FASTENER, WHEEL ARCH	9	MKB8A-51-W24A	rec	\$ 31.50
19	FASTENER, WHEEL ARCH	4	MKB8B-51-W24A	rec	\$ 14.00
20	FASTENER, WHEEL ARCH	4	MB45A-56-146A	rec	\$ 11.20
TOTAL PARTS				\$ 5,974.30	
LESS 10%				\$ 597.43	
TOTAL PARTS COST				\$ 5,376.87	
Labour Description					
1	MZ-BR-FRONT1	TO REPLACE FRONT BUMPER. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 630.00

2	MZ-SP-SFRT01	TO RESPRAY FRONT BUMPER.	✓	\$ 600.00
3	MZ-BR-FRTSEN	TO TRANSFER FRONT PEDESTRIAN SENSORS.	✓	NETT \$ 180.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	11 X	\$ 250.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	200	\$ 350.00
7		TO SUPPLY BRILA PREMIUM COATING.	100	NETT \$ 200.00
8	MZ-BR-SUNDRI	SUNDRIES.	net 10	NETT \$ 100.00

TOTAL LABOUR	\$ -	\$ 2,560.00
TOTAL PARTS	\$ -	\$ 5,376.87
TOTAL	\$ -	\$ 7,936.87
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

 Authorised Signature

LKK Auto Consultants hereby notify the Receiver of the following:

- To ensure satisfaction upon painting
- To ensure damaged parts being replaced
- Parts price is subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No direct cash payment is allowed
- Supplementary work(s) must be accepted and is subject to final approval from Insurance Company

Acknowledged by Receiver:

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119004369/UTD3N2

Date: 30/07/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1808161800	
Claimant Vehicle No :	SCK3131S	Insured Vehicle No :	GBF1967M	
Date of Loss:	05/03/2019	Nature of Claim:	TP	Claim No: SNM19D201090C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCK3131S	Engine No:	PE31268907
Make & Model:	MAZDA CX-5, 2.0 (A)	Chassis No:	JM6KF2W7AK0229245
Reg. Date:	11/09/2018 (Man. Year: 2018)	Odometer:	15211 km
Colour:	Black		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,476.87	4,366.00	1,110.87	20.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	1,830.00	630.00	25.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,936.87	6,196.00	1,740.87	21.93
+ GST 7.00/7.00% (S\$)	555.58	433.72	121.86	21.93
Nett Amount (S\$)	8,492.45	6,629.72	1,862.73	21.93

INSPECTION

Date of Assignment:	08/03/2019	Inspected At:	Trans Eurokars Pte Ltd (HQ)
Date Inspected:	12/03/2019		5 Ubi Close
			Singapore 408605
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Jul 2019)
Parts:	M1-SUV	MAZDA CX-5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCK3131S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Warped	974.30 FL	*974.30 FL
2	1		*FOAM, FRONT REINFORCEMENT	Not Necessary	45.50 FL	*- FL
3	2		*FASTENER, FOAM	Not Necessary	11.80 FL	*- FL
4	1		*RETAINER SIDE, SENSOR	Necessary	17.30 FL	*17.30 FL
5	1		*SENSOR SIDE, ULTRASONIC	Shorted	193.90 FL	*193.90 FL
6	3		*PAD PROTECTOR, SENSOR	Not Necessary	22.20 FL	*- FL
7	15		*CLIP, FRONT BUMPER	Necessary	52.50 FL	*52.50 FL
8	5		*FASTENER, FRONT BUMPER	Necessary	14.00 FL	*14.00 FL
9	8		*RIVET, FRONT BUMPER	Necessary	69.60 FL	*69.60 FL
10	14		*RIVETS, FRONT BUMPER	Necessary	53.20 FL	*53.20 FL
11	1		*FRONT GRILLE ASSY	Not Necessary	1,020.00 FL	*- FL
12	2		*PIN LOCATOR, FRONT GRILLE	Not Necessary	5.40 FL	*- FL
13	2		*GROMMET, FRONT GRILLE	Not Necessary	5.40 FL	*- FL
14	8		*FASTENER, FRONT GRILLE	Not Necessary	24.00 FL	*- FL
15	1		*HEADLAMP RHS	Scratched	3,393.00 FL	*3,393.00 FL
16	1		*RIVET, HEADLAMP	Necessary	3.30 FL	*3.30 FL
17	2		*CLIP, HEADLAMP	Necessary	12.20 FL	*12.20 FL
18	9		*FASTENER, WHEEL ARCH	Necessary	31.50 FL	*31.50 FL
19	4		*FASTENER, WHEEL ARCH	Necessary	14.00 FL	*14.00 FL
20	4		*FASTENER, WHEEL ARCH	Necessary	11.20 FL	*11.20 FL
21	1		*SUNDRIES	Necessary	100.00 FS	*10.00 FS

F=Franchise part. S=SpchNett. L=ListItemDisc.

Sub Total (\$\$)	6,074.30	4,850.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	597.43	484.00
Total Parts (\$\$)	5,476.87	4,366.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	New	630.00	630.00
2	TO SPRAY FRONT BUMPER.	New	600.00	600.00
3	TO TRANSFER FRONT PEDESTRIAN SENSORS.	New	180.00	180.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION.	New	250.00	0.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	New	250.00	120.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	New	350.00	200.00
7	TO SUPPLY BRILA PREMIUM COATING.	New	200.00	100.00
Gross Labour Cost (\$\$)			2,460.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >