

ASS. REC. BY:

REF:

CS3/PWD19004392/Gcd3

Special Instruction:

SURVAJOY

90

ASSIGNMENT (Office)

From (Person): Clara Li

of FWD

Date/Time: 11 March 2019 1:18PM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJA 8412J

Insured: SLD 6451 D

at Workshop m/s: Eco Automobile

Tel: 91765733

of 13 Kaki Bukit Road 4 # 03-29

Policy No: PNP2018-00008028

Claim No: 1201900006492

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A. 8 March 2019

CA / REV / REP. / REV 24 HRS (WP)

I.O.D. Endorsement:

Date/Time: 31 Spring 11/3/19

Person Contacted:

Alie

Vehicle  IN  OUT

Date/Time	Action/Instruction ( X ) Estimate
	<u>SJA 8412J - X</u>
	<u>SLD 6451 D - X</u>
	<u>Dismantle: 13/3/2019</u>
	<u>After repair: 15/3/2019</u>

CHY2100

PRS  
GA

REF:

C2194R

ASSIGNMENT

(-2019)


28 May 2009

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s Eco  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SIA 8412J Yr Regn: 28 May 2009  
 Type:  M.Cab / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Tajda v10s c.c. 1497  
 Colour: Silver A/C: Insured / Std / NI / NA  
 Sp. Reading: 184043 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: MR053HY9305113744  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  Inoper / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake:  Inoper / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi:  Nil / S/Rim / STD / R/Rim or \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$10k  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 3 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Tyre Size: F: 185/60R15  
 R: 11  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. _____	D.O.I. <u>11-03-19</u>
Survey held at <u>w/s</u>	<u>5pm</u>
Des. of Damages: Frt / <input checked="" type="radio"/> Rear / O/S / N/S / U/C / Rooftop or _____	

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>\$2000 - \$2000</u>

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

Days Of Repair: 3  
 Resurvey No. of Trip: 2

Date/Time, File Return to?  
 1) \_\_\_\_\_  
 2) \_\_\_\_\_

Add Fee:  : Site Insp (\$ )  
 : Interview (\$ )  
 : Tech. Invs (\$ )  
 : Weekend (\$ )

Report Format: PRE  
 Lump Sum / I.B.I: (\$ )

Survey Fee:	
Transportation:	
\$ + RS: \$	
Photos	
Others	
TOTAL	

## Nivitha (LKK Auto)

---

**From:** clara.li@fwd.com  
**Sent:** Monday, 11 March 2019 1:18 PM  
**To:** wengkit@chiaarul.com  
**Cc:** jerone@chiaarul.com; motorclaims.sg@fwd.com; assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com  
**Subject:** RE: Our Ref: SJQ 8412J (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SJQ 8412J & SLD 6451D [FWD] ALONG PASIR RIS DRIVE 1 ON 8 MARCH 2019  
**Attachments:** 20190311110411719.pdf

Hi LKK team,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen.

Thank you.

Kind Regards

Clara Li  
Senior Executive, Claims

FWD Singapore Pte. Ltd.  
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722  
E clara.li@fwd.com  
W fwd.com.sg

**FWD**  
insurance



---

**From:** Weng Kit [mailto:wengkit@chiaarul.com]  
**Sent:** Monday, 11 March, 2019 11:24 AM  
**To:** Motor Claims SG - SG Common  
**Cc:** jerone@chiaarul.com; Clara Li Zirong - SGUser  
**Subject:** RE: Our Ref: SJQ 8412J (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SJQ 8412J & SLD 6451D [FWD] ALONG PASIR RIS DRIVE 1 ON 8 MARCH 2019

Dear Sirs,

We refer to your email below.

Our client is not agreeable to your list of motor surveyors.

We are instructed by our client to propose the list of their surveyor as the mutual surveyor / single joint expert for your consideration as follows:

<u>Surveyor</u>	<u>Surveyor Firm</u>
S. Kumanan	SK Auto Consultants

Best Regards,

**Weng Kit (Mr.)**

Paralegal

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

---

**From:** [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com) [<mailto:motorclaims.sg@fwd.com>]

**Sent:** Monday, March 11, 2019 11:09 AM

**To:** [wengkit@chiaarul.com](mailto:wengkit@chiaarul.com)

**Cc:** [jerone@chiaarul.com](mailto:jerone@chiaarul.com); [clara.li@fwd.com](mailto:clara.li@fwd.com)

**Subject:** RE: Our Ref: SJQ 8412J (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SJQ 8412J & SLD 6451D [FWD] ALONG PASIR RIS DRIVE 1 ON 8 MARCH 2019

**Without Prejudice**

Dear Sir/Madam,

Please select one of our surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. APPRAISALS ASSOCIATES PTE LTD
5. VICOM LTD

If you are not agreeable to any of the above, we would proceed to appoint a surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We look forward to your reply.

Thank you.

Lionel

**From:** Weng Kit [mailto:wengkit@chiaarul.com]

**Sent:** Monday, March 11, 2019 11:06 AM

**To:** Motor Claims SG - SG Common

**Cc:** 'Jerone'

**Subject:** Our Ref: SJQ 8412J (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SJQ 8412J & SLD 6451D ALONG PASIR RIS DRIVE 1 ON 8 MARCH 2019

Dear Sirs,

We refer to the above matter.

Attached is a copy of our pre-repair survey notice dated 11 March 2019 for your attention.

Best Regards,

**Weng Kit (Mr.)**

Paralegal

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

**CHIA S ARUL LLC**  
ADVOCATES & SOLICITORS  
UEN 201330709H

ARULCHELVAN S • A. RAVIDASS

Our Ref : SJQ 8412J (wk)

Your Ref : To be advised

11 March 2019

FWD Singapore Pte. Ltd.

BY EMAIL

Dear Sirs,

**RE: PROPERTY DAMAGE CLAIM**  
**CLAIMANT : MFC ALLIANCE PTE LTD**  
**ACCIDENT INVOLVING SJQ 8412J & SLD 6451D ALONG PASIR RIS DRIVE 1**  
**ON 8 MARCH 2019**  
**PRE-REPAIR SURVEY NOTICE**

1. We act for MFC Alliance Pte Ltd, the owner of motor vehicle no. SJQ 8412J which was involved in the aforesaid accident.
2. We hereby in compliance with the Pre-Action Protocol for Non-Injury Motor Accident Claims, Appendix C of the State Courts Practice Directions Amendment No. 1 of 2016 ("the NIMA Protocol") give you **NOTICE** that we are claiming against your insured motor vehicle no. SLD 6451D for damages, costs and disbursements as a result of your insured driver's negligence.
3. Please let us know if you wish to conduct a pre-repair survey on our client's motor vehicle at:

Workshop	ECO Automobile Claims and Repair Pte Ltd
Address	13 Kaki Bukit Road 4 #03 - 29 Bartley Biz Centre Singapore 417807
Contact Person	Mr. Alfie (9176 5733)

4. Pursuant to paragraph 2.3 of the NIMA Protocol, in the event we do not receive your response within next **two (2) working days** (excluding any Saturday, Sunday or public holiday), our client will instruct the workshop to commence appraisal and repairs to the damaged motor vehicle without further reference to you.
5. Please advise the appointed surveyor to endorse on page 2 of this letter after the completion of each inspection.

Yours faithfully,

**MR ARULCHELVAN S**  
cc: Client (By Email)

151 CHIN SWEE ROAD • #03-09  
MANHATTAN HOUSE • SINGAPORE 169876  
TEL : (65) 6733 4647 • FAX : (65) 6733 8183 (not for Service of Court documents)  
EMAIL : info@chiaarul.com

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIAs Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/03/2019 13:19
Date Of Accident	08/03/2019 19:30
Exact Location Of Accident	ALONG PASIR RIS DRIVE 1
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJQ8412J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MFC ALLIANCE PTE. LTD.
Co Reg No	200412194R
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84889228
Alternative Phone No	OFFICE-84889228

### Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS G AUTO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5104046527
Cover Note Number	

### Driver


Name of Driver	LIM BOON POH
NRIC No	S1378259H
Date Of Birth	18/12/1959
Occupation	OUTDOOR
Date Of Driving Pass	10/06/1977
Driving Experience	41 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96883942
Fax Number	
Contact Number	
E Mail Address	NOEMAIL

Sketch Plan Pg. 1

SKETCH PLAN

Vehicle A = SJQ842J

Vehicle B = SLD6451D



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 8/3/19 at about 1930, I was stationary at a red traffic light along Pasir Ris Drive 1 when Vehicle B, SLD6451D suddenly hit in to the rear portion of my vehicle, Vehicle A, SJQ842J.

DECLARATION

I declare that the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

*[Handwritten signature]*

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

*[Handwritten signature]*

11 MAR 2019

IDAC KAKI BUKIT(VAC)  
23 KAKI BUKIT AVE 4

Reporting Centre Singapore 415633  
Name Tel: 67416697  
NRIC/FIN No: Fax: 67492305  
Email: vackb@singnet.com.sg

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2194R
Vehicle Details	
Vehicle No.:	SJQ8412J
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS G AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	1NZX911379
Chassis No.:	MR053HY9305113744
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$13,876.00
Original Registration Date:	28 May 2009
First Registration Date:	28 May 2009
Transfer Count:	1
Actual ARF Paid:	\$13,876.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 May 2019
PARF Rebate Amount:	\$6,938.00
Intended COE Rebate Details	
COE Expiry Date:	27 May 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$7,090.00
COE Rebate Amount:	\$146.00
<b>Total Rebate Amount:</b>	<b>\$7,084.00</b>

The information contained herein is correct as at 12 Mar 2019

OK

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Mar 2019 <a href="#">Edit Reg</a>		11 Mar 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	<b>Gan Yick Beng</b> , ID: S7003061F		
Main Claimant:	<b>MFC ALLIANCE PTE. LTD.</b> , Co. Reg. No.: 200412194R		
Vehicle Reg. No.:	<b>SJQ8412J</b>	Date of Loss:	08/03/2019 00:00 - :59 [117 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / 1201900006492</b>	Policy/Cover Note No.:	PNPV2018-00008028 (Comprehensive)
Vehicle Reg. No. (Insured):	<b>SLD6451D</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Eco Automobile Claims And Repair Pte Ltd (HQ)</b> 13 KAKI BUKIT ROAD 4, #03-29, 417807 Kaki Bukit - Tel:		
Handling Insurer:	<b>FWD Singapore Pte. Ltd. (HQ)</b> - Tel: 6727 5700 ... [Handled by <b>Clara Li Zi Rong</b> ]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 20/03/2019]		

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SJQ8412J (1201900006492)**  
[SLD6451D]

TP  
**MFC ALLIANCE PTE. LTD.**  
Mar 8 2019 12:00AM  
[Gan Yick Beng]

**Eco Automobile Claims And Repair Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			View	View in Browser ▼
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	12/03/19 10:37	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
2	12/03/19 10:37	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
3	12/03/19 10:37	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
4	12/03/19 10:37	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
5	12/03/19 10:37	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
6	12/03/19 10:37	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
7	12/03/19 10:37	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
8	12/03/19 10:37	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
9	12/03/19 10:37	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
10	12/03/19 10:37	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
11	12/03/19 10:37	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
12	12/03/19 10:37	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
13	12/03/19 10:37	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
14	12/03/19 10:37	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
15	12/03/19 10:38	<b>Odometer Reading</b>		Load JPG <input checked="" type="checkbox"/>
16	12/03/19 10:38	<b>Chassis Number</b>		Load JPG <input checked="" type="checkbox"/>
17	18/03/19 10:34	<b>Dismantled Parts</b>		Load JPG <input checked="" type="checkbox"/>
18	18/03/19 10:34	<b>Dismantled Parts</b>		Load JPG <input checked="" type="checkbox"/>
19	18/03/19 10:34	<b>Dismantled Parts</b>		Load JPG <input checked="" type="checkbox"/>
20	18/03/19 10:34	<b>Dismantled Parts</b>		Load JPG <input checked="" type="checkbox"/>
21	18/03/19 10:34	<b>Dismantled Parts</b>		Load JPG <input checked="" type="checkbox"/>
22	18/03/19 10:34	<b>Dismantled Parts</b>		Load JPG <input checked="" type="checkbox"/>
23	18/03/19 10:34	<b>Dismantled Parts</b>		Load JPG <input checked="" type="checkbox"/>
24	18/03/19 10:34	<b>Dismantled Parts</b>		Load JPG <input checked="" type="checkbox"/>
25	18/03/19 10:34	<b>Dismantled Parts</b>		Load JPG <input checked="" type="checkbox"/>
26	18/03/19 10:34	<b>Dismantled Parts</b>		Load JPG <input checked="" type="checkbox"/>
27	18/03/19 10:34	<b>Dismantled Parts</b>		Load JPG <input checked="" type="checkbox"/>
28	18/03/19 10:34	<b>Dismantled Parts</b>		Load JPG <input checked="" type="checkbox"/>
29	18/03/19 10:34	<b>Dismantled Parts</b>		Load JPG <input checked="" type="checkbox"/>
30	18/03/19 10:34	<b>Dismantled Parts</b>		Load JPG <input checked="" type="checkbox"/>
31	18/03/19 10:34	<b>Dismantled Parts</b>		Load JPG <input checked="" type="checkbox"/>
32	18/03/19 10:34	<b>Dismantled Parts</b>		Load JPG <input checked="" type="checkbox"/>
33	18/03/19 10:34	<b>Dismantled Parts</b>		Load JPG <input checked="" type="checkbox"/>
34	18/03/19 10:34	<b>Dismantled Parts</b>		Load JPG <input checked="" type="checkbox"/>
35	18/03/19 10:34	<b>Dismantled Parts</b>		Load JPG <input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	18/03/19 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	18/03/19 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
38	18/03/19 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	18/03/19 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	18/03/19 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	18/03/19 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	18/03/19 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	18/03/19 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	18/03/19 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	18/03/19 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	18/03/19 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	18/03/19 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	18/03/19 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	18/03/19 10:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	18/03/19 10:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	18/03/19 10:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	18/03/19 10:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	18/03/19 10:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	18/03/19 10:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	18/03/19 10:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	18/03/19 10:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	18/03/19 10:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	18/03/19 10:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	18/03/19 10:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	18/03/19 10:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	18/03/19 10:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	18/03/19 10:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:  Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD19004392/GCD3S2  
Date: 02/04/2019

## REFERENCE

Handling Insurer:	FWD Singapore Pte. Ltd.	Policy No:	PNPV2018-00008028
Claimant Vehicle No :	SJQ8412J	Insured Vehicle No :	SLD6451D
Date of Loss:	08/03/2019	Nature of Claim:	TP
		Claim No:	1201900006492

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	<b>SJQ8412J</b>	Engine No:	1NZX911379
Make & Model:	TOYOTA VIOS, 1.5 (A)	Chassis No:	MR053HY9305113744
Reg. Date:	28/05/2009 (Man. Year: 2009)	Odometer:	184043 km
Colour:	Silver		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment:	11/03/2019	
Date Inspected:	11/03/2019	Inspected At: Eco Automobile Claims And Repair Pte Ltd (HQ) 13 KAKI BUKIT ROAD 4, #03-29 Singapore 417807
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 02 Apr 2019)

**Parts:** 143      TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SJQ8412J)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >