

REF:

08/11/9004395/0303/12

Special instruction:

Survival

Marcus

ASSIGNMENT (Office)

From (Person)

Gabriel Wee

of



Date/Time: 11/3/19 2:35pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8K4 434R

Insured:

SHC 8493Y

at Workshop m/s

Polymath Garude

Tel:

8228 9818

of

11caki Bkt Ave 6 # 02-02

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/02/2019

CA / REV / REP. / REV 24 HRS

12/3/17 @ office 12pm

Date/Time:

4:02pm @ 11/3/12

Person Contacted:

Sebastian

H.O.D. Endorsement:

Vehicle-IN/OUT

| Date/Time | Action/Instruction (✓) Estimate |
|-----------|-------------------------------------|
| | SKY 4342-x |
| | SHC 8493Y-cc3 / III 18019928 / Kob3 |
| | DATA: 18/10/2018 |

Surveyor **Marius**

REF: **III**

ASSIGNMENT

From: _____ Date: **12/3/2019**

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspection Vehicle No: **SKU 434R**
at Workshop m/s **Polymath Garage**
of **1 Kaki Bkt Ave 6 # 02-02**

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

After 12pm

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

| | |
|-----|-----|
| N/S | O/S |
| | |

Bal. or Market Value: **56k.**

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **4** days Res.: Yes or No

Lum Sum: **20** % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 48254

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: **SKU 434R** Yr Regn: **6, 15**

Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**

Truck / Trailer or **LA /**

Make: **Honda** **verel** c.c **1496**

Colour: **Black** A/C: Insured / Std / NI / NA

Sp. Reading: **122219** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **RU11020630**

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: **Inorder** / Jammed / Leaked / Burnt or

Brake: **Inorder** / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: **F: 215 / 60 R16**

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. **6** mm

L/Bal. **6** mm

D.O.A. **27/2/19**

Survey held at _____

Rear

R/Bal. **6** mm

L/Bal. **6** mm

D.O.I. **12/3/19**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

015 R/L, 015 B/L
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

nett 7746

20/3/19 4/5 @ 6100 confirmed with rider
(\$ 10,821.20 Red - 64%)

RECEIVED 25 MAR 2019

Date/Time, File Pass to?

25/02/19

1) **Ty 4**

Date/Time, File Return to?

2) _____

☐

: Preli. Report

☒

: Final Report

Days Of Repair: **4**

Resurvey No. of Trip: **2**

Survey Fee: **150**

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Report Format :

Lump Sum / I.B.I.: (\$ **6,100/- HS**)

| |
|------------|
| 150 |
| |
| 10 |
| |
| 150 |

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 11 March 2019 2:35 PM
To: Ruby Ong; 'sur@lkkauto.com'; admin-d@lkkauto.com
Cc: Polymath Garage Pte Ltd; Sundari Nagarajan - III
Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKU 434R [OUR REF. TCL.GCN.RO.50147.19.pg]

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SKU434R and let us have your report urgently.

This claim will be handled by Ms Sundari.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Ruby Ong [mailto:ruby@htapartners.com.sg]
Sent: 11 March, 2019 11:17 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: Polymath Garage Pte Ltd <enquiry@polymathgarage.com.sg>
Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKU 434R [OUR REF. TCL.GCN.RO.50147.19.pg]
Importance: High

WITHOUT PREJUDICE

URGENT

Dear Sir

We refer to your email of even date.

Our client is agreeable to appoint Marcus of LKK Auto Consultants Pte Ltd as the single joint expert to carry out the pre-repair survey for SKU 434R.

Please make the necessary arrangements with the contact person. The details are as follows :

Venue : **POLYMATH GARAGE PTE LTD**
1 Kaki Bukit Avenue 6
#02-02 Autobay

Singapore 417883

Contact Person : **Mr Nigel Ong / Mr Sebastian Huang @ 8228 9818**

In the event that the pre-repair survey was not conducted during the prescribed time or already conducted at your end previously, we reserve our client's right to claim for compensation for loss of use for your current request for re-survey.

Best regards,
Ruby Ong
Secretary
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext 278

Fax : 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

From: Motor Claim - III <motorclaim@iii.com.sg>

Sent: Monday, March 11, 2019 10:31 AM

To: Ruby Ong <ruby@htapartners.com.sg>

Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKU 434R [OUR REF. TCL.GCN.RO.50147.19.pg]

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

From: Ruby Ong [<mailto:ruby@htapartners.com.sg>]

Sent: 11 March, 2019 9:31 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKU 434R [OUR REF. TCL.GCN.RO.50147.19.pg]

Importance: High

Your ref: SHC 8493Y

WITHOUT PREJUDICE

Our ref: TCL.GCN.ro.50147.19.pg

11 March 2019

URGENT

India International Insurance Pte Ltd

By Email only

64 Cecil Street

#04-00 IOB Building

Singapore 049711

Attn: Motor Claims Dept

Dear Sirs

CLAIMANT: HENG AIK YANG

NOTICE OF ACCIDENT AND PRE-REPAIR SURVEY - ACCIDENT INVOLVING SKU 434R & SHC 8493Y ALONG CECIL STREET NEAR MARKET STREET ON 27 FEBRUARY 2019 @ 2255HRS

We are instructed by Heng Aik Yang to notify you of a road traffic accident on 27 February 2019 at about 2255hrs along Cecil Street near Market Street involving our client's vehicle registration number SKU 434R and vehicle registration number SHC 8493Y driven by your insured at the material time.

As a result of the accident, our clients' vehicle has been damaged. Before our clients proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,

Ruby Ong

Secretary

M/s Hin Tat Augustine & Partners

20 Upper Circular Road

#02-10/12 The Riverwalk

Singapore 058416

Tel : 6533 0212 ext 278

Fax : 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby

notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

| | |
|-------------------------------------|--------------------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 6400D |
| Vehicle Details | |
| Vehicle No.: | SKU434R |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 12 Mar 2019 |
| Vehicle Make: | HONDA |
| Vehicle Model: | VEZEL 1.5X A |
| Primary Colour: | Black |
| Manufacturing Year: | 2015 |
| Engine No.: | L15B3520644 |
| Chassis No.: | RU11020630 |
| Maximum Power Output: | 96.0 kW (128 bhp) |
| Open Market Value: | \$18,454.00 |
| Original Registration Date: | 29 Jun 2015 |
| First Registration Date: | 29 Jun 2015 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$8,454.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 28 Jun 2025 |
| PARF Rebate Amount: | \$6,340.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 28 Jun 2025 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$66,590.00 |
| COE Rebate Amount: | \$41,914.00 |
| Total Rebate Amount: | \$48,254.00 |

The information contained herein is correct as at 12 Mar 2019

OK



ANNOUNCING Cosmo Automobiles

as sgCarMart Premium Dealer for the 4th Consecutive Year

C O S M O
AUTOMOBILES

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Classic Promo! Best Deal! Fast Selling! Hurry Down Now!



Flexible Loan, Trade In Available
Welcome, 100% Deposit Refund
For Unapproved Loan
Classic Credit Start!

PRIME MOTOR & LEASING
(CHENG YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES)
With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category ▼

Sort by Date Posted ▼

40 results/page ▼

14 vehicles

Honda Vezel

Advanced Search

| Make | Model | Price | Depreciation | Reg Date | Eng Cap | Mileage | Veh Type | Status |
|--|---|-----------------|--------------------|--------------------|-----------------|------------------|------------|------------------|
| Search Selection | Honda Vezel | Any | Any | 2015 | Any | Any | Any | Available |
|  | Honda Vezel 1.5A X | \$61,000 | \$8,580 /yr | 07-Oct-2015 | 1,496 cc | 93,000 km | SUV | Available |
| All Servicing Just Done On 06/3/19, Stock Rims And Stock Exhaust Available, Viewing Strictly By Appointment, Well Maintained And Serviced Regularly, All Receipts Of Servicing Kept, Accident Free Vehic... | | | | | | | | |
| Posted: 09-Mar-2019 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda | | | | | | | | |
|  | Honda Vezel 1.5A X | \$63,800 | \$8,760 /yr | 30-Nov-2015 | 1,496 cc | 53,000 km | SUV | Available |
| 1 Owner, Non Pte Hire Unit, Servicing Record Available, Safe Buy, One Of The Most Popular SUV, Loan Package Available, Call Or SMS For Viewing. | | | | | | | | |
| Posted: 09-Mar-2019 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda | | | | | | | | |
|  | Honda Vezel Hybrid 1.5A Z | \$62,800 | \$9,290 /yr | 05-Sep-2015 | 1,496 cc | 74,016 km | SUV | Available |
| Fuel Type: Petrol-Electric Highest Specs "Z" Model Vezel 1.5A Hybrid! Confirm Non-Grab/Gojek/Leasing Car! All Maintenance Done With Receipts! Genuine Low Mileage Done 74016km. New Tyres/Paintwork. 100% Accident Free. Call Now! | | | | | | | | |
| Lake View Credit Pte Ltd | | | | | | | | |
| Posted: 09-Mar-2019 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda | | | | | | | | |
|  | Honda Vezel 1.5A X | \$62,800 | \$8,700 /yr | 13-Nov-2015 | 1,496 cc | 40,700 km | SUV | Available |
| 100% Loan Available. Well Maintained Exterior And Interior, Vehicle In Showroom Condition, Grooming Done By Professional Groomer, Bank Loan/In-house Loan Available, Trade In Welcome. Call Our Senior C... | | | | | | | | |
| Posted: 09-Mar-2019 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda | | | | | | | | |
|  | Uber's fire-prone Honda Vezels fixed | | | | | | | |
| All of Uber's 1,220 faulty Honda Vezels have been recalled and have had their fire-prone parts replaced, according to the Land Transport Authority. | | | | | | | | |
| Read this article | | | | | | | | |
|  | Honda Vezel 1.5A X | \$58,800 | \$8,230 /yr | 15-Oct-2015 | 1,496 cc | 43,000 km | SUV | Available |
| Single Owner Unit With Really Low Mileage Done! This Vezel Has Been Religiously Maintained Both Interior And Exterior. Engine Is Ridiculously Smooth Due To Proper Maintenance Of Vehicle. Previous Own... | | | | | | | | |
| Posted: 08-Mar-2019 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda | | | | | | | | |
|  | Honda Vezel 1.5A X | \$63,800 | \$9,110 /yr | 02-Oct-2015 | 1,496 cc | 53,000 km | SUV | Available |
| Enjoy As Low As 2.18% Interest Rate When You Purchase The Car Now! Road Tax Till October 2019! Well Maintained And Serviced Regularly, 1 Owner, Accident Free! One Of The Most Popular Honda Vezel! Vehi... | | | | | | | | |
| Euro Performance Asia Pte Ltd | | | | | | | | |
| Posted: 04-Mar-2019 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda | | | | | | | | |
|  | Honda Vezel 1.5A X | \$60,888 | \$8,860 /yr | 13-Aug-2015 | 1,496 cc | 24,663 km | SUV | Available |
| Meticulously Cared By Lady Owner, Brand New Condition, 2 Digit Bidded Number To Retain By Owner Or To Be Discussed, Can't Go Wrong Silver Exterior With Black Interior, Regular Servicing Before Service... | | | | | | | | |
| Posted: 03-Mar-2019 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda | | | | | | | | |

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|-----------------------------------|
| Date Of Report | 28/02/2019 09:34 |
| Date Of Accident | 27/02/2019 22:55 |
| Exact Location Of Accident | ALONG CECIL ST NEAR MARKET STREET |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|-----------------------|
| Vehicle Registration Number | SKU434R |
| Insured/Policyholder | |
| Name Of Registered Owner | HENG AIK YANG |
| NRIC No | S1206400D |
| Email Address | AYHENG@SINGNET.COM.SG |
| Mobile Phone No | (LOCAL) +65-96788719 |
| Alternative Phone No | OFFICE-96788719 |

Vehicle Particulars

| | |
|--------------|--------------|
| Manufacturer | HONDA |
| Model | VEZEL 1.5X A |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

| | |
|---------------------------|-----------------------|
| Name of Insurance Company | AXA INSURANCE PTE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | GA365827/1 |
| Cover Note Number | 29/06/2018-28/06/2019 |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | HENG AIK YANG |
| NRIC No | S1206400D |
| Date Of Birth | 04/09/1956 |
| Occupation | INDOOR |
| Date Of Driving Pass | 09/02/1980 |
| Driving Experience | 39 YEARS AND 0 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-96788719 |
| Fax Number | |
| Contact Number | OFFICE-96788719 |
| Email Address | AYHENG@SINGNET.COM.SG |

| | |
|---|-------------------------------|
| Address | 898A TAMPINES ST 81 08-782 |
| Postcode | 521898 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|-------------------------------|
| Type Of Accident | COLLISION - CHANGE/CROSS LANE |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|--------------|
| Vehicle Registration Number | SHC8493Y |
| Vehicle Make/Model/Colour | HYUNDAI |
| Details Of Properties | |
| Vehicle Category | TAXI |
| Name of Driver | LIM HO CHUAN |
| NRIC/Passport Number | S1670067C |
| Contact Number | 97335617 |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


28/2/19 (10am)

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On Wednesday night, around 10.5pm driving along Cecil street, my car (SKU 434R) was hit by a taxi. (SHC 8493Y) at my driver side door area.
I was on the 2nd lane when the taxi hit on my car, from my right.

You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a **Fourteen (14) days clause** whereby the claim must be made within the stipulated timeframe from the day of occurrence.

| |
|--|
| Reporting Only |
| <input checked="" type="checkbox"/> Claim OD |
| <input checked="" type="checkbox"/> Claim TP |
| Claim OD / TP at other workshop |

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:
28/3/19 (10 am.)

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

AXA FORM



redefining / insurance

Date: 28/02/19

To: Owner of Vehicle Number: SRU 913WR



The following has been advised to you via your workshop, John Law through their staff, John Law

Please tick the applicable box if you had been advice on the content as seen below:

- ☒ You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
- ☒ You had been advised by the workshop on the liability and merits of the case accordingly.
- ☒ You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
- ☐ There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.
- ☐ There will be no cancellation/withdrawal of the Own Damage claim once the order of the spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
- ☐ The estimated waiting time for the spare parts to arrive is _____. The estimated arrival time does not include the repair period.
- ☐ You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy.
- ☐ For vehicles below Three (3) years old, your Insurance Company will use only genuine original parts to repair your vehicle.
- ☐ For vehicles above Three (3) years old, your Insurance Company will be carrying out repairs using **any combination** of genuine original parts and/or original equipment manufacturer (OEM) parts.
- ☐ You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.
- ☐ For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.
- ☒ Others Clarify back policy

Signed and acknowledge by:

[Signature]
Name and signature of policyholder/authorised driver

[Signature]
Name and signature of workshop personnel including company stamp



KIM HOE TYRE & BATTERY
KAKI BUKIT AUTOHUB
01-10 SINGAPORE 417921
TEL:67472427

Customer

Vehicle ident no.

Repair order no.

R000582

Technician

Date

9.3.19

License plate no.

SKU434R

First reg. date

Model

Honda : HR-V : 5 Door : 1999-2006

Odometer reading: km/miles

Complaints or reason for alignment check

| | | | Before | Target Data | Actual |
|------------|--------------------------|-------------|--------|------------------|---------------------|
| Rear axle | Camber | left | | -0°30' +/-1°00' | -1°33' * |
| | | right | | | -1°34' * |
| | | cross | | 0°00' | 0°01' |
| | Toe | left | | 0°05' +/-0°12' | 0°02' |
| | | right | | | 0°12' |
| | | total | | 0°09' +/-0°24' | 0°14' |
| | Geometrical driving axis | | | 0°00' | -0°05' |
| Front axle | Camber | left | | -0°15' +/-1°00' | -0°06' |
| | | right | | | -2°45' * |
| | | cross | | 0°00' | 2°39' |
| | Caster | left | | 2°15' +/-1°00' | |
| | | right | | | |
| | | cross | | 0°00' | |
| | SAI | left | | | |
| | | right | | | |
| | | cross | | 0°00' | |
| | Track differential angle | left | | | |
| | | right | | | |
| | Toe | left | | 0°00' +/-0°07' | -0°53' * |
| | | right | | | 2°32' * |
| | | total | | 0°00' +/-0°14' | 1°40' * |
| | Setback | | | 0°00' | |
| | Max steering lock | left steer | left | -35°00' +/-2°00' | |
| | | left steer | right | 30°00' +/-2°00' | |
| | | right steer | left | 30°00' +/-2°00' | |
| | | right steer | right | -35°00' +/-2°00' | |

* This value is not within specification. Tire wear, handling and safety problems may result.



Estimated repair checklist

12/3/2019

Vehicle Registration No.: SKU434R

Vehicle Make/Model: Honda Vezel

Qty List Items

| Qty | List Items | Amount \$ |
|-----|---|-----------|
| 1 | Front fender - RH | 680.90 |
| 1 | Front fender wheel arch garnish | 311.80 |
| 1 | Front fender inner shield | 212.60 |
| 15 | Front fender inner shield clips @ 4.50 | 67.50 |
| 1 | Front bumper | 881.90 |
| 2 | Front bumper side retainers - L/R @ 48.50 | 97.00 |
| 1 | Front door - RH | 1,257.60 |
| 1 | Front door side mirror | 681.60 |
| 1 | Front door outer handle | 180.90 |
| 1 | Front door glass outer moulding | 142.20 |
| 1 | Front door glass run channel | 155.60 |
| 1 | Front door glass regulator assy | 489.60 |
| 1 | Front door glass guide | 89.90 |
| 1 | Front door inner lock | 481.60 |
| 1 | Front door inner trim board | 861.60 |
| 1 | Front door insulation | 120.20 |
| 1 | Front door w/strip | 181.20 |
| 1 | Front door checker | 89.60 |
| 2 | Front door hinges @ 85.60 | 171.20 |
| 1 | Front door lower seal | 121.60 |
| 1 | Front shock absorber - RH | 445.20 |
| 1 | Front shock absorber top mount | 181.90 |
| 1 | Front lower arm | 415.60 |
| 1 | Front knuckle arm | 580.30 |
| 1 | Front stabilizer bar | 312.20 |
| 1 | Front stabilizer bar link | 89.60 |
| 1 | Front wheel bearing | 230.60 |
| 1 | Front steering rack assy | 1,635.60 |
| 1 | Side sill panel garnish | 689.60 |
| 1 | Rear door - RH | 1,257.60 |
| 1 | Rear door w/strip | 141.20 |
| 1 | Rear door seal | 89.90 |
| 1 | Rear door glass outer moulding | 126.20 |
| 1 | Rear door glass run channel | 155.60 |
| 1 | Rear fender wheel arch garnish | 311.80 |

Sub-total 13,939.00

Less 20% 2,787.80

Total List 11,151.20

Not Authorized
Unauthorized

12/3/19

Page 1 of 2

4 days
before After up

1/5 6100

6685.50
5348.40



Special Nett Items

| | | |
|-------|-------|--------------------------------|
| 1 | Front | sport wheel - RH |
| 1 | Front | tyre |
| 1 set | Front | door black tape |
| 1 set | Front | fender wheel arch garnish clip |
| 1 | Rear | sport wheel - RH |
| 1 set | Rear | door black tape |
| 1 set | Rear | fender wheel arch garnish clip |
| 1 set | Side | sill panel garnish clip |

| | | |
|----|--------|-----|
| 47 | 650.00 | 450 |
| 50 | 350.00 | X |
| 20 | 120.00 | 60 |
| 20 | 80.00 | 40 |
| 11 | 650.00 | X |
| 11 | 120.00 | X |
| 11 | 80.00 | X |
| 20 | 80.00 | ✓ |

Total Special Nett 2,130.00

630

Labour charges

| |
|---|
| To check front electrical wiring |
| To respray undercoating |
| To remove, refix front undercarriage |
| To check wheel alignment |
| To respray painting and etc |
| Panel beating, cut, weld remove & replacing above parts |

| | |
|----------|-----|
| 50.00 | 20 |
| 120.00 | 60 |
| 450.00 | 120 |
| 120.00 | 80 |
| 1,400.00 | 800 |
| 1,500.00 | 600 |

Total Labour 3,640.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

16,921.20

1680

Polymath Garage Pte Ltd
AutoBay@Kaki Bukit, 1 Kaki Bukit Ave 6 #02-02.
Singapore 417883
24 Hour : +65 8228 9818
Phone: +65 6871 8861 | Fax: +65 6871 8814
Email : enquiry@polymathgarage.com.sg
UEN: 201605123Z

Accepted by Customer
Signature
Date

P-5348.40
S.N 630.00
1680 - 1680.00
7658.40
202
6126.72

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|--|---------------|--|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 26 Mar 2019 12:49 Edit Reg | | 11 Mar 2019 00:00 Edit Adj Rpt | S\$6,100.00 Edit Estimates | S\$6,100.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|----------------------------------|--|--|--|----------------|----------------|--------------------|---------------------|-------------------|--------------|
| CLAIM SUBFOLDER DETAILS | | [Created by adjuster] | | | | | | | |
| Insured: | -, Co. Reg. No.: - | | | | | | | | |
| Main Claimant: | - | | | | | | | | |
| Vehicle Reg. No.: | SKU434R | Date of Loss: | 27/02/2019 00:00 - :59 [43 Months and 29 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP | Policy/Cover Note No.: | | | | | | | |
| Vehicle Reg. No. (Insured): | SHC8493Y | Policy No. (Claimant): | | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | Polymath Garage Pte Ltd (HQ) 1 KAKI BT AVENUE 6 #02-02 AUTOBAY, 417883 Kaki Bukit - Tel: | | | | | | | | |
| Handling Insurer: | India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 20/03/2019] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED | | View All Compose Case Mail | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS | | View All Search Tasks Create New Task Complete | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SKU434R
[SHC8493Y]

TP

















































-

Feb 27 2019 12:00AM

[-]

Polymath Garage Pte Ltd

| Upload Documents | | Upload Photos | Compose New Letter | View View in Browser | |
|------------------|-----------------|-----------------------------------|--------------------|-------------------------------------|-------------------------------------|
| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print |
| 1 | 25/03/19 10:21 | Chassis Number | | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 6 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 7 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 8 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 9 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 10 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 11 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 12 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 13 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 14 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 15 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 16 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 17 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 18 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 19 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 20 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 21 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 22 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 23 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 24 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 25 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 26 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 27 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 28 | 25/03/19 10:21 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 29 | 25/03/19 10:22 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 30 | 25/03/19 10:22 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 31 | 25/03/19 10:22 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 32 | 25/03/19 10:22 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 33 | 25/03/19 10:22 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 34 | 25/03/19 10:22 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 35 | 25/03/19 10:22 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 36 | 25/03/19 10:22 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 37 | 25/03/19 10:22 | General View | | Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 38 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 25/03/19 10:22 | Odometer Reading |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 56 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 57 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 58 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 59 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 60 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 61 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 62 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 63 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 64 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 65 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 66 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 67 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 68 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 69 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 70 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 71 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 72 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 73 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 74 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 75 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 76 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 77 | 25/03/19 10:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 78 | 25/03/19 10:22 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 79 | 25/03/19 10:22 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 80 | 25/03/19 10:22 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 81 | 25/03/19 10:22 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 82 | 25/03/19 10:22 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 83 | 25/03/19 10:22 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 84 | 25/03/19 10:22 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 85 | 25/03/19 10:22 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 86 | 25/03/19 10:22 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 87 | 25/03/19 10:22 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|--|--|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 88 | 25/03/19 10:22 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 89 | 25/03/19 10:22 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 90 | 25/03/19 10:22 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 91 | 25/03/19 10:22 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 92 | 25/03/19 10:22 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 93 | 25/03/19 10:22 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 94 | 25/03/19 10:22 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | India International Insurance Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 12/03/19 09:08 | Singapore Accident Statement |  Load PDF | |

Documents Checklist

| | | | |
|---|-----------------------|----------------------|-----------------------|
| DOCUMENTS CHECKLIST | Reset | Save | Print |
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) | | | |
| <div></div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer | | | |
| Note: Remarks are private unless you show it to other parties. | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III19004395/USD3E2

Date: 26/03/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SKU434R

Insured Vehicle No : SHC8493Y

Date of Loss: 27/02/2019

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKU434R

Make & Model: HONDA VEZEL, 1.5 X (A)

Engine No: L15B3520644

Reg. Date: 29/06/2015 (Man. Year: 2015)

Chassis No: RU11020630

Colour: Black

Odometer: 122219 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|------------------|-----------------|------------------|--------------|
| Parts | 13,281.20 | 5,978.40 | 7,302.80 | 54.99 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,640.00 | 1,680.00 | 1,960.00 | 53.85 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$\$) | 16,921.20 | 7,658.40 | 9,262.80 | 54.74 |
| Approved Total (Overridden) (\$\$) | | 6,100.00 | | |
| Nett Amount (\$\$) | 16,921.20 | 6,100.00 | 10,821.20 | 63.95 |

INSPECTION

Date of Assignment: 11/03/2019

Date Inspected: 12/03/2019 Inspected At:

Polymath Garage Pte Ltd (HQ)
1 KAKI BT AVENUE 6 #02-02 AUTOBAY
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|----------------------|--|---|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 26 Mar 2019) |
| Parts: | M1-SUV | HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SKU434R) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. Particulars | Condition | Repairer's | Amount |
|-----|-----|---|--------------------|-------------|--------------|
| 1 | 1 | *FRONT FENDER - RH | Badly Dented | 680.90 FL | *580.00 FL |
| 2 | 1 | *FRONT FENDER WHEEL ARCH GARNISH | Distorted | 311.80 FL | *248.50 FL |
| 3 | 1 | *FRONT FENDER INNER SHIELD | Torn | 212.60 FL | *166.20 FL |
| 4 | 15 | *FRONT FENDER INNER SHIELD CLIPS | Necessary | 67.50 FL | *67.50 FL |
| 5 | 1 | *FRONT BUMPER | Repair | 881.90 FL | *- FL |
| 6 | 2 | *FRONT BUMPER SIDE RETAINERS - L/R | Not Necessary | 97.00 FL | *- FL |
| 7 | 1 | *FRONT DOOR - RH | Badly Dented | 1,257.60 FL | *1,005.50 FL |
| 8 | 1 | *FRONT DOOR SIDE MIRROR | Cut / Damaged | 681.60 FL | *681.60 FL |
| 9 | 1 | *FRONT DOOR OUTER HANDLE | Not Necessary | 180.90 FL | *- FL |
| 10 | 1 | *FRONT DOOR GLASS OUTER MOULDING | Not Necessary | 142.20 FL | *- FL |
| 11 | 1 | *FRONT DOOR GLASS RUN CHANNEL | Not Necessary | 155.60 FL | *- FL |
| 12 | 1 | *FRONT DOOR GLASS REGULATOR ASSY | Bent / Jammed | 489.60 FL | *489.60 FL |
| 13 | 1 | *FRONT DOOR GLASS GUIDE | Not Necessary | 89.90 FL | *- FL |
| 14 | 1 | *FRONT DOOR INNER LOCK | Shorted / Jammed | 481.60 FL | *481.60 FL |
| 15 | 1 | *FRONT DOOR INNER TRIM BOARD | Deformed / Cracked | 861.60 FL | *485.30 FL |
| 16 | 1 | *FRONT DOOR INSULATION | Not Necessary | 120.20 FL | *- FL |
| 17 | 1 | *FRONT DOOR W/STRIP | Necessary | 181.20 FL | *181.20 FL |
| 18 | 1 | *FRONT DOOR CHECKER | Twisted | 89.60 FL | *89.60 FL |
| 19 | 2 | *FRONT DOOR HINGES | Bent / Twisted | 171.20 FL | *171.20 FL |
| 20 | 1 | *FRONT DOOR LOWER SEAL | Necessary | 121.60 FL | *121.60 FL |
| 21 | 1 | *FRONT SHOCK ABSORBER - RH | Not Necessary | 445.20 FL | *- FL |
| 22 | 1 | *FRONT SHOCK ABSORBER TOP MOUNT | Not Necessary | 181.90 FL | *- FL |
| 23 | 1 | *FRONT LOWER ARM | Bent | 415.60 FL | *415.60 FL |
| 24 | 1 | *FRONT KNUCKLE ARM | Bent | 580.30 FL | *580.30 FL |
| 25 | 1 | *FRONT STABILIZER BAR | Not Necessary | 312.20 FL | *- FL |
| 26 | 1 | *FRONT STABILIZER BAR LINK | Not Necessary | 89.60 FL | *- FL |
| 27 | 1 | *FRONT WHEEL BEARING | Necessary | 230.60 FL | *230.60 FL |
| 28 | 1 | *FRONT STEERING RACK ASSY | Not Necessary | 1,635.60 FL | *- FL |
| 29 | 1 | *SIDE SILL PANEL GARNISH | Distorted | 689.60 FL | *689.60 FL |
| 30 | 1 | *REAR DOOR - RH | Repair | 1,257.60 FL | *- FL |
| 31 | 1 | *REAR DOOR W/STRIP | Not Necessary | 141.20 FL | *- FL |
| 32 | 1 | *REAR DOOR SEAL | Not Necessary | 89.90 FL | *- FL |
| 33 | 1 | *REAR DOOR GLASS OUTER MOULDING | Not Necessary | 126.20 FL | *- FL |
| 34 | 1 | *REAR DOOR GLASS RUN CHANNEL | Not Necessary | 155.60 FL | *- FL |
| 35 | 1 | *REAR FENDER WHEEL ARCH GARNISH | Not Necessary | 311.80 FL | *- FL |
| 36 | 1 | *FRONT SPORT WHEEL - RH | Cut | 650.00 FS | *450.00 FS |
| 37 | 1 | *FRONT TYRE | Serviceable | 350.00 FS | *- FS |
| 38 | 1 | *SET FRONT DOOR BLACK TAPE | Necessary | 120.00 FS | *60.00 FS |
| 39 | 1 | *SET FRONT FENDER WHEEL ARCH GARNISH CLIP | Necessary | 80.00 FS | *40.00 FS |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------|------------|-----------|
| 40 | 1 | | *REAR SPORT WHEEL - RH | Not Necessary | 650.00 FS | *- FS |
| 41 | 1 | | *SET REAR DOOR BLACK TAPE | Not Necessary | 120.00 FS | *- FS |
| 42 | 1 | | *SET REAR FENDER WHEEL ARCH GARNISH CLIP | Not Necessary | 80.00 FS | *- FS |
| 43 | 1 | | *SET SIDE SILL PANEL GARNISH CLIP | Necessary | 80.00 FS | *80.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|------------------|-----------------|
| Sub Total (\$\$) | 16,069.00 | 7,315.50 |
| - List Item Discount on L Items 20.00/20.00% (\$\$) | 2,787.80 | 1,337.10 |
| Total Parts (\$\$) | 13,281.20 | 5,978.40 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|---|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | TO CHECK FRONT ELECTRICAL WIRING | New | 50.00 | 20.00 |
| 2 | TO RESPRAY UNDERCOATING | New | 120.00 | 60.00 |
| 3 | TO REMOVE, REFIX FRONT UNDERCARRIAGE | New | 450.00 | 120.00 |
| 4 | TO CHECK WHEEL ALIGNMENT | New | 120.00 | 80.00 |
| 5 | TO RESPRAY PAINTING AND ETC | New | 1,400.00 | 800.00 |
| 6 | PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS | New | 1,500.00 | 600.00 |
| Gross Labour Cost (S\$) | | | 3,640.00 | 1,680.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >