

NATIONAL Assessment Centre Services.

[wef 1 Jan'05] MJA/119 032826

Date In: 11/19-19:07	Job description	Date & Time Completed	Done by
Ref No: NA/INC19004424/24	SAS e-filing		
Veh No: R6780L	E-mail (within 3hrs, AIC 2hrs)		
D.O.A: 9/1/19-15:00	i-Motor Claim Form	M7/103542-201	11/1/19 20:03
OD TP: Reporting Only	i-Motor W/O (Within: OD 2hrs, TP 4hrs)		
	i-Photo Uploaded		
TP Insurer:	Assessment/Survey Report		
	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / QW: (

Tel:

Fax:

TP Particulars:

Veh No:

4245303

INC () / Non-INC ()

Owner / Driver: (

Tel:

Policy No: (

Period: (

Cover Type: (

Confirmed by: (

Date:

Time:

Insured/Driver Liability: (

%)

[Note-Est Status (WO): N: 0-20%; P: 21-79% P: 80-100%]

Year of Registration: (

Warranty: YES (

)/NO (

Excess: (\$

Loading: \$1,000 (

)/\$2,000 (

General Remarks:-

() Walk-In Customer: Customer's information strictly Confidential & Strictly NO refer of repairer.

() Total Loss Case: to e-mail Insurer URGENTLY.

Drive-In () / Towed-In (); Invoice: YES () / NO (); Towing Co: ()

Remarks:-

(INC hotline: 6788 6616)

Date & Time Completed

Done by

1) Apply for Transport Allowance () / Courtesy Car ()

2) QC Check / Post Repair Inspection ()

3) Upload Resurvey Photo [Repair Cost > \$3000] ()

Injury:

Date/Time

Actions

NA 190144

Invoice Preparation Checklist

Am't (\$)

Am't (\$)

Est Bill

Add Bill

Claimant's Particulars:-

Driver/Owner:

Contact No:

Damaged Portion:

QC Checked by (Engr-In-Charge):

Auditors' Comments:-

Sat. 1:

Sat. 2 / 3:

1) AR: Accident Reporting (\$30);		
2) DA: Damage Assessment (\$100); INC (\$80)		
3) TF: Towing Fee \$40/\$45		
4) FT: Follow-Through Survey \$120		
5) FT: Follow-Through Survey (Resurvey) \$30		
For claiming against INC Only (wef 10 Jan 2005)		
6) TR: Re-inspection \$75		
7) N1: Idac DA + SMRT Survey \$160		
8) NTUC Additional Services:-		
OD*		
*N5: Courtesy Car / Tpl Allowance \$5		
*N6: Repair Co-ordination \$10		
*N7: Post Repair Inspection \$25		
*N8: DV / Collect Excess Coordination \$5		
TP (N11): TP (Non INC) against INC \$20		
9) N12: Idac Mobile \$0		

Invoice dated

Fee Charged

Invoice dated

Fee Charged

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	11/03/2019 19:07
Date Of Accident	09/03/2019 15:00
Exact Location Of Accident	TUAS RD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	PC6780L
Insured/Policyholder	
Name Of Registered Owner	SAVA LEISURE (PTE) LTD
Co Reg No	201408067C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90053861
Alternative Phone No	OFFICE-90053861
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HIACE COMMUTER GL 3.0 AT 2WD 4DR LWB
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102809768
Cover Note Number	
Driver	
Name of Driver	MOHAMMED FADLY BIN T ABIDIN
NRIC No	S8015290F
Date Of Birth	25/05/1980
Occupation	OUTDOOR
Date Of Driving Pass	03/01/2019
Driving Experience	0 YEAR AND 2 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-83288256
Fax Number	
Contact Number	OFFICE-83288256
EEmail Address	NOEMAIL

Address	BLK 658A PUNGGOL EAST #05-701
Postcode	821658
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SENGKANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 2 SENGKANG SQUARE #01-02 SINGAPORE , POSTCODE: 545025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800 - 3438999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20190310/2052.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH TRAFFIC POLICE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP4530E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SKETCH PLAN

A: PC6780 L
B: YP4530E



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

FOLLOW POLICE REPORT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Date of Accident

: 09.03.2019 Accident Time: 1500 (24-HR-Format)

Accident Place

: TNAS ROAD

Vehicle Reg. No. (Car Plate No.)

: PC 6780 L

Vehicle Make/Model

: TOYOTA HIACE

Insurance Company

: Policy No.

Owner or Company Name / IC No.

: SAVA PTE LTD / ROC 201408067C

Owner or Company Contact No.

: 9005 3861

Owner's Hp

Company Tel

DRIVER'S Name / IC No.

: MOHAMMED FADLY BIN T ABIDIN / S8015290F

DRIVER'S Date Of Birth

: 25.05.1989

DRIVER'S License Pass Date 23.10.2022

Relationship of Owner & Driver

: Spouse \ Parents \ Children \ Sibling \ Employee \ Others:

DRIVER'S Address

: BLK 658 A, PUNGGOL EAST #05-701, S821658

DRIVER'S Contact No. / Alt No.

: 1) 83288 256

2)

DRIVER'S Occupation

: INDOOR \ OUTDOOR (e.g. working inside or outside office)

Email Address

: ~~SAVA~~ ADMIN@MYCAR.SG

Weather & Road Surface

: CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET

Reporting Type

: Reporting Only \ Claim Other Party \ Claim Own Insurance

Number of Passengers (Including Driver):

: 02 / DELA CRUZ EDILBERTO JR CAMELIT

Was there any video Captured by car camera: YES \ NO

Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose

Other Party Driver's Particular (if any)

Vehicle Reg. No:

: YP 4570 E

Vehicle Reg. No:

Vehicle Make/Model:

Vehicle Make/Model:

Name Driver:

Name Driver:

IC No. Driver:

IC No. Driver:

Driver's Contact & Add:

Driver's Contact & Add:



**SINGAPORE
POLICE FORCE**



T/20190310/2052

1 of 3

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

Report No. T/20190310/2052

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/03/2019 11:57	Vide Report No.: J/20190309/0115	Station Diary No.: 43
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: MOHAMMED FADLY BIN T ABIDIN			Address: APT BLK 658A PUNGGOL EAST #05-701 SINGAPORE 821658		
ID Type / ID No.: NRIC NO / S8015290F			Contact No.: Home/Office: Mobile: 83288256		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 38	Date of Birth: 25/05/1980	Type of Informant: Driver		
Race: Malay			Language:		Institution / School Name:
Occupation: Other car and light goods vehicle drivers nec			Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 09/03/2019 15:00	Type of Location: Straight Road
Location: Along Road 1 TUAS ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Side Swipe - Opposite Direction				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
PC6780L	Van				Seriously Damaged	1
YP4530E	Lorry					1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190310/2052

2 of 3

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

Report No. T/20190310/2052

CONTINUATION OF REPORT

Driver			
Name	MOHAMMED FADLY BIN T ABIDIN	ID No.	S8015290F
Related Vehicle	PC6780L (Van)	Contact No.	83288256
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	thirugnanam	ID No.	G6025869X
Related Vehicle	YP4530E (Lorry)	Contact No.	86528216
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

Brief Details.

On the stated date, time and location, I was involved in an accident.

I was driving my vehicle (PC6780L) along Tuas Road. While driving on the right lane, I saw an obstruction in my lane. As such, I went slightly to the right and I managed to avoid the said item.

While getting back into the lane, a vehicle (YP4530E) from the opposite direction came and crashed to the right side of my vehicle. As such we both alighted and ambulance and traffic police was called.

Subsequently, the driver was conveyed. I am not injured.

My memory card was given to the TP officer at scene, SSgt Noah.

Vide incident J/20190309/0115 .



**SINGAPORE
POLICE FORCE**



T/20190310/2052

3 of 3

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

Report No. T/20190310/2052

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
F /
Sgt 2 MUHAMMAD HAIKAL BIN LATIFF

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Sgt 3 MARIAH BINTE ZAKARIA
Contact No.: 65476433

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
10/03/2019 11:57

Classification Of Case:

REPUBLIC OF SINGAPORE DRIVING LICENCE

NRIC No. S8015290F

Name
MOHAMMED FADLY BIN T ABIDIN

Birth Date 25 May 1980
Renewal Date 11 Mar 2003

000276563J




REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8015290F



Name
MOHAMMED FADLY BIN T ABIDIN

Race
MALAY

Date of birth
25-05-1980

Country/Place of birth
SINGAPORE

Sex
M




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class	Description	Pass Date
Class 2B	Motorcycles not exceeding 200 cc	25 Feb 1999
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	23 Oct 2002

NP 428A

Licence No: S8015290F



5946514



NRIC No. S8015290F



Date of issue
26-05-2018

Address
APT BLK 658A PUNGGOL EAST
#05-701
SINGAPORE 821658

Land Transport Authority



VOCATIONAL LICENCE

Licence No : S8015290F

Name : MOHAMMED FADLY BIN T
ABIDIN

Please visit www.lta.gov.sg to check
the status of this vocational licence

This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type	Description	Issue Date
03	BUS VL	03/01/2019
04	BUS ATTENDANT	03/01/2019



Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960

ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5102809768

Cover : Comprehensive

1. Index mark and Registration Number of Vehicle : **PC6780L**
Chassis Number : KDH2230025181
2. Name of Policyholder : SAVA LEISURE (PTE) LTD
3. Effective Date of Insurance : 13 Aug 2018
4. Expiry Date of Insurance : 12 Aug 2019
5. Persons or Classes of Persons entitled to drive*
(a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use*
(a) Use for the carriage of passengers in connection with the Policyholder's business.
(b) Limited to carry 14 passengers

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

GEOGRAPHICAL LIMIT	: WITHIN THE REPUBLIC OF SINGAPORE ONLY
EXCESS (SECTION I)	: S\$2,000
EXCESS (SECTION II)	: S\$3,000
WINDSCREEN EXCESS	: S\$500
INSURE WITH COE	: YES
HIRE PURCHASE COMPANY	: MOTOR CREDIT PTE LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : HON BROTHERS MOTOR (00000571733)

Date of Issue : 10 Aug 2018 13:43 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident

Vehicle No.(For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5102809768		SAVA LEISURE (PTE) LTD	201408067C	GBS	Comprehensive	PC6780L	PC6780L	13/08/2018	12/08/2019

 Policy Information

Policy No.	5102809768	Policyholder Name	SAVA LEISURE (PTE) LTD	Policyholder NRIC	201408067C
Certificate No.					
Address	63 UBI AVENUE 1 #05-01 63@UBI SINGAPORE 408937				
Product Name	BUS INSURANCE	Plan		Group Policy Flag	N
Policy issue Date	10/08/2018	Effective Date	13/08/2018 00:00	Expiry Date	12/08/2019 23:59
Excess Type		All Claims Excess			
Third Party Excess	3000	Own damage Excess	2000	Windscreen Excess	500
Additional Excess		OS Premium	0		
Outside Singapore OD Excess		Outside Singapore TP Excess		Young/Inexperience Driver Excess	
Agent	HON BROTHERS MOTOR	Agent Tel.	68446450	GST Flag	Y
Co-insurance Flag	No				
Open Policy Info					
Certificate Info					

 Policyholder Mailing Address

Address 1	63 UBI AVENUE 1	Address 2	#05-01 63@UBI	Address 3	SINGAPORE 408937
Address 4		Address Type	Singapore address	Post Code	408937
Unit No.	08	Related Policy Number	5071220404-03		

 Insured Object: PC6780L

 Endorsements

Sequence	Date of Endorsement	Endorsement Type	Endorsement Status	Endorsement Content
1	13/08/2018 00:00	Basic Information Endorsement	Entry Rejected	
2	13/08/2018 00:00	Basic Information Endorsement	Endorsement Take Effective	orangeeye0514 -To less \$100 on renewal premium for Orange Eye discount.

Continue

Cancel

Claim Handling

Exit

Accident MT/1035462

Policy No.	5102809768	Vehicle No.	PC6780L	GST Registration No.	
Certificate No.					
Policyholder Name	SAVA LEISURE (PTE) LTD	Cover Type	Comprehensive	Policyholder NRIC	201408067C
Product Code	BUS INSURANCE	Contact No. (Office)	0	Loading	0
Contact No. (Mobile)	90053861	Special Remark		Contact No. (Home)	0
Email Address		TCA	☒ No ☐ Yes	eCode	71
KFK	☒ No ☐ Yes	NCD Entitlement(%)	0	eCode Reason	
NCD Protection	No			Private Hire	No

↳ Accident Details

Report Date	11/03/2019 19:57	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Head on collision
Date of Accident	09/03/2019	Time of Accident hh:mm	15:00	Country of Accident	Singapore
Reporting Centre		Orange Force		ICM No.	
Accident Location	TUAS RD				

↳ Excess

Own damage Excess	2,000.00	Additional Excess		Windscreen Excess	500.00
Unnamed Driver Excess		Outside Singapore OD Excess			
Third Party Excess	3,000.00	Outside Singapore TP Excess			

↳ Benefits

↳ GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

↳ Policyholder Mailing Address

Address 1	63 UBI AVENUE 3	Address 2	#05-01 63@UBI	Address 3	SINGAPORE 408937
Address 4		Address Type	Singapore address	Post Code	408937
Unit No.	08	Related Policy Number	5071220404-03		

↳ DI Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver	Driver DOB	25/05/1980
Unnamed driver Name	MHAMMED FAOZY BIN T ABIDI	Driver NRIC	S8015290F	Driving Experience	0
Register Date of Driver License	03/01/2019	Driver Age	38	Contact No. (Home)	0
Contact No. (Mobile)	83288256	Contact No. (Office)	0	Address 3	WATERWAY SUNRAY
Address 1	BLK 658A	Address 2	PUNGGOL EAST	Post Code	821658
Address 4	SINGAPORE 821658	Address Type	Singapore address		
Unit No.	05-701				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No
-------------------------------------	------	-------------	---

Modification History

Claim 001 New

Claim Type *	OD-HD	Insured Name	SAVA LEISURE (PTE) LTD	Insured NRIC	201408067C
Contact No. (Mobile)		Contact No. (Home)		Contact No. (Office)	
Email Address		OT Vehicle Number	PC6780L	TP Vehicle Number	YP4530E
Claimant Type Claimant *	Please Select	Type of Benefit *	Please Select		
Claimant Name *		Claimant NRIC *			
Claimant Address					
Claim Description	PC6780L / YP4530E ON 9 Mar 2019				
Preferred Workshop Contact No.	98888885	Insured Liability *	Fully at Fault	Name of Preferred Workshop	MY CAR CONSULTANT PTE LTD
Require Finalisation	Yes	Preferred Repair Option	Preferred Workshop (refer below)	GIA report	Received
Date Registered	11/03/2019 20:00	Claim Close Date		Date Received	11/03/2019 00:00
Report Taken By	Jackson			OD Excess Collected by Workshop	

☒ Print AK letter

Save Submit

Attachment

Accident No.	MT/1035462	Claim No.	001
Last Doc. Received	☒ Yes ☐ No	Upload Date	11/03/2019 20:01

Path *	Category *	Confidential	Urgency *	Description *
Browse... Clear	Please Select	☐ NO	Normal	
Browse... Clear	Please Select	☐ NO	Normal	
Browse... Clear	Please Select	☐ NO	Normal	
Browse... Clear	Please Select	☐ NO	Normal	

Please Select

Please Select

TVG

Normal

Please Select

Please Select

HIC

Normal

Attachment List

Attachment	Uploaded By/Date	Category	Urgency	Description	Msg Sent? (CO)	Action
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 11 Mar 2019 20:01	NRIC/ Driving License	Normal	NRIC/ Driving License 2019-3-11		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 11 Mar 2019 20:01	NRIC/ Driving License	Normal	NRIC/ Driving License 2019-3-11		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 11 Mar 2019 20:01	NRIC/ Driving License	Normal	NRIC/ Driving License 2019-3-11		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 11 Mar 2019 20:00	SAS	Normal	SAS 2019-3-11		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 11 Mar 2019 20:00	Photos	Normal	Photos 2019-3-11		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 11 Mar 2019 20:00	Photos	Normal	Photos 2019-3-11		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 11 Mar 2019 20:00	Photos	Normal	Photos 2019-3-11		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 11 Mar 2019 20:00	Photos	Normal	Photos 2019-3-11		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 11 Mar 2019 20:00	Photos	Normal	Photos 2019-3-11		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 11 Mar 2019 20:00	Photos	Normal	Photos 2019-3-11		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 11 Mar 2019 20:00	Photos	Normal	Photos 2019-3-11		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 11 Mar 2019 20:00	Photos	Normal	Photos 2019-3-11		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 11 Mar 2019 20:00	Photos	Normal	Photos 2019-3-11		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 11 Mar 2019 20:00	Photos	Normal	Photos 2019-3-11		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 11 Mar 2019 20:00	Photos	Normal	Photos 2019-3-11		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 11 Mar 2019 20:00	Photos	Normal	Photos 2019-3-11		Edit

Video List

Uploaded By/Date	Folder Date	File Name	Source	Action
Display in New Window Scan and uploading				

ASSIGNMENT (IDAC)

By CSO: Nature of Accident:

- 1) Vehicle hit Vehicle: 2) Vehicle hit ??
- a) Motorcar () a) Pedestrian ()
- b) Motorcycle () b) Animal ()
- c) Bicycle ()
- 3) Vehicle hit Road Side Objects:
- a) Govt Property () b) Road Work Object ()
(E.g. signboard, barrier, etc.)
- c) Private Property ()
- 4) Vehicle drop into drain ()
- 5) Damage due to Act of God:
- a) Fallen Object () b) Flood ()
- c) Other ()
- 6) Parked & Found Damaged:
- a) Vandalism () b) Hit by Moving Object ()
- 7) Theft Case
- a) Stolen () b) Damage found ()
when recovered
- 8) Fire
- a) Whilst driving () b) Parked ()
- 9) Accident date more than 24hrs ()

By Assessor- 1) Vehicle Information

Veh No: **PC 6780 L** Yt Regn: **1 Oct 2015**

Type: M.Car / M.Cycle / **Bus** / Van / Lorry / Taxi / Prime Mover /
/ Truck / Trailer or

Make & Model: **Toyota Proace Commuter GL** 2982

Colour: **Silver** Transmission Type: **Auto** Manual

Eng/No: Sp. Reading: **47666**

C/No: **KDH 223 00 25181**

Gen. Cond: **Good** / Fair / Poor / Burnt or

Steering: **In order** / Jammed / Leaked / Burnt or

Brake: **In order** / Jammed / Leaked / Burnt or

Modi: **Nil** / S/Rim / STD A/Rim or

Tyre Size: F: **195 R15**
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear
R/Bal. 7 mm		R/Bal. 7 mm
L/Bal. 7 mm		L/Bal. 7 mm

Parallel Import: Yes / No Towed-In: **Yes** / No

Repair Type: **LS** / I.B.I Towing Required: **Yes** / No

No of Repair Days: **9** Vehicle in Idac: **Yes** / No

D.O.I. **11/3/2019** Time: **3.15 pm**

By Assessor- 2) Comments

- 1) Damages not due to recent accident.
- 2) Damages do not seem hit onto:
- a. Vehicle () b. Motorcycle () c. Bicycle () d. Pedestrian ()
- e. Animal () f. Govt Object () g. Road Work Object ()
- h. Private Property () i. Drain () j. Road Kerb/Grass Verge ()
- 3) Vehicle does not seem damaged as a result of:
- a. Fallen Object () b. Flood () c. Vandalism () d. Fire ()
- e. Moving Object () f. Stolen () g. Stolen & Recovered ()

Time Started

Time completed:

1) CSO

2) ASS

3) Entire Operation Completed Time

Remarks for internal information

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ()
- 2) SRS Light on ()
- 3) ABS Light on ()

VAN / LORRY (Frt)

AC10081AC

(1)Replace (✓) (2)Repair (N) (3)Check (P)
(4)Not Consistent (NC)

Ass 2003

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1004	991300	Frt Bumper			
2001	991477	Frt Bumper <i>Clips</i>			
2002	991387	Frt Bumper <i>Grille</i>			
2003	991449	Frt Bumper Side Cover			
2004	991443	Frt Bumper Side			
1006	991325	Frt Bumper Bracket			
1008	991433	Frt Bumper Reinforcement			
2005	991466	Frt Bumper Signal Lamp			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
2006	990247	Frt Grille Sticker			
1023	991799	Frt Grille Chrome Moulding			
2007	991891	Frt Panel			
2008	991874	Frt Lower Panel			
2009	991328	Frt Panel Emblem			
2010	990247	Frt Panel Sticker			
2011	991893	Frt Panel Garnish			
1024	991222	Frt Apron Panel			
2012	991527	Frt Corner Panel <i>RH</i>			
2013	991532	Frt Corner Panel Signal Lamp			
2014	995245	Frt Signal Lamp LH			
2015	995246	Frt Signal Lamp RH			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
2016	992149	Frt Wiper Panel			
2017	995043	Frt Wiper Nozzle			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
2018	992145	Frt Wiper Link			
2019	992148	Frt Wiper Motor			
1122	995045	Wiper Panel Garnish			
1114	992093	Frt Windscreen			
1115	992097	Frt Windscreen Rubber			
1117	992098	Frt Windscreen Sealant			
2020	992114	Frt Windscreen Outer Pillar			
2021	992113	Frt Windscreen Inner Pillar			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
2022	991958	Frt Side Mirror (Big)			
2023	991959	Frt Side Mirror (Small)			
2024	991962	Frt Side Mirror (Round)			
2025	995015	Frt Wing Mirror Stay			
1025	992013	Frt Support Panel			
1033	990248	Bonnet			
1035	990287	Bonnet Lock			
1037	990273	Bonnet Hinge			
1039	990305	Bonnet <i>Rubber Emblem</i>			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1056	992758	Radiator Hose Top			
1058	992741	Radiator Expansion Tank			
2026	992596	Oil Cooler			
1079	994431	Power Steering Cooler Pipe			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1067	990219	Battery			
1069	990223	Battery Bracket			

Vehicle No:

PC 6780 L

NAC	INC	Item	CON	AC	Qty
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
2027	991500	Frt Cabin Assy			
2028	991501	Frt Cabin Mounting			
2029	991502	Frt Cabin Rear Panel			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
2030	990143	Air Con Evaporator Assy			
2031	990106	Air Con Blower			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
2032	990431	Brake Pedal			
2033	990021	Accelerator Pedal			
2034	990627	Clutch Pedal			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1131	990029	Airbag Control Unit			
1133	991922	Frt RH Seat Belt Assy			
1135	995182	Frt LH Seat Belt Assy			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
2035	994966	Frt LH Wheel Guard			
1102	995170	Frt LH Wheel Rim			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
2036	994966	Frt RH Wheel Guard			
1111	992087	Frt RH Wheel Rim			
1113	995065	Frt RH Tyre			
1255	995326	Frt LH Door			
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1272	991617	Frt LH Door Inner Trim Board			
1316	995327	Frt RH Door			
1317	991654	Frt RH Door <i>Outer Moulding</i>			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1333	991617	Frt RH Door Inner Trim Board			
2037	991644	Frt Door Frt Pillar <i>RH</i>			
2038	991657	Frt Door Rear Pillar			
2039	992072	Frt Wheel Arch Panel			
2040	992069	Frt Wheel Arch Panel Garnish			
2041	991996	Frt Step Panel <i>RH</i>			
2042	994498	Frt Step Panel Top Garnish			
2043	994495	Frt Step Panel Inner Garnish			
1073	995053	Wiper Washer Tank			
1136	990247	Sticker			
		<i>Instrument Cluster</i>			
		<i>Frt RH Door Checker</i>			
		<i>Lower Rubber</i>			
		<i>Lock</i>			
		<i>Inner Moulding</i>			

No of Items:

Assessor:

Claim Handling

Task Transfer Exit

Accident MT/1035462

UDS SAL SUB

Policy No.	5102809768	Vehicle No.	PC6780L	GST Registration No.	
Certificate No.					
Policyholder Name	SAVA LEISURE (PTE) LTD.	Cover Type	Comprehensive	Policyholder NRIC	201408067C
Product Code	BUS INSURANCE	Contact No. (Office)	0	Loading	0
Contact No. (Mobile)	90053861	Special Remark		Contact No. (Home)	0
Email Address		TCA	☒ No ☐ Yes	eCode	
KPK	☒ No ☐ Yes	NCD Entitlement(%)	0	eCode Reason	
NCD Protection	No			Private Hire	No

Accident Details

Report Date	11/03/2019 19:57	Accident Report Within 24 hrs	Yes	Accident Type	Collision - head on collision
Date of Accident	09/03/2019	Time of Accident hh:mm	15:00	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	TJAS RD				

Excess

Own damage Excess	2,000.00	Additional Excess		Windscreen Excess	500.00
Unnamed Driver Excess		Outside Singapore OD Excess			
Third Party Excess	3,000.00	Outside Singapore TP Excess			

Benefits

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	63 UBI AVENUE 1	Address 2	#05-01 63@UBI	Address 3	SINGAPORE 408937
Address 4		Address Type	Singapore address	Post Code	408937
Unit No.	08	Related Policy Number	5071220404-03		

OT Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver		
Unnamed driver Name	MUHAMMAD RADLY BIN T ABDI	Driver NRIC	S8015290F	Driver DOB	25/05/1980
Register Date of Driver License	23/10/2002	Driver Age	38	Driving Experience	16
Contact No. (Mobile)	83288256	Contact No. (Office)	0	Contact No. (Home)	0
Address 1	BLK 558A	Address 2	PUNGGOL EAST	Address 3	WATERWAY SUNRAY
Address 4	SINGAPORE 821658	Address Type	Singapore address	Post Code	821658
Unit No.	05-701				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyzer or Blood Test Reading?	0 mg	Any Injury?	☐ Yes ☒ No
Modification History	12/03/2019 08:58 s991212 Modify Register Date of Driver License(03/01/2019-->23/10/2002) 12/03/2019 08:58 s991212 Modify Driving Experience(0-->16)		

Investigation

Claim 001 OD-MD

Claim Case Officer Yap Chee Ling

UDS SAL SUB

Claim Type	OD-MD	Insured Name	SAVA LEISURE (PTE) LTD	Insured NRIC	201408067C
Contact No. (Mobile)		Contact No. (Home)		Contact No. (Office)	
Email Address		OT Vehicle Number	PC6780L	TP Vehicle Number	1P4530E
Claimant Type		Type of Benefit			
Claimant Name		Claimant NRIC			
Claimant Address					
Claim Description	PC6780L / 1P4530E ON 9 Mar 2019			Name of Preferred Workshop	MY CAR CONSULTANT PTE LTD.
Preferred Workshop Contact No.	98888885	Insured Liability	Fully at Fault	GIA report	Received
Require Finalisation	Yes	Preferred Repair Option	Preferred Workshop (refer below)	Date Received	11/03/2019 00:00
Date Registered	11/03/2019 20:01	Claim Close Date		Total Loss but Repaired	
Report Taken By	Jackson	Workshop Reparer		OD Excess Collected by Workshop	
☒ Print AK letter					
Modification History					

Special Claim Creation Approval

Approval	Reason
Remarks	

damage assessment Attachment

Vehicle Info

Vehicle Make	TOYOTA	Vehicle Model	HIACE COMMUTER BUS (D)	Engine Capacity	0.84
Date of Registration	01/10/2015	Class No.	KDH22300251B1		
Towing Required *	☒ Yes ☐ No	Vehicle in IDAC *	☒ Yes ☐ No	Parallel Import *	☐ Yes ☒ No

Type of Tender *	Own Damage	Assessor Name *	SIMON	Survey Current Status
IDAC/Workshop Name	NATIONAL ASSESSMENT CENTR	IDAC/Workshop Location	51 UBI AVENUE 1 #01-25 PAYA	
Windscreen Parts & Labour Cost		Total Loss *	☐ Yes ☒ No	
Market Value(\$)		Scrap Value(\$)		Economical Repair Value(\$)

REMARK: NO OF REPAIR DAY: 9 DAYS. 1 X FRT GRILLE CHROME MOULDING - UNCONFIRM. 1 X FRT RH DOOR WING MIRROR - REPLACE. 1 X FRT RH DOOR INNER TRIM BOARD - UNCONFIRM. 1 X FRT RH DOOR PILLAR - REPLACE. 1 X FRT RH STEP PANEL - UNCONFIRM. 1 X INSTRUMENT CHESTER - UNCONFIRM. 1 X FRT RH DOOR CHESTER - REPLACE. 1 X FRT RH DOOR LOWER RUBBER - UNCONFIRM. 1 X FRT RH DOOR LOCK - UNCONFIRM. 1 X FRT RH DOOR INNER MOULDING - REPLACE.

Remark for Supplementary

Damage Listing

DOOR	No.	Part No.	Description	Qty *	Repair Code *	
Not Applicable	1	16000101	BUMPER (FRONT)	1	Replace	☒
ABS	2	16002401	BUMPER CLIPS (FRONT)	6	Replace	☒
ACCELERATOR	3	16003201	BUMPER GRILLE (FRONT)	1	Replace	☒
ACTUATOR	4	16002702	BUMPER FOG LAMP (FRONT RIGHT)	1	Unconfirm	☒
ADVERTISEMENT STICKER	5	33000101	PANEL (FRONT)	1	Replace	☒
AIR BAG	6	27700102	HEAD LAMP (RIGHT)	1	Replace	☒
AIR BLOWER	7	30200102	LAMP (FRONT RIGHT)	1	Replace	☒
AIR BOX	8	454009	WIPER PANEL GARNISH	1	Replace	☒
AIR CHAMBER BOX	9	451020	WINDSCREEN SEALANT	1	Unconfirm	☒
AIR CLEANER	10	149001	BONNET	1	Repair	☒
AIR COMPRESSOR	11	149016	BONNET EMBLEM	1	Replace	☒
AIR CON	12	22600102	DASHBOARD (TOP)	1	Unconfirm	☒
AIR CON (VAN)	13	23300202	DOOR (FRONT RIGHT)	1	Replace	☒
AIR COOLER	14	23304602	DOOR MOULDING (OUTER) (FRONT RIGHT)	1	Replace	☒
AIR DISTRIBUTOR	15	23303102	DOOR HINGE (UPPER) (FRONT RIGHT)	2	Replace	☒
AIR FILTER	16	23302002	DOOR GLASS (FRONT RIGHT)	1	Replace	☒
AIR FLOW	17	23302402	DOOR GLASS REGULATOR (FRONT RIGHT)	1	Replace	☒
AIR GRILLE	18	23302502	DOOR GLASS REGULATOR MOTOR (FRONT RIGHT)	1	Unconfirm	☒
AIR HORN	19	23306102	DOOR RUBBER (FRONT RIGHT)	1	Replace	☒
AIR INTAKE	20	23302802	DOOR HANDLE (OUTER) (FRONT RIGHT)	1	Unconfirm	☒

LKK Paya Ubi

From: Yap Chee Ling <CheeLing.Yap@income.com.sg>
Sent: Thursday, 14 March 2019 9:31 AM
To: LKK Paya Ubi
Subject: PC6780L | MT/1035462 (Awarding Letter to My Car Consultant)
Importance: High

Hi IDAC,

Please release the vehicle to My Car Consultant.

Thank you.

Yap Chee Ling (Ms)
Executive
Motor Insurance
T +65 6430 7893
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at Income.com.sg/careers



Our Ref: MT/CA/OD/051/1035462-001/YCL

14 Mar 2019

MY CAR CONSULTANT (SIN MING)
53 UBI AVENUE 1
#01-33 PAYA UBI INDUSTRIAL PARK
SINGAPORE 408934

Dear Sir,

CLAIM NUMBER: MT/1035462-001
REPAIR OF VEHICLE NUMBER: PC6780L

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 14 Mar 2019
Make: TOYOTA
Model: HIACE COMMUTER BUS (D)
Estimated Repair Days: 7
Location: NATIONAL ASSESSMENT CENTRE SERVICES
Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits: Not applicable

Excess Applicable: 2,000

Please note that supplementary items will not be allowed.

If you have any queries, please contact Yap Chee Ling at 6430-7893 or email us at motor@income.com.sg.

Yours sincerely

Jenny Pe

Deputy Vice President

Motor Insurance

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



NATIONAL ASSESSMENT CENTRE SERVICES
(LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315



Vehicle Movement Form

Vehicle Check-In

Vehicle No: P6780L Date In: _____ Time In: _____ with Keys: Yes / No

For Office use

Attended by: _____

Workshop Collection of Vehicle

Workshop: my car consultant pte ltd

Collection Date: 14/3/2019 Time: 3:05 PM with Keys: Yes / No

Tow Truck No: _____ Tow Man: Jeremy Yeo NRIC: S8633133J

Signature: [Signature]

For office use

Attended by: Jackson

Approved by: _____

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No

* Tow In / Drive In

Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____