

<<

Service Request Details

Claim

S8M00LRC

Reference

CS3/ASM18011477/Gqd3s2-1



Loss Date

June 21, 2018

Report Date

Jun 22, 2018 12:00:00 AM

Request Date

March 12, 2019

Due Date

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Re-inspection

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident Vehicle Registration #

SKA8652E

Make

TPVD HONDA

Model

FIT 1.5RS A

Service Address

51 Ubi Avenue 1, #01-25, , , 408933

Primary Contact/Insured

TAN PAIY PEE

86 BUTTERFLY AVENUE, 349832, Singapore

97902586

Claim Handler

PAY Daniel

zhihao.pay@axa.com.sg

Additional Instructions

Please attend to the re-inspection 12 MARCH 2019 @ 4:00PM

MessagesInvoicesHistoryDocumentsAssessmentMetricsNotes

Document Type	Document SubType				
+ Upload Documents					
NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED	
 SKT4511E INS GIA	Reports & Statement	GIA Report	Merimen		
 LKKInvoice1[1].pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	March 19, 2019	
 LKKPhoto.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	March 19, 2019	
 Re-inspection details.msg	Letters and Correspondence	Third Party	PAY Daniel	March 12, 2019	
 TP LOD.pdf	Legal	Letter of Demand/Notice of Proceedings	KUMAR Shailendra	September 25, 2018	
 LKKPreRepairInspection[4].pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 28, 2018	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKPhoto(2).pdf	Evidence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 27, 2018
 LKKPhotosIn6-1.pdf	Evidence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 26, 2018
 GA204850-Policy Schedule.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	TEO Kitty	June 24, 2018
 GA204850-Certificate of Insurance.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	TEO Kitty	June 24, 2018
 SKA8652E TP GIA RPT.PDF	Reports & Statement	GIA Report	TEO Kitty	June 24, 2018