



**AUTOBAY@KAKIBUKIT** 

1. Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883 Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680

Reg. No.: 254678/00M



Your Ref : 57K 3069 G

Our Ref : YN 8738H

United Overseas Ins Ital

**Attn: Motor Claims Dept** 

# ACCIDENT ON 07.03.2019 INVOLVING VEHICLE YN 8738 H & SJK 3069 G ALONG LORNIE RD TWDS BRADDELL RD

With regards to the above, we are writing on behalf of the registered owner of vehicle YN 8738 H which was involved in the above mentioned accident.

We are informed that the above accident was caused solely by the negligence of your insured vehicle SJK 3069 G.As a result of the accident, our client's vehicle was damaged and our client had instructed us to submit his claims for loss and expenses, particulars of which are follows:

1) Repair cost 2) Loss of use-\$200 X 07 days

3) LTA search

\$	9,407.49
\$	7.49
\$	1,400.00
\$	8,000.00

We hereby enclosed herewith the following documents for your consideration of the above claim.

a) Final Repair Bill Of YN 8738 H

c) LTA SEARCH

Total

b) GIA report

d) Owner / Driver NRIC & Driving License

Yours faithfully, **HUA MENG SPRAY PAINTING WORKSHOP** 

> MENG SPRAY PAINTING WORKSHOF AUTOBAY@KAKI BUKIT 1 KAKI BUKIT AVE 6 #01-34 SINGAPORE 41788 TEL: 6747 8064, 6746 5519 FAX: 6743 489





**AUTOBAY@KAKIBUKIT** 

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883 Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680

Reg. No.: 254678/00M



Your Ref:

Our Ref :

8/12/2020

Date:.

**VEHICLE NO** 

:YN 8738 H

MAKE / MODEL

:ISUZU NHR85AUE4A

NAME

:ISLAND RECOVERY SERVICES

**ADDRESS** 

:59 UBI AVE 1

#07-08 BIZLINK CENTRE

S 408938

#### FINAL REPAIR BILL FOR VEHICLE NO:YN 8738 H

TO SUPPLY AND REPLACE PARTS, LABOUR CHARGES FOR REPAIRING, KNOCKING, WELDING AND TO RESPRAY PAINTING (LUMPSUM REPAIR)

8,000.00

SINGAPORE DOLLARS: EIGHT THOUSAND ONLY

MSME18031564 / SME Motor Pte Ltd - Kaki Bukit ENTRY DATE & TIME: 08/03/2019 16:31 SUBMITTED BY: Chia Pei Ying

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

A second processing the second	ACCIDENT STATEMENT
Date Of Report	08/03/2019 16:31
Date Of Accident	07/03/2019 12:50
Exact Location Of Accident	LORNIE RD TWDS BRADDELL RD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vohiala Bagistration Number	VAIGTORIA

venicie Registration Number		YN8/38H				
the control of the co						
1						

Insured/Policyholder

Name Of Registered Owner ISLAND RECOVERY SERVICES

Co Reg No 53120055L Email Address NOEMAIL

Mobile Phone No

Alternative Phone No OFFICE-91828211

Vehicle Particulars

Manufacturer ISUZU

Model NHR85AUE4A R1

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

**Insurance Company** 

Name of Insurance Company AXA INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number P1916177

Cover Note Number

Driver

Name of Driver

NRIC No G7792171R

Date Of Birth

22/04/1987

Occupation

Outdoor

Date Of Driving Pass

LI ZHONGYU

G7792171R

22/04/1987

0UTDOOR

13/12/2014

Driving Experience 4 YEARS AND 2 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-90217295

Fax Number

Contact Number

EMail Address NOEMAIL

Address BLK 131 JALAN BUKIT MERAH #04-1599

Postcode 160131

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident **COLLISION - HEAD TO REAR** 

Weather Conditions **CLEAR** DRY Road Surface

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by

ambulance?

NO

YES Was any other material or property damaged?

NO

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

**Details of Police Action** 

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Number of Passengers (Including Driver)

Police Station Name

**EUNOS NPP** 

Police Station Address

ROAD: 629 BEDOK RESERVOIR ROAD #01-1620, POSTCODE: 470629,

**COUNTRY: SINGAPORE** 

Police Station Contact Was notice of intended Prosecution given?

TEL NO: - FAX NO:

If Yes, against whom?

NO

#### **Circumstances of Accident**

REFER TO POLICE REPORT: T/20190308/2088.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

# DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJK3069G

Vehicle Make/Model/Colour

**Details Of Properties** Vehicle Category

**VEHICLE B** 

PRIVATE CAR LIM KHEE MING

NRIC/Passport Number S1182523J

Contact Number

Name of Driver

Address Postcode

Insurance Company Name

Nature Of Damage

Page 2 of 18

No. Of Passenger (Including Driver)

	DETAILS OF INJL	JRED PERSON 1	
Name	LI ZHONGYL	J . ·	
Approximate Age		5 + 1 + 1	
Injuries Sustain	•		
Injured person in which vehicle?	YN8738H		÷
Were seat belts worn?			
Was this injured conveyed to hospital by ambulance?			
Address		• :,	
Postcode	•	5 - <del>-</del>	

#### Sketch Plan Pg. 1

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested narties
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature (if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

# Sketch Plan #2 Pg. 1

· SKETCH PLAN		
VII.	LI MARESMY SAU	
Ve	48 SYR30629	
	traine tomans Box	rided trad
	<del>╡╸</del> ╬╸┇╶┊┈┆╸┆╶┌╼ <del>╍╸</del> ┪╸┇╸┆╶┆╶╏╶╏╺╅ ┥╶╧╶╁╶╅╶╌╾┪╼╈╾╸╺╇╌┩╶╬╾╏╶┆╶┼╌┼╴┦╼╏	
	<u> </u>	
DESCRIBE CIRCUMSTANCES OF	THE ACCIDENT	-
b (, , , , ,	refer to the pori	1 report 7/80196308/8086
Please	7790- 10 100 100-	
	<u> </u>	
, ·		
· · · · · · · · · · · · · · · · · · ·		
DECLARATION	29	
/We declare the facegoing particulars	s are true in every respect.	
	MAL	
olicyholder's Signelige	Driver's Signature	Reporting Centre Personnel's Signature
Date & Time:	(If driver is not the policyholder)	Name:
•	Date & Time:	NRIC/FIN No.:

# Sketch Plan #4 Pg. 1





Police Station Of Origin:

Eunos NPP

629 Bedok Reservoir Road #01-1620

SINGAPORE 470629 Tel No: 1800-4439999

1 of 3 Report No. T/20190308/2088

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/03/2019 13:24			Vide Report No.:	Station Diary No.: 14	
Informa	nt's Partic	ulars			
Name of LI ZHON	Informant: IGYU		Address: APT BLK 131 JALAN BUKIT 160131	MERAH #04-1599 SINGAPORE	
ID Type / ID No.: FIN NO / G7792171R Nationality:			Contact No.: Home/Office: Mobile: 90217295 Email:		
CHINES	•		Linds.		
Sex: Male	1.0-1		Type of Informant: Driver		
Race: Chinese			Language:	Institution / School Name:	
Occupation: Other heavy truck and lorry drivers			Driving Licence Information:	Date of Expiry:	

General Inform Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 07/03/2019 12	Type of Location: Straight Road
Location: Along Road 1 LORNIE ROAD			* 1. 1. 1. 1.	
TOWARDS BR Weather:	ADDELL ROAD	Road Surface:	į.	Road Speed Limit:
Clear		Dry	٠.	
Traffic Flow: One Way		Traffic Control: Not Controlled	• .	Traffic Volume:
Type of Collisio Between Movin	n: g Vehicles - Head To	Rear	:	Anyone conveyed by ambulance:

Details of V	ehicle involved			a de la Congresión de la constant		
Vehicle No.	Туре	Make	Model	Color ಸ್ಪೃತ್ತಿಕ್ಕ	Condition	No of Passenger
SJK3069G	Car	MERCEDES	E200K	Grey	Slightly	0
		BENZ			Damaged	
YN8738H	Lorry	ISUZU	NHR85AUE4	Blue	Slightly	0
	·	İ	A R1		Damaged	

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA		

#### Sketch Plan #5 Pg. 1



Police Station Of Origin: **Eunos NPP** 629 Bedok Reservoir Road #01-1620 SINGAPORE 470629

2 of 3 Report No. T/20190308/2088

Tel No: 1800-4439999

#### CONTINUATION OF REPORT

Driver		XX 5. 12 种物。	200 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	<u> </u>	61.100	= + .
Name	LIM KHEE MING			ID No		S1182523J
Related Vehicle	SJK3069G (Car)			Contact No.		NIL
Hospital/Clinic	NIL			Class Drivin Licent Expiry	g	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discl	harge	NIL	
No. of Days gran	ted Medical Leave	NIL	Degree of	Injury	NIL	
Driver	the Conference South of the Con-		() () 有牌 ()			
Name	LI ZHONGYU			ID No		G7792171R
Related Vehicle	YN8738H (Lorry)			Conta	ct No.	90217295
Hospital/Clinic	GALILEE CLINIC			Class Driving Licent Expiry	g ce &	Class: 3,4 Date of Expiry: NIL
Date Treatment	08/03/2019		Date Disch	narge	08/03	3/2019
No. of Days gran	ted Medical Leave	03	Degree of	Injury	Slight	t

#### Brief Details.

On 07/03/2019 at around 1252hrs, I was driving along Lornie Road towards Bradell road as I was transporting vehicles to the Traffic Police Compound on the third lane when I suddenly felt an impact from the rear. Due to the impact, my lorry was pushed to my right in lane 2 before I steer it back into lane 3 and that's when I saw one Grey vehicle passing by me on lane 3 and stopping at the road shoulder ahead. The driver of the car then alighted and apologized saying he lost control of the car. We then exchanged particulars and took photos of the scene before i reported the incident to my company. On 08/03/2019, I then visited the doctor as I felt unwell and was given 3 days MC. The insurance company then advised me to lodge a Police report. The vehicle that I am driving was damaged on the rear left portion and the nut controlling the movable platform is spoilt thus making it unusable now.

## Sketch Plan #6 Pg. 1







Police Station Of Origin: Eunos NPP 629 Bedok Reservoir Road #01-1620 SINGAPORE 470629 Tel No: 1800-4439999 3 of 3 Report No. T/20190308/2088

CONTINUATION OF REPORT

# Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:	Signature Of Informant:
G/	
Sgt 2 LIEW CHONG XIANG, VINCENT	The state of the s
2	/\V
Signature Of Interpreter:	Date/Time:
Not applicable	08/03/2019 13:24
Officer In Charge Of Case:	Classification Of Case:
TP / AEIT /	
SSI 2 YEO GEAK ENG CECILIA	
Contact No.: 65476404	W
Authentication Stamp	· ·
NP168	

Alex







LI ZHONGYU

Birth Date. 22 Apr 1987 issue Date: 13 Dec 2014 Valid Till 12 Dec 2019



# YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Cli Class 3

Mo or ware such that with  $s \in 7$  passengers, evaluate of the creating tractor tractor deshibles  $s \in 2500$  kg and motor tractors > 2500 kg

EFFECTIVE DATE

13 Dec 2014 13 Feb 2019

G7792171H

S/No.9000288832

NP 428A



# WORK PERMIT

Employment of Foreign Manpower Act (Chapter 91A)
Recurblic of Singapure

1 ISLAND RECOVERY SERVICES



Name LI ZHONGYU Work Permit blov 0 57133198

Sector: SERVICE





K0689855

VISIT PASS Immigration Regulations

15-08-2018

G7792171R

Name LI ZHONGYU

Date of Birth 22-04-1987

Nationality CHINESE

MULTIPLE JOURNEY VISA ISSUED



AXA INSURANCE PTE LT 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 Customer Service Centre #B1-01 Tel:(05)63387288 Fax:(65)83382522 Website:www.axa.com.sq GST Registration Number: 199903512M customer.service@exe.com.sg



#### CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act. (Chapter 189) Motor Vehicles (Third-Party Risks and Compensation) Rules. 1960 | Road Transport Act. 1987 (Malaysia) | Motor Vehicles (Third-Party Risks) Rulos, 1959 (Malaysia)

CERTIFICATE NO.

. VCA/P1916177

Account No.: 03936

Coverage

: Comprehensive

Sum Insured

: Market Value At The Time Of Loss

Name of Policy Holder

: ISLAND RECOVERY SERVICES

Vehicle Registration No. : YN8730H

Period of Insurance

: From 01/04/2018 To 31/03/2019 (Both Dates Inclusive)

#### PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE\*

Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

#### LIMITATIONS AS TO USE\*

(a) Use in connection with the Policyholder's business

- (b) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business
- (c) Use for social, domestic and pleasure purposes

- This Policy does not cover

  (a) Use for hire or reward or for racing, pace-making, reliability trial or speed-testing
- (b) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

(05)

#### EXCESS:

Sect I - Any Authorised Driver : SGD 900.00 : SGD 900.00 Sect II-Any Authorised Driver Windscreen Excess : SGD 100.00

(Please refer to your policy for Additional Excess)

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AKA INSURANCE PTE LTD

Authorized Signature

Issued by - SGOMOHA

on 27/02/2018

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.

3/9/2019 Vehicle Hub

# Enquire Vehicle & Owner Information (Vehicle No. SJK3069G As At 07 Mar 2019 / 12:50:00)

Law Firm Search Details

Search Reason:

Insurance claim in relation to traffic accident

Law Firm Case No.:

H47-YN8738H

Current Owner Details

Owner ID Type:

Singapore NRIC

Owner ID:

S1182523J

Owner Name:

LIM KHEE MING

Registered Address Type:

Private Residential (non-Condo Apt / non-House)

Registered Block/House No.:41C

Registered Street Name:

**CHARLTON ROAD** 

Registered Unit No.:

Registered Building Name: -

Registered Postal Code:

539613

**Current Vehicle Details** 

Vehicle No.:

5JK3069G

Make Description/Model:

MERCEDES BENZ/E200K

Insurance Company Name: UNITED OVERSEAS INS LTD