



Steve

REF:

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop n/s: \_\_\_\_\_

of: \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

X	
N/S	O/S

Veh No: SKH 335L Yt Regn: 29/04/09

Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or

Make: Volkswagen Beetle CC: 1595

Colour: Black A/C: \_\_\_\_\_ Insured / Std / NI / NA

Sp. Reading: 153017 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

Ci/No: WVW 222 9C2 9M 557620

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15  
R: "

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front		Rear	
R/Bal. <u>7</u> mm		R/Bal. <u>7</u> mm	
L/Bal. <u>7</u> mm		L/Bal. <u>7</u> mm	
D.O.A. <u>6/3/19</u>		D.O.I. <u>12/3/19</u>	

Survey held at: MJE motor

Des. of Damages: Frt Rear / O/S / N/S / UIC / Rooftop or  
frnt RH

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time: \_\_\_\_\_ Action / Instruction: MV - 12,000  
PV - 8862  
INV - 3138

Repair range 6k - 7k, 6 days

  
21/3/2019

Date/Time, File Pass to?  : Proll. Report  
 : Final Report

Days Of Repair: 6  
Resurvey No. of Trip: 1

Date/Time, File Return to? \_\_\_\_\_

Report Format: PRE

Lump Sum / I.B.I. (\$) \_\_\_\_\_

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech Invs (\$)  
 : Weekend (\$)

Survey Fee: 120

Transportation \_\_\_\_\_

Photos \_\_\_\_\_

Other \_\_\_\_\_

10

130

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Mar 2019		11 Mar 2019 16:21 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b>			<b>[Created by insurer]</b>						
Insured:	MUHAMMAD ZULQARNAIN BIN MOHD AZMAN, ID: S9411389Z, Tel: +6597487799, Email: NOEMAIL								
Main Claimant:	JASMIN KOH XIN RU, ID: S8947462J								
Vehicle Reg. No.:	SKH335L	Date of Loss:	06/03/2019 18:00 - :59 [118 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/19-000277	Policy/Cover Note No.:	MSD/VMS/18-995702-WTT(TPFT) (TP, Fire & Theft) Coverage: 03/10/2018 - 02/10/2019						
Vehicle Reg. No. (Insured):	FBN4498Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Mje Motor (sin Ming, #01-96) (HQ) Block 7 Sin Ming Industrial Estate Sector C, #01-96, 575642 Sin Ming - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... <b>[Imm.Advice due 12/03/2019]</b>								
Driver/Custodian (Insured):	MUHAMMAD ZULQARNAIN BIN MOHD AZMAN (24 / Male) , NRIC: S9411389Z, Tel: +6597487799 Email: NOEMAIL								
Adj Asg. Remarks:	on WP. Liability not clear TP reject SJE - Assign LKK Auto Consultants Pte Ltd Contact - Y Y / Jo 9225 1391 / 6454 2203								
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>			<a href="#">View All</a>	<a href="#">Search Tasks</a>					
			<a href="#">Create New Task</a>	<a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	7462J
<b>Vehicle Details</b>	
Vehicle No.:	SKH335L
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Mar 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	NEW BEETLE 1.6 A 6SPD
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	BFS074264
Chassis No.:	WVWZZZ9CZ9M557620
Maximum Power Output:	75.0 kW (100 bhp)
Open Market Value:	\$17,594.00
Original Registration Date:	29 Apr 2009
First Registration Date:	29 Apr 2009
Transfer Count:	2
Actual ARF Paid:	\$17,594.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Apr 2019
PARF Rebate Amount:	\$8,797.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	28 Apr 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$5,116.00
COE Rebate Amount:	\$65.00
<b>Total Rebate Amount:</b>	<b>\$8,862.00</b>

The information contained herein is correct as at 12 Mar 2019

OK

**SELL YOUR CAR YOURSELF**  
Get listed until it's sold + we will handle all the paperwork!



**POST AN AD NOW!**

Volkswagen Beetle Price Range Depreciation 2009 Vehicle Type

Advanced Search

Home » Used Cars » Carro » Volkswagen New Beetle 1.6A

Volkswagen New Beetle 1.6A

Overview Financial Insurance Accessories Similar Research Photos Map

CONSIGNMENT



THE BETTER AUTOMOTIVE EXPERIENCE FOR EVERYBODY

<b>Price</b>	<b>\$13,400</b>	<b>Reg Date</b>	12-Aug-2009 (4mths 30days COE left)
<b>Depreciation</b> ?	N.A.	<b>Manufactured</b> ?	2009
<b>Mileage</b>	102,000 km (10.6k /yr)	<b>Transmission</b>	Auto
<b>Road Tax</b> ?	\$740 /yr	<b>OMV</b> ?	\$17,816
<b>Dereg Value</b> ?	\$9,545 as of today (change)	<b>ARF</b> ?	\$17,816
<b>COE</b> ?	\$15,291	<b>Power</b>	75.0 kW (100 bhp)
<b>Engine Cap</b>	1,595 cc	<b>No. of Owners</b> ?	3
<b>Curb Weight</b> ?	1,240 kg		
<b>Type of Vehicle</b>	Hatchback		

**Features**

1.6L Inline 4 Cylinders FSI Engine, 6 Speed Automatic With Steptronic, 4 x Airbags, ABS, ESP, Knockdown Rear Seats. View specs of the Volkswagen New Beetle (2005-2011)

**Accessories**

Sport Rims, Premium Leather Seats, CD Changer Factory Integrated Audio Systems, Remote Key With Immobilizer, Reverse Sensors.

**Description**

Very Well Maintenance Car As I Need Regular Servicing. The Maintenance Cost Is Very Low Compare To Other European Cars. Schedule A Test Drive Today. Viewing Is Strictly By Appointment Only.

**Category**

PARF Car, Consignment Car

**Status**

Available

Compare

**Owner Consignment Car**

This car is for sale by direct owner via a consignment agent. Consignment agents help to market, sell and handle all documentation on the car seller's behalf.

- » List of owner consignment cars
- » List of consignment agents



Shortlist Compare Add note  
Report Error More Actions

**Seller Information**

<b>Company</b>	<b>Carro</b> » dealer's pricelist » 128 vehs sold   114 vehs availa
<b>Address</b>	26 Sin Ming Lane #01-111 Search cars nearby this location
<b>Location</b>	Midview City
<b>Office No</b>	67146652
<b>Contact Person(s)</b>	Francis 87539!

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date Of Report	07/03/2019 16:11
Date Of Accident	06/03/2019 18:30
Exact Location Of Accident	LOYANG AVE TOWARDS TPE(PIE)
Country/State of Loss	SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKH335L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	JASMIN KOH XIN RU
NRIC No	S8947462J
Email Address	JKXR@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-90076908
Alternative Phone No	OFFICE-90076908
<b>Vehicle Particulars</b>	
Manufacturer	VOLKSWAGEN
Model	BEETLE
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	S 28843688 SMA
Cover Note Number	
<b>Driver</b>	
Name of Driver	JASMIN KOH XIN RU
NRIC No	S8947462J
Date Of Birth	29/12/1989
Occupation	INDOOR
Date Of Driving Pass	20/11/2014
Driving Experience	4 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90076908
Fax Number	
Contact Number	OFFICE-90076908
Email Address	JKXR@HOTMAIL.COM

Address	BLK 23 BALAM ROAD #02-183
Postcode	370023
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

**General Information of the Accident**

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

REFER TO ATTACHED

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH OWNER
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	FBH4498Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	MUHD ZULQARNAIN BIN MOHD AZMAN
NRIC/Passport Number	S9411389Z
Contact Number	97487799
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Loyang Ave towards TPE (PIE) in lane 4. Approaching the above traffic junction, the traffic light was green, my lane without was clear and I proceeded straight. Suddenly, vehicle B changed lane in yellow box, cut into my lane and collided into the ~~rear~~ front of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Mar 2019		11 Mar 2019 16:21 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float:right">[Created by insurer]</span>									
Insured:	<b>MUHAMMAD ZULQARNAIN BIN MOHD AZMAN</b> , ID: S9411389Z, Tel: +6597487799, Email: NOEMAIL								
Main Claimant:	<b>JASMIN KOH XIN RU</b> , ID: S8947462J								
Vehicle Reg. No.:	<b>SKH335L</b>	Date of Loss:	06/03/2019 18:00 - :59 [118 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / MSC/V/19-000277</b>	Policy/Cover Note No.:	MSD/VMS/18-995702-WTT(TPFT) (TP, Fire & Theft) Coverage: 03/10/2018 - 02/10/2019						
Vehicle Reg. No. (Insured):	<b>FBN4498Z</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Mje Motor (sin Ming, #01-96) (HQ)</b> Block 7 Sin Ming Industrial Estate Sector C, #01-96, 575642 Sin Ming - Tel:								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Monica Chung Pei Zhen</b> - 6594 2552]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>CHEN TSUE YEE</b> ] ... [Imm.Advice due 12/03/2019]								
Driver/Custodian (Insured):	MUHAMMAD ZULQARNAIN BIN MOHD AZMAN (24 / Male) , NRIC: S9411389Z, Tel: +6597487799 Email: NOEMAIL								
Adj Asg. Remarks:	on WP. Liability not clear TP reject SJE - Assign LKK Auto Consultants Pte Ltd Contact - Y Y / Jo 9225 1391 / 6454 2203								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float:right"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float:right"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

**\*SKH335L (MSC/V/19-000277)  
[FBN4498Z]**

TP

**JASMIN KOH XIN RU**

Mar 6 2019 6:00PM

**[MUHAMMAD ZULQARNAIN BIN MOHD AZMAN]**

**Mje Motor (sin Ming, #01-96)**

Upload Documents		Upload Photos		Compose New Letter		View	View in Browser
<b>Assessment Reports</b>						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)			Thumbnail	Print	
1	08/03/19 13:28	<b>Accident Statement</b> From:SC - Reg. No: FBN4498Z, Claimant: MUHAMMAD ZULQARNAIN BIN MOHD AZMAN			Load HTM	<input type="checkbox"/>	
<b>Photos/Images</b>						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
2	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
3	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
4	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
5	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
6	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
7	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
8	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
9	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
10	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
11	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
12	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
13	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
14	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
15	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
16	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
17	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
18	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
19	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
20	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
21	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
22	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
23	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
24	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
25	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
26	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
27	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
28	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
29	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
30	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
31	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
32	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	
33	13/03/19 08:08	Front View			Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	13/03/19 08:08	<b>Odometer Reading</b>	 Load JPG	<input checked="" type="checkbox"/>
35	13/03/19 08:08	<b>Chassis Number</b>	 Load JPG	<input checked="" type="checkbox"/>
36	13/03/19 08:08	<b>Front View</b>	 Load JPG	<input checked="" type="checkbox"/>
37	13/03/19 08:08	<b>Front View</b>	 Load JPG	<input checked="" type="checkbox"/>
38	13/03/19 08:08	<b>Front View</b>	 Load JPG	<input checked="" type="checkbox"/>
39	13/03/19 08:08	<b>Front View</b>	 Load JPG	<input checked="" type="checkbox"/>
40	13/03/19 08:08	<b>Front View</b>	 Load JPG	<input checked="" type="checkbox"/>
41	28/03/19 15:59	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
42	28/03/19 15:59	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
43	28/03/19 15:59	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
44	28/03/19 15:59	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
45	28/03/19 15:59	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
46	28/03/19 15:59	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
47	28/03/19 15:59	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
48	28/03/19 15:59	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
49	28/03/19 15:59	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
50	28/03/19 15:59	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
51	28/03/19 15:59	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
52	28/03/19 15:59	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
53	28/03/19 15:59	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
54	28/03/19 15:59	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
55	28/03/19 15:59	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
56	28/03/19 15:59	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
57	28/03/19 15:59	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
58	28/03/19 15:59	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
59	28/03/19 15:59	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
60	28/03/19 15:59	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
61	28/03/19 15:59	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
62	28/03/19 15:59	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
63	28/03/19 15:59	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/03/19 16:36	<b>SKH335L E-FILE REPORT</b> From: SC - Reg. No: FBN4498Z, Claimant: MUHAMMAD ZULQARNAIN BIN MOHD AZMAN	 Load PDF	
2	08/03/19 17:20	<b>TP reject SJE - Assign LKK</b>	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19004443/ECD3E2

Date: 29/03/2019

#### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: MSD/VMS/18-995702-WTT (TPFT)	
Claimant Vehicle No: SKH335L	Insured Vehicle No: FBN4498Z	
Date of Loss: 06/03/2019	Nature of Claim: TP	Claim No: MSCV/19-000277

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: <b>SKH335L</b>	Engine No: BFS074264
Make & Model: VOLKSWAGEN NEW BETTLE, 1.6 (A)	Chassis No: WWWZZZ9CZ9M557620
Reg. Date: 29/04/2009 (Man. Year: 2009)	Odometer: 153017 km
Colour: Black	
Engine Capacity: 1595 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): <b>Market Value/New Car Price</b>	

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment:	11/03/2019	
Date Inspected:	12/03/2019 Inspected At:	Mje Motor (sin Ming, #01-96) (HQ) Block 7 Sin Ming Industrial Estate Sector C, #01-96 Singapore 575642
Estimated Period of Repair:	6.0 days	

**Adjuster:** CHEN TSUE YEE

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 -\$7,000.00

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 29 Mar 2019)
<b>Parts:</b> 144	VOLKSWAGEN NEW BETTLE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKH335L)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >