

1/01/2007

ASS. REC. BY:

REF: CS/MSG19004444/ksd3n2 Special Instruction:

Surveyor: Kenneth ASSIGNMENT (Office)From Person: Meimien Katherine Wong of MSIADate/Time: 11/3/19 @ 4.18pm

Estimated Cost: Bill to: ..

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: SME 3423 H Insured: SKZ 769 3Lat Workshop m/s: Optima Workz Tel: ..of 9A Serangoon North Ave 5Policy No: 29113428 QMX Claim No: ..

Sum Insured: Excess: ..

Make of Veh: D.O.A. 8/3/2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11:17am @ 12/3/19 Person Contacted: LilyVehicle IN/OUT

Date/Time Action/Instruction (✓) Estimate

SME 3423H - X

SKZ 7693L - X ..

14/03/19 @ 15:33 p.m. revised Ia to Katherine Wong via  
meimien.

28/3 @ 4068-50 email &amp; confirm (\$ 460/- Red - 10%)

ASS. REC. BY:

REF: *MSG 1*

## ASSIGNMENT

From: \_\_\_\_\_

Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop n/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

*04* days

Res.: Yes or No

Lum Sum: \_\_\_\_\_

*1.B.1* %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: \_\_\_\_\_

*PM-34234*

Yr Regn: \_\_\_\_\_

*11.18*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: \_\_\_\_\_

*Tuy Vellier*

c.c. \_\_\_\_\_

*2493*

Colour: \_\_\_\_\_

*M. Black*

A/C: Insured / Std / NI / NA

Sp. Reading \_\_\_\_\_

*5023*

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

*AGH30. 0190584*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: \_\_\_\_\_

F: \_\_\_\_\_

*215/85R16*

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal. \_\_\_\_\_

*9*

mm

R/Bal. \_\_\_\_\_

*9*

mm

L/Bal. \_\_\_\_\_

*9*

mm

L/Bal. \_\_\_\_\_

*9*

mm

D.O.A. \_\_\_\_\_

*8/3/19*

D.O.I. \_\_\_\_\_

*12/3/19*

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

*N/S/R*

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*1 File pass to*

RECEIVED 28 MAR 2019

*28/3/2019*

Date/Time, File Pass to?

*28/03/19*

1) \_\_\_\_\_

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Prell. Report☒ : Final Report

Days Of Repair: \_\_\_\_\_

*4*

Resurvey No. of Trip: \_\_\_\_\_

*1*Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees:

Others:

TOTAL

*150**10**160*

Report Format :

Lump Sum / I.B.I: (\$

*4,067.50 p/p*

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 14 Mar 2019

## Preliminary Advice

Insured Vehicle No : SKZ7693L  
TP Vehicle No : SMF3423H  
Make : TOYOTA VELLFIRE  
Date of Inspection : 12/03/2019  
Inspection At : Optima Werkz Pte Ltd (HQ)  
9A Serangoon North Ave 5  
Singapore 554500

Accident Date : 08/03/2019  
Assignment Date : 11/03/2019  
Est. Duration of Repair : 4 days

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,527.50
Revised Amount	:S\$	3,953.75
Check Items (Estimated)	:S\$	273.75
Total	:S\$	4,227.50

Lump Sum Repair :S\$

### Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Mar 2019 10:53		11 Mar 2019 16:18 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

### CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	CHEONG YOUNG KONG, ID: S0169846Z		
Main Claimant:	GAN SENG YII, ID: S8074523J		
Vehicle Reg. No.:	SMF3423H	Date of Loss:	08/03/2019 00:00 - :59 [4 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	29113428QMX Coverage: 02/02/2019 - 01/02/2020
Vehicle Reg. No. (Insured):	SKZ7693L	Policy No. (Claimant):	
		Excess:	
Repairer:	Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5, 554500 Serangoon - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/03/2019]		
Adj Asg. Remarks:	on WP, Liability unclear, TP want to use LKK as the SJE. TP said car will be in at 12pm later and owner will be waiting. Pls attend to it urgently.		

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	4523J
<b>Vehicle Details</b>	
Vehicle No.:	SMF3423H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	09 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VELLFIRE 2.5X AUTO
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	2ARJ086316
Chassis No.:	AGH300192587
Maximum Power Output:	134.0 kW (179 bhp)
Open Market Value:	\$37,187.00
Original Registration Date:	05 Nov 2018
First Registration Date:	05 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$44,062.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Nov 2028
PARF Rebate Amount:	\$33,046.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	04 Nov 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$33,420.00
COE Rebate Amount:	\$26,736.00
<b>Total Rebate Amount:</b>	<b>\$59,782.00</b>

The information contained herein is correct as at 09 Mar 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	08/03/2019 12:11
Date Of Accident	08/03/2019 08:45
Exact Location Of Accident	COMMONWEALTH AVE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SMF3423H
Insured/Policyholder	
Name Of Registered Owner	GAN SENG YII
NRIC No	S8074523J
Email Address	SYGAN80@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-93866221
Alternative Phone No	OTHERS-93866221
Vehicle Particulars	
Manufacturer	TOYOTA
Model	VELLFIRE 2.5X AUTO
Exact Purpose for which vehicle was being used at time of accident	GOING TO WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5105283088
Cover Note Number	
Driver	
Name of Driver	GAN SENG YII
NRIC No	S8074523J
Date Of Birth	19/04/1980
Occupation	INDOOR
Date Of Driving Pass	07/05/2005
Driving Experience	13 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93866221
Fax Number	
Contact Number	OTHERS-93866221
Email Address	SYGAN80@YAHOO.COM.SG

Address	BLK 425 CLEMENTI AVENUE 1 #04-295
Postcode	120425
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : YU MANYI
	GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO THE ATTACHED SKETCH PLAN. WILL REPAIR & CLAIM AT OPTIMA WERKZ PTE LTD.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PASS TO OWNER WORKSHOP
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKZ7693L
Vehicle Make/Model/Colour	RED / MERCEDES
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHEONG YOUNG KONG
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)



## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### Sketch Plan #2

### SKETCH PLAN



(A) SMF 3423H  
(B) SK77693L

Commonwealth Ave  
towards AYE

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 8/3/89 at about 8:47AM, I was travelling along Commonwealth Ave towards AYE. Out of sudden, vehicle (B) SKZ 7693L cut into my lane without signal and hit onto my vehicle (A) SMF 3423H left front side portion.

After accident, we exchange particulars.

I wish to lodge this report for insurance claim purpose

I prefer to repair at Optima Wreck Patrol

No one was injured.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature:  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Date: 08/03/2019  
 Vehicle No: SMF3423H  
 Model: TOYOTA VELLFIRE 2.5X AUTO  
 Chassis: AGH300192587 - 2018

Third Party Insurer: MSIG  
 Third Party Veh No: SKZ7693L  
 Date of Accident: 08/03/2019

## ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT HEADLAMP LH 3013	1		LM \$2,625.00 ✓
2	FRONT BUMPER 1655.10	1		Bu/LM \$1,500.00 ✓
3	FRONT BUMPER SIDE BRACKET LH	1		LM \$125.00 ✓
4	FRONT FENDER LH	1		REPAIR
SUB TOTAL				\$4,250.00
LESS 25%				-\$1,062.50
PARTS TOTAL				\$3,187.50

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1 SET		LM \$60.00 ✓
S/N TOTAL				\$60.00

### LABOUR CHARGES:

LABOUR CHARGES REMOVE & REPLACE REAR & FRONT ACCIDENT AREA & ETC 350h \$500.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINTS & FURNISHING MATERIALS 450h \$600.00

TO CHECK WIRING & ELECTRICAL DIAGNOSTICS 20h \$180.00

LABOUR TOTAL \$1,280.00

ONG TOTAL \$4,527.50

*[Signature]*  
 15/3/19

Not Notified  
 Repair by paint

4 days @ 4067.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:

Head office

6 Kung Chong Road Singapore 159143  
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500  
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Date:

Branch

551 Upper Thomson Road Singapore 574415  
 Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19004444/KSD3N2

Date: 03/04/2019

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29113428QMX
Claimant Vehicle No :	SMF3423H	Insured Vehicle No :	SKZ7693L
Date of Loss:	08/03/2019	Nature of Claim:	TP
		Claim No:	587247

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SMF3423H	Engine No:	2ARJ086316
Make & Model:	TOYOTA VELLFIRE, 2.5 (A)	Chassis No:	AGH300192587
Reg. Date:	05/11/2018 (Man. Year: 2018)	Odometer:	5023 km
Colour:	Metallic Black		
Engine Capacity:	2493 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/65R16	Rear Tyre Size:	215/65R16
Front Left Side:	Goodyear 9 mm	Rear Left Side:	Goodyear 9 mm
Front Right Side:	Goodyear 9 mm	Rear Right Side:	Goodyear 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,247.50	3,247.50	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	820.00	460.00	35.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,527.50</b>	<b>4,067.50</b>	<b>460.00</b>	<b>10.16</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>316.93</b>	<b>284.73</b>	<b>32.20</b>	<b>10.16</b>
<b>Nett Amount (S\$)</b>	<b>4,844.43</b>	<b>4,352.23</b>	<b>492.20</b>	<b>10.16</b>

## INSPECTION

Date of Assignment:	11/03/2019	Inspected At:	Optima Werkz Pte Ltd (HQ)
Date Inspected:	12/03/2019		9A Serangoon North Ave 5
			Singapore 554500

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 03 Apr 2019)
<b>Parts:</b> M1-MPV	TOYOTA VELLFIRE 2.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SMF3423H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP LH	Cut	2,625.00 FL	*2,625.00 FL
2	1		*FRONT BUMPER	Buckled/Cut	1,500.00 FL	*1,500.00 FL
3	1		*FRONT BUMPER SIDE BRACKET LH	Cracked	125.00 FL	*125.00 FL
4	1		*FRONT FENDER LH (NPA)	Repair	0.00 FL	*- FL
5	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*60.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (S\$)					4,310.00	4,310.00
- List Item Discount on L Items 25.00/25.00% (S\$)					1,062.50	1,062.50
Total Parts (S\$)					3,247.50	3,247.50

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES REMOVE & REPLACE REAR & FRONT ACCIDENT AREA & ETC	New	500.00	350.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINTS & FURNISHING MATERIALS	New	600.00	450.00
3	TO CHECK WIRING & ELECTRICAL DIAGNOSTICS	New	180.00	20.00
Gross Labour Cost (\$\$)			<b>1,280.00</b>	<b>820.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >