

DATE/TIME

ASS. REP. / BY

REF: CS3/ PWD 1900483X1 E-13021

Special Instruction

NAME(S) / UNIT
MINIMUN

Steve
Clark Li

ASSIGNMENT (Office)

PWD

Date/Time: 11/3/19 @ 2:04pm

Estimated Cost

Tel No:

OD WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

SKT 3420R

Insured

SLA 4094E

at Workshop/Int:

Sze kang Automobile

Tel:

6481 2712

of

10 Amk Ind. park 2A # 03-09/17

Policy No:

PNPV20B-0000237-01

Claim No:

1201900005878

Name Insured

Phone:

Make of Veh:

D.O.A

4/3/2019

(Chief's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Placement

Date/Time:

10:53am / 12/3/19

Person Controlled

Vehicle

IN

OUT

Date/Time


Action/Instruction (X) Estimate

Vehicle already dismantle today (12/3/19) when surveyor go down.

SKT 3420R - X

SLA 4094E - X

Paper Survey plus PRS.


26/4/2019

Revenue Steve

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SKT 3420 R Yr Regn: 30/05/15
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Nissan Qashqai c.c. 1197
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 70248 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: SJNFEAJ114 1342208
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 215/60R17
 R: _____

X X X	
N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Confidential

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS _____
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 4/3/19 D.O.I. 12/3/19
 Survey held at See kang Auto

Des. of Damages (Frt) Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
26/4	According to Nutha that clara say ^{(and) go ahead.} just take dismantle photo. on 12/march 2019. Submit \$6,600. 5days 4s. (Red)

RECEIVED 26 APR 2019

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) 26/4 Typst
 Date/Time, File Return to?

Days Of Repair: 5
 Resurvey No. of Trip: _____

Report Format: TP
 Lump Sum / I.B.I. (\$) 6,600

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Survey Fee:	<u>200</u>
Transportation:	<u>50</u>
S + RS \$	
Photos	<u>10</u>
Others	
TOTAL	<u>260</u>

Nivitha (LKK Auto)

From: clara.li@fwd.com
Sent: Wednesday, 24 April 2019 7:00 PM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Cc: motorclaims.sg@fwd.com
Subject: [Paper Resurvey] YSY/19.021792 - Accident invlg SKT 3420R & SLA 4094E along Admiralty Road West on 4.3.19 Our Ref: 1201900005878
Attachments: 20190422152207934.pdf

Hi LKK team,

Please submit survey photos in Merimen and assist with paper resurvey.

Attached is the relevant documents.

Thank you.

Regards,
Clara

From: Clara Li Zirong - SGUser
Sent: Wednesday, 13 March, 2019 10:40 AM
To: Eileen Cheong
Cc: Motor Claims SG - SG Common; assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Subject: RE: YSY/19.021792 - Accident invlg SKT 3420R & SLA 4094E along Admiralty Road West on 4.3.19 Our Ref: 1201900005878

Dear Eileen,

LKK Auto Consultants Pte Ltd has gone down to the workshop for photo taking.

Moving forward, please note that we do not accept fax and please send in any correspondences related (PRS, LOD, etc) to Motor Claims via e-mail to motorclaims.sg@fwd.com.

Thank you.

Kind Regards
Clara Li
Senior Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722
E clara.li@fwd.com
W fwd.com.sg

Nivitha (LKK Auto)

From: clara.li@fwd.com
Sent: Monday, 11 March 2019 2:04 PM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Cc: motorclaims.sg@fwd.com
Subject: RE: YSY/19.021792 - Accident invlg SKT 3420R & SLA 4094E along Admiralty Road West on 4.3.19 Our Ref: 1201900005878

Hi LKK team

Please create the case in Merimen.

Thank you.

Regards,
Clara

From: Clara Li Zirong - SGUser
Sent: Friday, 8 March, 2019 12:25 PM
To: 'Eileen Cheong'
Cc: Motor Claims SG - SG Common; 'assignments@lkkauto.com'; 'sur@lkkauto.com'; 'admin-a@lkkauto.com'; 'admin-d@lkkauto.com'
Subject: RE: YSY/19.021792 - Accident invlg SKT 3420R & SLA 4094E along Admiralty Road West on 4.3.19

WITHOUT PREJUDICE

Dear Sir/ Madam,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s LKK AUTO CONSULTANTS PTE LTD, to conduct the pre-repair survey (PRS) on your client's vehicle. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

**Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.*

**Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.*

Kind Regards
Clara Li
Senior Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722
E clara.li@fwd.com
W fwd.com.sg



From: Eileen Cheong [<mailto:eileencheong@ascentzialawcorp.com>]
Sent: Friday, 8 March, 2019 12:23 PM
To: Clara Li Zirong - SGUser
Cc: Motor Claims SG - SG Common
Subject: YSY/19.021792 - Accident invlg SKT 3420R & SLA 4094E along Admiralty Road West on 4.3.19

Dear Clara

We refer to your email dated 8 March 2019.

Our client is not agreeable to your list of surveyors. Our client's list of surveyors are as follows:-

- 1) Absolute Appraisal Services Pte Ltd
Block 16 Sin Ming Industrial Estate Sector A
#01-81
Singapore 575674
- 2) JP Knights Pte Ltd
33 Ubi Avenue 3 #05-47
Vertex Tower
Singapore 408868
- 3) Sincere Appraisal Services
81 Ubi Avenue 4 #06-28
UB One
Singapore 408830
- 4) Kelvin Automotive Appraising Services (KAAS)
6 Tampines Street 73 #01-03
Singapore 528825
- 5) MC-Coy Appraiser Pte Ltd
No. 1 Kaki Bukit Avenue 6 #01-28
Autobay@KB
Singapore 417883
- 6) Prominent Appraiser Services Pte Ltd
No. 1 Simei Street #02-24

Singapore 529890

- 7) Delta-V Consultant
Block 171 Kallang Way #01-07
Singapore 349250
- 8) Advanced Automotive Consultancy Pte Ltd
Block 159 Yishun Street 11 #04-166
Singapore 760159
- 9) Pal's Appraiser Pte Ltd
No. 1 Kaki Bukit Avenue 6 #01-28
Autobay@Kaki Bukit
Singapore 417883
- 10) S K Auto Consultants
Block 310B Anchorvale Link #06-15
Singapore 542310
- 11) Appraisal VP Pte Ltd

Kindly make the necessary arrangements with the workshop for the pre-repair inspection (if required).

If we do not receive a response by 8 March 2019, we will proceed on the basis that you have waived your rights to a pre-repair inspection.

Yours faithfully,

Eileen Cheong
Legal Manager

Ascentsia
Law Corporation

Ascentsia Law Corporation
(Company Registration No. 200204598E)
10 Anson Road
#03-22 International Plaza
Singapore 079903
Tel : (65) 6534 3552
DID: (65) 6327 5776
Fax : (65) 6535 9920

(Service of Court documents by fax not accepted)

CONFIDENTIALITY CAUTION: This message, including all the attachments, is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. The unauthorised use, disclosure or copying of this message, including all attachments, is strictly prohibited. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify me immediately by return e-mail and delete the original message, including any hardcopy printed by you. Ascentsia Law Corporation and the writer of this message do not accept liability whatsoever arising from this form of communication.

Please consider the environment before printing this email.

From: clara.li@fwd.com <clara.li@fwd.com>

Sent: Friday, March 8, 2019 11:45 AM

To: eileencheong@ascentsialawcorp.com

Cc: motorclaims.sg@fwd.com

Subject: RE: YSY/19.021792 - Accident invlg SKT 3420R & SLA 4094E along Admiralty Road West on 4.3.19

WITHOUT PREJUDICE

Dear Eileen,

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. Appraisals Associates Pte Ltd
5. VICOM Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

**Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.*

**Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.*

Kind Regards

Clara Li

Senior Executive, Claims

FWD Singapore Pte. Ltd.


6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E clara.li@fwd.com

W fwd.com.sg

FWD
insurance



From: Eileen Cheong [mailto:eileencheong@ascentsialawcorp.com]

Sent: Friday, 8 March, 2019 11:43 AM

To: Motor Claims SG - SG Common

Subject: YSY/19.021792 - Accident invlg SKT 3420R & SLA 4094E along Admiralty Road West on 4.3.19

Dear Sirs

We act for Mr Kai Beng Hee Gideon, who is the registered owner and driver of motor vehicle no. SLA 4094E at the material time.

Our client was involved in an accident on 4 March 2019 with your insured's motor vehicle no. SLA 4094E and has suffered damages, loss and expenses.

In accordance to the NIMA Protocol, we hereby give you 2 working days notice for you to conduct a pre-repair inspection of our client's motor vehicle at the following workshop:

Sze Kang Automobile Spraying Services

10 Ang Mo Kio Industrial Park 2A

#03-09/17

Singapore 568047

Tel: 6481 2712/8201 9979

Kindly make the necessary arrangements with the abovementioned workshop for your surveyor to conduct a pre-repair inspection (if required).

If we do not receive a response by 7 March 2019, we will proceed on the basis that you have waived your rights to a pre-repair inspection.

Yours faithfully,

Eileen Cheong
Legal Manager

Ascentsia
Law Corporation

Ascentsia Law Corporation
(Company Registration No. 200204598E)
10 Anson Road
#03-22 International Plaza
Singapore 079903
Tel : (65) 6534 3552
DID: (65) 6327 5776
Fax : (65) 6535 9920

(Service of Court documents by fax not accepted)

CONFIDENTIALITY CAUTION:This message, including all the attachments, is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. The unauthorised use, disclosure or copying of this message, including all attachments, is strictly prohibited. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify me immediately by return e-mail and delete the original message, including any hardcopy

printed by you. Ascentsia Law Corporation and the writer of this message do not accept liability whatsoever arising from this form of communication.

Please consider the environment before printing this email.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

< > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0156F
Vehicle Details	
Vehicle No.:	SKT3420R
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Apr 2019
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	HRA2129633A
Chassis No.:	SJNFEAJ11U1342208
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$19,382.00
Original Registration Date:	30 May 2015
First Registration Date:	30 May 2015
Transfer Count:	0
Actual ARF Paid:	\$9,382.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 May 2025
PARF Rebate Amount:	\$7,036.00
Intended COE Rebate Details	
COE Expiry Date:	29 May 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$67,749.00
COE Rebate Amount:	\$41,286.00
Total Rebate Amount:	\$48,322.00

The information contained herein is correct as at 25 Apr 2019

OK

MV - 64,000
 PV - 48,322
 NV - 15,678

**CHEAPEST CAR
INSURANCE RENEWAL**



Compare
10+ Insurers

GET A CHEAPER QUOTE NOW!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Nissan X-TR 3.0 Luxury Sedan



Beautiful Pearl White Body Color
Original Price \$100,000 Leased
Immaculate!
Direct Owner Touch

KA-HUP
VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND
HOTLINE: 6741 9997 [View Our Cars](#)

Browse by Category

< Back (1 2) Next >

Sort by Date Posted 20 results/page

23 vehicles

nissan qashqai

Advanced Search

Year	Model	Price	Depreciation	Eng Date	Eng Cap	Mileage	Veh Type	Status
2015	Any	Any	Any	2015	Any	Any	Any	Available
	Nissan Qashqai 1.2A DIG-T Premium	\$59,888	\$9,520 /yr	10-Feb-2015	1,197 cc	53,797 km	SUV	Available
<p>1 Owner, Fully Serviced And Maintained By Tan Chong Motors, Agent Warranty, Excellent Condition, Do Not Miss!</p> <p>Posted: 23-Apr-2015 Tags: 2015 Nissan Qashqai, 2015 Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Used Nissan</p>								
	Nissan Qashqai 1.2A DIG-T Premium	\$57,800	\$9,140 /yr	13-Feb-2015	1,197 cc	102,621 km	SUV	Available
<p>Number 1 SUV Ranking! Best Unit With Best Pricing In Market! Accident Free, Welcome Check! 6 Monthly Road Tax Just Renewed! In House High Loan Available! Contact/SMS Our Appointed Sales Person Directly...</p> <p>Posted: 06-Apr-2015 Tags: 2015 Nissan Qashqai, 2015 Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Used Nissan</p>								
	Nissan Qashqai 1.2A DIG-T	\$44,800	\$9,890 /yr	22-May-2015	1,197 cc	53,300 km	SUV	Available
<p>Enjoy Loan Interest Rate At 2.28%! Comes With Agent Warranty Of 5 Years, Extremely Well Maintained! This Beast Does Not Just Look Beautiful, It's 100% Accident-Free. View To Believe! Financing Possible...</p> <p>Posted: 20-Apr-2015 Tags: 2015 Nissan Qashqai, 2015 Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Used Nissan</p>								
	Nissan Qashqai 1.2A DIG-T Premium	\$69,800	\$10,550 /yr	30-Jun-2015	1,197 cc	-	SUV	Available
<p>One Year Warranty On Engine, Gearbox And Aircon! 100% Loan Available With Fast Approval! Superb Good Condition, Fully Agent Serviced! No Repair Needed! Always Parked Under Shelter! Smooth Drive! Welcom...</p> <p>Hua Yang Credit Pte Ltd</p> <p>Posted: 24-Apr-2015 Tags: 2015 Nissan Qashqai, 2015 Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Used Nissan</p>								
	New Audi A6 is cushy and techy	<p>The new Audi A6 proves capable of beating the Mercedes-Benz E-Class but lacks the sportiness of the BMW 5 Series.</p> <p>Find out more!</p>						
	Nissan Qashqai 1.2A DIG-T	\$48,800	\$9,730 /yr	29-Aug-2015	1,197 cc	54,000 km	SUV	Available
<p>1 Owner Unit, Fully Serviced By Agent, Spacious And Powerful With Comfortable Interior, Practical For Daily Use. Low On Road Tax And Maintenance! Full Loan Options Available! Call For A Viewing Apoin...</p> <p>Posted: 22-Apr-2015 Tags: 2015 Nissan Qashqai, 2015 Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Used Nissan</p>								
	Nissan Qashqai 1.2A DIG-T	\$48,800	\$9,770 /yr	21-Aug-2015	1,197 cc	79,500 km	SUV	Available
<p>Graded B by STRA</p> <p>Visit Us At Cars At EXPO This Weekend For Exciting And Exclusive Deals!</p> <p>Supreme Cars Pte Ltd</p> <p>Posted: 24-Apr-2015 Tags: 2015 Nissan Qashqai, 2015 Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Used Nissan</p>								
	Nissan Qashqai 1.2A DIG-T	\$43,800	\$8,600 /yr	19-Sep-2015	1,197 cc	82,000 km	SUV	Available
<p>Well Maintained By Owner, Original Paintwork, Clean And Comfort Interior, Low Road Tax And Fuel Consumption. Bank Loan / In House Loan Available, Trade In Welcome.</p> <p>Posted: 20-Apr-2015 Tags: 2015 Nissan Qashqai, 2015 Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Used Nissan</p>								
	Nissan Qashqai 1.2A DIG-T	\$46,800	\$9,370 /yr	23-Sep-2015	1,197 cc	48,670 km	SUV	Available
<p>Mileage Done 48670 Km Only, 1 Owner, Full Service By Tan Chong Agent, Well Taken Care Interior, Keyless Entry, Immaculate Condition, High Trade In Price, Loan Available! Flexible Repayment With In Res...</p> <p>Universal Motorsing</p> <p>Posted: 23-Apr-2015 Tags: 2015 Nissan Qashqai, 2015 Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Nissan Qashqai, Used Nissan</p>								
	Nissan Qashqai 1.2A DIG-T Premium	\$46,800	\$9,340 /yr	30-Sep-2015	1,197 cc	68,800 km	SUV	Available

Compare

AUTO PERFORMANCE APPRAISAL

12019 00005878(CD)

APA

TAX INVOICE

Kai Beng Hee Gideon
C/O Sze Kang Automobile Spraying Services
10 Ang Mo Kio Ind. Park 2A
Ang Mo Kio Auto Point #03-17/09
Singapore 568047

INVOICE NO : APA19001766
DATE : 25/03/2019

VEHICLE NO : SKT3420R
JOB REFERENCE NO : 19/001865
ACCIDENT DATE : 04/03/2019
SURVEY DATE : 05/03/2019

<u>DESCRIPTION</u>	<u>AMOUNT</u>
Survey Fees Inclusive Of Transportation	\$615.00
Photographs (\$1) Per Copies : 77	\$77.00
TOTAL AMOUNT	\$692.00

Notes :

All cheque payment should be "Crossed" and made payable to "Auto Performance Appraisal"

Auto Performance Appraisal



AUTO PERFORMANCE APPRAISAL

APA

VEHICLE SURVEY REPORTS																																
Kai Beng Hee Gideon C/O Sze Kang Automobile Spraying Services 10 Ang Mo Kio Ind. Park 2A Ang Mo Kio Auto Point #03-17/09 Singapore 568047																																
1	Reference Job Reference No : 19/001865 Claim No : - Claim Type : Third Party Accident Date : 04/03/2019 Survey Date : 05/03/2019 Survey Report Date : 25/03/2019																															
2	Particulars Of Vehicle Vehicle Registration No : SKT3420R Make & Model : Nisan Qashqai Vehicle Registration Date : 30/05/2015 Chassis No : SJNFEAJ11U1342208 Engine No : Blocked Colour : Blue																															
3	Condition Of Vehicle And Tyres <table border="0" style="width: 100%;"> <tr> <td><u>Mileage (KM)</u></td> <td><u>Brakes</u></td> <td><u>Steering</u></td> <td><u>Modification</u></td> </tr> <tr> <td>70248</td> <td>Serviceable</td> <td>Affected</td> <td>None</td> </tr> <tr> <td><u>Tyres</u></td> <td><u>Make</u></td> <td><u>Size</u></td> <td><u>Balance (MM)</u></td> </tr> <tr> <td>Front RHS</td> <td>Continental</td> <td>215/60R17</td> <td>5</td> </tr> <tr> <td>Front LHS</td> <td>Continental</td> <td>215/60R17</td> <td>5</td> </tr> <tr> <td>Rear RHS</td> <td>Continental</td> <td>215/60R17</td> <td>6</td> </tr> <tr> <td>Rear LHS</td> <td>Continental</td> <td>215/60R17</td> <td>6</td> </tr> </table>				<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>	70248	Serviceable	Affected	None	<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>	Front RHS	Continental	215/60R17	5	Front LHS	Continental	215/60R17	5	Rear RHS	Continental	215/60R17	6	Rear LHS	Continental	215/60R17	6
<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>																													
70248	Serviceable	Affected	None																													
<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>																													
Front RHS	Continental	215/60R17	5																													
Front LHS	Continental	215/60R17	5																													
Rear RHS	Continental	215/60R17	6																													
Rear LHS	Continental	215/60R17	6																													
4	Description Of Damages The vehicle sustained damages at frontal portion. (For information of damages please refer to Parts/Labour/Photographs attached)																															
5	Instruction This survey was conducted entirely on a "WITHOUT PREJUDICE" basis, and we have not authorised any repair.																															

AUTO PERFORMANCE APPRAISAL

Annex A

Vehicle Assessment Reports

Ref No : 19/001865

Damage And Repair Cost Adjustment

<u>S/No</u>	<u>Qty</u>	<u>Parts Description</u>	<u>Comments/condition</u>	<u>Workshop Estimate (\$)</u>	<u>Our Assessment (\$)</u>
List Items					
1	1	Front bumper ✓	Deformed	654.60	654.60 ✓
2	2	Front bumper fog lamp cover	Reuse	231.00	- X
3	2	Front bumper side retainer ✓	Deformed/broken	50.60	50.60 ✓
4	1 set	Front bumper clips ✓	Broken/necessary	30.00	30.00 ✓
5	1	Front bumper inner top ✓	Bent	371.50	371.50 ✓
6	2	Front bumper inner top reinforcement bracket	RH buckled/LH reuse	346.20	173.10 ✓
7	1	Front bumper inner lower reinforcement ✓	Bent/dented	675.40	675.40 ✓
8	1	Front bumper lower splash cover ✓	Deformed/torn	285.00	285.00 ✓
9	2	Headlamp ✓	Broken/cracked	1,318.00	1,318.00 ✓
10	1	Front grille ✓	Broken/cut	498.30	498.30 ✓
11	1	Front grille centre "NISSAN" logo ✓	Cut/necessary	73.60	73.60 ✓
12	1	Front bonnet ✓	Buckled	961.40	961.40 ✓
13	1	Front bonnet lock ✓	Bent	76.60	76.60 ✓
14	1	Front support panel X <i>NN R</i>	Buckled	617.50	617.50 X
15	1	Front support panel top X <i>NN</i> cover/garnish	Deformed	179.50	179.50 X
16	1	Front support panel side air garnish ✓ RH	Deformed	80.60	80.60 ✓
17	1	Front support panel side air garnish ✓ LH	Deformed	80.60	80.60 ✓
18	1	Horn	Broken	82.00	82.00 ✓
19	1	Front RH air cooler X <i>NN</i>	Dented/bent	504.20	504.20 X
20	1	Front lower inter cooler (<i>oil cooler</i>) X <i>NN</i>	Dented/bent	2,121.60	2,121.60 X
21	1	Front RH fender ✓	Buckled	685.00	685.00 ✓
22	1	Front RH fender under shield X <i>NN</i>	Deformed	94.60	94.60 X
23	1 set	Front fender under shield clips X <i>NN</i>	Necessary	30.00	30.00 X
24	1	Front RH fender wheel arch garnish ✓	Deformed/broken	584.40	584.40 ✓
				6,680.70	
				-10%	
Less discount 10%				6,012.63	
				10,632.20	10,228.10
				1,063.22	1,022.81
Total :				9,568.98	9,205.29
Special Nett Items					
25	1	Front number ✓	Broken/dented	45.00	45.00 ✓
26	1	Air con condenser ✓	Dented/bent	743.20	743.20 ✓

AUTO PERFORMANCE APPRAISAL

Annex A

Vehicle Assessment Reports

27 1 Radiator X NM
28 1 Radiator fan assy

Dented/bent
Reuse

687.40
621.40

687.40 X
- X

788.20

Total : 2,097.00 1,475.60

Total Spare Parts : 11,665.98 10,680.89

AUTO PERFORMANCE APPRAISAL

Annex B

Vehicle Assessment Reports

Ref No : 19/001865

Damage And Repair Cost Adjustment

<u>Items</u>	<u>Job Description</u>	<u>Workshop Estimate (\$)</u>	<u>Adjusted Costs (\$)</u>
1	To remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	1,200.00	800.00 500/-
2	To putty and respray painting on affected areas.	1,100.00	800.00 700/-
3	To check wirings and lightings.	50.00	30.00 /
4	To remove, refix aircon condenser, pipes, drier vacuum and recharge gas.	150.00	120.00 /
5	To remove, redix front inter cooler & air cooler.	80.00	50.00 /
6	To supplied and applied anti rust treatments.	100.00	60.00 30/-
Total Labour :		<u>2,680.00</u>	<u>1,860.00</u> 1430
Total Spare Parts :		11,665.98	10,680.89
Total Labour :		2,680.00	1,860.00
Total Repair Costs :		<u>14,345.98</u>	<u>12,540.89</u>

Assessor's Recommendation

Repairer Estimate : 14,345.98
Our Adjustment : 12,540.89

Remarks

The repairer has agreed to undertake the repair on a lump sum basis of \$10,000.00, with a repair period of 7 working days.

Surveyed By:



Lek Boon Hwee
Automobile Appraiser

P- 6012-63 L/S - 6584-66
N- 788-20 = 6600
L- 1430
8230.83 5 days repair

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/03/2019 13:45
Date Of Accident	04/03/2019 12:30
Exact Location Of Accident	ALONG ADMIRALTY ROAD WEST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT3420R
Insured/Policyholder	
Name Of Registered Owner	KAI BENG HEE GIDEON
NRIC No	S1700156F
Email Address	GIDEON_KAI@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-96949118
Alternative Phone No	OTHERS-96949118

Vehicle Particulars

Manufacturer	NISSAN
Model	QASHQAI 1.2 DIG-TURBO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100414694-03
Cover Note Number	

Driver

Name of Driver	KAI BENG HEE GIDEON
NRIC No	S1700156F
Date Of Birth	11/03/1965
Occupation	INDOOR
Date Of Driving Pass	04/04/1988
Driving Experience	30 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96949118
Fax Number	
Contact Number	OTHERS-96949118
EMAIL Address	GIDEON_KAI@YAHOO.COM.SG

Address	BLK 414 SEMBAWANG DRIVE #04-716
Postcode	750414
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLA4094E
Vehicle Make/Model/Colour	HONDA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KOH HOCK BENG
NRIC/Passport Number	S7415147G
Contact Number	91013151
Address	
Postcode	
Insurance Company Name	FWD SINGAPORE PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT GATE 3

The incident happened on 24/3/2019 about 12.30pm
 I was driving along Admiralty Road West towards Yickun
 Suddenly, the vehicle SLA 4094E drive out from
 Shipyard Gate 3 Knocked onto my vehicle. The driver of
 SLA 4094E explained there was a lorry blocking his view
 and sensor him that he can turning to right which
 the road was clear. He did admit that he was in
 his fault by sms message to me.

[Signature]

DECLARATION

(We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time: 24 MAR 2019

[Signature]
 Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

[Signature]
 Reporting Centre Personnel's Signature
 Name: Poh Kwae Choo
 NRIC/PIN No.: S6840583A

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/03/2019 18:15
Date Of Accident	04/03/2019 12:00
Exact Location Of Accident	ADMIRALTY ROAD WEST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA4094E
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	KOH HOCK BENG
NRIC No	S7415147G
Email Address	DANIELKOH2205@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-91013151
Alternative Phone No	OFFICE-91013151

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00002317-01
Cover Note Number	01/03/2019-29/02/2020

Driver

Name of Driver	KOH HOCK BENG
NRIC No	S7415147G
Date Of Birth	22/05/1974
Occupation	INDOOR
Date Of Driving Pass	15/01/1999
Driving Experience	20 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91013151
Fax Number	
Contact Number	OFFICE-91013151
E Mail Address	DANIELKOH2205@YAHOO.COM.SG

Address	BLK 262 TAMPINES STREET 21 #10-262
Postcode	520262
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : OLE JOHN NESJE GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKT3420R
Vehicle Make/Model/Colour	NISSAN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KAI BENG HEE GIDEON
NRIC/Passport Number	S1700156F
Contact Number	96949118
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

WAS COMING OUT FROM SEMBAYAN SHIPYARD
 TURNING RIGHT INTO SLIP ROAD ON ADMIRALTY
 WEST. VIEW WAS BLOKED BY A TRAILER OUTSIDE
 SHIPYARD ON 2ND LANE. PROCEEDED ~~ON~~ OUT
 SLOWLY TO SEE INCOMING TRAFFIC BEFORE
 TURNING RIGHT BUT COULDN'T SEE THE CAR
 ON THE BLINDSPOT OF TRAILER.
 JAMMED BRAKE TO STOP CAR MOVING FURTHER
 BUT CAR (SKT 3420R) COULDN'T STOP IN TIME
 AND HIT ON RIGHT FRONT SIDE OF MY CAR.

You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.	Reporting Only
	<input checked="" type="checkbox"/> Claim OD
	Claim TP
	Claim OD / TP at other workshop

DECLARATION

I/We declare the foregoing particulars are true in every respect.



 Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No:



(A) - SLA 4094E.
(B) - SKT 3420R.







CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.
All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2018-00002317-01 (Comprehensive - Classic Plan)

Car plate number: SLA4094E

Your name (As the policyholder): Koh Hock Beng

Coverage start date: 01/03/2019

Coverage end date: 29/02/2020

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

(a) You; and

(b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

Finance company: United Overseas Bank Limited

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 30/01/2019

Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please immediately inform us at +65-6820-8888
or email us at contact.sg@fwd.com if any details
in this Certificate of Insurance need to be changed.

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo





REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S1700156F



Name

KAI BENG HEE GIDEON



解明喜

Race

CHINESE

Date of Birth

11-03-1965

Sex

M

Country of Birth

SINGAPORE



Accident Photo



Addendum Sheet Pg. 1

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

IMPORTANT NOTE : Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MOR119029659 Vehicle Registration No : SLA4094E
Name(as shown in NRIC): KOH HOCK BENG
(*Vehicle Driver / Vehicle Owner) (* Please delete as appropriate)
NRIC/Passport No : S7415147G
Address : _____
Contact (Tel) : _____ (H/P) : 91013151
(Email) : _____
Date of Accident : 04/03/2019 Time of Accident : 12:00
Place of Accident : ADMIRALTY ROAD WEST
Insurance Company : FWD

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

AMEND INSURANCE FROM DIRECT ASIA INSURANCE TO FWD



Signature of Vehicle Owner / Driver
Date:

10 Anson Road #06-16 International Plaza Singapore 079903 Phone : + 65 6224 0010 Fax : +65 6224 0030
Operating Hours : Monday to Friday 9am to 5pm

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Mar 2019 Edit Reg		11 Mar 2019 00:00 Edit Adj Rpt	S\$6,600.00 Edit Estimates	S\$6,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Koh Hock Beng , ID: 57415147G								
Main Claimant:	-								
Vehicle Reg. No.:	SKT3420R	Date of Loss:	04/03/2019 12:00 - :59 [45 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201900005878	Policy/Cover Note No.:	PNPV2018-00002317-01 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLA4094E	Policy No. (Claimant):							
		Excess:	S\$700.00						
Repairer:	Sze Kang Automobile Spraying Services (HQ) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #03-17, 568047 Ang Mo Kio - Tel: 64812712								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 21/03/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKT3420R (1201900005878)

[SLA4094E]

TP

-

Mar 4 2019 12:00PM

[Koh Hock Beng]

Sze Kang Automobile Spraying Services

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
2	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
3	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
4	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
5	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
6	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
7	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
8	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
9	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
10	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
11	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
12	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
13	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
14	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
15	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
16	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
17	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
18	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
19	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
20	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
21	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
22	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
23	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
24	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
25	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
26	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
27	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
28	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
29	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
30	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
31	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
32	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
33	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
34	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
35	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
36	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
37	26/04/19 14:42	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	26/04/19 14:42	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	26/04/19 14:42	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	26/04/19 14:42	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	26/04/19 14:42	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	26/04/19 14:42	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	26/04/19 14:42	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	26/04/19 14:42	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	26/04/19 14:42	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	26/04/19 14:42	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	26/04/19 14:42	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	26/04/19 14:42	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	26/04/19 14:42	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	26/04/19 14:42	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	26/04/19 14:42	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	26/04/19 14:42	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/05/19 12:41	Colour Photo	 Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	13/03/19 10:45	E-filed GIA report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD19004484/ETD3E2
Date: 08/05/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00002317-01
Claimant Vehicle No : SKT3420R **Insured Vehicle No :** SLA4094E
 Date of Loss: 04/03/2019 Nature of Claim: TP Claim No: 1201900005878

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKT3420R**
 Make & Model: NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A) Engine No: HRA2129633A
 Reg. Date: 30/05/2015 (Man. Year: 2015) Chassis No: SJNFEAJ11U1342208
 Colour: Blue Odometer: 70248 km
 Engine Capacity: 1197 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,665.98	6,800.83	4,865.15	41.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,680.00	1,430.00	1,250.00	46.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,345.98	8,230.83	6,115.15	42.63
Approved Total (Overridden) (S\$)		6,600.00		
Nett Amount (S\$)	14,345.98	6,600.00	7,745.98	53.99

INSPECTION

Date of Assignment: 11/03/2019
 Date Inspected: 12/03/2019 Inspected At: Sze Kang Automobile Spraying Services (HQ)
 BLK 10 ANG MO KIO INDUSTRIAL PARK
 2A, #03-17
 Singapore 568047
 Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 May 2019)
Parts: M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKT3420R)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	654.60 FL	*654.60 FL
2	2		*FRONT BUMPER FOG LAMP COVER	Reuse	231.00 FL	*- FL
3	2		*FRONT BUMPER SIDE RETAINER	Deformed / Broken	50.60 FL	*50.60 FL
4	1		*SET FRONT BUMPER CLIPS	Broken / Necessary	30.00 FL	*30.00 FL
5	1		*FRONT BUMPER INNER TOP	Bent	371.50 FL	*371.50 FL
6	1		*FRONT BUMPER INNER TOP REINFORCEMENT BRACKET	O/S Buckled / N/S Reuse	346.20 FL	*173.10 FL
7	1		*FRONT BUMPER INNER LOWER REINFORCEMENT	Bent / Dented	675.40 FL	*675.40 FL
8	1		*FRONT BUMPER LOWER SPLASH COVER	Deformed / Torn	285.00 FL	*285.00 FL
9	2		*HEADLAMP	Broken / Cracked	1,318.00 FL	*1,318.00 FL
10	1		*FRONT GRILLE	Broken / Cut	498.30 FL	*498.30 FL
11	1		*FRONT GRILLE CENTRE NISSAN LOGO	Cut / Necessary	73.60 FL	*73.60 FL
12	1		*FRONT BONNET	Buckled	961.40 FL	*961.40 FL
13	1		*FRONT BONNET LOCK	Bent	76.60 FL	*76.60 FL
14	1		*FRONT SUPPORT PANEL	Repair	617.50 FL	*- FL
15	1		*FRONT SUPPORT PANEL TOP COVER / GARNISH	Not Necessary	179.50 FL	*- FL
16	1		*FRONT SUPPORT PANEL SIDE AIR GARNISH RH	Deformed	80.60 FL	*80.60 FL
17	1		*HORN	Broken	82.00 FL	*82.00 FL
18	1		*FRONT RH AIR COOLER	Not Necessary	504.20 FL	*- FL
19	1		*FRONT LOWER INTER COOLER	Not Necessary	2,121.60 FL	*- FL
20	1		*FRONT RH FENDER	Buckled	685.00 FL	*685.00 FL
21	1		*FRONT RH FENDER UNDER SHIELD	Not Necessary	94.60 FL	*- FL
22	1		*SET FRONT FENDER UNDER SHIELD CLIPS	Not Necessary	30.00 FL	*- FL
23	1		*FRONT RH FENDER WHEEL ARCH GARNISH	Deformed / Broken	584.40 FL	*584.40 FL
24	1		*AIR CON CONDENSER	Dented / Bent	743.20 FS	*743.20 FS
25	1		*RADIATOR	Not Necessary	687.40 FS	*- FS
26	1		*RADIATOR FAN ASSY	Reuse	621.40 FS	*- FS
27	1		*FRONT SUPPORT PANEL SIDE AIR GARNISH LH	Deformed	80.60 FL	*80.60 FL
28	1		*FRONT NUMBER	Broken / Dented	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,729.20	7,468.90
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,063.22	668.07

Total Parts (\$\$)	11,665.98	6,800.83
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CUT OUT DAMAGE PORTION, JACK OUT, STRAIGHTEN, PANEL BEATING, WELDING, ALIGN AND RENEW REPLACED PARTS	New	1,200.00	500.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS	New	1,100.00	700.00
3	TO CHECK WIRINGS AND LIGHTINGS	New	50.00	30.00
4	TO REMOVE, REFIX AIRCON CONDENSER, PIPES, DRIER VACUUM AND RECHARGE GAS	New	150.00	120.00
5	TO REMOVE, REFIX FRONT INTER COOLER & AIR COOLER	New	80.00	50.00
6	TO SUPPLIED AND APPLIED ANTI RUST TREATMENTS	New	100.00	30.00
Gross Labour Cost (S\$)			2,680.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >