

ASS. REQ. BY:

RECS /msg190044941.Grd312

Special Instruction

CA / REV / REP / REV 24 HRS

GB

ASSIGNMENT (Office)

Form (Person)

Ng Chen how

of

M&G

Date/Time

12/3/19 @ 1:30pm

Estimated Cost

Bill to:

OD / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No

GBF 8108R

Insured

WC 1838E

of Workshop n/a

tian Heng Painter

Tel

9863 2371

of

160 Sin Ming Drive #06-10

Policy No

29088496MKF

Claim No

587163

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A

7/13/2019

CA / REV / REP / REV 24 HRS

13/3/2019

H.O.D. Endorsement

Date/Time

4:39pm @ 12/3/19

Person Contacted

Henny

Vehicle

IN/OUT

Date/Time

Action/Instruction (X) Estimate Pls also inspect Insured vehicle for Brake & tyre malfunction.

Insured: 98502643 @ Mr. ore.

GBF 8108R - X

WC 1838E - X

3/4/19

Send preli revised via merimen vehicle TL

INSURANCE

PRS
Xme.

REF:

MSG

B 3924w

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Liam Heng Painter
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$46k
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 24 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBF8108R Yr Regn: 29 sep 2016
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Nissan NV200 c.c. 1597
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: _____ T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: VM200 99915
 Gen. Cond: Good / Fair / ☒ Poor / Burnt
 Steering: Inorder / ☒ Jammed / Leaked / Burnt or
 Brake: Inorder / ☒ Jammed / Leaked / Burnt or
 Modi: ☒ Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 165 R14
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / ☒ YOKO or

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. _____	D.O.I. <u>13-03-19</u>

Survey held at W/S
 Des. of Damages: ☒ Frt ☒ Rear ☐ O/S ☐ N/S ☐ U/C ☐ Rooftop or ck-30pm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>13/3</u>	<u>w/s said owner will loss Total loss the veh..</u>
	<u>\$18k - \$20k</u>

MV: \$46,000
 LTA: \$32,976
 Nat: \$13,024

RECEIVED 04 APR 2019

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation: _____ S + RS _____ SI

Photos

Others

TOTAL

150
10
160

Report Format : TP

Lump Sum / I.B.I. (\$) Extensive Total loss

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Mar 2019		12 Mar 2019 13:30 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	EECHAN ENTERPRISE PTE LTD, Co. Reg. No.: 200516266D		
Main Claimant:	CENTURY DESIGN & RENOVATION, Co. Reg. No.: 52993924W		
Vehicle Reg. No.:	GBF8108R	Date of Loss:	07/03/2019 13:00 - :59 [29 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 587163	Policy/Cover Note No.:	29088496MKF (Comprehensive) Coverage: 01/07/2018 - 30/06/2019
Vehicle Reg. No. (Insured):	WC1838E	Policy No. (Claimant):	
		Excess:	
Repairer:	Lian Heng Painter Company () 160 SIN MING DRIVE, #06-10 SIN MING AUTOCITY, 575722 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by NG CHEN HOW - 6643 1391]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/03/2019]		
Driver/Custodian (Insured):	SUBBAIYAN VEERIYAN (), NRIC: G2070462X, Tel: +6598989380 Email:		
Adj Asg. Remarks:	3rd party vehicle: Likely Total Loss Please also inspect Insured vehicle for brake and tyre malfunction.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

M NEDUMARAN & CO

Advocates & Solicitors
Commissioner for Oaths

UEN NO. 53181067D

Please reply to our Branch Office for this matter

Nedumaran Muthukrishnan
LLB (hons) [Buckingham]
Barrister at Law (Lincoln's Inn)

Branch Office: 11 Sin Ming Road
#B2-09 (Unit 2) Thomson V Two
Singapore 575629
Tel : 6509-8480 / 6509-8481
Fax : 6509-8482
Email : igene.lim@mneduco.com.sg
serene.tan@mneduco.com.sg

Our Reference : MN/IG/L1/1912958/st
Your Reference : WC 1838E

12th March 2019

MSIG INSURANCE (SINGAPORE) PTE.LTD
4 Shenton Way
#21/23-01, SGX Centre 2
Singapore 068807

BY EMAIL ONLY

Dear Sirs,

1. **NOTICE OF ACCIDENT TO INSURERS AND PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)**
2. **ACCIDENT ON 7/3/2019 INVOLVING VEHICLE NOS. GBF 8108R, WC 1838E & XE 446L ALONG PIE NEAR LORNIE ROAD EXIT AT ABOUT 1345 HOURS.**

We are instructed by **CENTURY DESIGN & RENOVATION** (owners of motor vehicle no. GBF 8108R) and/or **LIAN HENG PAINTER COMPANY** (the motor workshop for GBF 8108R) to notify you of a road traffic accident on 7/3/2019 at about 1345 hours along **PIE NEAR LORNIE ROAD EXIT** involving our client's vehicle registration number [GBF 8108R] and [WC 1838E] driven by you at the material time.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know **within 2 working days** of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you with the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

M NEDUMARAN & CO

NEDUMARAN MUTHUKRISHNAN
(Branch Office)

c.c. 1) **EECHAN ENTERPRISE PTE LTD**

(Vehicle : WC 1838E)

2) **Lian Heng Painter Company**
160 Sin Ming Drive
#06-10 Sin Ming AutoCity
Singapore 575722

(Vehicle : GBF 8108R)

Tel : 6453-5779 / 9863-2371 (Mr Henry)

Fax : 6453-3173

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	NG CHEN HOW	Date:	03 Apr 2019
Preliminary Advice			

Insured Vehicle No	: WC1838E	Accident Date	: 07/03/2019
TP Vehicle No	: GBF8108R	Assignment Date	: 12/03/2019
Make	: NISSAN NV200	Est. Duration of Repair	: 0.00
Date of Inspection	: 13/03/2019		
Inspection At	: LIAN HENG PAINTER COMPANY 160 SIN MING DRIVE, #06-10 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages			
The vehicle sustained impact / damages front portion, rear portion and rooftop and parts claimed are consistent to the accident.			
Repairer's Estimate (Gross)	:S\$	TOTAL LOSS	
Revised Amount	:S\$	TOTAL LOSS	
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	0.00	
Lump Sum Repair	:S\$		
Total Loss Consideration			
New for Old Value	:S\$		
Pre-Accident Value	:S\$		
COE / PARF Rebate	:S\$		
Salvage Value	:S\$		
Margin for Repair	:S\$		

Remarks	
<input type="checkbox"/>	The vehicle is economical/not economical for repair.
<input checked="" type="checkbox"/>	The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	3924W
Vehicle Details	
Vehicle No.:	GBF8108R
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Mar 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV200 DX-2 1.6 AUTO
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	HR16073216D
Chassis No.:	VM20099915
Maximum Power Output:	-
Open Market Value:	\$18,799.00
Original Registration Date:	29 Sep 2016
First Registration Date:	29 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$940.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Sep 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$43,726.00
COE Rebate Amount:	\$32,976.00
Total Rebate Amount:	\$32,976.00

The information contained herein is correct as at 13 Mar 2019

OK

► NV200 Used Vehicle List (4 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Nissan NV200 1.6A (Petrol)	\$42,500	\$6,170 /yr	01-Feb-2016	1,597 cc	48,000 km		Available

Personal Used. Great For Start-Up. Selling Due To Under Use. Just Changed The Battery. Come With New Set Of Tires.

Office No. - -

Ke Hanjie - 91873526

Nissan NV200 1.5M (Diesel)	\$46,800	\$6,740 /yr	19-Feb-2016	1,461 cc	-	MyCar Pte Ltd	Available
-----------------------------------	-----------------	-------------	-------------	----------	---	---------------	------------------

1 Owner Who Takes Great Care Of Their Van. Smooth Running Engine. No Repairs Needed. Most Popular Mid-Size Van. Call For Enquiries Or Arrange For Viewing And Test Drive.

Office No. - 65700007

Juliana Tan - 93200928 | Brad Chai - 96470879

Nissan NV200 1.5M (Diesel)	\$46,800	\$6,600 /yr	14-Apr-2016	1,461 cc	110,452 km	Yong Lee Seng Motor	Available
-----------------------------------	-----------------	-------------	-------------	----------	------------	---------------------	------------------

Evaluated By VICOM, Free 6 Months Maintenance And 1 Grooming.

Office No. - 68440123

Richmond Tang - 96200045 | Raymond Tang - 96250045

Nissan NV200 1.6A (Petrol)	\$46,800	\$6,390 /yr	11-Jul-2016	1,597 cc	-	Net Link Partners Pte Ltd	Available
-----------------------------------	-----------------	-------------	-------------	----------	---	---------------------------	------------------

Under Warranty! Full Agent Maintained! Cheapest In The Market! Almost New Condition! View To Believe! Engine And Gearbox Silky Smooth Powerful Torque For Convenient City Driving!

Office No. - 67531661

Jenson - 97680728 | Calvin - 90267602 | Wei Hong - 88281661

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	12/03/2019 13:38
Date Of Accident	07/03/2019 13:45
Exact Location Of Accident	PIE NEAR LORNIE RD EXIT
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GBF8108R
Insured/Policyholder	
Name Of Registered Owner	CENTURY DESIGN & RENOVATION
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97968108
Alternative Phone No	OFFICE-97968108
Vehicle Particulars	
Manufacturer	NISSAN
Model	-
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VCA/P1839737
Cover Note Number	
Driver	
Name of Driver	TAY CHEE BOON
NRIC No	S7378872B
Date Of Birth	12/06/1973
Occupation	INDOOR
Date Of Driving Pass	11/02/1999
Driving Experience	20 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97968108
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	-
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	THOMSON NPP 25 SIN MING ROAD
Police Station Address	ROAD: 25 SIN MING ROAD #01-180 , POSTCODE: 570025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

refer attached police report.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	WC1838E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number XE446L

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TAY CHEE BOON

Approximate Age

Injuries Sustain

Injured person in which vehicle? GBF8108R

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

CENTURY DESIGN & RENOVATION

Blk 446 Hougang Ave 8 #B1-1635

Singapore 530446

Tel: 96855695

9196-8108

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

PIE NEAR LORNE RD. EXIT



'A' GBF 8108 R

'B' WC 183PE

'C' XB 446L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer
to
police Report attached.

CERTIFICATION & RENEWAL

Like all insurance policies, the following particulars are true in every respect.

Singapore 530446

Tel: 9655665

9796-8108

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7378872B



Name
TAY CHEE BOON

Nation
CHINESE

Date of birth
12-08-1973

Country of birth
MALAYSIA




4054072


NRIC No. S7378872B




Date of issue
07-05-2007

108 PEMIMPIN PLACE
SINGAPORE 576103
NRIC No. S7378872B Date: 22/02/2018






Tay Chee Boon
ST3788 T2 B.



**SINGAPORE
POLICE FORCE**



T/20190310/2095

1 of 3

Report No. T/20190310/2095

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/03/2019 17:51		Vide Report No.:		Station Diary No.: 20	
Informants Particulars					
Name of Informant: TAY CHEE BOON			Address: 106 PEMIMPIN PLACE SINGAPORE 576103		
ID Type / ID No.: NRIC NO / S7378872B			Contact No.: Home/Office:		Mobile: 97968108
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 45	Date of Birth: 12/06/1973	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: SUPERVISOR			Driving Licence Information: Class: 2B,3		Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 07/03/2019 13:45	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY PIE NEAR LORNIE ROAD EXIT				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBF810BR	Van				Seriously Damaged	0
WC1838E	CEMENT MIXER					0
XE446L	TIPPER TRUCK					0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190310/2095

2 of 3

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570026
Tel No: 1800-4529999

Report No. T/20190310/2095

CONTINUATION OF REPORT

Name		TAY CHEE BOON		ID No.	S7378872B
Related Vehicle		GBF8108R (Van)		Contact No.	97988108
Hospital/Clinic		TAN TOCK SENG HOSPITAL		Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	07/03/2019	Date Discharge	09/03/2019		
No. of Days granted Medical Leave	16	Degree of Injury	Serious		

Brief Details.

On 07 March 2019, at about 1.45pm, I was driving my company van (GBF8108R) along PIE towards Changi near Lornie Road Exit on the most left lane. As the traffic ahead was building up and the vehicle (XE446L) ahead of me slowed down and came to a complete stop. As such, I followed suit and came to a complete stop.

While my vehicle was stationary, I then felt a huge impact from the rear of my vehicle. My airbags were instantly deployed and my vehicle surged forward and collided with the vehicle ahead of me. After the accident, I struggled out of my vehicle and observed that a cement mixer truck (WC1838E) with an indian driver had collided to my rear of the vehicle. I was in a state of shock and I vaguely remembered that some passerby render assistance and accompanied me to the road side. I vaguely remembered that I had asked some passerby to assist me to take some photograph of the accident scene which I had them captured on my phone.

Thereafter, ambulance arrived and I was conveyed to Tan Tock Seng Hospital in a conscious state. I felt pain on my head, neck, right hand and chest area. I was also facing breathlessness. I was then admitted to Tan Tock Seng Hospital and was warded for 3 days with a total of 16 days of Hospitalization Leave.

I also received a phone call from Traffic Police Investigation Officer Jeff to lodge a traffic accident report once I am feeling better. I wish to state that I do have any in vehicle camera however, I am unsure if it was working at that point of accident. I am lodging this traffic accident report in compliance with the road traffic act and for insurance claim purposes.



**SINGAPORE
POLICE FORCE**



T/20190310/2095

3 of 3

Report No. T/20190310/2095

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /
Sgt 1 CHENG XINLIANG

Signature Of Informant:

x


Signature Of Interpreter:
Not applicable

Date/Time:
10/03/2019 17:51

Officer In Charge Of Case:
TP / GIT /
SI YEO CHUN JIAN
Contact No.: 65476213

Classification Of Case:

Authentication Stamp
NP158



1070

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Mar 2019		12 Mar 2019 13:30 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	EECHAN ENTERPRISE PTE LTD, Co. Reg. No.: 200516266D		
Main Claimant:	CENTURY DESIGN & RENOVATION, Co. Reg. No.: 52993924W		
Vehicle Reg. No.:	GBF8108R	Date of Loss:	07/03/2019 13:00 - :59 [29 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 587163	Policy/Cover Note No.:	29088496MKF (Comprehensive) Coverage: 01/07/2018 - 30/06/2019
Vehicle Reg. No. (Insured):	WC1838E	Policy No. (Claimant):	
		Excess:	
Repairer:	Lian Heng Painter Company () 160 SIN MING DRIVE, #06-10 SIN MING AUTOCITY, 575722 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by NG CHEN HOW - 6643 1391]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 11/04/2019]		
Driver/Custodian (Insured):	SUBBAIYAN VEERIYAN (), NRIC: G2070462X, Tel: +6598989380 Email:		
Adj Asg. Remarks:	3rd party vehicle: Likely Total Loss Please also inspect Insured vehicle for brake and tyre malfunction.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBF8108R (587163)
[WC1838E]

TP

CENTURY DESIGN & RENOVATION

Mar 7 2019 1:00PM

[EECHAN ENTERPRISE PTE LTD]

Lian Heng Painter Company

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	12/03/19 13:13	Accident Statement From: SC - Reg. No: WC1838E, Claimant: EECHAN ENTERPRISE PTE LTD	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/04/19 16:31	Adjuster Immediate Advice	1	Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
29	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	25/03/19 11:27	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	25/03/19 11:27	General View	1	Load PDF	

Assessment Reports			1 per page	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
Documentation			1 per page	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/03/19 13:13	1st vehicle report: XE446L From: SC - Reg. No: WC1838E, Claimant: EECHAN ENTERPRISE PTE LTD	 Load PDF	
2	12/03/19 13:17	Truck Owner details Ore Ah Chuan, mobile No. 98502643.	 Load PDF	
3	12/03/19 13:17	PRI notice Likely total loss	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19004494/GVD3E2

Date: 04/04/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29088496MKF

Claimant Vehicle No : GBF8108R

Insured Vehicle No : WC1838E

Date of Loss: 07/03/2019

Nature of Claim: TP

Claim No: 587163

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBF8108R

Make & Model: NISSAN NV200, 1.6 DX-2 (A)

Engine No: HR16073216D

Reg. Date: 29/09/2016 (Man. Year: 2016)

Chassis No: VM20099915

Colour: Black

Odometer: 0 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 165 R14

Rear Tyre Size: 165 R14

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 12/03/2019

Date Inspected: 13/03/2019 Inspected At:

Lian Heng Painter Company
160 SIN MING DRIVE, #06-10 SIN MING
AUTOCITY
Singapore 575722

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$46,000.00
OMV :	\$18,799.00
PARF Rebate (1) :	\$0
Quota Premium Paid :	\$43,726.00
COE Rebate (2) :	\$32,976.00
Total Rebate (1) + (2) = :	\$32,976.00

The total amount incurred will be Market Value \$46,000.00 minus Total Rebate \$32,976.00 = \$13,024.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 04 Apr 2019)
Parts:	N/A	NISSAN NV200 1.6 DX-2 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBF8108R)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >