

INS. CASE OWNER:

CC 6, 1900 4519, Afa3

LKK:

IDAC:

Surveyor:

LMP

DOI:

ASSIGNMENT

11-3-19

Date / Time :

11/3/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : SKR 4476 J

Claim No. :

Name of Insured :

Policy No. :

Insured Tel No. : HP:

Make / Model :

Excess Sec II :SS D.O.A : 11/3/19

Place of Accident :

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SLR 7190 B

INSRS:
WSP: mg solution
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	STAGE	DATE / PIC
SLR 7190 B - 61/SPF 180 22884/62652; WOA: 2/6/18	Non-Reporting ltr (1st):	
SKR 4476 J - 04/11/18 20970/Afa3; WOA: 15/11/18	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice	
	LTA / GIA :	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	
PRELIMINARY ADVICE Date/Time:	Sent By:	
FINALIZATION Date/Time:	Confirm with:	Confirm by:
Repair Cost: S\$	(days) Reduction: %	Email ☐ Call ☐
FINAL SETTLEMENT Date/Time:	Confirm with	Email ☐ Call ☐
Final Liability: %	(Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia :
Repair Cost: S\$		
Loss of Rental (LOR): S\$	(days)	
Loss of Use (LOU): S\$	(\$ x days)	
Loss of Income (LOI): S\$	(\$ x days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]		
GIA/LTA Search	S\$	
Medical:	S\$	1) Claim status: Normal/Reject/Private Settle
Disbursement:	S\$ (e.g. Tow/ Independent)	2) Report Format:
Legal Cost	S\$	3) Survey fee:
Total: S\$	Global Sum S\$:	
FINAL PAYMENT Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	S\$ Name 1:	
Payee 2: (Strike if N.A.)	S\$ Name 2:	
Payee 3: (Strike if N.A.)	S\$ Name 3:	

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT

Person Contacted: _____

Veh No: SLR7190B Yr Regn: 2017, AugustType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz CLA180 C.C. 1595Colour: Black A/C: Insured / Std / NI / NASp. Reading: 18681 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD1173422N496929Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 225/40R18R: 225/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 11/03/19Survey held at MG SolutionDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPEQMV:PV:Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

Part Prices Check:

Survey Fee:

Date:

1)

2)

IN

OUT

Basic & Add.

___ S + RS, ___ SI

Photos

Others

TOTAL

Preli. Report:

Final Report: