

000000

ASS. REC. BY:

REP

CS/CT119004525/E v03

Special Instruction

Sw/evry

SWK

ASSIGNMENT (Office)

From (Person)

Elaine Cheong

of

CTI

Date/Time:

12/3/19 @ 2:49pm

Estimated Cost:

Bill to:

OD / TV / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle H/c

PC2284D

Insured:

SKB 9685

at Workshop m/c

Texbuild International

Tel:

845 63533 | 90296574

of

2 Woodlands Scfor 1 #05-12

Policy H/c:

DMPCSN 31217418022

Claim No:

8NM190200532

Sum Insured:

Excess:

Make of Veh.

(Client's Record)

D.O.A.

01/03/2019

CA / REV / REP / REV 24 HRS

13/3/19 @ 2:30pm

H.O.D. Endorsed

Date/Time:

4:11pm 12/3/19

Person Contacted

Shirley

Vehicle

AT IT

Date/Time

Action/Instruction (✓) Estimate

PC2284D-CS/MSG18018644/Mod32

Out: 8/10/18

SKB 9685-X

27/3/19

@ 2:35pm Yong Shun said vehicle has not send in for repair pending liability

26/4/19

@ 3:03pm Shirley said vehicle has not send in for repair

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
QD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop int: _____
 ed: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **PC 22840** Yt Regn: **3/01/2014**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Golden Dragon XML 6103J98** CC: **6693**
 Colour: **White** A/C Insured / Std / NI / NA
 Sp. Reading: **298766** T/Rulin: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **LL 38 GC OH 10 A 00 3603**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: **11R 22.5**
 R: **11**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Double Coin**

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	5 mm	L/Bal.	5 mm
D.O.A.	11/3/19	D.O.A.	13/3/19

Survey held at **Lex Build**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear RH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time : Action / Instruction

26/4/19 Submit preli report

RECEIVED 29 APR 2019

Date/Time, File Pass to?

☒ : Preli. Report
☐ : Final Report

4) Date/Time, File Return to?

5) **26/4/19**

Report Format :

Lump Sum / I.B.F. ()

Days Of Repair: **3**

Resurvey No. of Trip: **-**

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation

() : S + P. ()

() Photos

() Collect

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Mar 2019		12 Mar 2019 14:49 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	SINGAPORE COACH SERVICES PTE LTD, Co. Reg. No.: 201227110H		
Vehicle Reg. No.:	PC2284D	Date of Loss:	01/03/2019 13:00 - :59
Claim Type:	TP / SNM19D200532	Policy/Cover Note No.:	DMPCSN31217418022
Vehicle Reg. No. (Insured):	SKB968S	Policy No. (Claimant):	5092609656-01
		Excess:	S\$600.00
Repairer:	LexBuild International Pte Ltd (HQ) 2 Woodlands Sector 1 (Woodlands Spectrum 1), #05-12, 738068 Woodlands - Tel: 6456 3533		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/03/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7110H
Vehicle Details	
Vehicle No.:	PC2284D
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Mar 2019
Vehicle Make:	GOLDEN DRAGON
Vehicle Model:	XML6103J98
Primary Colour:	Multi-Colour
Manufacturing Year:	2013
Engine No.:	ISB67E530022051177
Chassis No.:	LL3BGCDH1DA003603
Maximum Power Output:	-
Open Market Value:	\$110,536.00
Original Registration Date:	03 Jan 2014
First Registration Date:	03 Jan 2014
Transfer Count:	0
Actual ARF Paid:	\$5,527.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	02 Jan 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$48,001.00
COE Rebate Amount:	\$23,058.00
Total Rebate Amount:	\$23,058.00

The information contained herein is correct as at 13 Mar 2019

OK

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	PC2284D		
Vehicle Type :	Z20 - Private Hire (Chauffeur) Bus/Coach/Minibus		
Vehicle Attachment 1 :	Air-Conditioned		
Vehicle Scheme :	Public Service Vehicle (Others)		
Vehicle Make :	GOLDEN DRAGON		
Vehicle Model :	XML6103J98		
Chassis No. :	LL3BGCDH1DA003603		
Propellant :	Diesel		
Engine No. :	ISB67E530022051177		
Engine Capacity :	6693 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	16000 kg		
Unladen Weight :	11240 kg		
Year Of Manufacture :	2013		
Original Registration Date :	03 Jan 2014		
Lifespan Expiry Date :	02 Jan 2034		
COE Category :	C - Goods Vehicle & Bus		
Quota Premium :	\$48,001.00		
COE Expiry Date :	02 Jan 2024		
Road Tax Expiry Date :	02 Jul 2019		
Inspection Due Date :	02 Jan 2020		
Intended Transfer Date :	13 Mar 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00
Message			
This vehicle has a road tax Over Payment of \$227.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.			

You may print this page for reference.

OK

Print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/03/2019 16:26
Date Of Accident	01/03/2019 13:45
Exact Location Of Accident	SCOTTS ROAD / CLAYMORE HILL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC2284D
Insured/Policyholder	
Name Of Registered Owner	SINGAPORE COACH SERVICES PTE LTD
Co Reg No	201227110H
Email Address	ACCOUNTS2@SINGAPORECOACHSERVICES.COM
Mobile Phone No	(LOCAL) +65-96204026
Alternative Phone No	OFFICE-66945458

Vehicle Particulars

Manufacturer	GOLDEN DRAGON
Model	XML6103J98-6.7 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category BUS

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5092609656-01
Cover Note Number	

Driver

Name of Driver	WONG KOK FEI
NRIC No	S7623058G
Date Of Birth	03/08/1976
Occupation	OUTDOOR
Date Of Driving Pass	05/05/1997
Driving Experience	21 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91797950
Fax Number	
Contact Number	
Email Address	NOEMAIL

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (i) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

[Signature]
4.10.19 14:55

Driver's Signature

(If driver is not the policyholder)

Date & Time:

[Signature]

Reporting Centre Personnel's Signature

Name: Shirley Lim

NRIC/IN No.:

[Signature]

08th March 2019

China Taiping Insurance (S) Pte Ltd
3 Anson Rd, #16-00 Springleaf Tower
Singapore 079909

Dear Sir / Mdm

Quotation: Accident on 01/03/2019, Scotts Road / Claymore Hill, involving PC2284D & SKB968S

We are pleased to submit herein, our quotation for your consideration.

S/N	Description	Qty.	Unit Price	Total Price
1	Supply skilled labor to • Repair, apply fiber & grinding rear RHS dome <i>To repair</i>	1 Day	\$ 880.00	\$ 880.00
2	Supply skilled painter & paint material to • Putty, grinding & spraypaint rear RHS dome <i>To paint</i>	1 lot	\$1,760.00	\$1,760.00
Sub-total				\$2,640.00
7% GST				\$184.80
Total				\$2,824.80

Terms and Conditions:

Payment Terms : 30 days upon invoice
Quotation Validity : 30 days
Price quoted subject to : 7% GST
Lead Time : 3 Working days

Yours faithfully



Tien Yong Shun
Operation Executive

Approval by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

LexBuild International Pte. Ltd.

2 Woodlands Sector 1, #05-12 (Woodlands Spectrum 1), Singapore 738068.

Tel: (65) 6456 3533, Fax: (65) 6456 3353

Website: www.LexBuild.com, Email: sales@LexBuild.com

畅通国际

LexBuild™

Quotation No.: Q19-OPS-0306

By email : claimsdept@sg.cntaiping.com

ROC / CR GST Reg No. 290004370R

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Mar 2019		12 Mar 2019 14:49 Edit Adj Rpt	S\$800.00 Edit Estimates	S\$800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ID: -								
Main Claimant:	SINGAPORE COACH SERVICES PTE LTD , Co. Reg. No.: 201227110H								
Vehicle Reg. No.:	PC2284D	Date of Loss:	01/03/2019 13:00 - :59 [61 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D200532	Policy/Cover Note No.:	DMPCSN31217418022						
Vehicle Reg. No. (Insured):	SKB968S	Policy No. (Claimant):	5092609656-01						
		Excess:	S\$600.00						
Repairer:	LexBuild International Pte Ltd (HQ) 2 Woodlands Sector 1 (Woodlands Spectrum 1), #05-12, 738068 Woodlands - Tel: 6456-3533								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 21/03/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*PC2284D (SNM19D200532)
[SKB968S]
TP
SINGAPORE COACH SERVICES PTE LTD
Mar 1 2019 1:00PM
[-]
LexBuild International Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser		☒	
Assessment Reports						1 per page		☐		☒	
No	Finalized On	LexBuild International Pte Ltd (HQ)					Thumbnail	Print			
1	04/03/19 17:45	Accident Statement					Load HTML				
Photos/Images						3 per page		☐		☒	
No	Finalized On	LexBuild International Pte Ltd (HQ)					Thumbnail	Print			
1	04/03/19 16:52	Identification Card [Linked Accident Report Documents]					Load JPG	☒			
2	04/03/19 16:52	log card [Linked Accident Report Documents]					Load JPG	☒			
3	04/03/19 16:52	Insurance [Linked Accident Report Documents]					Load JPG	☒			
4	04/03/19 16:52	Accident Photo [Linked Accident Report Documents]					Load JPG	☒			
5	04/03/19 16:52	Accident Photo [Linked Accident Report Documents]					Load JPG	☒			
6	04/03/19 16:52	TP Driving Licence [Linked Accident Report Documents]					Load JPG	☒			
7	04/03/19 16:52	Accident Photo [Linked Accident Report Documents]					Load JPG	☒			
8	04/03/19 16:52	Accident Photo [Linked Accident Report Documents]					Load JPG	☒			
9	04/03/19 16:52	Accident Photo [Linked Accident Report Documents]					Load JPG	☒			
10	04/03/19 16:52	Accident Photo [Linked Accident Report Documents]					Load JPG	☒			
11	04/03/19 16:52	Accident Photo [Linked Accident Report Documents]					Load JPG	☒			
12	04/03/19 17:43	log card [Linked Accident Report Documents]					Load JPG	☒			
13	04/03/19 17:43	Insurance [Linked Accident Report Documents]					Load JPG	☒			
14	04/03/19 17:43	Identification Card [Linked Accident Report Documents]					Load JPG	☒			
15	04/03/19 17:44	Accident Photo [Linked Accident Report Documents]					Load JPG	☒			
16	04/03/19 17:44	Accident Photo [Linked Accident Report Documents]					Load JPG	☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print			
1	13/03/19 18:27	General View					Load JPG	☒			
2	13/03/19 18:27	General View					Load JPG	☒			
3	13/03/19 18:27	General View					Load JPG	☒			
4	13/03/19 18:27	General View					Load JPG	☒			
5	13/03/19 18:27	General View					Load JPG	☒			
6	13/03/19 18:27	General View					Load JPG	☒			
7	13/03/19 18:27	General View					Load JPG	☒			
8	13/03/19 18:28	General View					Load JPG	☒			
9	13/03/19 18:28	General View					Load JPG	☒			
10	13/03/19 18:28	General View					Load JPG	☒			
11	13/03/19 18:28	General View					Load JPG	☒			

Assessment Reports				1 per page	☒
No	Finalized On	LexBuild International Pte Ltd (HQ)	Thumbnail	Print	
12	13/03/19 18:28	General View	 Load JPG	☒	
13	13/03/19 18:28	General View	 Load JPG	☒	
14	13/03/19 18:28	General View	 Load JPG	☒	
15	13/03/19 18:28	General View	 Load JPG	☒	
16	13/03/19 18:28	General View	 Load JPG	☒	
17	13/03/19 18:28	General View	 Load JPG	☒	
18	13/03/19 18:28	Chassis Number	 Load JPG	☒	
19	13/03/19 18:28	Odometer Reading	 Load JPG	☒	
Documentation				1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	12/03/19 14:58	TP SAS REPORT - PC2284D	 Load PDF		
2	12/03/19 14:58	AUTHORISATION TO ACT	 Load PDF		
3	12/03/19 14:58	CI	 Load PDF		
4	12/03/19 14:58	PRS - PC2284D	 Load PDF		
No	Finalized On	LexBuild International Pte Ltd (HQ)	Thumbnail	Print	
1	04/03/19 17:42	Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒	
2	04/03/19 17:42	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	☒	

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On	LexBuild International Pte Ltd (HQ)	Thumbnail	Print	
1	04/03/19 17:45	Accident Statement	 Load HTM		
Photos/Images				3 per page	☒
No	Finalized On	LexBuild International Pte Ltd (HQ)	Thumbnail	Print	
1	04/03/19 16:52	Identification Card	 Load JPG	☒	
2	04/03/19 16:52	log card	 Load JPG	☒	
3	04/03/19 16:52	insurance	 Load JPG	☒	
4	04/03/19 16:52	Accident Photo	 Load JPG	☒	
5	04/03/19 16:52	Accident Photo	 Load JPG	☒	
6	04/03/19 16:52	TP Driving Licence	 Load JPG	☒	
7	04/03/19 16:52	Accident Photo	 Load JPG	☒	
8	04/03/19 16:52	Accident Photo	 Load JPG	☒	
9	04/03/19 16:52	Accident Photo	 Load JPG	☒	
10	04/03/19 16:52	Accident Photo	 Load JPG	☒	
11	04/03/19 16:52	Accident Photo	 Load JPG	☒	
12	04/03/19 17:43	log card	 Load JPG	☒	
13	04/03/19 17:43	Insurance	 Load JPG	☒	
14	04/03/19 17:43	Identification Card	 Load JPG	☒	
15	04/03/19 17:44	Accident Photo	 Load JPG	☒	
16	04/03/19 17:44	Accident Photo	 Load JPG	☒	
Documentation				1 per page	☒
No	Finalized On	LexBuild International Pte Ltd (HQ)	Thumbnail	Print	
1	04/03/19 17:42	Sketch Plan	 Load JPG	☒	
2	04/03/19 17:42	Sketch Plan #2	 Load JPG	☒	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119004525/EVD3Q2

Date: 06/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN31217418022

Claimant Vehicle No: PC2284D Insured Vehicle No: SKB968S

Date of Loss: 01/03/2019 Nature of Claim: TP Claim No: SNM19D200532

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC2284D**

Make & Model: GOLDEN DRAGON XML6103J98, 6.7 D (M) Engine No: ISB67E530022051177

Reg. Date: 03/01/2014 (Man. Year: 2013) Chassis No: LL3BGCDH1DA003603

Colour: White Odometer: 298766 km

Engine Capacity: 6693 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 11 R22.5 Rear Tyre Size: 11 R22.5

Front Left Side: Double Coin 5 mm Rear Left Side: Double Coin 5 mm

Front Right Side: Double Coin 5 mm Rear Right Side: Double Coin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,640.00	800.00	1,840.00	69.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,640.00	800.00	1,840.00	69.70
+ GST 7.00/7.00% (S\$)	184.80	56.00	128.80	69.70
Nett Amount (S\$)	2,824.80	856.00	1,968.80	69.70

INSPECTION

Date of Assignment: 12/03/2019

Date Inspected: 13/03/2019 Inspected At: LexBuild International Pte Ltd (HQ)
2 Woodlands Sector 1 (Woodlands Spectrum 1), #05-12
Singapore 738068

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 06 May 2019)

Parts: N/A GOLDEN DRAGON XML6103J98 6.7 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for PC2284D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SUPPLY SKILLED LABOUR TO ,REPAIR ,APPLY FIBER & GRINDING REAR RHS DOME	New	880.00	350.00
2	SUPPLY SKILLED PAINTER & PAINT MATERIAL TO ,PUTTY ,GRINDING & SPRAYPAINT REAR RHS DOME	New	1,760.00	450.00
Gross Labour Cost (\$\$)			2,640.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >