

12/2016

SNG CASE OWNER

Syuzha

CC 6/AIG1600

5436

Kh 0392-1

Kim 39

LKK:  
IDAC:

Surveyor:

Kim 39

DOI:

22-3-16

Date / Time:

22-3-16

Registered in Merimen:

23-3-16

Pre-assign / CCU / FTE



Insured Vehicle No.:

SEX 789B

Name of Insured:

Low die hang

Insured Tel No.:

HP: 96778376

Excess Sec II :\$5

D.O.A.: 14-3-16

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

912413824456

Policy No.:

2100440316

Make / Model:

LEXUS ES250

Place of Accident:

Macpherson Rd

If NO, Driver Name / Age:

Driver Tel No.:

SJY 60676

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

K Kim Hin



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
22/3/16	SJY 60676-X, SEX 789B-X	Non-Reporting Itr (1st):	
	14.16 called OI. Spoke to Mr Low. Inquire about the claim. Confirm the accident. NO evidence. He said regarding about the car accident (issue with patric) from general motor.	Non-Reporting Itr (2nd):	
		Non-Reporting Itr (Final):	
		Notification Itr (if non-pickup):	
		Call OI:	22/3/16
		After call Itr to OI:	
		Documentation Check List: Handler / Typist	
		Notification Itr (if non-pickup)	<input checked="" type="checkbox"/>
		After call Itr to OI:	<input checked="" type="checkbox"/>
		Authorisation To Act:	<input checked="" type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/>
		Car Rental Invoice:	<input checked="" type="checkbox"/>
		Towing Invoice	<input type="checkbox"/>
		LTA / GIA:	<input checked="" type="checkbox"/>
		Medical Bill:	<input type="checkbox"/>
		PIR:	<input type="checkbox"/>
		Mandate/Reject Instruction:	<input type="checkbox"/>
		LOD	<input checked="" type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/>
		Others:	<input type="checkbox"/>

<b>PRELIMINARY ADVICE</b>	Date/Time:	Sent By:	Confirm by:
<b>FINALIZATION</b>	Date/Time:	Confirm with:	Confirm by:
Repair Cost: LG	\$5 3,150.00 ( 4 days) Reduction: 67 %		Email <input type="checkbox"/> Call <input type="checkbox"/>
<b>FINAL SETTLEMENT</b>	Date/Time: 04/10/19	Confirm with: HARGREAVES	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No.: ALL		If NO or B 28, Ass. Lia:
Repair Cost: (w/6rs)	\$5 3,370.50		(BOTH TAKING) 1/10/19
Loss of Rental (LOR):	\$5 720.00 ( 6 days) x \$ 120		TP VIDEO (N)
Loss of Use (LOU):	\$5 - ( 3 x days)		no developments
Loss of Income (LOI):	\$5 - ( 3 x days)		
LOR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]		
GIA/LTA Search	\$5 2.00		
Medical:	\$5 -		1) Claim status: Normal/Reject/Private Settle
Disbursement:	\$5 - (e.g. Tow/ Independent)		2) Report Format: WP
Legal Cost	\$5 -		3) Survey fee: \$320 (PAID)
<b>Total:</b>	\$5 4,092.50	Global Sum \$5: -	
<b>FINAL PAYMENT</b>	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	\$5 4,092.50	Name 1: K KIM HIN AUTO PTB LTD	
Payee 2: (Strike if N.A.)	\$5 -	Name 2: -	
Payee 3: (Strike if N.A.)	\$5 -	Name 3: -	

COPY SENT 4/10/19

ASS. REC. BY:

REF: A161

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD (TP / WS / TP RES / OD RES / EVA / INV / MV)

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s KK H/W

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 04 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: STY 6062 G Yr Regn: 09.10

Type: M/Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mer C180 CC 1796

Colour: W. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 75950 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: W00 2040492A 403583

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 7 mm

L/Bal. 6 mm L/Bal. 7 mm

D.O.A. 19/3/16 D.O.I. 22/3/16

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

C/S RA body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

23/3 File pass to Ashley

45 p 3150, 4 days

Reval \$ 6155.20, 67.1)

Cost/Term. File Pass 1st  : Prel. Report

1)  : Final Report

Cost/Term. File Return 1st

2)

Report Format :

Lump Sum / L.B.I: (5)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  Site Insp (5)

Interview (5)

Tech. Invs (5)

Weekend (5)

Survey Fee

Transportation

\_\_\_\_\_ S + RS \_\_\_\_\_

Phone

Other

1074

**K. Kim Hin AUTO PTE LTD**

金興(興)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號  
 Blk 34 Sin Ming Drive, #01-114, Singapore 575708.  
 Tel: 6452 7018 (5 Lines) Fax: 6458 3895  
 Email: service@kkinhin.com.sg

No. : 27767

Vehicle Insured : SKX 789 B  
 Accident Date : 14-Mar-2016

Date : 21-Mar-2016

Our Ref : 160194 (AIG ASIA) / XW

PAGE : 1

MR TAY HIAN MENG  
 Singapore

*Not Authorised*  
*Li Song & 7*  
*Resurvey After Paint 4 days*

ESTIMATED COST OF REPAIR FOR MERCEDES BENZ C180 CGI (2010) SJY6062G  
 =====

1 pc	o/s front fender	R	841.00	X	
1 pc	o/s front fender "BLUE EFFICENCY" emblem	Rs	56.00	✓	
1 pc	o/s front fender chrome moulding	Rs	34.00	✓	
1 pc	o/s wingmirror	Rs	1,080.00	✓	
1 pc	o/s wingmirror glass	Rs	1,450.00	X	
1 pc	o/s wingmirror cover c/w signallamp	Rs	350.00	X	
1 pc	o/s front door	Rs	1,682.00	✓	
1 pc	o/s front door chrome moulding	Rs	88.00	✓	
1 pc	o/s rear door	R	2,010.00	X	
1 pc	o/s rear door chrome moulding	Rs	87.00	✓	
1 pc	o/s rear door weatherstrip	Rs	125.00	X	
1 pc	o/s front door weatherstrip	Rs	125.00	50% (62.50)	3077.00
			7,928.00		
		Less 10% :	-792.80		
			-----		7,135.20

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

800.00 50%

To putty and respray on affected portions.

1,100.00 60%



金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號  
 Blk 34 Sin Ming Drive, #01-114, Singapore 575708.  
 Tel: 6452 7018 (5 Lines) Fax: 6458 3895  
 Email: service@kkimhin.com.sg

No. : 27767

Vehicle Insured : SKX 789 B  
 Accident Date : 14-Mar-2016

Date : 21-Mar-2016

Our Ref : 160194 (AIG ASIA) / XW

PAGE : 1

MR TAY HIAN MENG  
 Singapore

*Not Authorized*  
*61 Days & 7*  
*Recovery After Paint 4 days*

ESTIMATED COST OF REPAIR FOR MERCEDES BENZ C180 CGI (2010) SJY6062G

1 pc	o/s front fender	R	841.00	x	
1 pc	o/s front fender "BLUE EFFICENCY" emblem	Rs	56.00	✓	
1 pc	o/s front fender chrome moulding	Rs	34.00	✓	
1 pc	o/s wingmirror	Rs	1,080.00	✓	
1 pc	o/s wingmirror glass	Rs	1,450.00	x	
1 pc	o/s wingmirror cover c/w signallamp	Rs	350.00	x	
1 pc	o/s front door	Rs	1,682.00	✓	
1 pc	o/s front door chrome moulding	Rs	88.00	✓	
1 pc	o/s rear door	R	2,010.00	x	
1 pc	o/s rear door chrome moulding	Rs	87.00	✓	
1 pc	o/s rear door weatherstrip	Rs	125.00	x	
1 pc	o/s front door weatherstrip	Rs	125.00	50/100	
			7,928.00		
Less 10% :			-792.80		
			7,135.20		

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

800.00 *500*

To putty and respray on affected portions.

1,100.00 *600*

**金興(龔)汽車私人有限公司**

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkinhin.com.sg

Vehicle Insured : SKX 789 B  
Our Ref : 160194

Page : 2  
No. : 27767

To remove door's fittings

250.00 *801*

Total : S\$ 9,285.20  
=====

Singapore Dollars Nine Thousand Two Hundred and  
Eighty Five and Cents Twenty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

By the Insurer's Consultant, hence notify  
the Repairer of the following:

- To resurvey & re-estimate spray painting
- To advise & re-estimate (parts) during resurvey
- Parts prices are subject to confirmation
- Turn over survey is on a "Without Prejudice" basis
- To accept modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Your Ref: SKX789B  
Our Ref : 160194/03

Mr Tay Hian Meng  
Correspondence Address:  
c/o M/s K. Kim Hin Auto Pte Ltd  
Blk 34 Sin Ming Drive #01-114  
Singapore 575708

Date : 03 MAY 2017

AIG Asia Pacific Insurance Pte Ltd  
Motor Claims Dept  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

Dear Sir/Madam

**ACCIDENT INVOLVING SJY 6062 G AND SKX 789 B ALONG MACPHERSON ROAD  
SLIP ROAD BEFORE CTE ON 14 MARCH 2016**

---

I am the owner of the m/vehicle SJY 6062 G which was involved  
in the above accident.


My vehicle sustained damages as a result of the said accident and  
I am now claiming against you for the followings:-

1. Costs of repairs	.. .. .	\$ 3,370.50
2. Loss of use of vehicle at \$ per day for 06 day(s) (SC Car Rental)	.. .. .	\$ 1,080.00
3. Police documents/Search fees	.. .. .	\$ 2.00
4. Surveyor report fee	.. .. .	\$
	Total:	\$ 4,452.50 =====

Please advise whether you are prepared to settle my claim as  
outlined above. As I have yet to settle my repair bill with my  
repairers, I hereby authorise my repairers and/or their  
representatives to negotiate/compromise settlement of above claim  
on my behalf.

Looking forward to hear from you soon.

Yours faithfully,



encl.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG16005436/Kza3

4 April 2016

**LAU CHE HUNG**  
49 Hindhede Walk  
#05-04  
Singapore 587976

Dear Sir/Madam,

**ACCIDENT INVOLVING SKX 789B & SJY 6062G ON 14/03/2016**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by 14/4/2016, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Zayer  
DID: 6841 2409  
FAX: 6741 4108  
Email: [zayer@lkkauto.com](mailto:zayer@lkkauto.com)

Case Handler  
c.c. **AIG Asia Pacific Insurance Pte Ltd**  
(Motor Claims Dept)

Letter of Authorization

To Whom It May Concern

Accident on 14 MARCH 2016 involving SJY 6062G AND SKX789E


Along MACPHERSON ROAD SUIP ROAD BEFORE CTE

I/We TAY HIAN MENG NRIC NO. S1220410H of  
56 JALAN CHENG KER, S'PORE 369279

owner of Motor Vehicle Registration No. SJY 6062G insured by  
ERB INSURANCE (S'PORE) LTD under Policy No. B-V000 8926-MVA-2001

do hereby authorize M/s K KIM HIN AUTO PTE LTD as my/our  
representative with full authority to write, negotiate and settle claim for damages on my/our  
behalf against the owner and /or driver of Motor Vehicle Regn No. SKX789E  
in regard to the above mentioned accident

I /We also consent to the agreed settlement sum be made in favour of my/our representative,  
M/s K KIM HIN AUTO PTE LTD and the said  
payment be forwarded to them to be construed as full and final discharge of my/our claim.

  
Owner's Signature & Company Stamp

22/3/2016  
Date

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, **K.KIM HIN AUTO PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$3,370.50** (Repair Cost), **S\$720.00** (Loss of Rental/Use), **S\$2.00** (Disbursement), for vehicle no. **SJY 6062G** that was damaged pursuant to the accident which occurred on **14/03/2016** (date) along **MACPHERSON ROAD** (location) involving vehicle no/s **SKX 789B**. This is pursuant to the inspection conducted on **22/03/2016** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **TAY HIAN MENG** ("the third party claimant") of vehicle no. **SJY 6062G** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SJY 6062G** (vehicle no.) as a result of the accident.


We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 4<sup>th</sup> (day) of October (month) **2019** (year)

A circular stamp with the letters "LKK" in the center, surrounded by a double-line border. A handwritten signature is written over the stamp.

Signed by appointed surveyor

A circular stamp with the text "K.KIM HIN AUTO PTE LTD" around the perimeter. A handwritten signature is written over the stamp.

Signed by "the workshop" (with chop)



CO. REG. NO: 199402370D  
GST NO: M2-0123250-3

AUTO PTE LTD

**金興(興)汽車私人有限公司**

新民通道(大牌34座)門牌114號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6454 9575

Email: service@kkimhin.com.sg

No. : 22551

Vehicle Insured : SKX 789 B

Accident Date : 14-Mar-2016

Date : 28-Mar-2016

Our Ref : 160194 (AIG ASIA) / MARGARET

PAGE : 1

MR TAY HIAN MENG  
Singapore

COST OF REPAIR FOR MERCEDES BENZ C180 CGI (2010) SJY6062G  
=====

To supply spare parts

To remove, cut out damaged parts,  
panel beating, welding, align,  
refix and to renew affected parts.

To putty and respray on affected  
portions.

To remove door's fittings

	-----
	3,150.00
Add 7% GST :	220.50
	-----
Total :	S\$ 3,370.50
	=====

Singapore Dollars Three Thousand Three Hundred  
and Seventy and Cents Fifty Only

金興(興)汽車私人有限公司  
K. KIM HIN AUTO PTE LTD

# SC CAR RENTAL PTE. LTD.

Co. Reg. No.: 201323288W

Blk 34 Sin Ming Drive #01-112 Singapore 575708  
Tel: 6452 7684 Fax: 6454 9575

## RENTAL AGREEMENT

No: 30629

Vehicle No.	Make / Model
SAR 3406 R	Toyota Altis 1.8A

Date: \_\_\_\_\_

HIRER'S PARTICULARS	
Name	: <u>Jay Hian Meng</u>
Address	: <u>516 Jalan Chengkok</u> <u>8 (269279)</u>
Telephone (Home)	:
(Office)	:
H/Phone	: <u>9694 3380</u>
NRIC or Passport No	: <u>S1220410 H</u>
Nationality	:
Date of Birth	: _____ Age : _____
Driving Licence No	: _____ Expires : _____
Type	: Local / Int'l Issued : _____
Driving Experience	:

CHARGES		
	\$	cts.
Day(s) @ \$5/80	1080	00
Week(s) @ \$5		
Month(s) @ \$5		
Insurance		
Additional Rental Payable		
Surcharge of Fuel		
Total	1080	00
Less Deposit (Cash / Cheque No. )		
Balance Payable / Refundable		
Refund Received (Cash / Cheque No. )		

Note: 1) Hirer is liable for all parking fines and traffic violations.

- 2) Excess - In the event of any accident, the Hirer is liable to pay first (SS 2500.00) plus loss of earnings before the damaged vehicle is being repaired.
- 3) Young, Inexperienced or Aged driver, additional excess of (SS 2500.00) will apply.

I/We declare that the above particulars are true and correct in every respect and I/We have read and understood the terms and conditions of the Hire Agreement printed overleaf.

\* Windscreen Breakage \$100.00 if Stone hit. otherwise full price will apply.

Stamp & Signature of Hirer


Signature of Driver  
(If different from Hirer)

Date \_\_\_\_\_

Date \_\_\_\_\_

Date Out	<u>22-3-16</u>	Date In	<u>28-3-16</u>
Time Out	<u>2:20 pm</u> AM / PM	Time In	<u>3:00</u> AM / PM
Mileage at Delivery / Pick-up		Mileage on Returning	
Fuel Level at Delivery / Pick-up	E 1/4 1/2 <u>3/4</u> 1 1	Fuel on Returning	E 1/4 1/2 3/4 1 P
Surcharge of Fuel will be at SS	per 1/4 tank.		

Remarks: **Kindly note the following:-**  
No work permit holders are allowed to drive;  
No drivers below 23 years old are allowed to drive;  
Driving to Malaysia is strictly not allowed.

SJY 60629  




RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

10 Anson Road, #06-16 International Plaza, Singapore 079903  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

### Third Party Insurer Enquiry

Our Ref No: GR-16-028197

Date of Request: 15/03/2016

Your Ref No:

Online Purchase

K Kim Hin Auto Pte Ltd  
Blk 34, #01-114  
Sin Ming Drive  
Singapore 575708

Dear Sir/Madam,

Enquiry Date 15/03/2016

Enquiry By Jane

TP Vehicle No. SKX789B

Accident Date 14/03/2016

#### Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKX789B	AIG Asia Pacific Insurance Pte. Ltd.	27/11/2015-13/08/2016	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



**GENERAL  
INSURANCE  
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

10 Anson Road, #06-16 International Plaza, Singapore 079903

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

## TAX INVOICE

Our Ref No: GR-16-028197  
Date of Request: 15/03/2016

Your Ref No: Online Purchase

K Kim Hin Auto Pte Ltd  
Blk 34, #01-114  
Sin Ming Drive  
Singapore 575708

Dear Sir/Madam,

Enquiry Date 15/03/2016  
Enquiry By Jane  
TP Vehicle No. SKX789B  
Accident Date 14/03/2016

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

GIRO  Cash  Cheque

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Mar 2016 16:11 <a href="#">Edit Reg</a>		22 Mar 2016 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$3,150.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,150.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>Lau Che Hung</b> , ID: S2197399H								
Main Claimant:	<b>TAY HIAN MENG</b> , ID: S1220410H								
Vehicle Reg. No.:	<b>SJY6062G</b>	Date of Loss:	14/03/2016 12:00 - :59 <b>[65 Months and 27 Days From LTA Reg Date (Man Yr)]</b>						
Claim Type:	<b>TP / 9124135244SG</b>	Policy/Cover Note No.:	2100440316 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SKX789B</b>	Policy No. (Claimant):	8-V0008926-MVA-R001						
		Excess:							
Repairer:	<b>K Kim Hin Auto Pte Ltd (HQ)</b> 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (SG)</b> - Tel: 65-6419-3000 ... [Handled by <b>Chan, Yoke Shi</b> ] yokeshi.chan@aig.com								
Claimant's Insurer:	<b>QBE Insurance (Singapore) Pte Ltd (HQ)</b> - Tel: 62246633								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... <b>[Final Rpt due 15/03/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• AIG_SG (13/03/2019): <b>Report Send Back Alerts - SJY6062G (TP)</b>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJY6062G (9124135244SG)  
[SKX789B]  
TP  
TAY HIAN MENG  
Mar 14 2016 12:20PM  
[Lau Che Hung]  
K Kim Hin Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View <input type="button" value="View in Browser"/>	
<b>Video</b>														1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	03/10/19 16:48	<b>Video - Accident</b> TP VIDEO FOOTAGE											Load MP4	<input type="checkbox"/>		
<b>Letters/Correspondences</b>														1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	(Draft)	<b>Third Party Express Settlement - Payment Breakdown</b>											Edit	<input type="checkbox"/>		
<b>Photos/Images</b>														3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	23/03/16 17:41	<b>Odometer Reading</b>											Load JPG	<input checked="" type="checkbox"/>		
2	23/03/16 17:41	<b>Chassis Number</b>											Load JPG	<input checked="" type="checkbox"/>		
3	23/03/16 17:41	<b>General View</b>											Load JPG	<input checked="" type="checkbox"/>		
4	23/03/16 17:41	<b>General View</b>											Load JPG	<input checked="" type="checkbox"/>		
5	23/03/16 17:41	<b>General View</b>											Load JPG	<input checked="" type="checkbox"/>		
6	23/03/16 17:41	<b>General View</b>											Load JPG	<input checked="" type="checkbox"/>		
7	23/03/16 17:41	<b>General View</b>											Load JPG	<input checked="" type="checkbox"/>		
8	23/03/16 17:41	<b>General View</b>											Load JPG	<input checked="" type="checkbox"/>		
9	23/03/16 17:41	<b>General View</b>											Load JPG	<input checked="" type="checkbox"/>		
10	23/03/16 17:41	<b>General View</b>											Load JPG	<input checked="" type="checkbox"/>		
11	23/03/16 17:41	<b>General View</b>											Load JPG	<input checked="" type="checkbox"/>		
12	23/03/16 17:41	<b>General View</b>											Load JPG	<input checked="" type="checkbox"/>		
13	23/03/16 17:41	<b>General View</b>											Load JPG	<input checked="" type="checkbox"/>		
14	23/03/16 17:41	<b>General View</b>											Load JPG	<input checked="" type="checkbox"/>		
15	17/01/17 12:01	<b>LKK RESURVEY PHOTO</b>											Load JPG	<input checked="" type="checkbox"/>		
16	17/01/17 12:01	<b>LKK RESURVEY PHOTO</b>											Load JPG	<input checked="" type="checkbox"/>		
17	17/01/17 12:01	<b>LKK RESURVEY PHOTO</b>											Load JPG	<input checked="" type="checkbox"/>		
<b>Documentation</b>														1 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	23/03/16 17:23	<b>TP ESTIMATE - MARKED</b>											Load PDF	<input type="checkbox"/>		
2	23/03/16 17:23	<b>TP GIA REPORT</b>											Load PDF	<input type="checkbox"/>		
3	13/01/17 19:12	<b>email to AIG</b>											Load PDF	<input type="checkbox"/>		
4	25/01/17 12:48	<b>LETTER TO OI</b>											Load PDF	<input type="checkbox"/>		
5	13/03/19 10:52	<b>TP LO</b>											Load PDF	<input type="checkbox"/>		
6	09/10/19 14:30	<b>WORKSHOP INVOICE</b>											Load PDF	<input type="checkbox"/>		
7	09/10/19 14:30	<b>AUTHORISATION TO ACT FORM</b>											Load PDF	<input type="checkbox"/>		
8	09/10/19 14:30	<b>Release Voucher</b>											Load PDF	<input type="checkbox"/>		
9	09/10/19 14:30	<b>RENTAL RECEIPT</b>											Load PDF	<input type="checkbox"/>		
10	09/10/19 14:30	<b>GIA SEARCH</b>											Load PDF	<input type="checkbox"/>		
11	09/10/19 14:30	<b>LOD</b>											Load PDF	<input type="checkbox"/>		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail	Print			
1	24/03/16 09:56	<b>OI GIA Report</b>											Load PDF	<input type="checkbox"/>		

## Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**AIG THIRD PARTY EXPRESS SETTLEMENT  
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008  
(PAYMENT BREAKDOWN)**

Vehicle No:	SKX789B (Insd veh)	Model:	MERCEDES-BENZ C180 1.8 CGI (A)
	SJY6062G (TP veh)		
Date of Accident:	14/03/2016		

Global Sum Settlement	:	[ ] Yes	[ X ] No
Repair Estimate	\$		9,935.16
Final Repair Cost	\$		3,370.50
Loss of Use	\$		days at \$0.00 per day
Rental (if any)	\$		720.00    6 days
LTA / GIA Search Fee	\$		2.00
Others:	\$		0.00
	\$		
Final Settlement Sum	\$		4,092.50
Is Third Party Workshop GIA Registered?    [ X ] YES    [ ] NO    (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No    BOLA Scenario No:	
		_____ NIL _____	
BOLA Liability: _____ 100 _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	K.Kim Hin Auto Pte Ltd	:	\$ 4,092.50
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

09 Oct  
2019

\_\_\_\_\_  
LKK Auto Consultants Pte Ltd

\_\_\_\_\_  
Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;  
Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC8/AIG16005436/KHA3Q2-1

Date: 09/10/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100440316  
 Claimant: SJY6062G Insured Vehicle No: SKX789B  
 Vehicle No: SJY6062G Nature of Claim: TP Claim No: 9124135244SG  
 Date of Loss: 14/03/2016

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SJY6062G**  
 Make & Model: MERCEDES-BENZ C180, 1.8 CGI (A) Engine No: 27182030079441  
 Reg. Date: 16/09/2010 (Man. Year: 2010) Chassis No: WDD2040492A403588  
 Colour: Metallic Grey Odometer: 75950 km  
 Engine Capacity: 1796 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17  
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 7 mm  
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,135.20	2,786.80	4,348.40	60.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	1,180.00	970.00	45.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,285.20</b>	<b>3,966.80</b>	<b>5,318.40</b>	<b>57.28</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,150.00</b>		
(S\$)	9,285.20	3,150.00	6,135.20	66.08
<b>+ GST 7.00/7.00% (S\$)</b>	649.96	220.50	429.46	66.07
<b>Nett Amount (S\$)</b>	<b>9,935.16</b>	<b>3,370.50</b>	<b>6,564.66</b>	<b>66.08</b>
<b>+ Car Rental (6.0 x S\$120.00/day) (S\$)</b>		720.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>4,092.50</b>		

## INSPECTION

Date of Assignment: 22/03/2016  
 Date Inspected: 22/03/2016 Inspected At: K Kim Hin Auto Pte Ltd (HQ)  
 Blk 34, #01-114, Sin Ming Drive  
 Singapore 575708

Estimated Period of Repair: 4.0 days

---

**Adjuster:** KENNETH KONG

**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S FRONT FENDER	Repair	841.00 FL	*- FL
2	1		*O/S FRONT FENDER BLUE EFFICENCY EMBLEM	Necessary	56.00 FL	*56.00 FL
3	1		*O/S FRONT FENDER CHROME MOULDING	Necessary	34.00 FL	*34.00 FL
4	1		*O/S WINGMIRROR	Cut	1,080.00 FL	*1,080.00 FL
5	1		*O/S WINGMIRROR GLASS	Serviceable	1,450.00 FL	*- FL
6	1		*O/S WINGMIRROR COVER C/W SIGNALLAMP	Serviceable	350.00 FL	*- FL
7	1		*O/S FRONT DOOR	Bent / Warped	1,682.00 FL	*1,682.00 FL
8	1		*O/S FRONT DOOR CHROME MOULDING	Necessary	88.00 FL	*88.00 FL
9	1		*O/S REAR DOOR	Repair	2,010.00 FL	*- FL
10	1		*O/S REAR DOOR CHROME MOULDING	Necessary	87.00 FL	*87.00 FL
11	1		*O/S REAR DOOR WEATHERSTRIP	Serviceable	125.00 FL	*- FL
12	1		*O/S FRONT DOOR WEATHERSTRIP (50%)	Necessary	112.50 FS	*62.50 FS

F=Franchise part. S=SpcNett. L=ListitemDisc.

<b>Sub Total (\$\$)</b>	<b>7,915.50</b>	<b>3,089.50</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	780.30	302.70
<b>Total Parts (\$\$)</b>	<b>7,135.20</b>	<b>2,786.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ,CUT OUT DAMAGED PARTS ,PANEL BEATING,WELDING ,ALIGN,REFIX AND TO RENEW AFFECTED PARTS	New	800.00	500.00
2	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	1,100.00	600.00
3	TO REMOVE DOORS FITTINGS	New	250.00	80.00
<b>Gross Labour Cost (S\$)</b>			<b>2,150.00</b>	<b>1,180.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >