





Team: ARC Repair TP(CLSO)1

**JOB CARD**

Sales Order:

JC NO.: 305276831

CUSTOMER

RMS

CUSTOMER NO.

ADDRESS

L (R)

(P)

COMFORT TRANSPORTATION PTE LTD VARS  
 7010045  
 383 SIN MING DRIVE  
 Singapore SINGAPORE 575717  
 65508755

REGN NO.: SHC8519H

MILEAGE

MAKE: HYUNDAI

FUEL

E.....1/2.....F

MODEL I-40

DATE/TIME IN 12.03.2019 09:30

YR OF MANU 03.12.2015

TARGET DATE

CHASSIS CODE RMHLB41UMGU080714

COMPLETION DATE/TIME:

SCOUNT CARD NO.

JOB DESCRIPTION

Accident Date: 05.03.2019


NATURE: 3P 05.03.2019 )

Q/NO

LABOR CODE

DESCRIPTION

EQ - Rear  
 LKIC/Kalmi -



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Name:

Job No.:

Vehicle No.:

SHC8519H

LARRY

Vehicle No.:

SHC8519H

Larry Ng

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard