



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD	Ref : CC4/ASM19004535/Apa3s2
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811	Date : 12-08-2020
ATTN: RICHARD ANG	Code : ASM



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKH 1792T	Veh. Inspected	SLJ 5375R
Policy No.	GA340074/1	Coverage (\$)	0.00
Claim No.	S9M01GT6	Excess (\$)	0.00
Assign From	RICHARD ANG	Assign Date	13/03/2019

2. Vehicle Particulars & Condition

Make & Model	LEXUS IS250	c.c	2500
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JTHBK262305116608	Colour	WHITE
Odometer	112173	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40 R18	CONTINENTAL	6 mm
L/H Front Tyre	225/40 R18	CONTINENTAL	6 mm
R/H Rear Tyre	225/40 R18	CONTINENTAL	6 mm
L/H Rear Tyre	225/40 R18	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/03/2019	Inspection Date	14/03/2019
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **10 Working Days**