



OFFICIAL FERRARI IMPORTER SINGAPORE

Ital Auto Pte Ltd

Date: 22-Feb-19

**QUOTATION**

To: AXA INSURANCE PTE LTD  
8 SHENTON WAY, #24-01, AXA TOWER  
Singapore 068811

Tel: 1800 8804741 Fax:  
email:

Our Ref: 187858 - EZ489C  
Reg. No: EZ489C  
Model: California  
VIN: 187858  
Mileage: 36219 KM  
Terms: INSURANCE

| Item | Description | Qty | Unit Price Excl GST | Line Discount | Line Amount Excl GST |
|------|-------------|-----|---------------------|---------------|----------------------|
|------|-------------|-----|---------------------|---------------|----------------------|

**LABOUR**

|                           |                                                                       |    |             |  |              |
|---------------------------|-----------------------------------------------------------------------|----|-------------|--|--------------|
| L                         | 20 DAYS LABOUR - TO DO WELDING, REMOVE AND REPLACE FRONT DAMAGE PARTS | 20 | \$ 1,920.00 |  | \$ 38,400.00 |
| Sub Total                 |                                                                       |    |             |  | \$ 38,400.00 |
| Total Amount Include GST: |                                                                       |    |             |  | \$ 41,088.00 |

28,800.

**RESPRAY PAINT**

|                           |                                                                            |   |             |  |             |
|---------------------------|----------------------------------------------------------------------------|---|-------------|--|-------------|
| L                         | TO RESPRAY PAINT FOR FRONT BUMPER, BONNET, FENDERS AND INTERNAL STRUCTURES | 1 | \$ 7,000.00 |  | \$ 7,000.00 |
| Sub Total                 |                                                                            |   |             |  | \$ 7,000.00 |
| Total Amount Include GST: |                                                                            |   |             |  | \$ 7,490.00 |

6000.

**MISCELLANEOUS**

|                           |                                         |   |           |  |           |
|---------------------------|-----------------------------------------|---|-----------|--|-----------|
| L                         | TOWING FEE, NUMBER PLATE, AC GAS TOP UP | 1 | \$ 750.00 |  | \$ 750.00 |
| Sub Total                 |                                         |   |           |  | \$ 750.00 |
| Total Amount Include GST: |                                         |   |           |  | \$ 802.50 |

**PARTS**

|                           |                     |   |              |  |              |
|---------------------------|---------------------|---|--------------|--|--------------|
| P                         | REFER TO PARTS LIST | 1 | \$ 84,586.94 |  | \$ 84,586.94 |
| Sub Total                 |                     |   |              |  | \$ 84,586.94 |
| Total Amount Include GST: |                     |   |              |  | \$ 90,508.03 |

Grand Total before Tax: \$ 130,736.94  
Grand Total Including GST: \$ 139,888.53

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer: [Signature] work to be completed for the job as described above. This estimate is based on our evaluation of the requirements necessary to complete the job and does not include material price increases or additional labor and material which may be required should unforeseen problems arise after the work has started. This quotation is valid for thirty (30) days only.

Signature: [Signature]  
Date: 14/3/19

Not Authorise 14/3/19C 1110am.

\* Resurvey before paint, Resurvey check items  
\* Supplementary items, to get approval from insurance.

20 days. Ex: \$10,000.

sure@lkkauto.com.

| S/N | TABLE | Ref | Description                                   | Qty | U/PRICE      | E/PRICE  | REMARKS                   |
|-----|-------|-----|-----------------------------------------------|-----|--------------|----------|---------------------------|
| 1   | 0014  | 1   | COMPL AIR DUCT - photo                        | 1   | 4240.44      | 4240.44  | OK                        |
| 2   | 0022  | 1   | WATER RADIATOR                                | 1   | 1995         | 1995     | ?                         |
| 3   | 0022  | 8   | RH LOWER BRACKET                              | 1   | 333          | 333      | ?                         |
| 4   | 0022  | 9   | RUBBER BUSHING                                | 4   | 17.59        | 70.36    | ?                         |
| 5   | 0022  | 10  | BUSHING                                       | 4   | 11.51        | 46.04    | ?                         |
| 6   | 0022  | 14  | COMPL. ELECTRIC FAN ASSEMBLY                  | 1   | 3600.11      | 3600.11  | ?                         |
| 7   | 0101  | 2   | RH BRAKE AIR INTAKE FASTENER                  | 1   | 2133.57      | 2133.57  | ?                         |
| 8   | 0101  | 11  | COMPL. LH FRONT FENDER 2/inner/4/inner        | 1   | 10949.71     | 10949.71 | OK                        |
| 9   | 0101  | 12  | CPL. RH. FRONT MODGUARD 4/inner/4/inner       | 1   | 11569.9      | 11569.9  | OK                        |
| 10  | 0101  | 20  | LOWER CROSS-MEMBER - photo                    | 1   | 2533.61      | 2533.61  | ?                         |
| 11  | 0101  | 29  | COMPL. FRONT BUMPER CROSS MEMBER - photo      | 1   | 2133.57      | 2133.57  | Request ASM authorisation |
| 12  | 0107  | 13  | RH FRONT CRASH BOX UPRIGHT - photo            | 1   | 1064.12      | 1064.12  | Request ASM authorisation |
| 13  | 0112  | 1   | FRONT SECTION OF FRONT FLAT UNDERFLOOR        | 1   | 634.55       | 634.55   | OK                        |
| 14  | 0112  | 2   | SCREW                                         | 51  | 2.81         | 143.31   | OK                        |
| 15  | 0112  | 3   | CENTRAL SECTION OF FRONT FLAT UNDERFLOOR      | 1   | 634.55       | 634.55   | OK                        |
| 16  | 0113  | 1   | FRONT GRAVEL GUARD FOR RH FRONT WHEELHOUSE 14 | 1   | 705.07       | 705.07   | OK                        |
| 17  | 0114  | 1   | COMPLETE FRONT BUMPER                         | 1   | 15055.53     | 15055.53 | OK                        |
| 18  | 0114  | 2   | FRONT SPOILER                                 | 1   | 2190.03      | 2190.03  | OK                        |
| 19  | 0114  | 3   | FRONT BUMPER GRILL                            | 1   | 5610.07      | 5610.07  | OK                        |
| 20  | 0114  | 4   | CAVALLINO RAMPANTE BADGE                      | 1   | 196.03       | 196.03   | OK                        |
| 21  | 0114  | 5   | NUT                                           | 2   | 1.36         | 2.72     | OK                        |
| 22  | 0114  | 6   | R.H. BRAKE AIR INTAKE - photo                 | 1   | 214.49       | 214.49   | OK                        |
| 23  | 0114  | 12  | FRONT LICENSE PLATE INSTALLATION              | 1   | 86.28        | 86.28    | OK                        |
| 24  | 0114  | 13  | BRACKET                                       | 1   | 46.91        | 46.91    | OK                        |
| 25  | 0114  | 17  | FRONT PARKING SENSOR CABLE - photo            | 1   | 310.29       | 310.29   | ?                         |
| 26  | 0114  | 18  | SENSOR                                        | 2   | 472.01       | 944.02   | OK - 2 RH-M/S             |
| 27  | 0114  | 19  | CLEAR SILICONE RING                           | 2   | 24.35        | 48.7     | OK                        |
| 28  | 0114  | 22  | PARKING SENSOR non photo                      | 2   | 517.21       | 1034.42  | M/S                       |
| 29  | 0114  | 23  | GASKET                                        | 2   | 25.57        | 51.14    | OK                        |
| 30  | 0114  | 24  | INNER RH SENSOR BRACKET                       | 1   | 96.29        | 96.29    | OK                        |
| 31  | 0114  | 25  | INNER LH SENSOR BRACKET                       | 1   | 91.42        | 91.42    | OK                        |
| 32  | 0114  | 26  | CLIP                                          | 25  | 2.95         | 73.75    | OK                        |
| 33  | 0127  | 16  | GASKET                                        | 1   | 750.06       | 750.06   | OK                        |
| 34  | 0144  | 1   | R.H. FRONT HEADLIGHT - photo                  | 1   | 14720.53     | 14720.53 | OK                        |
| 35  | 0146  | 1   | CENTRAL ENGINE COMPARTMENT COVER              | 1   | 277.35       | 277.35   | OK                        |
|     |       |     |                                               |     | S\$ 84586.94 |          |                           |