

Document

ASS. REP. BY

Self/Agency

Mr Lim

CS3/LPC 19004374 1Bvd3

P2

Special Instruction

ASSIGNMENT (Office)

From (Person)

Creuld poh

at

lpc

Date/Time

5/3/19 9:00am

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No.

GV 8158C

Insured

81752585

at Workshop n/o

Hup Lay Huat

Tel.

9677 3832

of

1 Kaki Bkt Ave 6 #01-35

Policy No.

Claim No.

18/19/19/VPOS /021469

Sum Insured

Excess

Make of Veh.

D.O.A

28/2/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time

12/3/19 11:11am

Person Contacted

Mr. Tan

Vehicle IN (OUT)

Date/Time

Action/Instruction (X) Estimate

Celine call since 5/3/19 - 11/3/19 - No answer from the wesp.
12/3/19 - he just answer.

GV 8158C - CS3/AIG 13022289/K1ha3W2

D.O.A - 26/11/2013

SJT 52585 - CS3/AWA 19004105/13cd3

D.O.A - 27/02/2019

29/3/19

@ 4:17pm Mr Tan said no estimate

29/3/19

Submit PRS report

(08/11/19)

Surveyor

REF:

JPC

PR3

ASSIGNMENT

From: _____ Date: 19/3/19

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GV 8158C

at Workshop m/s Hup Ley Huat

of 1 Kaki Blk Ave 6 #01-35 Autobay

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GV 8158C Yr Regn: 4/8/2006

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA DYNA 150 D C.C. 2986

Colour: SILVER A/C: Insured / Std / NI / NA

Sp. Reading: 583358 T/Radio: Insured / Std / NI / NA

Eng/No: 5L5657119

C/No: JTFUF349303012084

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil S/Rim / STD A/Rim or

Tyre Size: F: 185 R 14 C

R: 155 R 12 C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 28/2/19 D.O.I. 19/3/19

Survey held at Hup Ley Huat 417

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range 3,000/2 - 4,000/2

RECEIVED 01 APR 2019

MV 17,000/2

PV 10,904/2

NV 6,096/2

T. Lim
25/3/19

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2) 29/3 - typist

Add Fee: ☐ : Site Insp (\$)

Survey Fee: 490

Transportation:

S + RS, SI

Photos

Others

Report Format :

Lump Sum / I.B.I. (\$))

☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

TOTAL

490

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Tuesday, 5 March 2019 9:11 AM
To: assignments
Subject: FW: PRE-REPAIR SURVEY OF GV8158C [External Confidential]
Attachments: 05032019090014.pdf

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

96773832
Mr Tan.
Hap ley Huat motor.
NI

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, 5 March 2019 9:09 AM
To: Cheonghoh Law <mail@cheonghoh.sg>
Cc: MT_Claim_SG <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: PRE-REPAIR SURVEY OF GV8158C [External Confidential]

Lonpac External - Confidential

WITHOUT PREJUDICE

Our Ref : 18/19/19/VP050/021469

Dear Sirs,

We are not agreeable to your list of Single Joint Experts and shall appoint LKK Auto Consultants Pte Ltd for the pre-repair survey.

Please confirm if the pre-repair survey is for GV8158C or SGL3311Z.

Aside to LKK – Attn : Catherine,
Please see attached and proceed accordingly.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

Cheonghoh Law Corporation

(Incorporated with limited liability) Blk 53 Chin Swee Road #03-05 . Singapore 180053
Co. Reg No.201108070G Tel: 63378700 Fax: 63373700 E-mail: mail@cheonghoh.sg

In reply, please quote our Reference Number

Our Ref: LCH.ct/2KB02-90198.19
Your Ref: 18/19/19/VP05/021469

4 March 2019

Lonpac Insurance Berhad
300 Beach Road #17-04/07
The Concourse
Singapore 199555
Attn: Gerald Poh



BY FAX & BY HAND
Fax No: 62862708

Dear Sirs

ACCIDENT INVOLVING VEHICLES NO GV 8158 C AND SJT 5258 S AND YP 6771 M ON 28 FEBRUARY 2019 AT/ALONG WOODLANDS AVENUE 10 -

We refer to the above matter and to your letter of 4 March 2019.

Pursuant to the NIMA protocol of the Practice Directions Amendment No. 1 of 2016, we have our client's instructions to reject your list of appointed surveyors as stated in your said letter.

We are further instructed to append below our client's 10 proposed surveyors as follows:

- 1) Fong Kok Heng
- 2) Danny Yap
- 3) Willy Goh
- 4) Francis Ng
- 5) Dennis Yap
- 6) Louis Ng
- 7) Michael Yap
- 8) LimYong Tian
- 9) Patrick Ng
- 10) Philip Foo

If you are not agreeable to our list of surveyors above, kindly appoint your surveyor to proceed with the pre-repair survey of our client's vehicle SLG 3311 Z at our client's repairer workshop as follows :-

Hup Lay Huat Motor Spray Painting Services
Blk 1 Kaki Bukit Avenue 6 #01-35
Singapore 417883

Person to contact : Mr Tan Boon Seng (contact no. 96773832)

Yours faithfully

A handwritten signature in black ink, appearing to be "Lee Cheong Hoh".

Lee Cheong Hoh
CHEONGHOH LAW CORPORATION

cc: client - via fax only (GV 8158 C)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	8581C
Vehicle Details	
Vehicle No.:	GV8158C
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 D
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	5L5657119
Chassis No.:	JTFUF34Y303012084
Maximum Power Output:	-
Open Market Value:	\$23,681.00
Original Registration Date:	04 Aug 2006
First Registration Date:	04 Aug 2006
Transfer Count:	2
Actual ARF Paid:	\$1,185.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	03 Aug 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$23,127.00
COE Rebate Amount:	\$10,904.00
Total Rebate Amount:	\$10,904.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 25 Mar 2019

OK

Avg dep 8500/yr
708/mth

MV 17,000/2
PV 10,904/2
NV 6096/2

25/3/19



Toyota Dyna 150 (COE till 05/2022)

-

N.A

02-May-2007

2,982 cc

-

Truck

CLOSED

Fuel Type: Diesel

Auction Closing Time: 20th Feb 2019 at 04:00 PM

AUCTION VEH

Posted: 19-Feb-2019 Tags: 2007 Toyota Dyna, 2007 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 100 (COE till 04/2022)

\$20,900

\$6,860 /yr

11-Apr-2007

2,982 cc

-

Truck

Available

Fuel Type: Diesel

Drive With Assurance! All Our Quality Consignment Vehicles Are Selling At The Most Reasonable Price With A Peace Of Mind! Lowest Pricing In Market! Smooth Engine And Gear Box. Regular Maintained.No Gl...

CarQuotz Singapore

Posted: 24-Mar-2019 Tags: 2007 Toyota Dyna, 2007 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 (COE till 03/2022)

-

N.A

23-Mar-2007

2,982 cc

-

Truck

SOLD

Fuel Type: Diesel

Cny Sales Is Here! \$614 Per Month Only! In House Loan And High Trade In Available! Full Loan Also Available Subject To Approval! 10 Feet Dyna Lorry With Box Good Condition, Well Maintained Vehicle, Ju...

Bell Auto Pte Ltd

Posted: 28-Jan-2019 Tags: 2007 Toyota Dyna, 2007 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 (COE till 02/2022)

\$22,800

\$7,930 /yr

07-Feb-2007

2,982 cc

-

Truck

Available

Fuel Type: Diesel

\$638 Monthly Only! Definitely A Cheap Buy! Flexible Loan Scheme Of Up To 100% Loan! Tip Top Condition With Guaranteed No Repairs Needed Till End Of Lifespan! Comes With Full Canopy! High Trade In Valu...

Car (S) Pte Ltd

Posted: 18-Mar-2019 Tags: 2007 Toyota Dyna, 2007 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Find the right car through consignment.

Purchase pre-loved, owner consigned cars at affordable prices through our dedicated consignment agents. Arrange a test drive today.

Find out more!



Toyota Dyna 150 (COE till 12/2021)

-

N.A

03-Jan-2007

2,982 cc

-

Truck

SOLD

Fuel Type: Diesel

Well Kept, Accident Free.

Posted: 08-Jan-2019 Tags: 2007 Toyota Dyna, 2007 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 (COE till 12/2021)

\$21,800

\$7,940 /yr

22-Dec-2006

2,982 cc

-

Truck

Available

Fuel Type: Diesel

Very Good Condition. Please Call To Make Appointment.

Posted: 06-Mar-2019 Tags: 2006 Toyota Dyna, 2006 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 (COE till 12/2021)

\$27,800

\$10,230 /yr

12-Dec-2006

2,982 cc

-

Truck

Available

Fuel Type: Diesel

Free 6 Months Road Tax And Inspection!. Value For Money. High Trade In And High Loan Possible! Call Now For An No Obligations Discussion! Door Step Viewing Possible!

Net Link Partners Pte Ltd

Posted: 03-Mar-2019 Tags: 2006 Toyota Dyna, 2006 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 (COE till 07/2021)

\$18,800

\$8,190 /yr

11-Jul-2006

2,986 cc

-

Truck

Available

Fuel Type: Diesel

Selling Cheap As It Condition. Suitable For Loading And Unloading As It Comes With Two Sliding Doors. Pass Vehicle Inspection, Free 6 Months Road Tax Will Be Given Upon Purchase. Still Can Renew Anoth...

ABWIN (1994) Pte Ltd

Posted: 04-Mar-2019 Tags: 2006 Toyota Dyna, 2006 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 (COE till 06/2021)

-

N.A

28-Jun-2006

2,986 cc

-

Truck

SOLD

Fuel Type: Diesel

10 Feet Dyna Lorry With Box Good Condition, Full (In House) Loan Available Subject To Approval, Interested Party Please Come Down To Our Showroom For Viewing, To Find Out More.

Bell Auto Pte Ltd

Posted: 02-Jan-2019 Tags: 2006 Toyota Dyna, 2006 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

Compare

yota Dyna 150 (COE till

-

N.A

28-Apr-2006

2,986 cc

-

Truck

SOLD

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	01/03/2019 11:04
Date Of Accident	28/02/2019 11:30
Exact Location Of Accident	WOODLANDS AVENUE 10
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GV8158C
Insured/Policyholder	
Name Of Registered Owner	BESTDECO PTE LTD
Co Reg No	199608581C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67523983
Vehicle Particulars	
Manufacturer	TOYOTA
Model	DYNA 150 D
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102801208
Cover Note Number	
Driver	
Name of Driver	KALYANASUNDARAM SOUNDARARAJAN
Passport No/FIN	G8481503P
Date Of Birth	18/07/1988
Occupation	OUTDOOR
Date Of Driving Pass	30/09/2013
Driving Experience	5 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96289782
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	10 ADMIRALTY STREET #04-64 NORTH LINK BUILDING
Postcode	757695
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN:

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJT5258S
Vehicle Make/Model/Colour	HYUNDAI AVANTE 1.6 AT ABS D/AB 2WD 4DR
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHOO LIAK HUNG
NRIC/Passport Number	S0204021B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	YP6771M
-----------------------------	---------

Accident Sketch Plan Pg. 1

SKETCH PLAN



IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


- 1 MAR 2019

IDAC KAKI BUKIT (VAG)

Reporting Centre Roadside Assistance
Name: 23 Kaki Bukit Ave 4
Singapore 415933
NRIC/ID No: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


straight

I was on woodlands ave 10, heading towards gambas ave.

Suddenly, My front vehicle slowed down, from which

I followed. Suddenly, I heard a loud crash at

the rear of my vehicle.



DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Reporting Centre Personnel's Signature

Name:

NRIC/PR No.:

Tel: 67416697 Fax: 67492305

Email: vackb@singnet.com.sg

- 1 MAR 2019

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Ref: CS3/LPC19004574/Bvd3e2 Date: 04-04-2019 Code: LPC2	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SJT 5258S	Veh. Inspected	GV 8158C
Policy No.		Coverage (\$)	0.00
Claim No.	18/19/19/VP05/021469	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	05/03/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA DYNA 150 D	c.c	2986
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	JTFUF34Y303012084	Colour	SILVER
Odometer	583358 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185 R14C	YOKOHAMA	6 mm
L/H Front Tyre	185 R14C	YOKOHAMA	6 mm
R/H Rear Tyre	155 R12C	YOKOHAMA	6 mm
L/H Rear Tyre	155 R12C	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information			
Accident Date	28/02/2019	Inspect Date / Time	19/03/2019 (04:17 PM)
Survey held at	HUP LEY HUAT MOTOR SPRAY PAINTING SVS BLK 1 KAKI BUKIT AVE 6, #01-35 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/LPC19004574/Bvd3e2

Inspected By



LIM TEOW GUAN

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.