

120/02/001

ASS. REC. BY:

REF: CS/2M 19004578 / R1 sd 302

Special Instruction:

Surveyor:

Rashid

ASSIGNMENT (Office)

From (Person):

Dante I koh

of

INC

Date/Time:

13/3/19 @ 9.22am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TT RES / OD RES / EVA / INV / MVT CS

To Inspect Vehicle No.:

GBC 7565B

Insured:

YM 53685

at Workshop m/s:

Sin Sheng

Tel:

G8634595

of

3feeh park Crescent

Policy No:

Claim No:

MT-103407E-002

Sum Insured:

Excess:

Make of Vch:

D.O.A

26/2/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:30am @ 13/3/18

Person Contacted:

Susan

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓)

Estimate

YM 7565B-X

YM 53685-X

*Form*

REF:

NO. OF PARTS

1176N  
COG KPIR 7:2023/0CT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / LVA / INV / MV  
To inspect Vehicle No: \_\_\_\_\_  
at Workshop no: \_\_\_\_\_  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No: \_\_\_\_\_  
Claims No: \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Report: \_\_\_\_\_ Consistent? Yes or No  
GIA / PIR / Green: \_\_\_\_\_ Consistent? Yes or No  
Est. Repairs: \_\_\_\_\_ days Res: Yes or No  
Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No

GA / REV / REP / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: **GBC 7565B** of Reg: **2013 OCT**  
Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: **FIAT DOBLO CARRO 1-6m** CC: **1598**  
Colour: **YELLOW** AL: Insured / Std / HI / NA  
Sp Reading: **171358** T/A: Insured / Std / HI / NA  
Eng No: \_\_\_\_\_  
C/N: **2FA263000009256546**  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: **8** / Jammed / Leaked / Burnt or  
Brake: **8** / Jammed / Leaked / Burnt or  
Mod: **8** / S/Rim / STD A/Rim or  
Tyre Size: **195/60R16**  
R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /  
TOYO / YOKO or **FALKEN**

Front	Rear
R/Bal: <b>5</b> mm	R/Bal: <b>5</b> mm
L/Bal: <b>5</b> mm	L/Bal: <b>5</b> mm
D.O.A: <b>26/02/19</b>	D.O.A: <b>14/03/19 @ 1001AM</b>
Survey held at: <b>San Sion</b>	

Des. of Damages: Fd / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
25/04/19	Continued HS @ 1,350/- @ 3 days with Resv / (\$929.68 Red - 41%)

RECEIVED 05 APR 2019

Date Time File Pass for: **25/04/19**  
Type: **Typist**  
Name Time File Column for: \_\_\_\_\_  
☐ : Prelim. Report  
☒ : Final Report

Days Of Repair: **3**  
Resurvey No. of Trip: **1**

Survey Fee  
Transportation

290

Add Fee: ☐ Gate Trip 1%  
☐ Inter-city 1%  
☐ Fresh Items 1%  
☐ Wash and 1%

Report Format:

Lump Sum / LCU: **1,350/- HS**

290

## Nivitha (LKK Auto)

---

**From:** Daniel Koh <daniel.koh@income.com.sg>  
**Sent:** Wednesday, 13 March 2019 9:22 AM  
**To:** 'assignments@lkkauto.com'  
**Cc:** Toh Choon Hin; Thio Tse Kiat  
**Subject:** FW: TP CASES FARMED OUT TO LKK ON 13/3/2019

Dear Veron / Nivitha

Please assist to survey the vehicles as per Mr Toh's instruction :-

S/NO	THIRD PARTY	OUR INSURED	WORKSHOP / CONTACT	DOA / REF / OFFICER
1	GBC7565B	YM5368S	SIN SHENG ENGINEERING / Susan 68639595	26-2-2019 / MT-1034078-002 / Jared Liu
2	SLL507A	SJQ1078L	BP AUTO / Yvonne 62660555	9-3-2019 / MT-1035579-001 / Eric Tang

**Please contact workshops.**

Please ack.

Thank You

Daniel Koh  
Senior Admin Assistant, Motor Insurance  
T +65 6430 7901  
[www.income.com.sg](http://www.income.com.sg)



---

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the

recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

## Shirley Hiew (LKK Auto)

---

**From:** sinsheng engineering services <sinsheng1981@gmail.com>  
**Sent:** Thursday, 4 April 2019 3:30 PM  
**To:** Rasul (LKKAuto)  
**Subject:** Re: FW: Accident Involving GBC7565B with YM5368S on 26/02/2019

Yes, confirmed.

*Thank You  
Regards*

*Susan  
Sin Sheng Engineering Services  
3 Tech Park Crescent  
Tuas Tech Park  
Singapore 638129  
Tel: 6863 9595  
Fax: 6863 6477*

On Thu, 4 Apr 2019 at 15:09, Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)> wrote:

Hi Susan,

Refer to attachment

Finalise amount is \$ 1,350.00 / 3 days lump sum

Kindly confirm

Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** sinsheng engineering services [mailto:[sinsheng1981@gmail.com](mailto:sinsheng1981@gmail.com)]  
**Sent:** Thursday, 4 April, 2019 3:03 PM  
**To:** Rasul (LKKAuto)  
**Subject:** Re: FW: Accident Involving GBC7565B with YM5368S on 26/02/2019

Hi Mr Rasul,

As per your request.

*Thank You  
Regards*

*Susan  
Sin Sheng Engineering Services  
3 Tech Park Crescent  
Tuas Tech Park  
Singapore 638129  
Tel: 6863 9595  
Fax: 6863 6477*

On Thu, 4 Apr 2019 at 14:48, Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)> wrote:

Hi Susan,

Can you forward to me the revised estimate. the file is not with me now

Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

**From:** sinsheng engineering services [mailto:[sinsheng1981@gmail.com](mailto:sinsheng1981@gmail.com)]

**Sent:** Wednesday, 3 April, 2019 11:17 AM

**To:** Rasul (LKKAuto)

**Cc:** SUR

**Subject:** Re: FW: Accident Involving GBC7565B with YM5368S on 26/02/2019

Hi Mr Rasul,

## REMINDER

Please have your finalized please.

*Thank You*

*Regards*

*Susan*

*Sin Sheng Engineering Services*

*3 Tech Park Crescent*

*Tuas Tech Park*

*Singapore 638129*

*Tel: 6863 9595*

*Fax: 6863 6477*

On Mon, 18 Mar 2019 at 15:14, sinsheng engineeringservices <[sinsheng1981@gmail.com](mailto:sinsheng1981@gmail.com)> wrote:

Hi Mr Rasul,

Please find attached and have your finalized please.

*Thank You  
Regards*

*Susan  
Sin Sheng Engineering Services  
3 Tech Park Crescent  
Tuas Tech Park  
Singapore 638129  
Tel: 6863 9595  
Fax: 6863 6477*

On Tue, 12 Mar 2019 at 16:29, [MTCL@income.com.sg](mailto:MTCL@income.com.sg) <[mtcl@income.com.sg](mailto:mtcl@income.com.sg)> wrote:

Dear Sir/Mdm

We have registered the claim.

OIC – Jared Liu

Our ref – MT/ 1034078 - 002



With Regards

**Azlin Rani**

Senior Administrator, Motor Insurance

[www.income.com.sg](http://www.income.com.sg)



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
**Find out more at [income.com.sg/careers](http://income.com.sg/careers)**

in

**From:** sinsheng engineering services [mailto:[sinsheng1981@gmail.com](mailto:sinsheng1981@gmail.com)]

**Sent:** Tuesday, 12 March 2019 12:01 PM

**To:** [MTCL@income.com.sg](mailto:MTCL@income.com.sg); MTSurvey

**Subject:** Accident Involving GBC7565B with YM5368S on 26/02/2019

Dear Officer Incharge,

We are repairer of vehicle GBC7565B. Kindly assist to arrange for the Pre-Repair Inspection to be conducted within two(2) workings days upon receipt of this email. Enclosed Accident Statement and LTA search fee for your attention please.

Kindly be informed vehicle already in our premises located at No 3 Tech Park Crescent, Tuas Tech Park, Singapore 638129

Please to avoid assign LKK for survey.

*Thank You  
Regards*

*Susan  
Sin Sheng Engineering Services  
3 Tech Park Crescent*

*Tuas Tech Park  
Singapore 638129  
Tel: 6863 9595  
Fax: 6863 6477*

---

**Disclaimer**

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	27/02/2019 17:02
Date Of Accident	26/02/2019 09:45
Exact Location Of Accident	ALONG UPP BUKIT TIMAH ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GBC7565B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GOLDBELL LEASING PTE LTD
Co Reg No	199001196N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64942833
<b>Vehicle Particulars</b>	
Manufacturer	FIAT
Model	DOBLO-1.6 D CARGO MJ (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
<b>Insurance Company</b>	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	29090793
Cover Note Number	
<b>Driver</b>	
Name of Driver	TOH YANG BOON
NRIC No	S1497366D
Date Of Birth	23/04/1961
Occupation	OUTDOOR
Date Of Driving Pass	12/09/1978
Driving Experience	40 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87558551
Fax Number	
Contact Number	
EMail Address	SYAHMI.AZIZ@HONESTBEE.COM

Address	BLK 488 SEGAR ROAD #14-568
Postcode	670488
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - LESSEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NOT APPLICABLE GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON 26/02/19 AT ABOUT 9:45AM, I WAS STATIONARY IN THE QUEUE ON THE EXTREME RIGHT LANE ALONG UPP BUKIT TIMAH ROAD TOWARDS BUKIT BATOK ROAD. SUDDENLY I FELT AN IMPACT FROM THE REAR. I ALIGHTED FROM MY VEHICLE TO CHECK. I REALIZED THAT VEHICLE B HAD COLLIDED INTO MY REAR. AN APPROACHING MOTORBIKE HAD SWERVED TO THE LEFT TO AVOID THE COLLISION. HOWEVER, ITS HANDLE BAR COLLIDED INTO MY VEHICLE, CAUSING THE LEFT SIDE MIRROR TO BREAK. THE MOTORIST DROVE OFF WITHOUT STOPPING. MY VEHICLE WAS DAMAGED AT THE REAR.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YM5368S
Vehicle Make/Model/Colour	ISUZU / NPR71L / WHITE
Details Of Properties	VEH B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MENG QINGFU
NRIC/Passport Number	G2979663M
Contact Number	81148428
Address	

Postcode

Insurance Company Name

Nature Of Damage

FRONT PORTION

No. Of Passenger (Including Driver)

1

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number

UNKNOWN

Vehicle Make/Model/Colour

Details Of Properties

VEH C

Vehicle Category

MOTORCYCLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

CIBC 7565



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Sketch Plan #2

### SKETCH PLAN



### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 24/11/19 at about 9:45 am, I was stationary in the queue on the extreme right lane along Upd. Bt Trench Rd the Bt Bank Rd. Suddenly, I felt an impact from the rear. I looked from my vehicle to check. I realised that vehicle B had collided in my rear. An approaching motorbike had swerved to the left to avoid the collision. However, the handlebar entered my vehicle, along the side mirror to break. The motorist drove off without stopping. My vehicle was damaged at the rear.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002770

Date : 12/03/2019

Vehicle Num. : GBC7565B

Make/Model : FIAT DOBLO 1.6MJTD-2013

Chassis/Eng# : ZFA26300009256546/198A30006986

Accident Date : 26/02/2019

Claim No. :

Reference : YM5368S

Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BUMPER <i>cut ✓</i>		734.34
2.	2	BUMPER SIDE BRACKET <i>X suc</i>	95.20	190.40
3.	1	BUMPER REINFORCEMENT <i>8t ✓</i>		420.95
4.	2	REFLECTOR <i>X suc</i>	65.20	130.40
List Total S\$ :				1,476.09
15.00% Discount S\$ :				221.41
				1,254.68
NETT ITEMS :				
1.	1	REVERSE SENSOR	<i>S/N 200.00</i>	<del>250.00</del>
Nett Total S\$ :				250.00
10.00% Discount S\$ :				25.00
				225.00
LABOUR :				
TO PANEL BEAT/REPAIR REAR BODY			<i>300</i>	<del>450.00</del>
TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS				
SPRAY PAINTING			<i>200</i>	<del>350.00</del>

CONTINUE / ...



# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002770

Date : 12/03/2019

Vehicle Num. : GBC7565B

Make/Model : FIAT DOBLO 1.6MJTD-2013

Chassis/Eng# : ZFA26300009256546/198A3000698E

Accident Date : 26/02/2019

Claim No. :

Reference : YM5368S

Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LOSS OF USE : 3 DAYS @ \$ 120/DAY

Labour Total S\$ :

800.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

*Pass*  
*18/3/19*  
*4p 90000068*  
*3 days*  
*4/5*  
*14/03/19 @ 1000h*  
*Resy after regu'*

Total S\$ : 2,279.68

=====

SIN SHENG ENGINEERING SERVICES

2304.68

# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002770

Date : 12/03/2019

Vehicle Num. : GBC7565B

Make/Model : FIAT DOBLO 1.6MJTD-2013

Chassis/Eng# : ZFA26300009256546/198A30006986

Accident Date : 26/02/2019

Claim No. :

Reference : YM5368S

Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	2	REAR BUMPER <i>cut</i>		734.34
3.	1	BUMPER SIDE BRACKET <i>X su</i>	95.20	190.40
4.	2	BUMPER REINFORCEMENT <i>8t</i>		420.95
		REFLECTOR <i>X su</i>	65.20	130.40

List Total S\$ :

15.00% Discount S\$ :

1155.29	1,476.09
15%	221.41
981.99	1,254.68

1.	1	NETT ITEMS :		
		REVERSE SENSOR		

Nett Total S\$ :

10.00% Discount S\$ :

200	200	250.00	S/N
		25.00	
		225.00	

LABOUR :

TO PANEL BEAT/REPAIR REAR BODY

TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS

SPRAY PAINTING

8w	300	450.00
	200	350.00

981.99

CONTINUE / ...

200.00

500.00

1681.99

20%

1345.59

4/5 - 1,350

3 days

# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002770

Date : 12/03/2019

Vehicle Num. : GBC7565B

Make/Model : FIAT DOBLO 1.6MJTD-2013

Chassis/Eng# : ZFA26300009256546/198A30006986

Accident Date : 26/02/2019

Claim No. :

Reference : YM5368S

Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LOSS OF USE : 3 DAYS @ \$ 120/DAY

Labour Total S\$ :

800.00

*From*  
*4p 9000000*  
*3 days*  
*4/8*  
*14/03/19 @ 1000hr*  
*Reg after repair*

Total S\$ : 2,279.68

=====



SIN SHENG ENGINEERING SERVICES



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19004578/R1sd3e2

73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 09-04-2019



ATTN : JARED LIU

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YM 5368S	Veh. Inspected	GBC 7565B
Policy No.		Coverage (\$)	0.00
Claim No.	MT-1034078-002	Excess (\$)	0.00
Assign From	DANIEL KOH	Assign Date	13/03/2019

#### 2. Vehicle Particulars & Condition

Make & Model	FIAT DOBLO CARGO 1.6 M	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	ZFA26300009256546	Colour	YELLOW
Odometer	171358 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R16	FALKEN	5 mm
L/H Front Tyre	195/60 R16	FALKEN	5 mm
R/H Rear Tyre	195/60 R16	FALKEN	5 mm
L/H Rear Tyre	195/60 R16	FALKEN	5 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	26/02/2019	Inspect Date / Time	14/03/2019 ( 10:01 AM )
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 7565B**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	CUT	734.34	734.34
2	BUMPER SIDE BRACKET @\$95.20	SERVICEABLE	190.40	-
1	BUMPER REINFORCEMENT	BENT	420.95	420.95
2	REFLECTOR @\$65.20	SERVICEABLE	130.40	-
	LESS 15% DISCOUNT		-221.41	-173.29
			1,254.68	982.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REVERSE SENSOR (SN)	NOT WORKING	250.00	200.00
			250.00	200.00
<b><u>LABOUR</u></b>				
	TO PANEL BEAT / REPAIR REAR BODY.		450.00	300.00
	TO DISMANTLE / REPLACE ABOVEMENTIONED PARTS.		350.00	200.00
			800.00	500.00
<b>GRAND TOTAL</b>			<b>2,304.68</b>	<b>1,682.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>1,350.00</b>

Report Ref No. CS/INC19004578/R1sd3e2

**MOHAMMED RASUL BIN MOHD YUNUS**

Automotive Assessor

**ADRIAN LING WAI PING****B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.