



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	1 2007 TOYOTA COROLLA ALTIS 1.6 (SGV446Z)
Date of Loss	8 March 2019
Time of Loss	11.00
Loss Description	SGV446Z (INSD) REVERSED AND HIT PILLAR
Comment	<input type="text"/>

Workshop Details

Total Rebate Amount	<input type="text" value="16275"/>
Nett Loss Amount	\$3,725.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Days of work completion *	<input type="text" value="72"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

Purchase Date

Registration State

Registration Date *

Mileage

Age of Vehicle

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	<input type="text" value="2007"/>	<input type="text" value="2007"/>
Make	<input type="text" value="TOYOTA"/>	<input type="text" value="TOYOTA"/>
Model	<input type="text" value="COROLLA ALTIS 1.6"/>	<input type="text" value="COROLLA ALTIS 1"/>

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	<input type="text" value="ABDUL RAHMAN BIN AHMAD DASAH"/>	<input type="text"/>
Date of Birth	<input type="text" value="10 February 1963"/>	<input type="text" value="dd/mm/yyyy"/>
Age	<input type="text" value="56"/>	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No	MR053ZEC107145054	<input type="text" value="MR053ZEC10714!"/>
Engine No	3ZZ4641472	<input type="text" value="3ZZ4641472"/>
Engine Capacity		<input type="text" value="1598"/>
Sum Insured	0	<input type="text" value="0"/>
Market Value	0	<input type="text" value="20000"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	23	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="dd/mm/yyyy"/> 
License Expiration Date		<input type="text" value="dd/mm/yyyy"/> 
Address	C/O TAYLOR NELSON SOFRES, Singapore	<input type="text" value=""/>
Address type	Residential	<input type="text" value=""/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	<input type="text" value=""/>
Marital status	Married	<input type="text" value=""/>
Identification #	S1621507D	<input type="text" value=""/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

13/03/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

500

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair



Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

185/65R14

Rear Tyre Size

185/65R14

Front left side

DUNLOP5mm

Rear left side

DUNLOP5mm

Front right side

DUNLOP5mm

Rear right side

DUNLOP5mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes No

Part Supplied by AXA

Yes No



<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGEX	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			REAR BUMPER (WCP) (10%)			Deformed	154				154	Reviewing	
		2	1			L/R BUMPER BRACKET (WCP) (10%)			Necessary	8.8				8.8	Reviewing	
		3	1			R/R BUMPER BRACKER (WCP) (10%)			Necessary	8.8				8.8	Reviewing	
		4	1			L/R CTR BUMPER BRKT (WCP) (10%)			Necessary	11				11	Reviewing	
		5	1			R/R CTR BUMPER BRKT (WCP) (10%)			Necessary	11				11	Reviewing	
		6	1			RR BUMPER CLAMP KIT (WCP) (10%)			Necessary	16.5				16.5	Reviewing	
		7	1			REAR PANEL (WCP) (10%)			Bent	165				165	Reviewing	
		8	1			BOOTLID SEAL (WCP) (10%)			Twisted	24.2				24.2	Reviewing	

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTRK	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	9	1			BOOT / TAILGATE LOCK (WCP) (10%)			Bent	16.5				16.5	Reviewing	
	10	1			MANUFACTURER BADGE (WCP) (10%)			Necessary	11				11	Reviewing	
	11	1			BADGE (WCP) (10%)			Necessary	13.2				13.2	Reviewing	
	12	1			BADGE (WCP) (10%)			Necessary	19.8				19.8	Reviewing	
	13	1			BADGE MODEL (WCP) (10%)			Necessary	13.2				13.2	Reviewing	
	14	1			TYPE BADGE (WCP) (10%)			Necessary	16.5				16.5	Reviewing	
	15	1			L/R OUTER LAMP			Serviceable	0	0	0	0	0	Deny	
	16	1			R/R OUTER LAMP			Serviceable	0	0	0	0	0	Deny	
	17	1			LUGGAGE COMPART CARPET			Serviceable	0	0	0	0	0	Deny	
	18	1			END PANEL TRIM (WCP) (10%)			Deformed	22				22	Reviewing	
	19	1			RIVET(WCP) (10%)			Necessary	13.2				13.2	Reviewing	

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		89.0 WU X 45.00 SGD / H	265.5	0	0	Reviewing		

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		2		LABOUR COST 138.0 WU X 45.00 SGD / H	351	0	0	Reviewing		
		3		MATERIAL COST	144.15	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

- Add
- Approve
- Deny
- Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR : 4 DAYS	Reviewing			



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount

\$785.35

Claim Amount

\$785.35

CATEGORY

ESTIMATE

REVISED AMOUNT

Spare Parts

\$524.70

\$524.70

Labour

\$760.65

\$760.65

Excess

-\$500.00

-\$500.00

Submit for Review