

5.000000

ASSIGNMENT

REF CS3/CTI 19004586/ECd3cy per of Instruction

SMV/vegar Steve

ASSIGNMENT (Office)

From (Person) chong Boon sen of CTI

Date/Time: 12/3/19 @ 5:31pm

Estimated Cost Bill to

OD  TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: SMH 8096A Insured: GBF 541A

at Workshop of: N-SI Automotive Tel: 88420081

of 2 kelci Bkt Ave 2 # 01-17/18

Policy No: DMCV8N30S65718022 Claim No: SNM19D2 01126002

Sum Insured Excess:

Make of Vch: (Client's Record) D.O.A: 8/3/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time: 11:35am @ 13/3/19 Person Contacted: Ziting

Vehicle:  IN  OUT

Date/Time	Action/Instruction (X) Estimate
	SMH 8096A - X
	GBF 541A - X
	Dismantle = 14/3/2019
	After repair: 12/3/2019

02/14

Surveyor

Steve

REF: C11

PRS

ASSIGNMENT

From: \_\_\_\_\_ Date: 13/3/19

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SMH 8096A

at Workshop m/s N-51 Automotive

of 2 Kelci Bkt Ave 2 #01-18

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

Veh No: SMH 8096A Yr Regn: 7/2/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toyota Altis c.c 1598

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 876 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MR 053R416 045958/5

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or


Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45R17  
R: 11

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>1 up</sup>

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front	Rear
R/Bal. 7 mm	R/Bal. 7 mm
L/Bal. 7 mm	L/Bal. 7 mm
D.O.A. 8/3/19	D.O.I. 13/3/19

Survey held at N-51

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV - 94,000
	PV - 42,195
	NV - 51,805
	Repair range 2K - 5K, 3 days
	<i>[Signature]</i>
	27/3/2019

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Report Format : PRS

Lump Sum / I.B.I. (\$) \_\_\_\_\_

Days Of Repair: 3

Resurvey No. of Trip: 2

Add Fee:  : Site Insp (\$ )  : Interview (\$ )  : Tech. Invs (\$ )  : Weekend (\$ )

Survey Fee: 150

Transportation: S + RS, SI

Photos

Others

TOTAL 150

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 May 2019		13 May 2019 10:19 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b>				<b>[Created by insurer]</b>					
Insured:									
Main Claimant:	<b>sim meng huat</b>								
Vehicle Reg. No.:	<b>SMH8096A</b>	Date of Loss:	08/03/2019 00:00 - :59						
Claim Type:	<b>TP / SNM19D201126C02</b>	Policy/Cover Note No.:	DMCVSN30565718022						
Vehicle Reg. No. (Insured):	<b>GBF541A</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>N-51 Automotive Pte Ltd (HQ)</b> BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>CHEN TSUE YEE</b> ] ... <b>[Final Rpt due 23/05/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a> <a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>				<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Tuesday, 12 March 2019 5:31 PM  
**To:** Chio Ziting  
**Cc:** assignments  
**Subject:** RE: SMH8096A & GBF541A - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS - ANR + PRS-SNM19D201126  
**Attachments:** 8096.pdf

**WITHOUT PREJUDICE**  
**SAVE AS TO COSTS**

Dear Sir,

We refer to your email.

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards,  
**Chong Boon Sen**  
Claims Executive  
Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 63896171  
Fax: 62247175  
Email: boonsen.chong@sg.cntaiping.com  
Website: www.sg.cntaiping.com

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

**From:** Chio Ziting [mailto:ziting@n51.com.sg]  
**Sent:** Tuesday, 12 March, 2019 4:25 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Subject:** Re: SMH8096A & GBF541A - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS - ANR + PRS-SNM19D201126

Dear Sir / Madam,

We refer to your list of motor surveyors proposed.

We do not agree to your list of motor surveyors.

Please see attached.

Thank you.

On Tue, Mar 12, 2019 at 4:13 PM Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)> wrote:

**WITHOUT PREJUDICE**

Dear Sir,

We refer to your email below.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert

Regards,

**Chong Boon Sen**

Claims Executive

Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Angie Foo

**Sent:** Tuesday, 12 March, 2019 3:35 PM

**To:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; Alfred Toh <[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>;  
[ziting@n51.com.sg](mailto:ziting@n51.com.sg)

**Subject:** FW: SMH8096A & GBF541A - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS - ANR + PRS-SNM19D201126

Dear Boon Sen,

Please conduct PRS asap-GBF541A-SNM19D201126.

BOON SEN-63896171.

Best Regards,

**Angie Foo**

Claims Executive

Claims Department – Motor Division

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6186

Fax (65) 6224 7175 / 6224 7478

Email: [angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)

Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)



*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Claims Dept of CTI

**Sent:** Monday, 11 March, 2019 7:05 PM

**To:** Angie Foo

**Subject:** FW: SMH8096A & GBF541A - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS - ANR + PRS

**From:** Chio Ziting [<mailto:ziting@n51.com.sg>]

**Sent:** Monday, March 11, 2019 10:52 AM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Subject: SMH8096A & GBF541A - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS**

Dear Sir/Madam,

As per above subject,

Please refer attachment and:-

Kindly propose / provide your 10 surveyors

Thank you.

Regards,


Zi Ting

N-51 Automotive Pte Ltd

Office: 6842 0051

Fax: 6741 0510

[www.n51.com.sg](http://www.n51.com.sg)



For more information please visit <http://www.symanteccloud.com>

---

Regards,  
Zi Ting  
N-51 Automotive Pte Ltd  
Office: 6842 0051  
Fax: 6741 0510  
[www.n51.com.sg](http://www.n51.com.sg)



---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub  
2 Kaki Bukit Ave 2, #01-17  
Singapore 417921  
Tel No. : +65 6744 0510 / 6842 0051 Fax No. : +65 6741 0510  
Company Reg. No. : 200714616M  
GST Registration No. : 200714616M

Our Ref: **SMH 8096 A**  
Your ref: **GBF 541 A**

12 March 2019

**CHINA TAIPING INSURANCE (S) PTE LTD**  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
Attn: Motor Claims Department

BY EMAIL: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com) ONLY

Dear Sir/Madam,

**NAME OF CLAIMANT : SIM MENG HUAT**  
**VEHICLE NUMBER : SMH 8096 A**  
**YOUR INSURED VEHICLE NUMBER : GBF 541 A**  
**ACCIDENT ON 08 Mar 2019 ALONG YISHUN AVE 2 JUNCTION YISHUN AVE 5**  
**AT ABOUT 19:30 HOURS**

- 1) We refer to your fax / email of **12 Mar 2019** informing that you wish to conduct a pre-repair survey and to your List of Surveyors.
- 2) TAKE NOTICE that we object to all your surveyors stated in your said List, for appointment as the Single joint Expert.
- 3) Pursuant to Pre-Action Protocol for NIMA cases, we now propose for appointment as Single Joint Expert the following 10 surveyors for your consideration:-

(a) B J Loi	PAR AUTOMOTIVE CONSULTANCY
(b) Patrick Ng	CARLINK CONSULTANCY
(c) Sebastian Lim Yong Tian	CONSTANT APPRAISER SERVICES
(d) Dave Chang Fuh Keong	SINCERE APPRAISAL SERVICES
(e) Ng Cheng Meng	CM AUTOMOTIVE CONSULTANCY
(f) Danny Ho Joo Long	HJL AUTO APPRAISER SERVICES
(g) Lee Kok Weng	LEE AUTOMOBILE APPRAISER SERVICES
(h) Philip Foo	PRECISION APPRAISAL SERVICES
(i) Ong Ah Heng, Kent	KTO AUTOMOBILE ASSESSORS
(j) Zali Saidi	ISP MANAGEMENT PTE LTD
- 4) Please reply within 2 working days.

Yours faithfully,



Twincar Automotive Pte Ltd

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0219I
Vehicle Details	
Vehicle No.:	SMH8096A
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 ELEGANCE (AUTO)
Primary Colour:	Silver
Manufacturing Year:	2019
Engine No.:	1ZR0D03001
Chassis No.:	MR053REH604595815
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,858.00
Original Registration Date:	07 Feb 2019
First Registration Date:	07 Feb 2019
Transfer Count:	0
Actual ARF Paid:	\$22,602.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Feb 2029
PARF Rebate Amount:	\$16,951.00
Intended COE Rebate Details	
COE Expiry Date:	06 Feb 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$25,501.00
COE Rebate Amount:	\$25,244.00
<b>Total Rebate Amount:</b>	<b>\$42,195.00</b>

The information contained herein is correct as at 13 Mar 2019

OK



# CADET PILOT PROGRAMME

To a limitless high flying career!

**Post an Advertisement**  
 Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

Fully Rebuilt Toyota Mark X COE Till 09/2028 At \$57k.



Nice Bidded Number 9889 And Lots Of Accessories Going Together With The Car! Direct Owner StarAd

**PRIME MOTOR & LEASING**  
 (CHENG YONG CREDIT ENTERPRISES PTE.LTD. GROUP OF COMPANIES)  
 With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

Sort by Date Posted 20 results/page

2 vehicles

toyota altis

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	toyota altis	Any	Any	2018	Any	Any	Any	Availabl
	<b>Toyota Corolla Altis 1.6A Elegance</b>	<b>\$91,800</b>	<b>\$8,670 /yr</b>	29-Jun-2018	1,598 cc	9,800 km	Sedan	Availabl
Borneo Motors Management Car, Well Maintained, Low Mileage, Like New Interior, Agent Maintained. Agent In House 5 Years Extended Warranty. Borneo Motors (S) <span style="float:right">PREMIUM</span>								
Posted: 10-Mar-2019 Tags: 2018 Toyota Corolla, 2018 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	<b>Toyota Corolla Altis 1.6A Elegance</b>	<b>\$87,800</b>	<b>\$8,400 /yr</b>	26-Apr-2018	1,598 cc	3,520 km	Sedan	Availabl
Facelifted Elegance Model! 1 Owner, Low Mileage Done Only 3,520km, Like New Interior, Agent Maintained. High Loan Available, Trade In Welcome. View Now! <span style="float:right">PREMIUM</span>								
Posted: 28-Feb-2019 Tags: 2018 Toyota Corolla, 2018 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/pag

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rate insurance. Find buy used toyota altis, toyota altis Singapore, used toyota altis Singapore, used toyota altis, used vehicles Singapore or even buy used toyota altis Singapore. We have new dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

**Follow sgCarMart.com**

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2019 sgCarMart. All rights reserved.

Compare

MSME19032263 / SME Motor Pte Ltd - Kaki Bukit  
 ENTRY DATE & TIME: 11/03/2019 12:14  
 SUBMITTED BY: Chia Pei Ying

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/03/2019 12:14
Date Of Accident	08/03/2019 19:30
Exact Location Of Accident	YISHUN AVE 2 JUNCTION YISHUN AVE 5
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMH8096A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SIM MENG HUAT
NRIC No	S1220219I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98223684
Alternative Phone No	OFFICE-98223684

### Vehicle Particulars

Manufacturer	TOYOTA
Model	ALTIS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P2242276
Cover Note Number	

### Driver

Name of Driver	SIM MENG HUAT
NRIC No	S1220219I
Date Of Birth	10/12/1955
Occupation	INDOOR
Date Of Driving Pass	29/03/1976
Driving Experience	42 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98223684
Fax Number	
Contact Number	OFFICE-98223684
Email Address	NOEMAIL

Address	BLK 223 YISHUN ST 21 #08-463
Postcode	2776
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

**General Information of the Accident**

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

ON 08/03/2019 AT 1930HRS, I STOPPED MY VEHICLE (SMH8096A) ALONG YISHUN AVE 2 JUNCTION YISHUN AVE 5 ON THE THIRD LANE FROM THE LEFT WAITING FOR THE TRAFFIC LIGHT TO TURN GREEN. SUDDENLY, A VAN (GBF541A) FROM BEHIND COLLIDED ONTO THE REAR PORTION OF MY VEHICLE.

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	GBF541A
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	NALLAMPALAYAM PALANIYANDI SIVAKUMAR
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**DETAILS OF INJURED PERSON 1**

Name SIM MENG HUAT  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SMH8096A  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance?  
Address  
Postcode

## Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:


11/3/19

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 08/03/19 at @ 1930 hrs, I stopped my vehicle (SMH 8096A) along Yishun Ave 2 junction Yishun Ave 5 on the third lane from the left waiting for the traffic light to turn green. Suddenly, a van (GBF 541 A) from behind collided onto the rear portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 May 2019		13 May 2019 10:19 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>sim meng huat</b>								
Vehicle Reg. No.:	<b>SMH8096A</b>	Date of Loss:	08/03/2019 00:00 - :59 [1 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D201126C02</b>	Policy/Cover Note No.:	DMCVSN30565718022						
Vehicle Reg. No. (Insured):	<b>GBF541A</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>N-51 Automotive Pte Ltd (HQ)</b> BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>CHEN TSUE YEE</b> ] ... <b>[Final Rpt due 23/05/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SMH8096A (SNM19D201126C02)  
 [GBF541A]  
 TP  
 sim meng huat  
 Mar 8 2019 12:00AM  
 [-]  
 N-51 Automotive Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			View <input type="button" value="View in Browser"/>
<b>Photos/Images</b>			3 per page <input type="button" value="v"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
2	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
3	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
4	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
5	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
6	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
7	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
8	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
9	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
10	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
11	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
12	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
13	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
14	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
15	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
16	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
17	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
18	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
19	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
20	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
21	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
22	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
23	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
24	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
25	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
26	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
27	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
28	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
29	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
30	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
31	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
32	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
33	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
34	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
35	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
36	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>
37	14/05/19 11:01	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	14/05/19 11:01	General View	 Load JPG	<input checked="" type="checkbox"/>
39	14/05/19 11:01	General View	 Load JPG	<input checked="" type="checkbox"/>
40	14/05/19 11:01	General View	 Load JPG	<input checked="" type="checkbox"/>
41	14/05/19 11:01	General View	 Load JPG	<input checked="" type="checkbox"/>
42	14/05/19 11:01	General View	 Load JPG	<input checked="" type="checkbox"/>
43	14/05/19 11:01	General View	 Load JPG	<input checked="" type="checkbox"/>
44	14/05/19 11:01	General View	 Load JPG	<input checked="" type="checkbox"/>
45	14/05/19 11:01	General View	 Load JPG	<input checked="" type="checkbox"/>
46	14/05/19 11:01	General View	 Load JPG	<input checked="" type="checkbox"/>
47	14/05/19 11:01	General View	 Load JPG	<input checked="" type="checkbox"/>
48	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	14/05/19 11:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	14/05/19 11:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
123	14/05/19 11:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
124	14/05/19 11:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
125	14/05/19 11:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
126	14/05/19 11:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
127	14/05/19 11:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
128	14/05/19 11:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
129	14/05/19 11:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
130	14/05/19 11:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
131	14/05/19 11:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
132	14/05/19 11:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
133	14/05/19 11:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
134	14/05/19 11:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
135	14/05/19 11:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
136	14/05/19 11:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
137	14/05/19 11:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	14/05/19 11:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
139	14/05/19 11:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
140	14/05/19 11:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
141	14/05/19 11:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
142	14/05/19 11:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
143	14/05/19 11:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
144	14/05/19 11:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
145	14/05/19 11:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
146	14/05/19 11:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
147	14/05/19 11:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
148	14/05/19 11:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
149	14/05/19 11:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
150	14/05/19 11:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
151	14/05/19 11:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/05/19 10:20	pri contact	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19004586/ECD3E2

Date: 24/05/2019

#### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSN30565718022	
Claimant Vehicle No: SMH8096A	Insured Vehicle No: GBF541A	
Date of Loss: 08/03/2019	Nature of Claim: TP	Claim No: SNM19D201126C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH8096A	Engine No:	1ZR0D03001
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 Elegance (A)	Chassis No:	MR053REH604595815
Reg. Date:	07/02/2019 (Man. Year: 2019)	Odometer:	876 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment:	13/05/2019	
Date Inspected:	13/03/2019 Inspected At:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 -\$3,000.00

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2019)	
<b>Parts:</b> 143	TOYOTA COROLLA ALTIS 1.6 Elegance (A) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for SMH8096A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >