

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way,
AIG Building #09-16
Singapore 079120
Attn: Motor Claims Department

Date : 12/03/2019
Vehicle No : SLA916K
Veh Make/Model : Volk. Jetta GP 1.4 TSI
YOM : 2015
Chassis No : WVWZZZ16ZGM007019
Date of Accident : 08/03/2019

Not Authorised

11 Day 87

Resurvey After Paint

11 day

No	Qty	Description	Amount \$
		List Items:-	
			\$ <i>R</i> 1,097.50 X
1	1	Bonnet	\$ <i>Rn</i> 545.00 ✓
2	1	Front grille assy	\$ <i>CM</i> 2,380.00 ✓
3	1	RH headlamp *	\$ 2,380.00 ✓
4	1	LH headlamp *	\$ <i>Rn</i> 1,017.00 ✓
5	1	Front bumper	\$ <i>CM</i> 257.50 ✓
6	1	Front bumper grille	\$ <i>CM</i> 61.20 ✓
7	2	Front bumper side retainer	\$ <i>Rn</i> 2,250.00 ✓
8	1	Bootlid	\$ <i>Rn</i> 137.50 ✓
9	1	Bootlid logo	\$ <i>Rn</i> 72.00 ✓
10	1	Bootlid "JETTA" emblem	\$ <i>Rn</i> 54.00 ✓
11	1	Bootlid "TSI" emblem	\$ <i>Rn</i> 126.00 X
12	1	Bootlid number plate lamp	\$ <i>CM</i> 337.50 ✓
13	1	Bootlid reflector (LH)	\$ <i>CM</i> 337.50 ✓
14	1	Bootlid reflector (RH)	\$ <i>CM</i> 162.50 ✓
15	1	Bootlid lock	\$ <i>Dis</i> 264.00 ✓
16	1	Bootlid weatherstrip	\$ 250.00 ?
17	1	Bootlid inner trim board	\$ 408.00 ?
18	1	LH tail lamp	\$ <i>CM</i> 408.00 ✓
19	1	RH tail lamp	\$ <i>R</i> 1,504.00 X
20	1	Rear fender (LH)	\$ <i>R</i> 1,504.00 X
21	1	Rear fender (RH)	\$ <i>Rn</i> 992.80 ✓
22	1	Rear bumper	\$ <i>Rn</i> 65.00 X
23	1	Rear bumper reflector (LH)	\$ <i>CM</i> 65.00 ✓
24	1	Rear bumper reflector (RH)	\$ <i>Rn</i> 451.20 ✓
25	1	Rear bumper lower cover	\$ 72.00 ?
26	1	Rear bumper centre bracket	\$ <i>Dis</i> 188.00 ✓
27	2	Rear bumper side retainer	\$ 188.00 ?
28	2	Rear bumper side bracket	\$ <i>Rn</i> 582.50 ✓
29	1	Rear bumper reinforcement	\$ <i>Rn</i> 876.10 ✓
30	1	End panel	\$ Balance b/f 19,033.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to final approval from Insurance Company
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Date : 12/03/2019
Vehicle No : SLA916K
Veh Make/Model : Volk. Jetta GP 1.4 TSI
YOM : 2015
Chassis No : WVWZZZ16ZGM007019
Date of Accident : 08/03/2019

[illegible]

