

2003/08/01

ASS. REC. BY:

REF: CS3/MSG18015201/11903-1^{er}

Instruction:

Surveyor: Tauhiah
 From (Person): Elaine Ngu

ASSIGNMENT (Office)

of MSLG

Date/Time: 11/03/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 811 5256P

Insured: GBE 9204

at Workshop in/s: A-tee Automotive

Tel: 6384 5206

of 8 Kalci Bldg Ave 4# 05-27

Policy No: MSD/VCC/17/002004

Claim No: MSD/V/18-001128

Sum Insured:

Excess:

Make of Veh:
 (Client's Record)

D.O.A. 16/08/2018

CA / REV / REP. / REV 24 HRS 1up?


Date/Time: 10:28am @ 21/11/18

Person Contacted: Michael

H.O.D. Endorsement:

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate	
	811 5256P-CS3/INC/2007101/Gen-1	DOA: 13/4/2012
	GBE 9204-NA/MSG18004362/1c4	DOA: 6/3/2018
	Dismantle: 23/8/2018	
26/3/19	Submit LS \$4700, 8 days. (Red \$1900, 25%)	

 26/3/2019
 45\$4700, 8 days

RECEIVED 27 MAR 2019

Taufik

REF:

MS16

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s: _____
of: _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

WP' PRS'

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SSL5256P** Yr Regn: **Dec / 2008**
Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Mitsubishi Lancer.** S.C. **1584**
Colour: **Shw** A/C: **Insured / Std / NI / NA**
Sp Reading: **121437** T/Ratio: **Insured / Std / NI / NA**

Eng/No:

C/No: **JM85TCS3A84 010785**

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Inorder / Jammed / Leaked / Burnt or**

Brake: **Inorder / Jammed / Leaked / Burnt or**

Modi: **Nil / S/Rim / STD A/Rim or**

Tyre Size: F: **195/60R15**
R: **~ ~**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Falken.**

Front: **6** mm R/Bal. **6** mm
L/Bal. **6** mm L/Bal. **6** mm
D.O.A. **21/5/18**

Survey held at **A-Tee Auto**

Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop or**
Frt o/s, 4/c

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time: _____ Action / Instruction: **No GIA. 8.kali Bukit Ave 4 #05-27**

Estimated repair range \$4,000 - \$5,000

[Signature]
6/9/2018

Date/Time: File Pass to? ☐ : Preli. Report

☐ : Final Report

Date/Time: File Return to?

2)

Report Format: **PRS**

Lump Sum / I.B. / I.S

Days Of Repair:

Resurvey No. of Trip: **1**

Survey Fee

Transportation

S + RS = 3

Photos

Notes

Add Fee: ☐ Site Insp. (\$)

☐ Interview (\$)

☐ Tech. Insp. (\$)

☐ Workshop (\$)

TOTAL

120

10

130

Nivitha (LKK Auto)

From: Accounts (LKKAuto) <account@lkkauto.com>
Sent: Tuesday, 12 March 2019 11:19 AM
To: Admin-D (LKKAuto)
Cc: Accounts (LKKAuto)
Subject: RE: Report Send Back Alerts - SJL5256P (TP)

Dear Nivitha,

FYNA Please...

Pending for Survey Report - CS3/MSG18015201/T1Z4D3E2

11 Mar 2019 14:41	Ins Send Back Adj Rpt	To conduct paper survey.	[I] Elaine Ngu Siau Mei
11 Mar 2019 14:41	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/03/13	[I] Merimen Administrator
11 Mar 2019 14:41	Adj Mandate Set	Maintained.	[I] Merimen Administrator

Best Regards,

SuthaShelia (Shelia) | Accounts Dept.

LKK Auto Consultants Pte Ltd

Phone: 6742 9588 | email: account@lkkauto.com | fax: 6844-8805

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Do-Not-Reply [mailto:do-not-reply@merimen.com]

Sent: Monday, 11 March 2019 3:00 PM

To: account@lkkauto.com

Subject: Report Send Back Alerts - SJL5256P (TP)

Dear Sir / Madam,

Please login to Merimen Online at www.merimen.com.sg for more information.


Thanks,
The Merimen Team



This email has been checked for viruses by AVG antivirus software.
www.avg.com

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN 201330709H

EN



ARULCHELVAN S

Your Ref : To be advised
Our Ref : AS.181792.DT(MQ)

18/09/2018

25 September 2018

MSIG Insurance (S) Pte Ltd
16 Raffles Quay
#24-01 Hong Leong Building 2
Singapore 048581

BY PDX

KST AUTO RENTAL PTE LTD
3021A UBI ROAD 1
#01-42
SINGAPORE 408715

BY CERTIFICATE OF POSTING

Dear Sirs,

ACCIDENT INVOLVING SJL 5256P & GBE 920U ALONG WOODLANDS DRIVE 16 ON 16 AUGUST 2018

We refer to the above matter.

We act for COVE RENTALS, the owner of motor vehicle SJL 5256P involved in the captioned accident.

We were instructed by our client to claim damages against you in connection with a road traffic accident ALONG WOODLANDS DRIVE 16 ON 16 AUGUST 2018 involving our client's motor vehicle SJL 5256P and your motor vehicle GBE 920U driven by you at the material time.

We are instructed that the accident was caused by your negligent driving and/or management of your vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:

a)	Costs of Repair		S\$ 7,062.00
b)	Rental (\$120 x 12 days)		S\$ 1,440.00
c)	Survey Report fee		S\$ 628.00
d)	LTA		S\$ 7.49
e)	GIA		S\$ 29.00

f)	Costs		S\$ 2,000.00
g)	Total		S\$11,166.49

A copy of each of the following supporting documents is enclosed.

- a) A copy of our client's police report;
- b) A copy of Final Repair Bill;
- c) A copy of the LTA search; and
- d) A copy of the survey report, invoice and photographs of our client's motor vehicle.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully,

MR ARULCHELVAN S

Enclosure(s)

8, Kaki Bukit Ave 4 #05-27 Premier Singapore 415875

Email: dreamcarzleasing@gmail.com

Tel: +65 6384 5206 Fax: +65 6384 5205

DCL

DREAM CARZ LEASING
PTE LTD

ROC No: 201433037R

VEHICLE RENTAL AGREEMENT

VHA No: 1923

HIRER'S PARTICULAR

Name: (as in I/C) A ZAINI BIN ABU BAKAR

NRIC/PASSPORT No: S72315041

Address (Res): BLK 705A WOODLANDS RISE
#13-98 SINGAPORE 731785

Name & Address of Employer: _____

Occupation: _____ Driving Exp: 7 YRS

Driving Licence No: S72315041 D/L Type: Local / International

Issue Date: 06/07/18 Date of Birth: 21/01/1972

Tel: (O) _____ (R) _____ HP / PG _____

ADDITIONAL DRIVER'S PARTICULARS

(as in I/C) _____

NRIC/PASSPORT No: _____


Address (Res): _____

Driving Licence No: _____ D/L Type: Local / International

Issue Date: _____ Date of Birth: _____

Occupation: _____ Driving Exp: _____

VEHICLE CHECK LIST



ACCESSORIES CHECK

- | | | |
|---------------------------------------|--------------------------------------|-------------------------------------|
| <input type="checkbox"/> Ashtray | <input type="checkbox"/> Cig Lighter | <input type="checkbox"/> S/Tyre |
| <input type="checkbox"/> STD Tools | <input type="checkbox"/> Jack | <input type="checkbox"/> Hub Caps |
| <input type="checkbox"/> Radio / Cass | <input type="checkbox"/> CD | <input type="checkbox"/> Cartridges |

Vehicle No: SJS0080 Replace Veh No: _____

Mileage Out: _____ Mileage Out: _____

Make & Model: KIA CERATO Auto / Manual
Group: _____

Out : Date 17/08/2018 Time: _____

HIRE / PERIOD EXPIRY Time: _____

NON-WAIVER EXCESS=\$ 2000 / 2000

CHARGES

Daily	12	@ \$ 120	per day	1440	00
Weekly		@ \$	per week		
Monthly		@ \$	per month		
Hours		@ \$	per hour		
Others		@ \$			
CDW		@ \$	per day/month		
PAI		@ \$	per day/month		
Delivery/ Collection Service					

SUB-TOTAL \$ 1440 00

PETROL LEVEL

Out	E	1/4	1/2	3/4	F	
In	E	1/4	1/2	3/4	F	

EXTENSION

Misc. _____

TOTAL CHARGES \$ _____

I have read and agree to the terms and condition on both sides of the agreement. If I have presented a charge/ credit card for payment, agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/ credit card voucher. All information I have given Dream Carz Leasing Pte Ltd in connection with this agreement is true.

IMPORTANT

ONLY PERSON ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE. ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER, AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.

THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE. IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS. VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY. AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY WIN WIN CAR RENTAL.

TURN OF VEHICLE, THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN* SINGAPORE OF HIRER / DRIVER * FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO WIN WIN CAR RENTAL AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN TIME IN MILEAGE CHECKED BY REMARKS

9/08/18

SIGNATURE OF HIRER/DRIVER

Enquire Vehicle & Owner Information (Vehicle No. GBE920U As At 17 Aug 2018 / 17:42:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: SJL5256P

Current Owner Details

Owner ID Type: Company

Owner ID: 200806860W

Owner Name: KST AUTO RENTAL PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 3021A

Registered Street Name: UBI ROAD 1

Registered Unit No.: # 01 - 42

Registered Building Name: -

Registered Postal Code: 408715

Current Vehicle Details

Vehicle No.: GBE920U

Make Description/Model: NISSAN / NV200 1.5L MT ABS AIRBAG 2WD 6DR EURO 5

Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD



Your last login date and time was 19 Sep 2018, 16:55:12.

For security reasons, please **CLEAR YOUR CACHE** after each session.

S/No	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount
1	Vehicle	GBE920U	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49

ARUL

dt

JOB SUMMARY REPORT**A-TEC AUTOMOTIVE PTE LTD****8 Kaki Bukit Ave 4****#05-27 Premier****Singapore 415875****BILLING****BILL to -**

Vehicle NO : SJL5256P
Repair Type : LUMPSUM
Repair As Per Surveyor Report: \$ 6,600.00
Material Cost :
Less Repair Items/Adjustment
Special Nett Items :
Total Repair Cost : \$ 6,600.00
Add Gst 7% \$ 462.00
Final Repair Cost : \$ 7,062.00

Others

Search Fees (LTA) \$ -
Surveyor Fees \$ 628.00
Loss of Rental \$ 1,440.00 12 Days (Include waiting for third party surveyor,
Saturday and Sunday)
Loss Of Use \$ -
Towing Fees \$ -
Gia Report \$ 29.00
VEP \$ -
Total Amount Bill : \$ 9,159.00

Approved By : Cheong Chip Huat
Date :

Signature:



A-TEC AUTOMOTIVE PTE LTD

8 Kaki Bukit Ave 4 #05-27 Premier Singapore 415875

Company Reg No: 201227298M

GST Reg No: 201227298M

EMAIL : atec_automotive@yahoo.com.sg

TEL: 6384-5206

FAX: 6384-5205

NAME Cove Rentals Pte Ltd

DATE : 13/9/2018

PROFORMA TAX INVOICE 7298676

ADDRESS : 264 Tampines Street 21
#01-112
Singapore 520264

JOB NO.

VEHICLE NO.

MAKE&MODEL :

TERM

SJL5256P

Mitsubishi Lancer

ITEM	DESCRIPTION	QTY	RATE	AMOUNT
1	Lump Sum Repair As Per Surveyor Report			\$ 6,600.00
SUB-TOTAL				\$ 6,600.00
ADD GST 7%				\$ 462.00
TOTAL AMOUNT				\$ 7,062.00

IMPORTANT

Please remit payment within 7 days from the due date

All cheques must be made payable to **A-TEC AUTOMOTIVE PTE LTD**

This a computer generated document.No signature is required.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6878M
Vehicle Details	
Vehicle No.:	SJL5256P
Vehicle to be Exported:	No
Intended De-registration Date:	27 Aug 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	4G18JT2871
Chassis No.:	JMYSTCS3A8U010785
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$13,131.00
Original Registration Date:	01 Dec 2008
First Registration Date:	01 Dec 2008
Transfer Count:	1
Actual ARF Paid:	\$13,131.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Nov 2018
PARF Rebate Amount:	\$6,565.00
Intended COE Rebate Details	
COE Expiry Date:	30 Nov 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$10,455.00
COE Rebate Amount:	\$270.00
Total Rebate Amount:	\$6,835.00

The information contained herein is correct as at 27 Aug 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/08/2018 17:42
Date Of Accident	16/08/2018 14:30
Exact Location Of Accident	WOODLANDS DRIVE 16(NEARBY MSCP 546A)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJL5256P
Insured/Policyholder	
Name Of Registered Owner	COVE RENTALS PTE LTD
Co Reg No	201626878M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90000000
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	LANCER
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5099019650
Cover Note Number	
Driver	
Name of Driver	A ZAINI BIN ABU BAKAR
NRIC No	S7231504I
Date Of Birth	21/08/1972
Occupation	OUTDOOR
Date Of Driving Pass	25/02/2011
Driving Experience	7 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96787914
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 264 #01-112 TAMPINES STREET 21
Postcode	520264
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles Involved In the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE920U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MD HAFIZURRAHMAN BIN MD HAINI
NRIC/Passport Number	S8936104D
Contact Number	93584826
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	A ZAINI BIN ABU BAKAR
Approximate Age	

Injuries Sustain

Injured person in which vehicle?

SJL5256P

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

Address

Postcode


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 KAKI BUKIT AVE 4
SINGAPORE 413117
Reporting Centre Personnel's Signature
Name: Tel: 67416697
NRIC/IN No: Fax: 67492305
Email: vackb@singnet.com.sg

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Woodlands Drive 16. Suddenly vehicle B passing from my right side with a high speed and hit into the right portion of my vehicle. I wish to stated that was a two direction road, and vehicle B was came from opposite direction.

DECLARATION

I/we declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time



Driver's Signature
(If driver is not the policyholder)
Date & Time

IDAC KAKI BUKIT

23 KAKI BUKIT


Reporting Officer's Signature

Name: Tel: 67410000

NRIC/FIN No.: Fax: 67490000

Email: vackh@idac.gov.sg

SKETCH PLAN



(A) SJL5756P
(B) GB6920U

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along woodlands Drive 16. Suddenly vehicle B passing from my right side with a high speed and hit onto the right portion of my vehicle I wish to stated that was a two direction roads and vehicle B was come from opposite direction.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-130415

Date of Request: 24/08/2018

Your Ref No: WALK IN CHUA

A-TEC AUTOMOTIVE PTE LTD
1 KAKI BUKIT AVE 6 #02-11 AUTOBAY
SINGAPORE 417883

Dear Sir/Madam,

Date of Accident: 16/08/2018

Vehicle No: SJL5256P

Place of Accident: WOODLANDS DRIVE 16(NEARBY MSCP 546A)

Involving Vehicle No: GBE920U

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
GBE920U	WOODLANDS DRIVE 16(NEARBY MSCP 546A)	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque



**GENERAL
INSURANCE
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-128455

Date of Request: 21/08/2018

Your Ref No: WALK IN CHUA

A-TEC AUTOMOTIVE PTE LTD
1 KAKI BUKIT AVE 6 #02-11 AUTOBAY
SINGAPORE 417883

Dear Sir/Madam,

Your Vehicle No: SJL5256P

Date of Accident: 16/08/2018

Place of Accident: WOODLANDS DR 16

Involving Vehicle No: GBE920U (NO REPORT) CALL WITHIN 7 DAYS 23-31/8

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	
GST Amount	14.02
Total Amount Due (GST Inclusive)	0.98
	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

SJL 5256P-3rd
GIA

ACCIDENT STATEMENT

Date Of Report 23/08/2018 18:02
Date Of Accident 16/08/2018 13:30
Exact Location Of Accident CARPARK WOODLANDS) IN PROXIMITY TO VISTA POINT
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBE920U
Insured/Policyholder
Name Of Registered Owner KST AUTO RENTAL PTE LTD
Vehicle Particulars
Manufacturer NISSAN
Model NV200 1.5L MT ABS AIRBAG 2WD 6DR EURO 5
Vehicle Category COMMERCIAL VEHICLE
Insurance Company
Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 7VCC1735580
Cover Note Number
Driver
Name of Driver MUHAMMAD HAFIZURRAHMAN BIN MOHAMED HAINI
NRIC No S8936104D
Address BLK 539 WOODLANDS DRIVE 16
#06-117

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
Number of Passengers (Including Driver) 1

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time: 23/11/2018 11:10 hours

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINCERE
APPRAISAL SERVICES PTE LTD

SINCERE APPRAISAL SERVICES PTE LTD Co.Reg no: 201800639R

60 Paya Lebar Road #07-41 Paya Lebar Square Singapore 409051

Tel : 6636 4628 Fax : 6636 4638 E-mail : sincereappraisal@gmail.com

INVOICE

Cove Rentals Pte Ltd
C/O A-Tec Automotive Pte Ltd
8 Kaki Bukit Avenue 4
#05-27 Premier
Singapore 415875

Invoice No: 140918-565
Our ref: 565/TP/2018
Date: 14/9/2018

Claim Type: Third Party

Date of Loss: 16/8/2018

Vehicle Reg No: SJL5256P


Claimant: Cove Rentals Pte Ltd

Vehicle Make/Model: Mitsubishi Lancer 1.6 A

Description	Amount (S\$)
1. Professional Fee (including Transport, 28 Photographs and Miscellaneous charges)	628
Total	628

Singapore Dollar: Six hundred and twenty eight dollars only.

Cheques should be crossed A/C PAYEE and made payable to Sincere Appraisal Services Pte Ltd



Sincere Appraisal Services Pte Ltd



SINCERE

APPRAISAL SERVICES PTE LTD

VEHICLE DAMAGE INSPECTION REPORT

Our Ref: 565/TP/2018

Date: 14/9/2018

REFERENCE

Date of loss: 16/8/2018
Claimant: Cove Rentals Pte Ltd

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL5256P	Make &	Mitsubishi
Reg date:	1/12/2008	Model	Lancer 1.6 A
Colour:	Silver	Engine No:	4G18JT2871
Type:	Motor Car	Chassis No:	JMYSTCS3A8U010785
Type of Claims:	Third Party	Odometer No:	171437km
		Engine Cap:	1584cc

CONDITION OF VEHICLE AT THE TIME OF SURVEY (STATIC ONLY)

General Condition:	Good	Steering:	Good	Engine Modification:	Nil
Paint work:	Good	Handbrake:	Good	Pre-accident	
		Footbrake:	Good	Damage:	Nil

CONDITION OF TYRES

Front Left Size:	Falken 195/60R15 70%	Front Right Size:	Falken 195/60R15 70%
Rear Left Size:	Falken 195/60R15 70%	Rear Right Size:	Falken 195/60R15 70%

The above percentages represent the remaining life of the tyre threads

COST OF REPAIRS

	Repairer S\$	Adjuster S\$
Parts	\$ 6,040.10	\$ 5,428.40
Labour	\$ 3,470.00	\$ 2,840.00
Calculated Cost (S\$) :	\$ 9,510.10	\$ 8,268.40


Recommended Lump Sum Repair Cost (S\$) : \$ 6,600.00

Date of Assignment: 17/8/2018
Date Inspected: 17/8/2018
Est. repair Period: 12 days

Inspected At: A-Tec Automotive Pte Ltd
8 Kaki Bukit Avenue 4
#05-27 Premier
Singapore 415875

POINT OF IMPACT

Damaged at the right hand front portion



BRIEF CIRCUMSTANCES OF ACCIDENT

The Insured's vehicle collided onto the Third Party's vehicle at the entrance of Multi-Storey carpark of Woodlands Drive 16, Block 546A.

GENERAL DESCRIPTION OF DAMAGES

Our visual inspection of the vehicle revealed that the damages noted are at the right hand front portion.

SPECIAL REMARKS

We have inspected the actual damages found on the vehicle and recommend the replacement of parts and repairs accordingly. The estimated repair cost is \$9,510.10. The repairer has agreed to undertake the repairs at our adjusted lump sum amount of \$6,600.00.

We have not authorised the repair. Under normal circumstances, estimated 12 working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.



Dave Chang
Automotive Appraiser
AUTO. ENG, CAE, CGI
MIRTE, MSAAA, MTM

Automotive Appraiser: Dave Chang

Please note that this report is solely based on our findings at the time and place of inspection. This inspection has been carried out to our best knowledge and ability. Any other liability is hereby excluded.

ANNEX A

REPAIR DETAILS

Recommended Parts

No	Qty	Description	Condition	Repairer's Amount	Adjuster's Amount
1	1	Front bumper assy	warped	\$ 695.00	\$ 695.00
2	1	Front bumper right bracket	bent/necessary	\$ 58.00	\$ 58.00
3	1	Front bumper right retainer	bent/necessary	\$ 59.00	\$ 59.00
4	1	Front right headlamp	bent/cut	\$ 619.00	\$ 619.00
5	1	Front right fender assy	deformed	\$ 639.00	\$ 639.00
6	1	Front right fender lamp	cut	\$ 68.00	\$ 68.00
7	1	Front right fender inner cowl	necessary	\$ 121.00	\$ 121.00
8	1	Front right door panel	dented	\$ 983.00	\$ 983.00 <i>RT</i>
9	1	Front right suspension assy	bent	\$ 650.00	\$ 650.00
10	1	Front right knuckle arm	bent	\$ 352.00	\$ 352.00
11	1	Front right wheel hub bearing	bent	\$ 252.00	\$ 252.00
12	1	Front right lower arm	bent	\$ 430.00	\$ 430.00
13	1	Front support panel assy	repair	\$ 563.00	\$ -
Less 10%				\$ 5,489.00	\$ 4,926.00
				\$ 548.90	\$ 492.60
				\$ 4,940.10	\$ 4,433.40

Special Nett Items

1	10	Front bumper clips	warped	\$ 50.00	\$ 50.00 <i>30</i>
2	6	Front right fender inner cowl clips	necessary	\$ 20.00	\$ 20.00
3	1	Front right sports rim	grazed/cut	\$ 680.00	\$ 680.00 <i>380</i>
4	1	Front right tyre	grazed	\$ 350.00	\$ 245.00 <i>150</i>
				\$ 1,100.00	\$ 995.00
Total parts				\$ 6,040.10	\$ 5,428.40 <i>580</i>

ANNEX B

REPAIR DETAILS

Recommended Labour

No	Description	Repairer's Amount	Adjuster's Amount
1	Labour for panel beating, cut, weld, straighten front right and front portion and replace front right and front damaged parts.	\$ 1,200.00	\$ 1,000.00 700
2	To putty and spray painting front right and front portion.	\$ 1,200.00	\$ 1,000.00 700
3	To check wiring and focus front headlamp.	\$ 50.00	\$ 30.00 ✓
4	To apply anti rust proofing to front right affected area.	\$ 120.00	\$ 100.00 40
5	To balance front right wheel.	\$ 50.00	\$ 30.00 ✓
6	To conduct wheel alignment.	\$ 80.00	\$ 60.00 ✓
7	To remove and install front right undercarriage parts.	\$ 350.00	\$ 300.00 150
8	To remove and install front right door lock mechanism.	\$ 80.00	\$ 60.00 Xnn.
9	To transfer front right door glass to new door.	\$ 80.00	\$ 60.00 Xnn.
10	To check front right door for function.	\$ 80.00	\$ 60.00 30
11	To remove and install front right door visor to facilitate the repair.	\$ 80.00	\$ 60.00 Xnn.
12	Towing service.	\$ 100.00	\$ 80.00 1740
Total labour :		\$ 3,470.00	\$ 2,840.00

ANNEX C

REPAIR DETAILS

Adjusted Repair Cost

	Repairer's Amount	Adjuster's Amount
Total parts :	\$ 6,040.10	\$ 5,428.40
Total labour :	\$ 3,470.00	\$ 2,840.00
Total repair cost :	\$ 9,510.10	\$ 8,268.40

Adjusted Repair Cost (Lump Sum Repair)

\$ 6,600.00

5868.70
 1534700 #
 8 days

...CLAIM SUBFOLDER...(Pending for Survey Report)




































Paper Survey

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Aug 2018		20 Aug 2018 15:56 Edit Adj Rpt	S\$4,700.00 Edit Estimates	S\$4,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	KST AUTO RENTAL PTE LTD , Co. Reg. No.: NA								
Main Claimant:	COVE RENTALS PTE LTD , Co. Reg. No.: 201626878M								
Vehicle Reg. No.:	SJL5256P	Date of Loss:	16/08/2018 00:00 - :59 [116 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/18-001128	Policy/Cover Note No.:	MSD/VCC/17/002004 (Comprehensive) Coverage: 29/08/2017 - 28/08/2018						
Vehicle Reg. No. (Insured):	GBE920U	Policy No. (Claimant):							
		Excess:							
Repairer:	A-Tec Automotive Pte Ltd (Kaki Bukit) 8 Kaki Bukit Avenue 4 # 05-27 Premier, 415875 Kaki Bukit - Tel: (1) 90626929 , (2) 97103383								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 13/03/2019]								
Adj Asg. Remarks:	SJE Disagree Please appoint LKK and contact Ms Peggie @ 6384 5206. Liability (Non-reporting)								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
<ul style="list-style-type: none"> MSIG_SG (11/03/2019): Report Send Back Alerts - SJL5256P (TP) 									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJL5256P (MSC/V/18-001128)**
[GBE920U]
TP
COVE RENTALS PTE LTD
Aug 16 2018 12:00AM
[KST AUTO RENTAL PTE LTD]
A-Tec Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/08/18 12:28	Non Reporting Letter to OI	 Load HTML	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
2	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
3	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
4	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
5	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
6	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
7	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
8	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
9	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
10	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
11	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
12	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
13	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
14	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
15	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
16	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
17	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
18	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
19	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
20	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
21	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
22	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
23	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
24	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
25	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
26	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
27	24/08/18 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
28	04/09/18 11:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	04/09/18 11:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	04/09/18 11:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	04/09/18 11:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	04/09/18 11:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	04/09/18 11:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	04/09/18 11:18	Photographs of Damaged Parts	 Load JPG	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	04/09/18 11:18	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
36	04/09/18 11:18	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
37	04/09/18 11:18	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
38	04/09/18 11:18	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
39	04/09/18 11:18	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
40	04/09/18 11:18	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/08/18 10:56	SJE DISAGREE LKK	Load PDF	
2	20/08/18 12:24	PRI	Load PDF	
3	22/10/18 09:32	LOD, RENTAL AGREEMENT, LTA SEARCH, JOB SUMMARY REPORT, REPAIR BILL, SJLS256P GIA REPORT, GIA SEARCH, GBE920U GIA REPORT, TAX INVOICE, SURVEY REPORT,	Load PDF	
4	11/03/19 14:45	Survey photo	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/03/19 08:57	Colour Photo	Load PDF	
2	28/03/19 08:57	PRS Invoice	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18015201/T1QD3E2-1

Date: 28/03/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VCC/17/002004		
Claimant Vehicle No :	SJL5256P	Insured Vehicle No :	GBE920U		
Date of Loss:	16/08/2018	Nature of Claim:	TP	Claim No:	MSC/V/18-001128

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL5256P		Engine No:	4G18JT2871
Make & Model:	MITSUBISHI LANCER, 1.6 (A)		Chassis No:	JMYSTCS3A8U010785
Reg. Date:	01/12/2008 (Man. Year: 2008)		Odometer:	171437 km
Colour:	Silver			
Engine Capacity:	1584 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,040.10	4,128.70	1,911.40	31.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,470.00	1,740.00	1,730.00	49.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,510.10	5,868.70	3,641.40	38.29
Approved Total (Overridden) (S\$)		4,700.00		
Nett Amount (S\$)	9,510.10	4,700.00	4,810.10	50.58

INSPECTION

Date of Assignment:	20/08/2018	
Date Inspected:	21/08/2018	Inspected At: A-Tec Automotive Pte Ltd (Kaki Bukit) 8 Kaki Bukit Avenue 4 # 05-27 Premier Singapore 415875
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Mar 2019)
Parts:	143	MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL5256P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ASSY	Warped	695.00 FL	*695.00 FL
2	1		*FRONT BUMPER RIGHT BRACKET	Bent / Necessary	58.00 FL	*58.00 FL
3	1		*FRONT BUMPER RIGHT RETAINER	Bent / Necessary	59.00 FL	*59.00 FL
4	1		*FRONT RIGHT HEADLAMP	Bent / Cut	619.00 FL	*619.00 FL
5	1		*FRONT RIGHT FENDER ASSY	Deformed	639.00 FL	*639.00 FL
6	1		*FRONT RIGHT FENDER LAMP	Cut	68.00 FL	*68.00 FL
7	1		*FRONT RIGHT FENDER INNER COWLING	Necessary	121.00 FL	*121.00 FL
8	1		*FRONT RIGHT DOOR PANEL	Repair	983.00 FL	*- FL
9	1		*FRONT RIGHT SUSPENSION ASSY	Bent	650.00 FL	*650.00 FL
10	1		*FRONT RIGHT KNUCKLE ARM	Bent	352.00 FL	*352.00 FL
11	1		*FRONT RIGHT WHEEL HUB BEARING	Bent	252.00 FL	*252.00 FL
12	1		*FRONT RIGHT LOWER ARM	Bent	430.00 FL	*430.00 FL
13	1		*FRONT SUPPORT PANEL ASSY	Repair	563.00 FL	*- FL
14	10		*FRONT BUMPER CLIPS	Warped	50.00 FS	*30.00 FS
15	1		*FRONT RIGHT FENDER INNER COWLING CLIPS (6PCS)	Necessary	20.00 FS	*20.00 FS
16	1		*FRONT RIGHT SPORTS RIM	Grazed / Cut	680.00 FS	*380.00 FS
17	1		*FRONT RIGHT TYRE	Grazed	350.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,589.00	4,523.00
- List Item Discount on L Items 10.00/10.00% (S\$)	548.90	394.30
Total Parts (S\$)	6,040.10	4,128.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT RIGHT AND FRONT PORTION AND REPLACE FRONT RIGHT AND FRONT DAMAGED PARTS	New	1,200.00	700.00
2	TO PUTTY AND SPRAY PAINTING FRONT RIGHT AND FRONT PORTION	New	1,200.00	700.00
3	TO CHECK WIRING AND FOCUS FRONT HEADLAMP	New	50.00	30.00
4	TO APPLY ANTI RUST PROOFING TO FRONT RIGHT AFFECTED AREA	New	120.00	40.00
5	TO BALANCE FRONT RIGHT WHEEL	New	50.00	30.00
6	TO CONDUCT WHEEL ALIGNMENT	New	80.00	60.00
7	TO REMOVE AND INSTALL FRONT RIGHT UNDERCARRIAGE PARTS	New	350.00	150.00
8	TO REMOVE AND INSTALL FRONT RIGHT DOOR LOCK MECHANISM	New	80.00	0.00
9	TO TRANSFER FRONT RIGHT DOOR GLASS TO NEW DOOR	New	80.00	0.00
10	TO CHECK FRONT RIGHT DOOR FOR FUNCTION	New	80.00	30.00
11	TO REMOVE AND INSTALL FRONT RIGHT DOOR VISOR TO FACILITATE THE REPAIR	New	80.00	0.00
12	TOWING SERVICES	New	100.00	0.00
Gross Labour Cost (S\$)			3,470.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >