



Your Ref: 19.26510 PD-O

Date: 24th Jun 2019

Our Ref : CS3/ASM19000420/Gtd3e2-1

M/s AXA Insurance Pte Ltd
C/O: Seah Ong & Partners LLP
36 Robinson Road
#12-03 City House
Singapore 068877
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKF 7051U
INSURED VEHICLE: SKW 2847J
ACCIDENT DATE: 03/01/2019**

We thank you for your instruction on 01/03/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKF 7051U from M/s C L Appraiser Pte Ltd.
- b) Singapore Accident Statement of Vehicle SKF 7051U, SKW 2847J and SLF 4181K.
- c) Final Repair Bill of SKF 7051U from M/s Motor Intelligence Automo Pte Ltd.
- d) Colour damaged vehicle photographs of SKF 7051U.

Pre-Repair Inspection Date : 08/01/2019 at M/s Motor Intelligence Automo Pte Ltd, Bartley Biz Centre, 13 Kaki Bukit Road 4, #01-20, Singapore 417807.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SKF 7051U
Make & Model : Ford Focus 1.6 Titanium Station
Year of Registration : 2012
Chassis Number : WF0LXXGCBLCC01670
Engine Capacity : 1596 cc

2. We recommend that the repairs of the entire damage require about 8 (Eight) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.