



Your Ref: 19.26578 PD-O

Date: 29th Apr 2019

Our Ref : CS3/ASM19000214/Gvd3e2-1

M/s AXA Insurance Pte Ltd
C/O: Seah Ong & Partners LLP
36 Robinson Road
#12-03 City House
Singapore 068877
(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKA 8288Z
INSURED VEHICLE: SKB 1688T
ACCIDENT DATE: 21/12/2018

We thank you for your instruction on 09/03/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKA 8288Z from M/s Absolute Appraisal Services Pte Ltd.
- b) Singapore Accident Statement of Vehicles SKA 8288Z and SKB 1688T.
- c) Final Repair Bill of SKA 8288Z from M/s Lian Heng Painter Company.
- d) Colour damaged vehicle photographs of SKA 8288Z.

Pre-Repair Inspection Date : 04/01/2019 at M/s Lian Heng Painter Company, 160 Sin Ming Drive #06-10 Sin Ming Autocity, Singapore 575722.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKA 8288Z
Make & Model	: B.M.W. 520I 2.0L AT D/AB 2WD 4DR GAS/D NAV
Year of Registration	: 2012
Chassis Number	: WBAXG12000DX50680
Engine Capacity	: 1997 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.