

ASSIGNMENT

REF

03/CTI19004897/Kqd3<sup>n2</sup>

per of Instruction

ASSIGNMENT

Menmen

Kenneke

ASSIGNMENT (Office)

From (Person)

Irene Lay

CTI

Date/Time: 13/3/17 @ 12:58pm

Estimated Cost

Rate

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No

SLN 2727H

Insured

YM 7377C

at Workshop no

Accord Auto

Tel

69819517

of

10 AMK Ind. park 2A # 03-11

Policy No

DMCVSN1905681900

Claim No

SNM19D20112302

Sum Insured

Excess

Make of Veh

D.O.A

11103/2017

(Client's Record)

CA / REV / REP / REV 24 HRS

H.O.D. Endorsement

Date/Time

1:40pm @ 13/3/17

Person Contacted

Jessie

Vehicle

INT/OUT

Date/Time

Action/Instruction (✓) Estimate

SLN 2727H -X

YM 7377C -X

28/3

8694.88 Cash (Red 5120, 15%)

ASS. REC. BY:

REF: C721

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

1-B 1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLN 27274

Yr Regn:

08, 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3

c.c

1498

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

49838

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JMBN22481017272

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/50R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

11/3/19

D.O.I.

13/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt L/don mira

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

RECEIVED 28 MAR 2019

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1) 28/3/2019

Date/Time, File Return to?

2)

Days Of Repair:

2

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ - RS. \$

Photos

Others

TOTAL

220

Report Format:

MER-11

Lump Sum / I.B.I. (\$

694.88

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Mar 2019		13 Mar 2019 12:58 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:				
Main Claimant:	NG GEOK CHOO			
Vehicle Reg. No.:	SLN2727H	Date of Loss:	11/03/2019 10:00 - :59	
Claim Type:	TP / SNM19D201123C02	Policy/Cover Note No.:	DMCVSN1905681900	
Vehicle Reg. No. (Insured):	YM7377C	Policy No. (Claimant):		
		Excess:	S\$0.00	
Repairer:	Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point, 568047 Ang Mo Kio - Tel: 64819517/85715140			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/03/2019]			

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

### Enquire Transfer Fee

VEHICLE DETAILS	
Vehicle No.:	SLN2727H
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	With Sun Roof
Vehicle Scheme:	Normal
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT LED EU6
Chassis No.:	JM6BN22A8H0172772
Propellant:	Petrol
Engine No.:	P520463066
Engine Capacity:	1496 cc
Maximum Power Output:	88.0 kW (118 bhp)
Maximum Laden Weight:	1835 kg
Unladen Weight:	1331 kg
Year Of Manufacture:	2017
Original Registration Date:	11 Aug 2017
Lifespan Expiry Date:	-
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium:	\$42,801.00
COE Expiry Date:	10 Aug 2027
Road Tax Expiry Date:	10 Aug 2019
PARF Eligibility Expiry Date:	10 Aug 2027
Inspection Due Date:	10 Aug 2020
Intended Transfer Date:	11 Mar 2019
CO2 Emission:	131.00 (g/km)
CEV/VES Rebate Utilised Amount:	\$5,000.00
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
<b>Total Amount Payable:</b>			<b>25.00</b>

You may print this page for reference.

OK

Print

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/03/2019 14:45
Date Of Accident	11/03/2019 10:35
Exact Location Of Accident	CTE EXIT TOWARDS UPPER SERANGOON ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN2727H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NG GEOK CHOO
NRIC No	S1734750J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91993355
Alternative Phone No	OFFICE-91993355

### Vehicle Particulars

Manufacturer	MAZDA
Model	3-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01013030
Cover Note Number	

### Driver

Name of Driver	CHEN YAN HAN
NRIC No	S8705393H
Date Of Birth	03/03/1987
Occupation	OUTDOOR
Date Of Driving Pass	02/07/2009
Driving Experience	9 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91993355
Fax Number	
Contact Number	
EMail Address	BRYANCHEN6554@GMAIL.COM

Address	BLK 669 JURONG WEST STREET 64 #07-80
Postcode	642669
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	RELATIVE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON 11/03/2019 AROUND 10:35AM, I WAS EXITING CTE TOWARDS UPPER SERANGOON ROAD. SUDDENLY VEHICLE B (YM7377C) ON EXTREME LEFT LANE CHANGE LANE, CUT INTO MY FRONT AND HIT ONTO MY LEFT SIDE MIRROR.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YM7377C
Vehicle Make/Model/Colour	MIT. CANTER
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 8/03/2019  
2:06pm

Reporting Centre Personnel's Signature  
Name: Jessy Soe  
NRIC/FIN No.: G2031072W

### Accident Sketch Plan

SKETCH PLAN Vehicle A: SLN 2727 H Vehicle B: YM7377C



CTE exit towards  
Upper Serangoon Road


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature:   
(if driver is not the policyholder)  
Date & Time: 11/03/2019  
2:06pm

Reporting Centre Personnel's Signature  
Name: Jessy See  
NRIC/FIN No.: G2031072W



# ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

## ESTIMATE

China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road

#15-00 Springleft Tower

Singapore 079909

Attn: Accident Claims Department

Date :

12/03/2019

Vehicle No :

SLN2727H

Veh Make/Model :

Mazda 3 Sedan 1.5 AT

YOM :

2017

Chassis No :

JM6BN22A8H0172772

Date of Accident :

11/03/2019

*Not Authorised  
Respray Bp painting  
2 days*

No	Qty	Description	Amount \$
<b>List Items:-</b>			
1	1	LH side mirror <i>378</i>	\$ <i>Br</i> 378.00
2	1	LH side mirror glass	\$ <i>mi</i> 50.60
3	1	LH side mirror cover	\$ <i>mi</i> 122.00
4	1	LH side mirror lamp	\$ <i>CM</i> 118.00
<b>Total - List Item</b>			\$ <b>668.60</b>
<b>Less 20%</b>			\$ <b>133.72</b>
<b>Total</b>			\$ <b>534.88</b>
<b>Labour Charges:-</b>			
1		Spray painting on all affected area.	\$ 100.00
2		To dismantle and install LH side mirror.	\$ 120.00
3		To check wiring system & light.	\$ 60.00
<b>Total - L/C</b>			\$ <b>280.00</b>
<b>Sub-Total</b>			\$ <b>814.88</b>
<b>7% GST</b>			\$ <b>57.04</b>
<b>Total</b>			\$ <b>871.92</b>

*601  
801  
201*

*EEK Auto Consultants hence notify the Repairer of the following:*

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

## LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119004597/KQD3N2

Date: 01/04/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1905681900
Claimant Vehicle No :	SLN2727H	Insured Vehicle No :	YM7377C
Date of Loss:	11/03/2019	Nature of Claim:	TP
		Claim No:	SNM19D201123C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLN2727H	Engine No:	P520463066
Make & Model:	MAZDA 3, 1.5 (A)	Chassis No:	JM6BN22A8H0172772
Reg. Date:	11/08/2017 (Man. Year: 2017)	Odometer:	49638 km
Colour:	Metallic Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/50ZR17	Rear Tyre Size:	215/50ZR17
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	534.88	534.88	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	280.00	160.00	120.00	42.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>814.88</b>	<b>694.88</b>	<b>120.00</b>	<b>14.73</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>57.04</b>	<b>48.64</b>	<b>8.40</b>	<b>14.73</b>
<b>Nett Amount (\$\$)</b>	<b>871.92</b>	<b>743.52</b>	<b>128.40</b>	<b>14.73</b>

## INSPECTION

Date of Assignment:	13/03/2019	
Date Inspected:	13/03/2019	Inspected At: Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point Singapore 568047

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 01 Apr 2019)
<b>Parts:</b> 144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLN2727H)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH SIDE MIRROR	Broken	378.00 FL	*378.00 FL
2	1		*LH SIDE MIRROR GLASS	Missing	50.60 FL	*50.60 FL
3	1		*LH SIDE MIRROR COVER	Missing	122.00 FL	*122.00 FL
4	1		*LH SIDE MIRROR LAMP	Cracked	118.00 FL	*118.00 FL
F=Franchise part, L=ListItemDisc.						
Sub Total (S\$)					668.60	668.60
- List Item Discount on L Items 20.00/20.00% (S\$)					133.72	133.72
Total Parts (S\$)					534.88	534.88

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	SPRAY PAINTING ON ALL AFFECTED AREAS	New	100.00	60.00
2	TO DISMANTLE AND INSTALL LH SIDE MIRROR	New	120.00	80.00
3	TO CHECK WIRING SYSTEM & LIGHT	New	60.00	20.00
Gross Labour Cost (S\$)			<b>280.00</b>	<b>160.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >