

ASS. REC. BY:

REP: CS3 / MSG 17004599 / Jcd3

Special Instruction:

Surveyor: Hwee Jie

ASSIGNMENT (Office)

Menmen

From (Person): Chhia Nyuk Pui

of MSG

Date/Time: 12/3/19 @ 4:14pm

Estimated Cost:

Bill to:

OD / (P) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP 5908T

Insured:

YP 6925L

at Workshop n/s

Kent Seng Car

Tel:

9004 8759

of

13K 1016 Yishun Ind. Park A # 01-238

Policy No:

B29086832MLC

Claim No:

582997

Sum Insured:

Excess:

Make of Veh:

D.O.A.

2/1/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:37pm @ 12/3/19

Person Contacted:

Ah Sing

Vehicle IN / OUT

OUT

Date/Time	Action/Instruction (X) Estimate
	YP 5908T - CS/MSG 17020197 / R1 + b2
	YP 6925L - X
	Dismantle: 25/4/2019
	After repair: 25/4/2019

D.O.A - 17/10/2017

REF: MS16

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop n/s BILK1016 Yishun Ind
 of #01-238
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No. YP5908T Yr Regn: 25 Apr 2017
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Hino c.c. 4009
 Colour: multi colour A/C: Insured / Std / NI / NA
 Sp. Reading: 55048 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JHNUCT3H60K020623
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/85R16
 R: _____
BS/DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front Rear
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 21/1/19 D.O.I. 22/4/19
 Survey held at Kant Seng
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	PRS
	Range: \$4000-\$5000 4 days
	<u>23/4/2019</u>

Date/Time. File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

1 \$ + PS. 1 \$

☐ Photos

☐ Others

TOTAL

1)

Date/Time. File Return to?

2)

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format : PRS

Lump Sum / I.B.I: (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jan 2019		12 Mar 2019 16:14 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	LIM KIAN SENG FOOD SUPPLIER PTE LTD, Co. Reg. No.: 201024469W		
Main Claimant:	ACELINK LOGISTICS PTE LTD, Co. Reg. No.: 199202352M		
Vehicle Reg. No.:	YP5908T	Date of Loss:	21/01/2019 11:00 - :59 [20 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 582997	Policy/Cover Note No.:	B29086832MKC (Comprehensive) Coverage: 20/07/2018 - 19/07/2019
Vehicle Reg. No. (Insured):	YP6925L	Policy No. (Claimant):	
		Excess:	S\$700.00
Repairer:	Kent Seng Car Services (yishun) (HQ) Blk 1016 Yishun Industrial Park A #01-238, 768758 Yishun - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/03/2019]		
Driver/Custodian (Insured):	WANG KHENG HWA (), NRIC: S1182258D, Tel: +6590863985 Email:		
Adj Asg. Remarks:	on WP. SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY: UNCLEAR. CONTACT:AH SENG 9004 8759		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/01/2019 17:40
Date Of Accident	21/01/2019 11:20
Exact Location Of Accident	90 HOUGANG AVE 10 NTUC LOADING BAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP5908T
Insured/Policyholder	
Name Of Registered Owner	ACELINK LOGISTICS PTE LTD
Co Reg No	NA
Email Address	FEREMYCHUA@ACELINK-LOGISTICS.COM
Mobile Phone No	(LOCAL) +65-83554246
Alternative Phone No	OFFICE-68809877

Vehicle Particulars

Manufacturer	HINO
Model	LORRY
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B 29070295 MKF
Cover Note Number	

Driver

Name of Driver	SATHURUKKANAN PREMANAND
Passport No/FIN	G8480448M
Date Of Birth	30/05/1976
Occupation	OUTDOOR
Date Of Driving Pass	31/05/2017
Driving Experience	1 YEAR AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83554246
Fax Number	
Contact Number	OFFICE-68809877
Email Address	NOEMAIL

Address	1 SENOKO ROAD TEE YIH JIA BUILDING SINGAPORE
Postcode	758134
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH COMPANY
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP6925L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	WANG KHENG HWA
NRIC/Passport Number	
Contact Number	90863985
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was doing delivery to 90 Hongkong Ave 10 NTUC, I parked at loading bay and went to NTUC to deliver goods. When I finished delivery and go to my lorry, I saw my bumper got damaged. The driver parking beside my lorry told me another party hit and ~~can~~ ran away. I want to follow up and manage to chase him and took his photo/IC and Contact number.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2352M
Vehicle Details	
Vehicle No.:	YP5908T
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Apr 2019
Vehicle Make:	HINO
Vehicle Model:	XZU710R 14FT WIDE CAB 7T
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	N04CUT20335
Chassis No.:	JHHUCT3H60K020623
Maximum Power Output:	-
Open Market Value:	\$41,506.00
Original Registration Date:	25 Apr 2017
First Registration Date:	25 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$2,076.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Apr 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$12,761.00
COE Rebate Amount:	\$10,212.00
Total Rebate Amount:	\$10,212.00

The information contained herein is correct as at 23 Apr 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jan 2019		12 Mar 2019 16:14 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LIM KIAN SENG FOOD SUPPLIER PTE LTD , Co. Reg. No.: 201024469W		
Main Claimant:	ACELINK LOGISTICS PTE LTD , Co. Reg. No.: 199202352M		
Vehicle Reg. No.:	YP5908T	Date of Loss:	21/01/2019 11:00 - :59 [20 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 582997	Policy/Cover Note No.:	B29086832MKC (Comprehensive) Coverage: 20/07/2018 - 19/07/2019
Vehicle Reg. No. (Insured):	YP6925L	Policy No. (Claimant):	
		Excess:	S\$700.00
Repairer:	Kent Seng Car Services (yishun) (HQ) Blk 1016 Yishun Industrial Park A #01-238, 768758 Yishun - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Imm.Advice due 13/03/2019]		
Driver/Custodian (Insured):	WANG KHENG HWA (), NRIC: S1182258D, Tel: +6590863985 Email:		
Adj Asg. Remarks:	on WP. SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY: UNCLEAR. CONTACT:AH SENG 9004 8759		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***YP5908T (582997)**

[YP6925L]

TP

ACELINK LOGISTICS PTE LTD

Jan 21 2019 11:00AM

[LIM KIAN SENG FOOD SUPPLIER PTE LTD]

Kent Seng Car Services (yishun)

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1 per page ▼	Thumbnail	Print
1	12/03/19 11:55	Accident Statement From:SC - Reg. No: YP6925L, Claimant: LIM KIAN SENG FOOD SUPPLIER PTE LTD	1	Load HTM	

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page ▼	Thumbnail	Print
1	23/04/19 10:12	General View	1	Load JPG	✓
2	23/04/19 10:12	General View	1	Load JPG	✓
3	23/04/19 10:12	General View	1	Load JPG	✓
4	23/04/19 10:12	General View	1	Load JPG	✓
5	23/04/19 10:12	General View	1	Load JPG	✓
6	23/04/19 10:12	General View	1	Load JPG	✓
7	23/04/19 10:12	General View	1	Load JPG	✓
8	23/04/19 10:12	General View	1	Load JPG	✓
9	23/04/19 10:12	General View	1	Load JPG	✓
10	23/04/19 10:12	General View	1	Load JPG	✓
11	23/04/19 10:12	General View	1	Load JPG	✓
12	23/04/19 10:12	General View	1	Load JPG	✓
13	23/04/19 10:12	General View	1	Load JPG	✓
14	23/04/19 10:12	General View	1	Load JPG	✓
15	23/04/19 10:12	General View	1	Load JPG	✓
16	23/04/19 10:12	General View	1	Load JPG	✓
17	23/04/19 10:12	General View	1	Load JPG	✓
18	23/04/19 10:12	General View	1	Load JPG	✓
19	26/04/19 09:08	Dismantled Parts	1	Load JPG	✓
20	26/04/19 09:08	Dismantled Parts	1	Load JPG	✓
21	26/04/19 09:08	Dismantled Parts	1	Load JPG	✓
22	26/04/19 09:08	Dismantled Parts	1	Load JPG	✓
23	26/04/19 09:08	Photo After Spray	1	Load JPG	✓
24	26/04/19 09:08	Photo After Spray	1	Load JPG	✓
25	26/04/19 09:08	Photo After Spray	1	Load JPG	✓
26	26/04/19 09:09	Photo After Spray	1	Load JPG	✓
27	26/04/19 09:09	Photo After Spray	1	Load JPG	✓

Documentation

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1 per page ▼	Thumbnail	Print
1	12/03/19 11:57	YP5908T TP E-FILE REPORT	1	Load PDF	
2	12/03/19 11:57	PRI - M NEDUMARAN & CO	1	Load PDF	

Assessment Reports			1 per page ▼	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
3	12/03/19 13:09	SURVEY DISAGREE ON SJE - ASSIGN LKK	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19004599/JCD3S2

Date: 07/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

B29086832MKC

Claimant Vehicle No : YP5908T

Insured Vehicle No :

YP6925L

Date of Loss: 21/01/2019

Nature of Claim:

TP

Claim No: 582997

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YP5908T

Make & Model: HINO XZU710R, 4.0 D 14FT WIDE CAB 8.5T (M)

Engine No:

N04CUT20335

Reg. Date: 25/04/2017 (Man. Year: 2017)

Chassis No:

JHHUCT3H60K020623

Colour: Multi-colour

Odometer:

55048 km

Engine Capacity: 4009 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/85R16

Rear Tyre Size:

215/85R16

Front Left Side: Bridgestone 7 mm

Rear Left Side:

Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side:

Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 12/03/2019

Date Inspected: 22/04/2019 Inspected At:

Kent Seng Car Services (yishun) (HQ)

Blk 1016 Yishun Industrial Park A #01-238

Singapore 768758

Estimated Period of Repair: 4.0 days

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 07 May 2019)

Parts: N/A HINO XZU710R 4.0 D 14FT WIDE CAB 8.5T (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YP5908T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >