

INS. CASE OWNER:

CC 4, Asm 1900

LKK:

IDAC:

103945

## ASSIGNMENT

Surveyor:

DOI:

Date / Time :

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

Claim No. :

Name of Insured :

Policy No. :

Insured Tel No. :

HP:

Make / Model :

Excess Sec II :SS

D.O.A :

Place of Accident :

Is driver the owner? ( YES / NO )

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. :

If NO or B 28, Ass. Lia :

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent )

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:





## Case Details

Case Reference Number : BUS/03/19/5003  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SMB3584Y

Company Type : SMRT Buses Ltd  
 Estimation ID : EST-6077-ID  
 Assigned By : Audrey Woo Yee Shin

Insurance Company Name : AXA Insurance Singapore Pte Ltd  
 Accident Date and Time : 01/03/2019 08:20 AM  
 Vehicle Age(In Months) : 47

## Documents / Photographs

View Documents / Photographs

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

| SMRT Recommendation   |              |            |                 |                                       |     |                         |                |        |                 |                 | Surveyor Approval        |                              |                               |             |
|-----------------------|--------------|------------|-----------------|---------------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|--------------------------|------------------------------|-------------------------------|-------------|
| BOM Type              | Costing Type | Portion    | Material Number | Part Name                             | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity        | Surveyor Final Price(\$)     | Repair/Replace                | Remarks     |
| Standard              | Main         | BODY LH    | 6011228         | PANEL,EXTERIOR:L/H,FOR ADL DD BUS     | 1   | 436.30                  | 436.30         | 10.00  | 392.67          | Replace         | <div><div>1</div></div>  | <div><div>392.67</div></div> | <div><div>Replace</div></div> | <div></div> |
| Standard              | Main         | BODY LH    | 6011234         | PANEL,EXTERIOR:L/H,FOR ADL DD BUS     | 1   | 537.40                  | 537.40         | 10.00  | 483.66          | Replace         | <div><div>1</div></div>  | <div><div>483.66</div></div> | <div><div>Replace</div></div> | <div></div> |
| Standard              | Main         | Body       | 6011241         | MOULDING,WHEELARCH:LH & RH,FOR ADL DD | 2   | 88.03                   | 176.06         | 10.00  | 158.45          | Replace         | <div><div>2</div></div>  | <div><div>158.45</div></div> | <div><div>Replace</div></div> | <div></div> |
| Standard              | Main         | CONSUMABLE | 4006314         | ADHESIVE,DIRECT GLAZING               | 12  | 37.00                   | 444.00         | 0.00   | 444.00          | Replace         | <div><div>12</div></div> | <div><div>0.00</div></div>   | <div><div>Replace</div></div> | <div></div> |
| Standard              | Main         | CONSUMABLE | 4006313         | PRIMER (SIKA 206 G+P)                 | 1   | 80.00                   | 80.00          | 0.00   | 80.00           | Replace         | <div><div>1</div></div>  | <div><div>80.00</div></div>  | <div><div>Replace</div></div> | <div></div> |
| Standard              | Main         | CONSUMABLE | 4006315         | ACTIVATOR                             | 1   | 80.00                   | 80.00          | 0.00   | 80.00           | Replace         | <div><div>1</div></div>  | <div><div>80.00</div></div>  | <div><div>Replace</div></div> | <div></div> |
| Total Spare Part Cost |              |            |                 |                                       |     |                         |                |        | 1,638.78        |                 | Surveyor Total           |                              | 1,194.78                      |             |
| Lump Sum Discount (%) |              |            |                 |                                       |     |                         |                |        | 0.00            |                 | Lump Sum Dis (%)         |                              | <div><div>20</div></div>      |             |
| Final Spare Part Cost |              |            |                 |                                       |     |                         |                |        | 1,638.78        |                 | Final Sur Total          |                              | 955.82                        |             |

### Labour's Cost Detail

| S.No.  | Costing Type | Job Scope                                                                     | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|-------------------------------------------------------------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. | 2,120.00                | 1,590                   |         |
| Total: |              |                                                                               | 2,120.00                | 1,590.00                |         |

### Spray Cost Detail

| S.No.  | Costing Type | Job Scope          | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|--------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO PUTTY & RESPRAY | 1,218.00                | 1,048                   |         |
| Total: |              |                    | 1,218.00                | 1,048.00                |         |

### Other Cost Detail

| S.No.  | Costing Type | Job Scope | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|-----------|-------------------------|-------------------------|---------|
| Total: |              |           | 0.00                    | 0.00                    |         |

## Summary

|                         | Estimator Assesment(\$) | Surveyor Assesment(\$) |
|-------------------------|-------------------------|------------------------|
| Total Spare Part Detail | 1,638.78                | 955.82                 |
| Total Labour Cost       | 2,120.00                | 1,590.00               |
| Total Spray Painting    | 1,218.00                | 1,048.00               |



|                          | Estimator Assesment(\$)                                                           | Surveyor Assesment(\$)                                                              |
|--------------------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Other                    | 0.00                                                                              | 0.00                                                                                |
| Overall Total            | 4,976.78                                                                          | 3,593.82                                                                            |
| Lump Sum Repair Option   | <input type="checkbox"/>                                                          | <input checked="" type="checkbox"/>                                                 |
| Lump Sum Total           | 0.00                                                                              | 3,600.00                                                                            |
| Surveyor Approved Amount |                                                                                   | 3,600.00                                                                            |
| No of Repair Days*       | 6                                                                                 | 5                                                                                   |
| Remarks                  | -                                                                                 | L/S Repair, PHOTO after paint.                                                      |
| Surveyor Name            |                                                                                   | Hwee jie                                                                            |
| Signature                |  |  |
| Survey Date              | 14/03/2019                                                                        | <input type="button" value="Save"/> <input type="button" value="Clear"/>            |