





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 13/03/2019

User ID : JeongCH

Section A - Accident Details	
Registration Number	SMB3584Y
Case Reference Number	BUS/03/19/5003
Registration Date	4/1/2015
Company Type	SMRT Buses Ltd
Make	ALEXANDER DENNIS
Model	ENVIRO 500
Name of Driver	TAN MING SING
Type of Accident	Side Swipe
Accident Date and Time	3/1/2019 4:20 PM
Accident Reported Date and Time	3/1/2019 11:45 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC,if any	Our bus : left centre body scratches TP: right front corner damaged (AXA)
Prepared Date and Time	3/13/2019 1:50 PM
Chassis Number	SFD76CLR5EMTL3751
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$0.00
Total Spray Cost	\$1,218.00	\$0.00
Total Spare Part Cost	\$1,490.78	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$4,828.78	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	
Prepared / Adjusted By	Jeong Choon Hwee	
ARC / Surveyor Sign Off Date	13/03/2019 2:10 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/03/2019

User ID : JeongCH

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$2,120.00						
Total Labour			\$2,120.00						
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
TO PUTTY & RESPRAY			\$1,218.00						
Total Spray Painting & Panel Beating			\$1,218.00						
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6011241	Body	3612001L02	MOULDING,WHEELARC H:LH & RH,FOR ADL DD	2.00	\$88.03	10.00	\$158.45	Replace	
4006314	CONSUMABLE	Sikaflex-265	ADHESIVE:DIRECT GLAZING	8.00	\$37.00	0.00	\$296.00	Replace	
6011224	BODY LH	30106489	PANEL,EXTERIOR:L/H,F OR ADL DD BUS	1.00	\$537.40	10.00	\$483.66	Replace	
6011224	BODY LH	30106489	PANEL,EXTERIOR:L/H,F OR ADL DD BUS	1.00	\$436.30	10.00	\$392.67	Replace	
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	
4006315	CONSUMABLE		ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	
Total					\$1,258.73		\$1,490.78		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									