



SMRT Accident Vehicle Repair Estimates

Asher

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 07/05/2019

User ID : CatherineLee

Section A - Accident Details



Registration Number	SMB3584Y
Case Reference Number	BUS/03/19/5003
Registration Date	1/4/2015
Company Type	SMRT Buses Ltd
Make	ALEXANDER DENNIS
Model	ENVIRO 500
Name of Driver	TAN MING SING
Type of Accident	Side Swipe
Accident Date and Time	1/3/2019 4:20 PM
Accident Reported Date and Time	1/3/2019 11:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24100597
Special Instruction to ARC, if any	Our bus, left centre body scratches TP: right front corner damaged (AXA)
Prepared Date and Time	13/3/2019 1:50 PM
Chassis Number	SFD76CLR5EMTL3751
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$1,580.00
Total Spray Cost	\$1,218.00	\$1,048.00
Total Spare Part Cost	\$1,412.22	\$1,412.22
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$4,750.22	\$4,050.22
Lump Sum Total	\$0.00	\$4,050.00
Number of Repair Days	6.0	5.0
Prepared / Adjusted By	Jeong Choon Hwee	Hwee jie
ARC / Surveyor Sign Off Date	16/03/2019 1:33 PM	18/03/2019 3:50 PM
Signature		
Remarks		US Repair. PHOTO after paint.

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



L/S \$4050/- Slaps.



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 07/05/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$2,120.00	\$1,590.00
Total Labour	\$2,120.00	\$1,590.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$1,218.00	\$1,048.00
Total Spray Painting & Panel Beating	\$1,218.00	\$1,048.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6011224	BODY LH	30106489	PANEL,EXTERIOR:L/H,F OR ADL DD BUS	1.00	\$436.30	10.00	\$392.67	Replace	Replace
6011224	BODY LH	30106489	PANEL,EXTERIOR:L/H,F OR ADL DD BUS	1.00	\$537.40	10.00	\$483.66	Replace	Replace
6011241	Body	3612001L02	MOULDING,WHEELARC H:LH & RH, FOR ADL DD	2.00	\$88.03	10.00	\$158.45	Replace	Replace
4006314	CONSUMABLE	Sikaflex-265	ADHESIVE,DIRECT GLAZING	12.00	\$37.00	0.00	\$444.00	Replace	Replace
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	Replace
4006315	CONSUMABLE		ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	Replace
Total					\$1,258.73		\$1,638.78		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
6011224	BODY LH	30106489	PANEL,EXTERIOR:L/H,F OR ADL DD BUS	1.00	\$140.56	10.00	\$126.50	Replace	Replace
Total					140.56		126.50		