



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS/III19004614/R1td3e2

64 CECIL STREET  
#05-02 IOB BUILDING SINGAPORE 049711

Date : 27-08-2019



Code : III2

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SKU 3631T
Policy No.		Coverage (\$)	0.00
Claim No.	AC190064	Excess (\$)	0.00
Assign From	GERALDINE ANG	Assign Date	07/03/2019

#### 2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ S400L	c.c	2996
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WDD2221652A188080	Colour	BLACK
Odometer	58218	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/40 R20	PIRELLI	6 mm
L/H Front Tyre	245/40 R20	PIRELLI	6 mm
R/H Rear Tyre	245/40 R20	PIRELLI	6 mm
L/H Rear Tyre	245/40 R20	PIRELLI	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.
---

#### 5. General Information

Accident Date	16/02/2019	Inspection Date	08/03/2019
Survey held at	MOTORWAY CAR CARE CENTRE PTE LTD 1094 LOWER DELTA ROAD MOTORWAY BUILDING . SINGAPORE 169205		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------